

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NOT ADVISED

HQ - Transport Command
Kwangi Camp 3
151, Chua Chu Kang Way
(685248)

Attention : Motor Claim Department

Estimate : ES005256

Date : 06/11/2017

Vehicle Num. : SLM 4476Z (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 04/11/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

REAR BUMPER (PIRUS) ✓ Cut
REAR BUMPER CENTER GUARD (PIRUS) ? ✓ Deform.
REAR BUMPER REINFORCEMENT (PIRUS) ? ✓ DT

423.90

552.30

318.80

1,295.00

323.75

List Total S\$:

25.00% Discount S\$:

971.25

LABOUR :

To labour charge for removing rear bumper assy
reinforcement out to facilitate repairs and
replacement of damaged parts
To respray rear bumper

Labour Total S\$:

1) Parts : \$ 971.25

2) Labour : \$ 400.00

\$ 1371.25 @ 3 days.

200 600.00

200 400.00

1,000.00

E. & O.E.

Total S\$: 1,971.25

for WORLD AUTO PTE LTD

Parts 1295.00
Lev 25% 323.75
971.25
Labu 400.00
Net 1,371.25

Sebastian.
14/11/2017.

- Part by part repair.
- Question Mark Item
- Photo.
- Photo Before Paint

9003614
sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Before Paint Survey
15/11/2017 1615