

Signature

REF:

NS/TNC17021321/Sq62

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: SJK 7469JPolicy No. 5085089779-01 31.10.2017 - 30.10.18Claims No. MT/0969143-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SH D6476E Yr Regn: 4/5/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Epica c.c. 1791Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 124769 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KL1CH69KJB15124879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Valve

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 4/11/2017 D.O.I. 3/11/2017Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHD 6476E - N87 / 00116024770/Y

DIN: 191216

TAX/11/17/2015

SJK 7469J - (33/TNC12009489)/Avn-1

DIN: 100512

L&amp;K

NTUC

US \$4800, 5 days (Red \$6203.14, 56%)

Date/Time, File Pass to?

☐

Preli. Report

1) 21/11/2017

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1+1

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lum Sum / I.B.I. (\$

TP  
4800

TOTAL

160
35
195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17021321/Sqb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-11-2017	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJK 7469J	Veh. Inspected	SHD 6476E	
Policy No.	5085089779-01	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	04/11/2017	Inspection Date	07/11/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0967919-002	SMRT TAXIS PTE LTD	SHF 472U	GBF 6529Y
2	MT/0962029-002	SMRT BUSES LTD	SMB 1572U	SKX 6335M
3	MT/0968532-003	SMRT TAXIS PTE LTD	SHB 1953M	SDB 6808P
4	MT/0969143-002	SMRT TAXIS PTE LTD	SHD 6476E	SJK 7469J
5	MT/0912702-002	SMRT BUSES LTD	SMB 1630K	FQ 8465D
6	MT/0970438-001	SMRT TAXIS PTE LTD	SHB5851Y	SLQ 3128P
7	MT/0970441-001	SMRT TAXIS PTE LTD	SHB 1960S	SKM 5998P
8	MT/0959634-002	SMRT BUSES LTD	SMB 1580X	SLD 9017E
9	MT/0968476-002	SMRT TAXIS PTE LTD	SHB 5800U	SHD 2021K
10	MT/0953202-003	SMRT TAXIS PTE LTD	SHC 4540X	WC3406E

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5085089779-01	CARSONRENT	53320759B	GPC	drive CLASSIC	SJK7469J	SJK7469J	31/10/2017	30/10/2018

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	5369K
<b>Vehicle Details</b>	
Vehicle No.	SHD6476E
Vehicle to be Exported	No
Intended De-registration Date	08 Nov 2017
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour	Maroon
Manufacturing Year	2012
Engine No.	Z20S1442668K
Chassis No.	KL1LA69RJBB124874
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$14,384.00
Original Registration Date	04 May 2012
First Registration Date	04 May 2012
Transfer Count	0
Actual ARF Paid	\$14,384.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 May 2020
PARF Rebate Amount	\$10,068.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	03 May 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
QP Paid	\$38,490.00
COE Rebate Amount	\$11,960.00
<b>Total Rebate Amount</b>	<b>\$22,028.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Nov 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 13 Oct 2017 at 07:07 PM

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/11/2017 09:23
Date Of Accident	04/11/2017 21:55
Exact Location Of Accident	NICOLL HIGHWAY TOWARDS GEYLANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6476E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	NG PENG NAM
NRIC No	S1581972C
Date Of Birth	19/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	27/06/1980
Driving Experience	37 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions RAINING  
 Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TAMPINES NORTH NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7818999 - FAX NO: 67838603  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20171105/2037 On the above mentioned date time and location, I was travelling along Nicoll Highway towards Geylang on the 3rd lane of a three-lane carriageway. Subsequently, I then felt a bump from the back. The vehicle behind me had hit my rear bumper. My vehicle sustained damages to the rear bumper and the boot. I suffered from a strained neck and back and I have 5 days of MC. No Police or ambulance was at the scene.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO LARGE  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK7469J  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)



### Details of Witness

Name

Phone Number

Email Address

### DETAILS OF INJURED PERSON 1

Name

NG PENG NAM

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD6476E

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



# Sketch Plan Pg. 2

## Describe Circumstances of the Accident

REFER TO POLICE REPORT - 7/20171105/2037

## Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20171105/2037

1 of 3

Report No. T/20171105/2037

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/11/2017 12:36	Vide Report No.:	Station Diary No.: 5
--	------------------	-------------------------

**Informant's Particulars**

Name of Informant: NG PENG NAM			Address: APT BLK 451 TAMPINES STREET 42 #11-226 SINGAPORE 520451	
ID Type / ID No.: NRIC NO / S1581972C			Contact No.:	Mobile: 97435265
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 54	Date of Birth: 19/01/1963	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 04/11/2017 21:55	Type of Location:
Location: Along Road 1 NICOLL HIGHWAY				
Towards geylang				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD6476E	Car				Slightly Damaged	2
SJK7469J	Car				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE  
POLICE FORCE**



T/20171105/2037

2 of 3

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No. T/20171105/2037

## CONTINUATION OF REPORT

Driver			
Name	NG PENG NAM		ID No. S1581972C
Related Vehicle	SHD6476E (Car)		Contact No. 97435265
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	05/11/2017	Date Discharge	05/11/2017
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On the above mentioned date time and location, I was travelling along Nicoll Highway towards geylang on the 3rd lane of a three-lane carriageway. Subsequently, I then felt a bump from the back. The vehicle behind me had hit my rear bumper. My vehicle sustained damages to the rear bumper and the boot. I suffered from a strained neck and back and I have 5 days of MC. No Police or Ambulance was at the scene.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999



T/20171105/2037

3 of 3

Report No. T/20171105/2037

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 MUHAMMAD FIRDAUS BIN YUSOFF

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 YEO GEAK ENG CECILIA  
Contact No.: 65476404

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
05/11/2017 12:36

Classification Of Case:



Signature:

Singapore Police Force

SM 162

## SMRT Accident Vehicle Repair Estimates

NTUC

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6476E  
 Ref. No : TAX/11/17/2025  
 Reg. Date : 04/05/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : NG PENG NAM  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 04/11/2017 09:55:00 PM  
 Accident Reported Date / Time : 06/11/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024092922  
 Special Instruction to ARC, if any :  
 SJK7469J  
 Prepared Date : 06/11/2017 09:42:22 AM



Sebastian,  
 7/11/2017.  
 - Lump Sum Repair.  
 - Question Mark In Photo  
 - Photo After Paint.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB124874

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,014.00	0.00
Total Spray Painting Charges	1,116.00	0.00
Total Material Charges	5,602.26	5,602.26
Other Charges	860.00	0.00
<b>TOTAL</b>	<b>8,592.26</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>8,600.00</b>	<b>0.00</b>
No. of Repair Days	6.00	0.00
Prepared / Adjusted By		4 days
Arc / Surveyor Sign Off Date	06/11/2017 05:32:10 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/11/2017 05:30:33 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :



## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00 ?	0.00
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REMOVE & REFIT EXHAUST	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>860.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓ DT	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ?	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ?	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ✓ CAK	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓ NEC	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓ NEC	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ OMG	No
96647117	COMMO N		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Replace ?	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace X	No
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace R	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓ DT	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓ JM	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace X	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓ TN	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ NEC	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓ NEC	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓ NEC	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ?	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
<b>TOTAL MATERIALS</b>								<b>7,002.83</b>	<b>7,002.83</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>5,602.26</b>	<b>5,602.26</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									


# SMRT Accident Vehicle Repair Estimates

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6476E  
Ref. No : TAX/11/17/2025  
Reg. Date : 04/05/2012  
Vehicle Type : TAXI  
Make : CHEVROLET EPICA 2.0 VCDI  
Model : EPICA-2.0  
Name of Driver : NG PENG NAM  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 04/11/2017 09:55:00 PM  
Accident Reported Date / Time : 06/11/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024092922  
Special Instruction to ARC, if any :

SJK7469J - NTUC IDAC 45  
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121  
LUMPSUM REPAIR

Prepared Date : 06/11/2017 09:42:22 AM



97435265 Ng. 6855 ✓

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1<sup>st</sup> witness

Date

2<sup>nd</sup> witness

Date

Attached  
Supplementary

E 12 F  
KM 124 762

Vehicle to Mega Data In: 8/11 Towing:  
Time In: 1129 Driver: Two  
Wega Job No: 13700/11  
Vehicle sent to SMRT Date In: 11/11/17 Towing:  
Time In: 1000 Driver: [Signature]  
Rec: [Signature]

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB124874

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	800.00
Total Spray Painting Charges	: 1,116.00	500.00
Total Material Charges	: 2,944.58	4,359.30
Other Charges	: 860.00	-859.30
<b>TOTAL</b>	<b>: 5,934.58</b>	<b>4,800.00</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	5.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 06/11/2017 05:32:10 AM	07/11/2017 03:55:49 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/11/2017 05:30:33 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1711-0370

Invoice No :

Quotation Date : 16/11

Invoice Date :

Invoice Amount :

Prepared Date :

4359.30 /  
+ 800.00 /  
+ 820.00 /  
-----  
5979.30 /  
- 208 /  
-----  
4783.44 /  
45 \$4800/- /

Sebastian  
20/11/2017

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	800.00 /
<b>Total Labour</b>	<b>1,014.00</b>	<b>800.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR BOOT LID	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>500.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	140.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO REMOVE & REFIT EXHAUST	120.00	30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-1,179.30
<b>Total Other Costs</b>	<b>860.00</b>	<b>-859.30</b>



**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No	DT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace S	No	CRK
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace S	No	DT
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No	CRK
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No	NFC
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No	NFC
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	DMG
96647117	COMMON		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Check	No X	NW
			EXHAUST PIPE MOUNTING, REAR	0	4.40	10.00	0.00	Replace	Not given	No X	NW
96418400			MUFFLER A-EXH,RR	1	2,909.00	100.00	0.00	Replace	Repair	No	R
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No	DT
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No	JM
96636426	REAR	6504633	REAR BOOT STRIKER	0	15.00	10.00	0.00	Replace	Not given	No X	NW
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No	TN
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No	
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No	
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No	
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	NFC
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace S	No	DT
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X	NW
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace S	No	CRK
<b>TOTAL MATERIALS</b>							<b>4,600.91</b>	<b>4,359.30</b>			
<b>TOTAL MATERIALS(Discounted)</b>							<b>2,944.58</b>	<b>4,359.30</b>			

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
96858576	REAR	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						237.60			

11003.14

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17021321/Sqbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 22-11-2017	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJK 7469J	Veh. Inspected	SHD 6476E	
Policy No.	5085089779-01	Coverage (\$)	0.00	
Claim No.	MT/0969143-002	Excess (\$)	0.00	
Assign From		Assign Date	07/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	CHEVROLET EPICA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB124874	Colour	MAROON	
Odometer	124764	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R15	FALKEN	6 mm	
L/H Front Tyre	205/55 R15	FALKEN	6 mm	
R/H Rear Tyre	205/55 R15	FALKEN	6 mm	
L/H Rear Tyre	205/55 R15	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/11/2017	Inspection Date	07/11/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6476E**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER RR (DISC 10%)	DENTED	1,238.00	1,114.20
1	ABSORBER ENGY RR BUMPER (DISC 10%)	CRACKED	70.00	63.00
1	BEAM RR BUMPER IMPACT (DISC 10%)	BENT	1,221.00	1,098.90
1	REFLECTOR REFLEX RR LH (DISC 10%)	CRACKED	264.00	237.60
1	BRACKET RR BUMPER SIDE LH (DISC 10%)	NECESSARY	49.00	44.10
1	BRACKET RR BUMPER SIDE RH (DISC 10%)	NECESSARY	49.00	44.10
1	REAR BOOT LID (DISC 10%)	DENTED	974.00	876.60
1	REAR BOOT LOCK (DISC 10%)	JAMMED	77.00	69.30
1	REAR BOOT WEATHERSTRIP (DISC 10%)	TORN	49.00	44.10
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	LETTERING "CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING "EPICA" (DISC 10%)	NECESSARY	28.00	25.20
1	PANEL END REAR (DISC 10%)	DENTED	255.00	229.50
1	REFLECTOR REFLEX RR RH (DISC 10%)	CRACKED	264.00	237.60
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	W/HARNESS RR BPR	NOT NECESSARY	227.34	-
1	EXHAUST PIPE MOUNTING, REAR	NOT NECESSARY	4.40	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	REAR BOOT STRIKER	NOT NECESSARY	15.00	-
1	MUFFLER A-EXH, RR	TO REPAIR	2,909.00	-
			8,013.14	4,359.30
<b><u>LABOUR</u></b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,714.00	1,100.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,116.00	500.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,990.00	1,620.00

Report Ref No. NS/INC17021321/Sqbe2





Page No.:2 of 2

GRAND TOTAL		11,003.14	5,979.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONSITION) (CONFIRMED)			4,800.00

Report Ref No. NS/INC17021321/Sqbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.