

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17013261/T1VBS2
Date: 27/09/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28882752QMX
Claimant Vehicle No :	SHB1209D	Insured Vehicle No :	SJV8022A
Date of Loss:	06/07/2017	Nature of Claim:	TP
		Claim No:	522431

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1209D		
Make & Model:	CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)	Engine No:	Z20S1454423K
Reg. Date:	05/06/2013 (Man. Year: 2012)	Chassis No:	KL1LA69RJBB139066
Colour:	Maroon	Odometer:	650195 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,558.00	1,186.60	371.40	23.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	996.00	450.00	546.00	54.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,554.00	1,636.60	917.40	35.92
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	2,554.00	1,450.00	1,104.00	43.23

INSPECTION

Date of Assignment:	19/09/2017		
Date Inspected:	07/07/2017	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2017)

Parts: 143 CHEVROLET EPICA 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SHB1209D/27/09/2017 08:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER RR (DISC 30%)	Deformed	1,238.00 F	*866.60 F
2	1		*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F
3	1		*SHIELD REAR BUMPER (SN)	Necessary	140.00 F	*140.00 F
					Total Parts (S\$)	1,558.00 1,186.60

F=Franchise part.

LKK Auto Consultants Pte Ltd/SHB1209D/27/09/2017 08:11. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODYWORK.	New	338.00	200.00
2	SPRAY PAINT.	New	378.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
4	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
5	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			996.00	450.00

LKK Auto Consultants Pte Ltd/SHB1209D/27/09/2017 08:11. Not valid without Reference section.

< END OF ESTIMATES >