

Sanctioned

Adnan

ASSIGNMENT (Office)

CWS

From (Person)

Serene Lee

FCI

Date/Time

12:15pm @ 8/11/17

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF2463D

Insured

SHB4289C

at Workshop no:

SM Automotive

Tel

G7479241

of

Blk C, 1kaki Bukit Ave 6 # 01-43

Policy No

Claim No

D17616333MFSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A.

4/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

12:20pm @ 8/11/17

Person Consented

Sukyi

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

GBF2463D-NA/CTI17021170/24-D.O.A.: 4/11/2017

SHB4289C-NA/CTI17021170/24-D.O.A.: 4/11/2017

1914 9596 2166

Summit

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF2463D Yr Regn: 2016 / AugustType: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Every c.c. 658Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 15231 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: DA17V162807Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 145/80R12R: 145/80R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 06/11/17Survey held at SMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

9/11/17 email to Serene - pending est from wksp.
45 \$ 4100 (Red: 8488, 67%).

RECEIVED 11 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.I: (\$ 4100)

TOTAL

2x15 = 30

170 + 30

50

50

59

359



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021326/Agb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4289C	Veh. Inspected	GBF 2463D
Policy No.		Coverage (\$)	0.00
Claim No.	D17010333MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	08/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/11/2017	Inspection Date	08/11/2017
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No.	D17010333MFSH
Accident Date	04-11-2017	Claim Type.	Third Party
Insured Vehicle	SHB4289C	Third Party Vehicle.	GBF2463D
Survey Location	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43		
Contact Person.	SUKYI		
Contact No.	67479241/ 0	Fax No.	67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SM AUTOMOTIVE	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229875)



PRI Documents



Close



PRI Header Details

Claim No	D17010333MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SM AUTOM
Workshop Name	SM AUTOMOTIVE (Contact Person : SUKYI)	Survey Location & Contact Details	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 Mobile: 0 , Phone: 67479241 , Fax: 67417276 EmailId: ADMIN@NHTMOTOR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4289C	TP Vehicle No	GBF2463D
PRI Recieved Date	06-11-2017 06:26:54 PM	Surveyor Appointed Date	08-11-2017 12:15:09 PM	Surveyor Accept Date	08-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-11-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Thursday, 9 November, 2017 3:58 PM
To: 'Claim Workflow System'
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010333MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle GBF 2463D on 06-11-2017.
We are pending estimate from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 8 November, 2017 12:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010333MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 8 November, 2017 12:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010333MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type

Company

Owner ID

6872N

Vehicle Details

Vehicle No.

GBF2463D

Vehicle to be Exported

No

Intended De-registration Date

04 Nov 2017

Vehicle Make

SUZUKI

Vehicle Model

EVERY PA 660 AUTO

Primary Colour

Silver

Manufacturing Year

2016

Engine No.

R06A1830768

Chassis No.

DA17V162807

Maximum Power Output

-

Open Market Value

\$13,137.00

Original Registration Date

18 Aug 2016

First Registration Date

18 Aug 2016

Transfer Count

1

Actual ARF Paid

\$657.00

Intended PARF Rebate Details

PARF Eligibility

No

PARF Eligibility Expiry Date

-

PARF Rebate Amount

\$0.00

Intended COE Rebate Details

COE Expiry Date

17 Aug 2026

COE Category

C - Goods Vehicle & Bus

COE Period(Years)

10

PQP Paid

\$37,612.00

COE Rebate Amount

\$33,041.00

Total Rebate Amount

\$33,041.00

The information contained herein is correct as at 04 Nov 2017

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
 Email: SM_AUTOMOTIVE@HOTMAIL.COM
 Tel: (65) 6747 9241 Fax: (65) 6741 7276
 RCB No.: 53231488C

6/11/2017

SAGACHIKU SINGAPORE PTE LTD

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap

Ai Phing

Accident date: 04/11/2017

Estimated repair cost for vehicle no: GBF2463D SUZUKI EVERY PA 660 AUTO '16

CHASSIS: DA17V162807

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,450.00 899
2	2	Rear Boot Lid Hinge <i>3 pr</i>	\$35.00	\$70.00 X
3	2	Rear Boot Lid Shock Absorber <i>2 pr</i>	\$120.00	\$240.00 X
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$48.00
5	1	Rear Boot Lid 70km/H Sticker <i>3 pr</i>		\$20.00 15 (sn)
6	1	Rear Boot Lid 4pax Sticker <i>3 pr</i>		\$20.00 15 (sn)
7	1	Rear Boot Lid Every Sticker <i>new</i>		\$32.00
8	1	Rear Boot Lid Outer Handle <i>new</i>		\$75.00
9	1	Rear Boot Lid Inner Lock <i>2 pr</i>		\$275.00
10	1	Rear Boot Lid Inner Rubber <i>new</i>		\$185.00 X
11	1	Rear Boot Lid Inner Trim Board <i>3 pr</i>		\$285.00 X
12	10	Rear Boot Lid Inner Trim Board Clip <i>1 pr</i>	\$6.50	\$65.00
13	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$60.00
14	1	Rear Bumper <i>Dented</i>		\$1,050.00 625
15	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
16	2	Rear Bumper Side Retainer <i>new</i>	\$28.00	\$56.00 ✓
17	1	Rear Bumper Number Plate <i>Cracked</i>		\$50.00 25 (sn)
18	1	Rear Bumper Number Plate Lamp <i>new</i>		\$65.00 X
19	2	Rear Bumper Tail Lamp <i>LH Cracked</i>	\$285.00	\$570.00 285
20	1	Rear End Panel Outer <i>Dented</i>		\$370.00 ✓
21	1	Rear End Panel Inner <i>new</i>		\$380.00 X
22	1	Rear Spare Tyre Bracket <i>Best</i>		\$260.00 ✓
23	1	Rear Floor Panel <i>new</i>		\$1,050.00 450
24	1	Rear Exhaust <i>Best</i>		\$950.00 X
25	1	Rear Centre Exhaust <i>new</i>		\$850.00 X

Subtotal :- \$8,528.00

3490 524 45
 2966.5

Labour charges

To remove & refit rear & centre exhaust

~~\$380.00~~ 80

To remove & refit rear windscreen

~~\$120.00~~ 100

Gum (54)

~~nee \$50.00~~

To check wiring

~~\$60.00~~ 30

Towing fee

~~\$100.00~~ X

Tuff kote

~~\$150.00~~ 40

Panel beating

2100

~~\$1,600.00~~ 900

Spray painting

~~\$1,600.00~~ 900

Subtotal :- \$4,060.00

Total:- \$12,588.00

Total: 5111.50

4/5 4.1K

05 Days

4.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021326/Agbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4289C	Veh. Inspected	GBF 2463D	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010333MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	08/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI EVERY	c.c	658	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	DA17V162807	Colour	SILVER	
Odometer	15231	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	145/80 R12	BRIDGESTONE	6 mm	
L/H Front Tyre	145/80 R12	BRIDGESTONE	6 mm	
R/H Rear Tyre	145/80 R12	BRIDGESTONE	6 mm	
L/H Rear Tyre	145/80 R12	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2017	Inspection Date	08/11/2017	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2463D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	1,450.00	899.00
2	REAR BOOT LID HINGE @\$35.00	NOT NECESSARY	70.00	-
2	REAR BOOT LID SHOCK ABSORBER @\$120.00	NOT NECESSARY	240.00	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	48.00	48.00
1	REAR BOOT LID EVERY STICKER	NECESSARY	32.00	32.00
1	REAR BOOT LID OUTER HANDLE	NOT NECESSARY	75.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	275.00	275.00
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	185.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	285.00	-
10	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	65.00	-
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	60.00	60.00
1	REAR BUMPER	DEFORMED	1,050.00	625.00
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$28.00	NECESSARY	56.00	56.00
1	REAR BUMPER NUMBER PLATE LAMP	NOT NECESSARY	65.00	-
2	REAR BUMPER TAIL LAMP @\$285.00	N/S CRACKED	570.00	285.00
1	REAR END PANEL OUTER	DENTED	370.00	370.00
1	REAR END PANEL INNER	NOT NECESSARY	380.00	-
1	REAR SPARE TYRE BRACKET	BENT	260.00	260.00
1	REAR FLOOR PANEL	NOT NECESSARY	1,050.00	-
1	REAR EXHAUST	BENT	950.00	550.00
1	REAR CENTRE EXHAUST	NOT NECESSARY	850.00	-
	LESS 15% DISCOUNT		-	-523.50
			8,438.00	2,966.50
SPECIAL NETT ITEMS				
1	REAR BOOT LID 70KM/H STICKER (SN)	NECESSARY	20.00	15.00
1	REAR BOOT LID 4 PAX STICKER (SN)	NECESSARY	20.00	15.00
1	REAR BUMPER NUMBER PLATE (SN)	CRACKED	50.00	25.00
1	GUM (SN)	NECESSARY	50.00	50.00
			140.00	105.00

Report Ref No. CS/FCI17021326/Agbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	100.00
	TO CHECK WIRING.		60.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	PANEL BEATING.		1,600.00	900.00
	SPRAY PAINTING.		1,600.00	900.00
			4,010.00	2,050.00
	GRAND TOTAL		12,588.00	5,121.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00

Report Ref No. CS/FCI17021326/Agbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.