

ASSIGNMENT (Office) RES CS/FCI17021379 / Gtbnz

From (Person) AK cws Karen Tan FCI Date/Time 12.26pm @ 8/11/17

Estimated Cost Bill to

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SLH 5260Z Insured: SHC 8296A

at Workshop no: WTS Automotive Tel: 68 44 9449 / 8720 4664

of 17 kaki Bukit Rd 4 #01-58/59

Policy No: Claim No: D17610326MFSH

Sum Insured Excess:

Make of Veh: D.O.A. 5/11/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up' 10/11/17 @ 11 am - 12 pm

Date/Time 12.44pm @ 8/11/17 Person Contacted Jeffrey Ho Vehicle IN (OUT)

Date/Time	Action/Instruction (☒) Estimate
-----------	---

	<u>SLH 5260Z - X</u>
--	----------------------

	<u>SHC 8296A - CS/FCI17003972 / R1gh3n2 - D.O.A: 16/01/17</u>
--	---

<u>14/11/17 @ 4.44pm</u>	<u>revised to Karen Tan by email.</u>
--------------------------	---------------------------------------

--	--

	<u>Part by Part \$9,054.48 (Red: 3811.06 : 29%)</u>
--	---

Surveillance

XKL

REF: FCI

ASSIGNMENT

From: _____ Date: 10/11/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 52602

at Workshop m/s WTS Automotive

of 17 kaki Bukit Rd # 01-58/59

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

11am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 52602 Yr Regn: 08 Nov 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1498

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 7013 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC1660 GT000211

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10-11-17

12pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 5 DEC 2017

Date/Time, File Pass to?

5/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos 838

Others _____

TOTAL

3x15 = 45

170 + 45

50

50 + 50

136

501

Report Format: TP

Lump Sum / I.B.I. (\$) 90'54.47



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021379/Gtb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8296A	Veh. Inspected	SLH 5260Z
Policy No.		Coverage (\$)	0.00
Claim No.	D17010326MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	08/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/11/2017	Inspection Date	
Survey held at	WTS AUTOMOTIVE SERVICES PTE LTD 17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62 BARTLEY BIZCENTRE SINGAPORE 417809		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010326MFSH
Our Ref: CS/FCI17021379/Gtb

Date: 14 November 2017

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 5260Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/11/2017 at the premises of M/s WTS AUTOMOTIVE . and have the following to report:-

Workshop Estimate Amount	: S\$ 10,071.64 .
Revised Estimate Amount	: S\$ 6,457.72 .
"Check" Items Amount	: S\$ 52.96 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the front and rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No. D17010326MFSH
Accident Date	05-11-2017	Claim Type. Third Party
Insured Vehicle	SHC8296A	Third Party Vehicle. SLH5260Z
Survey Location	17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62Bartley BizCentre	
Contact Person.	JEFFREY HO	
Contact No.	68449449/ 0	Fax No. 68449463
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WTS AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229947)



PRI Documents



Close



PRI Header Details

Claim No	D17010326MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	2 & WTS AUTO
Workshop Name	WTS AUTOMOTIVE SERVICES PTE LTD (Contact Person : JEFFREY HO)	Survey Location & Contact Details	17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62Bartley Biz Mobile: 0 , Phone: 68449449 , Fax: 68449463 EmailId: JEFFREYHO@PITSTOP.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8296A	TP Vehicle No	SLH5260Z
PRI Recieved Date	07-11-2017 11:07:24 PM	Surveyor Appointed Date	08-11-2017 12:26:07 PM	Surveyor Accept Date	08-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 November, 2017 4:44 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010326MFSH/2
Attachments: CSFCI17021379Gtb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLH 5260Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 8 November, 2017 4:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010326MFSH/2

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer arrange survey on 10.11.2017.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 8 November, 2017 12:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010326MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Enquire Transfer Fee

Vehicle Details		
Vehicle No.	SLH5260Z	
Vehicle Type	P10 - Passenger Motor Car	
Vehicle Attachment 1	With Sun Roof	
Vehicle Scheme	Normal	
Vehicle Make	HONDA	
Vehicle Model	CIVIC 1.5 TURBO VTIS SR	
Chassis No.	MRHFC1660GT000211	
Propellant	Petrol	
Engine No.	L15B71626341	
Engine Capacity	1498 cc	
Maximum Power Output	127.0 kW (170 bhp)	
Maximum Laden Weight	1740 kg	
Unladen Weight	1324 kg	
Year Of Manufacture	2016	
Original Registration Date	08 Nov 2016	
Lifespan Expiry Date	-	
COE Category	B - Car above 1600cc or 97kW (130bhp)	
Quota Premium	\$57,903.00	
COE Expiry Date	07 Nov 2026	
Road Tax Expiry Date	07 Nov 2018	
PARF Eligibility Expiry Date	07 Nov 2026	
Inspection Due Date	07 Nov 2019	
Intended Transfer Date	14 Nov 2017	
CO2 Emission	135.00 (g/km)	
CEVS Rebate Utilised Amount	\$5,000.00	
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.		
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.		
Amount Payable		
Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)



WTS Automotive Services Pte Ltd

Spare Parts (Appendix A)

Vehicle No. : **SLH5260Z**
 Make & Model : **CIVIC 1.5 TURBO VTIS SR**
 Chassis No. : **MRHFC1660GT000211**

Submit By : **JEFFREY**
 Year Manufactur : **8-Nov-16**
 Engine No. : **L15B71626341**

List

S/No.	Part Description	Qty	List Price	Disposition by Surveyor
1	Rear Bumper / <i>re</i>	1	\$617.80	/
2	Rear Bumper Retainer - Left / <i>re</i>	1	\$16.40	/
3	Rear Bumper End Panel \$ / <i>buc</i>	1	\$230.70	/
4	Rear Bumper reflector - LH X	1	\$16.80	X
5	Rear Bumper reflector - RH X	1	\$16.80	X
6	Rear Bumper reflector Cover - RH X	1	\$17.40	X
7	Rear Bumper reflector Cover - LH / <i>re</i>	1	\$17.40	/
8	Rear Bumper lower Skirt / <i>CAA</i>	1	\$64.50	/
9	Rear Boot Lock/Catch / <i>BT</i>	1	\$70.60	/
10	Rear Boot Catch X	1	\$27.50	X
11	Rear Boot Hinge - LH X	1	\$42.60	X
12	Rear Boot Hinge - RH X	1	\$42.60	X
13	Rear Boot Emblem (Honda Logo) X	1	\$11.60	X
14	Rear Boot catch cover / <i>cut</i>	1	\$41.60	/
15	Rear Boot Wording (CIVIC) X	1	\$21.10	X
16	Rear Boot Wording (VTEC TURBO) X	1	\$33.00	X
17	Rear Boot X <i>repair</i>	1	\$461.50	X
18	Front Bumper / <i>CAA</i>	1	\$579.90	/
19	Front emblem (Honda Logo) / <i>MC</i>	1	\$24.30	/
20	Front Bonnet Hinge - LH X	1	\$41.30	X
21	Front Bonnet Hinge - RH X	1	\$41.30	X
22	Front Radiator grille / <i>CAA</i>	1	\$105.00	/
23	Front Grille Chrome Center /	1	\$95.20	/
24	Front Grille Chrome - LH / <i>re</i>	1	\$81.30	/
25	Front Grille Chrome- RH /	1	\$81.30	/
26	Headlamp Assy - LH / <i>CAA</i>	1	\$1,129.00	/
27	Headlamp Assy - RH / <i>BR</i>	1	\$1,129.00	/
28	Front Right Fender X <i>repair</i>	1	\$306.90	X
29	Front Left Fender / <i>buc</i>	1	\$306.90	/
30	Front Bumper Lower Grille X <i>NN</i>	1	\$66.20	X
31	Front Bonnet X <i>repair</i>	1	\$568.30	X
Total Parts			\$6,305.80	
List Price less -20%			(\$1,261.16)	
Sub Total			\$5,044.64	

2991-36

Special Nett Items				
1	Reverse Sensor - 4 Heads (S/N) / DM	1	\$312.00	220 /
2	Front Number plate with ganish / BT	1	\$45.00	/
Total for special nett items			\$357.00	
Total for Parts			\$5,401.64	

Labour (Appendix B)

S/No.	Labour Description	Unit	Disposition by Surveyor
		Price	
1	To Remove & Refit Rear Bumper, Rear Boot, Bumper Retainer, Bumper lower Skirt, Reverse sensor	\$1,150.00	1000 600 /
2	To Spray Paint Rear Bumper, Rear boot, Bumper lower Skirt	\$1,200.00	600 /
3	To check wiring on reverse sensor & taillamp	\$100.00	60 /
4	To Tuff Coat (Front & Rear)	\$120.00	60 /
5	To Remove & Refit Frt bumper, Frt Radiator grille, bonnet hinge, Headlamp assy LH/RH, Front fender, Lower grille, bonnet	\$1,000.00	400 /
6	To Spray Paint Frt bumper, hinge, fender LH/RH, Bonnet	\$1,100.00	800 /
Total for Labour		\$4,670.00	

Grand Total for Parts & Labour	\$10,071.64	Before GST
--------------------------------	-------------	------------

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

9-10 Days.

part by part.

before paint photos.

Guo Qiang - 82860282

Guo Qiang@lkkauto.com

10/11/17.

12853-54
13018-40
22/11/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PITSTOP

WTS Automotive Services Pte Ltd

Spare Parts (Appendix A)

Vehicle No. : **SLH5260Z**

Submit By : **JEFFREY**

Make & Model : **CIVIC 1.5 TURBO VTIS SR**

Year Manufactur : **8-Nov-16**

Chassis No. : **MRHFC1660GT000211**

Engine No. : **L15B71626341**

List

S/No	Part Description	Qty	List Price	Disposition by Surveyor
1	Rear Bumper	1	\$617.80	Approved
2	Rear Bumper Retainer - Left	1	\$16.40	Approved
3	Rear Bumper End Panel	1	\$230.70	Approved
7	Rear Bumper reflector Cover - LH	1	\$17.40	Approved
8	Rear Bumper lower Skirt	1	\$64.50	Approved
9	Rear Boot Lock/Catch	1	\$70.60	Approved
14	Rear Boot catch cover	1	\$41.60	Approved
18	Front Bumper	1	\$579.90	Approved
19	Front emblem (Honda Logo)	1	\$24.30	Approved
22	Front Radiator grille	1	\$105.00	Approved
23	Front Grille Chrome Center	1	\$95.20	Approved
24	Front Grille Chrome - LH	1	\$81.30	Approved
25	Front Grille Chrome- RH	1	\$81.30	Approved
26	Headlamp Assy - LH	1	\$1,129.00	Approved
27	Headlamp Assy - RH	1	\$1,129.00	Approved
29	Front Left Fender	1	\$306.90	Approved
32	Condenser / <i>cut</i>	1	\$704.40	Supplementary
33	Front Support Panel / <i>BT</i>	1	\$499.20	Supplementary
34	Front bonnet Hinge - LH / <i>got</i>	1	\$42.60	Supplementary
35	Front bonnet Hinge - RH / <i>got</i>	1	\$42.60	Supplementary
36	Front Bumper Clips x 10 / <i>NBC</i>	1	\$39.00	Supplementary
37	Rear Reinforcement / <i>BT</i>	1	\$156.40	Supplementary
38	Rear Bumper Clips x 10 / <i>NBC</i>	1	\$39.00	Supplementary
39	Radiator / <i>cut</i>	1	\$1,100.50	Supplementary
40	Headlamp lower bracker - LH / <i>got</i>	1	\$25.50	Supplementary
41	Headlamp lower bracker - RH / <i>got</i>	1	\$25.50	Supplementary
Total Parts			\$7,265.60	
List Price less -20%			(\$1,453.12)	
Sub Total			\$5,812.48	
Special Nett Items				
1	Reverse Sensor - 4 Heads (S/N)	1	\$220.00	Approved
2	Front Number plate with ganish	1	\$45.00	Approved
3	Coolant / <i>NBC</i>	1	\$45.00	Supplementary
Total for special nett items			\$310.00	

Total for Parts	\$6,122.48
-----------------	------------

Labour (Appendix B)

S/No	Labour Description	Unit	Disposition by Surveyor
		Price	
1	To Remove & Refit Rear Bumper, Rear Boot, Bumper Retainer, Bumper lower Skirt, Reverse sensor	\$600.00	Approved
2	To Spray Paint Rear Bumper, Rear boot, Bumper lower Skirt	\$600.00	Approved
3	To check wiring on reverse sensor & taillamp	\$60.00	Approved
4	To Tuff Coat (Front & Rear)	\$60.00	Approved
5	To Remove & Refit Frt bumper, Frt Radiator grille, bonnet hinge, Headlamp assy LH/RH, Front fender, Lower grille, bonnet	\$400.00	Approved
6	To Spray Paint Frt bumper, hinge, fender LH/RH, Bonnet	\$800.00	Approved
7	To Panel Beat/Spray paint on Spare tyre well panel	\$750.00	Supplementary (A)
		400. /	
Total for Labour		\$3,270.00	

Grand Total for Parts & Labour	\$9,392.48	Before GST
--------------------------------	------------	------------

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Gino Q. 14.

14/11/17



WTS Automotive Services Pte Ltd

Spare Parts (Appendix A)

Vehicle No. : **SLH5260Z**

Submit By : **JEFFREY**

Make & Model : **CIVIC 1.5 TURBO VTIS SR**

Year Manufactur : **8-Nov-16**

Chassis No. : **MRHFC1660GT000211**

Engine No. : **L15B71626341**

List

S/No	Part Description	Qty	List Price	Disposition by Surveyor
1	Rear Bumper	1	\$617.80	Approved
2	Rear Bumper Retainer - Left	1	\$16.40	Approved
3	Rear Bumper End Panel	1	\$230.70	Approved
7	Rear Bumper reflector Cover - LH	1	\$17.40	Approved
8	Rear Bumper lower Skirt	1	\$64.50	Approved
9	Rear Boot Lock/Catch	1	\$70.60	Approved
14	Rear Boot catch cover	1	\$41.60	Approved
18	Front Bumper	1	\$579.90	Approved
19	Front emblem (Honda Logo)	1	\$24.30	Approved
22	Front Radiator grille	1	\$105.00	Approved
23	Front Grille Chrome Center	1	\$95.20	Approved
24	Front Grille Chrome - LH	1	\$81.30	Approved
25	Front Grille Chrome- RH	1	\$81.30	Approved
26	Headlamp Assy - LH	1	\$1,129.00	Approved
27	Headlamp Assy - RH	1	\$1,129.00	Approved
29	Front Left Fender	1	\$306.90	Approved
32	Condenser	1	\$704.40	Supplementary
33	Front Support Panel	1	\$499.20	Supplementary
34	Front bonnet Hinge - LH	1	\$42.60	Supplementary
35	Front bonnet Hinge - RH	1	\$42.60	Supplementary
36	Front Bumper Clips x 10	1	\$39.00	Supplementary
37	Rear Reinforcement	1	\$156.40	Supplementary
38	Rear Bumper Clips x 10	1	\$39.00	Supplementary
39	Radiator	1	\$1,100.50	Supplementary
40	Headlamp lower bracker - LH	1	\$25.50	Supplementary
41	Headlamp lower bracker - RH	1	\$25.50	Supplementary
42	Rear Bumper tow hook cover / <i>NGC. (CA)</i>	1	\$15.00	Supplementary
Total Parts			\$7,280.60	
List Price less -20%			(\$1,456.12)	
Sub Total			\$5,824.48	
Special Nett Items				
1	Reverse Sensor - 4 Heads (S/N)	1	\$220.00	Approved
2	Front Number plate with ganish	1	\$45.00	Approved
3	Coolant	1	\$45.00	Supplementary
Total for special nett items			\$310.00	
Total for Parts			\$6,134.48	

Labour (Appendix B)

S/No	Labour Description	Unit	Disposition by Surveyor
		Price	
1	To Remove & Refit Rear Bumper, Rear Boot,Bumper Retainer,Bumper lower Skirt, Reverse sensor	\$600.00	Approved
2	To Spray Paint Rear Bumper, Rear boot, Bumper lower Skirt	\$600.00	Approved
3	To check wiring on reverse sensor & taillamp	\$60.00	Approved
4	To Tuff Coat (Front & Rear)	\$60.00	Approved
5	To Remove & Refit Frt bumper, Frt Radiator grille, bonnet hinge, Headlamp assy LH/RH, Front fender, Lower grille, bonnet	\$400.00	Approved
6	To Spray Paint Frt bumper, hinge, fender LH/RH, Bonnet	\$800.00	Approved
7	To Panel Beat/Spray paint on Spare tyre well panel	\$400.00	Supplementary
Total for Labour		\$2,920.00	

Grand Total for Parts & Labour	\$9,054.48	Before GST
--------------------------------	------------	------------

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021379/Gtbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHC 8296A	Veh. Inspected
	Policy No.	D-15072701MFSH	Coverage (\$)
	Claim No.	D17010326MFSH	Excess (\$)
	Assign From	KARENT	Assign Date
			08/11/2017
2. Vehicle Particulars & Condition			
	Make & Model	HONDA CIVIC	c.c
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.	MRHFC1660GT000211	Colour
	Odometer	7013	Steering
	Brakes	IN ORDER	Modification
	General	GOOD	SPORTS RIM
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	215/50 R17	Balance
	L/H Front Tyre	215/50 R17	YOKOHAMA
	R/H Rear Tyre	215/50 R17	6 mm
	L/H Rear Tyre	215/50 R17	YOKOHAMA
			6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	05/11/2017	Inspection Date
	Survey held at	WTS AUTOMOTIVE SERVICES PTE LTD	
		17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62 BARTLEY BIZCENTRE SINGAPORE 417809	
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT.			
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5260Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	617.80	617.80
1	REAR BUMPER RETAINER-LEFT	NECESSARY	16.40	16.40
1	REAR BUMPER END PANEL	BUCKLED	230.70	230.70
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	16.80	-
1	REAR BUMPER REFLECTOR-RH	NOT NECESSARY	16.80	-
1	REAR BUMPER REFLECTOR COVER-RH	NOT NECESSARY	17.40	-
1	REAR BUMPER REFLECTOR COVER-LH	DEFORMED	17.40	17.40
1	REAR BUMPER LOWER SKIRT	CRACKED	64.50	64.50
1	REAR BOOT LOCK/CATCH	BENT	70.60	70.60
1	REAR BOOT CATCH	NOT NECESSARY	27.50	-
1	REAR BOOT HINGE-LH	NOT NECESSARY	42.60	-
1	REAR BOOT HINGE-RH	NOT NECESSARY	42.60	-
1	REAR BOOT EMBLEM (HONDA LOGO)	NOT NECESSARY	11.60	-
1	REAR BOOT CATCH COVER	CUT	41.60	41.60
1	REAR BOOT WORDING (CIVIC)	NOT NECESSARY	21.10	-
1	REAR BOOT WORDING (VTEC TURBO)	NOT NECESSARY	33.00	-
1	REAR BOOT	TO REPAIR SEE LABOUR	461.50	-
1	FRONT BUMPER	CRACKED	579.90	579.90
1	FRONT EMBLEM (HONDA LOGO)	NECESSARY	24.30	24.30
1	FRONT BONNET HINGE-LH	NOT NECESSARY	41.30	-
1	FRONT BONNET HINGE-RH	NOT NECESSARY	41.30	-
1	FRONT RADIATOR GRILLE	CRACKED	105.00	105.00
1	FRONT GRILLE CHROME CENTER	DEFORMED	95.20	95.20
1	FRONT GRILLE CHROME-LH	DEFORMED	81.30	81.30
1	FRONT GRILLE CHROME-RH	DEFORMED	81.30	81.30
1	HEADLAMP ASSY-LH	CRACKED	1,129.00	1,129.00
1	HEADLAMP ASSY-RH	BROKEN	1,129.00	1,129.00
1	FRONT RIGHT FENDER	TO REPAIR SEE LABOUR	306.90	-
1	FRONT LEFT FENDER	BUCKLED	306.90	306.90

Report Ref No. CS/FC117021379/Gtbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	66.20	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	568.30	-
1	CONDENSER (ADDITIONAL)	CUT	704.40	704.40
1	FRONT SUPPORT PANEL (ADDITIONAL)	BENT	499.20	499.20
1	FRONT BONNET HINGE-LH (ADDITIONAL)	BENT	42.60	42.60
1	FRONT BONNET HINGE-RH (ADDITIONAL)	BENT	42.60	42.60
10	FRONT BUMPER CLIPS (ADDITIONAL)	NECESSARY	39.00	39.00
1	REAR REINFORCEMENT (ADDITIONAL)	BENT	156.40	156.40
10	REAR BUMPER CLIPS (ADDITIONAL)	NECESSARY	39.00	39.00
1	RADIATOR (ADDITIONAL)	CUT	1,100.50	1,100.50
1	HEADLAMP LOWER BRACKET-LH (ADDITIONAL)	CRACKED	25.50	25.50
1	HEADLAMP LOWER BRACKET-RH (ADDITIONAL)	CRACKED	25.50	25.50
1	REAR BUMPER TOW HOOK COVER (ADDITIONAL)	NECESSARY	15.00	15.00
	LESS 20% DISCOUNT		-1,799.10	-1,456.12
			7,196.40	5,824.48
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR-4 HEADS (SN)	DAMAGED	312.00	220.00
1	FRONT NUMBER PLATE WITH GARNISH (SN)	BENT	45.00	45.00
1	COOLANT (SN)(ADDITIONAL)	NECESSARY	45.00	45.00
			402.00	310.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT REAR BUMPER,REAR BOOT,BUMPER RETAINER,BUMPER LOWER SKIRT,REVERSE SENSOR.INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,150.00	600.00
	TO SPRAY PAINT REAR BUMPER,REAR BOOT,BUMPER LOWER SKIRT.		1,200.00	600.00
	TO CHECK WIRING ON REVERSE SENSOR & TAILLAMP.		100.00	60.00
	TO TUFF COAT (FRONT & REAR).		120.00	60.00
	TO REMOVE & REFIT FRT BUMPER,FRT RADIATOR GRILLE,BONNET HINGE,HEADLAMP ASSY LH/RH,FRONT FENDER,LOWER GRILLE,BONNET.INCLUSIVE OF THE REPAIR OF FRONT RIGHT FENDER AND FRONT BONNET.		1,000.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT FRT BUMPER,HINGE,FENDER LH/RH,BONNET.		1,100.00	800.00
	TO PANEL BEAT/SPRAY PAINT ON SPARE TYRE WELL PANEL.(ADDITIONAL)		750.00	400.00
			5,420.00	2,920.00
GRAND TOTAL			13,018.40	9,054.48

RECOMMENDED COST OF REPAIRS				9,054.48
-----------------------------	--	--	--	----------

Report Ref No. CS/FC117021379/Gtbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.