

ASS. REC. BY:

REF:

CS/CTU7021402/mitbez

Special Instruction:

Surveyor:
me/min

MO.

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTL

Date/Time:

09.11.2017 1.31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GQ 1713

Insured:

G88 9799K

at Workshop m/s

K Kim Hin Auto

Tel:

6452 7018 / 9717 6881

of

160 Sin Ming Driv #02-20

Policy No:

DMCWSN1553361601

Claim No:

QNM17D0647202/9

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06.11.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.P. Endorsement:

Date/Time:

09.11.2017 1.50pm

Person Contacted:

Shunian

Vehicle IN/OUT

176.5.50

Date/Time	Action/Instruction (✓) Estimate
	GQ 1713 x
	G88 9799K - CCA / MGA13013098 / MISA392
	176.5.50
	Lump Sum \$1650/- (Red: 1020.25! 38%)

Surveys


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s KK HIN.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 90715 Yr Regn: 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA DYNA. C.C. 2982
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 20350 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JTFAT35160K 207841.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/25/R15

R: 155/R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>6/1/2017</u>	D.O.I. <u>9/1/2017</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation: _____

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$) 16500

130

130




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17021402/M1tb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 9799K	Veh. Inspected	GQ 171S	
Policy No.	DMCVSN1553361601	Coverage (\$)	0.00	
Claim No.	SNM17D06472C02/9	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	09/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/11/2017	Inspection Date	09/11/2017	
Survey held at	160 SIN MING DRIVE #02-20			
Repairer	K KIM HIN AUTOMOTIVE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'd	Status
Main	08 Nov 2017 18:48		08 Nov 2017 18:54 S\$2,670.25			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	nil, ID: 0		
Main Claimant:	TEKTRONZ PTE LTD, Co. Reg. No.: 201309948K		
Vehicle Reg. No.:	GQ171S	Date of Loss:	06/11/2017 14:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	GBB9799K	Policy No. (Claimant):	5089250538
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Driver/Custodian (Insured):	nil (/ Male), NRIC: 0		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2017 18:12
Date Of Accident	06/11/2017 14:55
Exact Location Of Accident	TOH GUAN ROAD EAST SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GQ171S
Insured/Policyholder	
Name Of Registered Owner	TEKTRONZ PTE LTD
Co Reg No	201309948K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91052493
Alternative Phone No	OFFICE-65644281

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089250538
Cover Note Number	

Driver

Name of Driver	SOKKALINGAM CHELLAPPAN
Passport No/FIN	G8387814U
Date Of Birth	01/04/1984
Occupation	INDOOR
Date Of Driving Pass	05/09/2013
Driving Experience	4 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94456031
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	C/O 7 ALPHA IND BUILDING #07-04 TOH GUAN ROAD EAST
Postcode	608599
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9799K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	62960271/81572631
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


07/11/2017 13:45pm


Policyholder's Signature
Date & Time:


7/11/17 @ 12h

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DRIVING TO EXIT TO H GUAN ROAD EAST
AND STOPPED AT SLIP ROAD TO CHECK TRAFFIC.
SUDDENLY VEHICLE B HIT MY VEHICLE REAR
PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	9948K
Vehicle Details	
Vehicle No.	GQ171S
Vehicle to be Exported	No
Intended De-registration Date	07 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	DYNA 150 5MT
Primary Colour	Blue
Manufacturing Year	2017
Engine No.	1KD2694172
Chassis No.	JTFAT35Y60K207841
Maximum Power Output	-
Open Market Value	\$26,436.00
Original Registration Date	10 Apr 2017
First Registration Date	10 Apr 2017
Transfer Count	0
Actual ARF Paid	\$1,322.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	09 Apr 2027
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$31,264.00
COE Rebate Amount	\$29,457.00
Total Rebate Amount	\$29,457.00

The information contained herein is correct as at 07 Nov 2017

OK

CO. REG. NO: 199402370D
GST NO: M2-0123250-3



金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
nil

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/11/2017
Vehicle Reg. No.:	GQ171S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SOKKALINGAM CHELLAPPAN	Driver (Insured):	NIL
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	10/04/2017
Vehicle Colour:	BLUE		
Engine No:	1KD2694172	Chassis No:	JTFAT35Y60K207841
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN THE WORKSHOP. PLS ARRANGE FOR SURVEY AND REPAIRS. THANK YOU - SANDRA		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,430.25
Miscellaneous Items	0.00
Labour	1,240.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,670.25
+ GST 7.00% (\$\$)	186.92
Nett Amount (\$\$)	2,857.17

This claim is handled by: SANDRA KHONG

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 08 Nov 2017)**Parts:** N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GQ171S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE	0.00	0.00	← *500.00 F CH/BA
2	1		*TAILGATE TOYOTA STICKER	0.00	0.00	← *45.00 F n/c
3	1		*TAILGATE DYNA STICKER	0.00	0.00	← *30.00 F n/c
4	2		*REAR NUMBER PLATE LAMP	0.00	0.00	X *130.00 F n/c
5	1		*TAILGATE 70KM/H STICKER	0	0.00	← *25.00 FS n/c
6	1		*TAILGATE 13 PAX STICKER	0	0.00	← *25.00 FS n/c
7	1		*REAR STEP PANEL	0	0.00	← *380.00 FS 250
8	1		*REAR NUMBER PLATE	0	0.00	*40.00 FS n/c
9	1		*REVERSE SENSOR	0	0.00	← *220.00 FS n/c

F=Franchise part, S=SpcNett.

Sub Total (S\$)	1,395.00
+ Margin on L,N Items 5.00% (S\$)	35.25
Total Parts (S\$)	1,430.25

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	450 580.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	60 80.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	450 580.00
Gross Labour Cost (S\$)			1,240.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Not Authorised.
Part / Part Repair
Before part also
Ltk Auto (MTR)
9/11/2012
Sulay S

CO. REG. NO: 199402370D

GST NO: M2-0123250-3



金興(龔)汽車私人有限公司

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
nil

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM			
----------------------	--	--	--

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/11/2017
Vehicle Reg. No.:	GQ171S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SOKKALINGAM CHELLAPPAN	Driver (Insured):	NIL
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	10/04/2017
Vehicle Colour:	BLUE	Chassis No:	JTFAT35Y60K207841
Engine No:	1KD2694172		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN THE WORKSHOP. PLS ARRANGE FOR SURVEY AND REPAIRS. THANK YOU - SANDRA		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,430.25
Miscellaneous Items	0.00
Labour	1,240.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,670.25
+ GST 7.00% (\$\$)	186.92
Nett Amount (\$\$)	2,857.17

This claim is handled by: SANDRA KHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 08 Nov 2017)
Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GQ171S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE	0.00	0.00	*500.00 F d/B
2	1		*TAILGATE TOYOTA STICKER	0.00	0.00	*45.00 F n/c
3	1		*TAILGATE DYNA STICKER	0.00	0.00	*30.00 F n/c
4	2		*REAR NUMBER PLATE LAMP	0.00	0.00	X *130.00 F n/c
5	1		*TAILGATE 70KM/H STICKER	0	0.00	*25.00 FS n/c
6	1		*TAILGATE 13 PAX STICKER	0	0.00	*25.00 FS n/c
7	1		*REAR STEP PANEL	0	0.00	380.00 FS 250
8	1		*REAR NUMBER PLATE	0	0.00	*40.00 FS n/c
9	1		*REVERSE SENSOR	0	0.00	*220.00 FS n/c

F=Franchise part. S=SpcNett.

Sub Total (S\$) 1,395.00
+ Margin on L,N Items 5.00% (S\$) 35.25
Total Parts (S\$) 1,430.25

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

\$ 575.00 Part
+ 5.2
\$ 603.75
\$ 550.00 - sl
\$ 960.00

\$ 2,113.75

lump sum
1650/-
5.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	450 580.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	60 80.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	450 580.00
Gross Labour Cost (S\$)			1,240.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not Authorised.
Part / Part Repair
Before paint also
Wkk Auto (MTR)
9/11/2017
Sundays

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2017 Sendback Est	08 Nov 2017 18:54 S\$2,670.25	09 Nov 2017 13:31 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case






Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: nil , ID: 0									
Main Claimant: TEKTRONZ PTE LTD , Co. Reg. No.: 201309948K									
Vehicle Reg. No.: GQ171S		Date of Loss: 06/11/2017 14:00 - :59 [6 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM17D06472C02/9		Policy/Cover Note No.: DMCVSN1553361601							
Vehicle Reg. No. (Insured): GBB9799K		Policy No. (Claimant): 5089250538							
		Excess: S\$0.00							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 20/11/2017]									
Driver/Custodian (Insured): nil (/ Male), NRIC: 0									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GQ171S (SNM17D06472C02/9)
[GBB9799K]

TP
TEKTRONZ PTE LTD
Nov 6 2017 2:00PM
[nil]
K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/11/17 19:14	Accident Statement	Load HTM	<input type="checkbox"/>
2	08/11/17 18:54	Repairer Estimates	Load HTM	<input type="checkbox"/>
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	07/11/17 19:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
2	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
16	22/02/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
17	22/02/18 18:36	General View	 Load JPG	✓
18	22/02/18 18:36	Reinspection Photo	 Load JPG	✓
19	22/02/18 18:36	Reinspection Photo	 Load JPG	✓
20	22/02/18 18:36	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/11/17 19:11	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT17021402/M1TBE2

Date: 21/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1553361601

Claimant Vehicle
No : GQ171SInsured Vehicle
No : GBB9799K

Date of Loss: 06/11/2017

Nature of Claim: TP

Claim
No: SNM17D06472C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GQ171S**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2694172

Reg. Date: 10/04/2017 (Man. Year: 2017)

Chassis No: JTFAT35Y60K207841

Colour: Blue

Odometer: 20350 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15

Rear Tyre Size: 155 R12

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,430.25	1,123.75	306.50	21.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	960.00	280.00	22.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,670.25	2,083.75	586.50	21.96
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,670.25	1,650.00	1,020.25	38.21
+ GST 7.00/7.00% (S\$)	186.92	115.50	71.42	38.21
Nett Amount (S\$)	2,857.17	1,765.50	1,091.67	38.21

INSPECTION

Date of Assignment: 09/11/2017 Present Location:

Date Inspected: 09/11/2017 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)

K Kim Hin Auto Pte Ltd (HQ)

160 Sin Ming Drive #02-20, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 May 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GQ171S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Dented/Bent	500.00 F	*500.00 F
2	1		*TAILGATE TOYOTA STICKER (WCP)	Necessary	45.00 F	*45.00 F
3	1		*TAILGATE DYNA STICKER (WCP)	Necessary	30.00 F	*30.00 F
4	2		*REAR NUMBER PLATE LAMP (WCP)	Serviceable	130.00 F	*- F
5	1		*TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*25.00 FS
6	1		*TAILGATE 13 PAX STICKER	Necessary	25.00 FS	*25.00 FS
7	1		*REAR STEP PANEL	Bent	380.00 FS	*250.00 FS
8	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
9	1		*REVERSE SENSOR	Shorted	220.00 FS	*220.00 FS
					Sub Total (S\$)	1,395.00
					+ Margin on L,N Items 5.00/5.00% (S\$)	35.25
					Total Parts (S\$)	1,430.25
						1,095.00
						28.75
						1,123.75

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	580.00	450.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	80.00	60.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	580.00	450.00
Gross Labour Cost (S\$)			1,240.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >