



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0107/11/17
M/S : SHINERS FACILITIES PTE LTD
120 LOWER DELTA ROAD
#09-10/11 CENDEX CENTRE
SINGAPORE 169268
Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBC1208Y - NISSAN NV200
INSURED : SHINERS FACILITIES PTE LTD
DATE OF ACCIDENT : 04/11/17
POLICY NO : DMCV16S012352

Page 1/2
LRF Auto Consultants hence notify
Date: 08/11/2017

- The Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modifications allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear bumper side retainer LH	1@	35.20	35.20	35.20
				35.20
Less 30%				-10.56
Total Material				\$24.64
Netts Items				

2 rear lamp LH	SCN 1@	255.60	255.60	255.60
3 rear bumper	Cur 1@	650.40	650.40	650.40
				906.00
Less 10%				-90.60
Total Nett				\$815.40

Labour & Misc

1 Remove & install r/lamp, r/bumper, knock r/fender and restraigthen body.	250	300.00
2 Spray painting.	230	280.00
3 Check wiring system.		25.00
4 Remove & install rear boot carpet.	11	80.00
		685.00

Total Labour

Nett Total Before Gst

\$685.00
\$1,525.04

1760.4

not Akhil
hu

Wahyolo After repair

2 dy.
9/11/17

21/1/5 \$1050