

25/05/2004

ASS. REC BY

REF: CS/FCI17021425/Kgbnz Special Instructions

Surveyor Kenneth  
CWS

ASSIGNMENT (Office)

From (Person): Eileen Lee

of FCI

Date/Time 2:41pm @ 9/11/17

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SH8438B

To Inspect Vehicle No: SGZ 67851

Tel: 64538686

at Workshop m/s: Alan's United Auto

of Blk 7 8th Ming Ind. Est #01-76

Claim No: D17010395MFSH

Policy No:

Excess:

Sum Insured:

D.O.A. 6/11/2017

Make of Veh.  
(Client's Record)

R.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time: 2:52pm @ 9/11/17

Person Contacted

Kenny

Vehicle ☒ IN ☐ OUT

Date/Time Action/Instruction ( ☒ ) Estimate

SGZ 67851 - X

SH8438B-NA/INC16018496/64-D.O.A.: 29/09/2016

ASS. REC. BY:

REF: 1702Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Alan's

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 839K \$42K Kenneth

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/12

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SG26785JYr Regn: 17, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Honda Streamc.c. 1799Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 216094

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTHMRN684085200386Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 7 mmL/Bal. 6 mmL/Bal. 7 mmD.O.A. 6/11/17D.O.I. 8/11/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/11/17File ps117 Carbury9/11/17email preti to steel.4s \$2900 (Red: 1534.32, 35%).MV: \$42000, LTA: \$36142, NV: \$5858

RECEIVED 11/12/2017

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

1355050+5019304Report Format: TPLump Sum / I.B.I. (\$ 2900)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021425/Kgb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8438B	Veh. Inspected	SGZ 6785J
Policy No.		Coverage (\$)	0.00
Claim No.	D17010395MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	09/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	06/11/2017	Inspection Date	09/11/2017
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date	08-11-2017	Our Ref No. D17010395MFSH
Accident Date	06-11-2017	Claim Type. Third Party
Insured Vehicle	SH8438B	Third Party Vehicle. SGZ6785J
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 64538686	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229956)



PRI Documents



Close



## PRI Header Details

Claim No	D17010395MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & ALAN'S U
Workshop Name	ALAN'S UNITED AUTO PTE LTD (Contact Person : KENNY)	Survey Location & Contact Details	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Mobile: 64538686 , Phone: 64538686 , Fax: 0 EmailId: KENNYCHAN@ALANUTD.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8438B	TP Vehicle No	SGZ6785J
PRI Recieved Date	08-11-2017 05:56:44 PM	Surveyor Appointed Date	09-11-2017 02:41:13 PM	Surveyor Accept Date	09-11-2017 0

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Ai Phing (LKKAuto)

---

**From:** Ai Phing (LKKAuto)  
**Sent:** Friday, 10 November, 2017 4:18 PM  
**To:** 'Claim Workflow System'  
**Cc:** EILEENLEE@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17010395MFSH/1  
**Attachments:** SGZ 6785J.pdf

Dear Eileen,

Enclosed herewith preliminary advise of SGZ 6785J.

Best Regards,

**Ai Phing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 9 November, 2017 2:53 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@first-insurance.com.sg](mailto:cwsmotorclaims@first-insurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D17010395MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Thursday, 9 November, 2017 2:41 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [EILEENLEE@FIRST-INSURANCE.COM.SG](mailto:EILEENLEE@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17010395MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010395MFSH/1

Date: 10-11-2017

Our Ref: CS/FCI17021425/Kgb

The Motor Claims Department  
First Capital Insurance Ltd

**Without Prejudice**

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGZ 6785J.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08-11-2017 at the premises of M/s ALAN'S UNITED AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,434.32</u>
Revised Estimate Amount	: S\$ <u>3,616.08</u>
"Check" Items Amount	: S\$ <u>422.80</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

Kenneth Kong  
Automotive Assessor

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3458F

### Vehicle Details

Vehicle No.	SGZ6785J
Vehicle to be Exported	No
Intended De-registration Date	10 Nov 2017
Vehicle Make	HONDA
Vehicle Model	STREAMSUNROOF 1.8L A
Primary Colour	White
Manufacturing Year	2007
Engine No.	R18A12800386
Chassis No.	JHMRN68408S200386
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$20,095.00
Original Registration Date	13 Nov 2007
First Registration Date	13 Nov 2007
Transfer Count	1
Actual ARF Paid	\$22,105.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Nov 2017
PARF Rebate Amount	\$11,052.00

### Intended COE Rebate Details

COE Expiry Date	31 Oct 2022
COE Category	B - Car (1601cc & above)
COE Period(Years)	5
PQP Paid	\$25,226.00
COE Rebate Amount	\$25,090.00
<b>Total Rebate Amount</b>	<b>\$36,142.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Nov 2017

OK



**Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5095304327

**Cover :** drive CLASSIC

- |   |                     |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle  | : SGZ6785J          |
| Chassis Number  | : JHMRN68408S200386 |
| 2. Name of Policyholder   | : ANG KIANG LENG    |
| 3. Effective Date of Insurance  | : 30 Oct 2017       |
| 4. Expiry Date of Insurance   | : 12 Nov 2018       |
| 5. Persons or Classes of Persons entitled to drive#   |                     |
| (a) The Policyholder.   |                     |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.   |                     |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                     |

6. Limitations as to Use#
- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

**This Policy does not cover**

- (a) Use for racing, pace-making, reliability trial or speed-testing.  
(b) Use for the carriage of goods (other than samples) in connection with any trade or business.  
(c) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: ANG KIANG LENG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: HONG LEONG FINANCE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : S & M ALLIANCE PTE LTD (00000614373)  
Date of Issue : 30 Oct 2017 11:27 hrs



For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Max Unladen Weight:	1385 kg
Maximum Laden Weight:	1775 kg
Open Market Value:	\$20,095.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2017
Minimum PARF Benefit:	\$11,052.00
No. of Transfers:	1
IU Label No.:	1121289028
COE No.:	2007110103001238G
COE Expiry Date:	31 Oct 2022
COE Category:	B - Car (1601cc & above)
COE Registration Category:	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium:	\$17,589.00 / -
PQP Paid:	\$25,226.00
QP (Regn Cat):	\$17,589.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$17,589.00
Additional Registration Fee Rate:	110.00 %
Actual ARF Paid:	\$22,105.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
Message:	The vehicle will be de-registered upon expiry of its 5-year COE on 31 Oct 2022. No further renewal will be allowed. You are required to affix a pair of PHC decals on your vehicle windscreens at Authorised Inspection Centres within 3 calendar days, regardless of usage. The vehicle cannot be converted out until the decals have been affixed. This is a public service vehicle.

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05666

Vehicle Insured : SH8438B

Accident Date : 06-Nov-2017

Date : 07-Nov-2017

Our Ref : 217170 (FIRST) / CHAN

PAGE : 1

ANG KIANG LENG  
BLK 504 JELAPANG ROAD  
#07-356  
Singapore 670504

*Not Attached  
61 Lpg & 290d  
Put away After Repair*

## ESTIMATED COST OF REPAIR FOR HONDA STREAM SGZ6785J

1 pc Tail gate	B <sub>1</sub>	983.00	✓
1 pc Tail gate glass inner seal	M <sub>1</sub>	85.60	—
1 pc Tail gate "STREAM" emblem	M <sub>1</sub>	37.60	—
1 pc Rear bumper fascia	Bu	588.90	✓
1 pc Rear bumper tow cover	Sn	13.90	X
2 pcs Rear bumper bracket	D <sub>1</sub>	46.80	7✓
1 pc Rear end panel -outer	B <sub>1</sub>	386.70	7✓
1 pc Rear end panel -inner	B <sub>1</sub>	95.00	7✓
1 pc End panel top garnish	Sn	136.70	X
8 pcs Rear bumper clip	@ S\$ 3.90	nn	31.20 X
		2,405.40	
	Less 20% :	481.08	
		1,924.32	320sn
1 pc Rear bumper reverse sensor(4pcs	Put short	400.00	sn
1 pc Rear w/s glass sealant	M <sub>1</sub>	40sn	60.00 sn
To remove & refix rear windscreen glass and conduct water leak test.		120/	150.00
To remove roof lining, front and rear seats, trim board and carpet		120.00	60/
To apply undersealing		80.00	60/
To putty and spray replaced parts		800.00	660/

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SH8438B

Page : 2

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

600  
900.00

Total : S\$ 4,434.32  
=====

Singapore Dollars Four Thousand Four Hundred  
and Thirty Four and Cents Thirty Two Only

L/SUM

2900 ✓ ok

②

5 days ✓ ok

→  
KLOUNT PLs confirm

P 1778.88

SN 360

L 1500

3638.88

727.78

-20%

2911.10

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05666

Vehicle Insured : SH8438B  
Accident Date : 06-Nov-2017

Date : 07-Nov-2017

Our Ref : 217170 (FIRST) / CHAN

PAGE : 1

ANG KIANG LENG  
BLK 504 JELAPANG ROAD  
#07-356  
Singapore 670504

*Not Authored  
11 Nov 87  
Resurvey After Repair*

## ESTIMATED COST OF REPAIR FOR HONDA STREAM SGZ6785J

1 pc	Tail gate	Bz	983.00	✓
1 pc	Tail gate glass inner seal	nn	85.60	—
1 pc	Tail gate "STREAM" emblem	nn	37.60	—
1 pc	Rear bumper fascia	Bur	588.90	✓
1 pc	Rear bumper tow cover	nn	13.90	X
2 pcs	Rear bumper bracket	@ S\$ 23.40	46.80	?
1 pc	Rear end panel -outer		386.70	?
1 pc	Rear end panel -inner		95.00	?
1 pc	End panel top garnish	nn	136.70	X
8 pcs	Rear bumper clip	@ S\$ 3.90	31.20	X
			2,405.40	
Less 20% :			481.08	

- 1 pc Rear bumper reverse sensor(4pc
- 1 pc Rear w/s glass sealant

*Put short 1,924.32 320sn  
nn 400.00 sn  
nn 40sn 60.00 sn*

To remove & refix rear windscreen  
glass and conduct water leak test.

*1201*  
150.00

To remove roof lining, front and  
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

80.00 *601*

To putty and spray replaced parts

800.00 *6601*

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SH8438B

Page : 2

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

*6002*  
900.00

Total : S\$ 4,434.32

Singapore Dollars Four Thousand Four Hundred  
and Thirty Four and Cents Thirty Two Only




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021425/Kgbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-11-2017	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8438B	Veh. Inspected	SGZ 6785J	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010395MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	09/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMRN68408S200386	Colour	METALLIC PEARL WHITE	
Odometer	216094	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	TOYO	6 mm	
L/H Front Tyre	225/40 R18	TOYO	6 mm	
R/H Rear Tyre	225/40 R18	TOYO	7 mm	
L/H Rear Tyre	225/40 R18	TOYO	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/11/2017	Inspection Date	09/11/2017	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 6785J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAIL GATE	BENT	983.00	983.00
1	TAIL GATE GLASS INNER SEAL	NECESSARY	85.60	85.60
1	TAIL GATE "STREAM" EMBLEM	NECESSARY	37.60	37.60
1	REAR BUMPER FACIA	BUCKLED	588.90	588.90
1	REAR BUMPER TOW COVER	SERVICEABLE	13.90	-
2	REAR BUMPER BRACKET @\$23.40	DISTORTED	46.80	46.80
1	REAR END PANEL-OUTER	BENT	386.70	386.70
1	REAR END PANEL-INNER	BENT	95.00	95.00
1	END PANEL TOP GARNISH	SERVICEABLE	136.70	-
8	REAR BUMPER CLIP @\$3.90	NOT NECESSARY	31.20	-
	LESS 20% DISCOUNT		-481.08	-444.72
			1,924.32	1,778.88
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER REVERSE SENSOR (4 PCS)(SN)	DENTED / SHORTED	400.00	320.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
			460.00	360.00
<b>LABOUR</b>				
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET.		120.00	60.00
	TO APPLY UNDERSEALING.		80.00	60.00
	TO REMOVE,CUT-OUT DAMAGED PARTS.PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		900.00	600.00
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	660.00
			2,050.00	1,500.00
<b>GRAND TOTAL</b>			<b>4,434.32</b>	<b>3,638.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CS/FCI17021425/Kgbn2





Report Ref No. CS/FCI17021425/Kgbn2

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$36,142.00=NETT VALUE: \$5,858.00

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.