

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	1530HRS
ACCIDENT DATE	8-Nov-17
BUS CAPTAIN NAME	KU SIEW HOE
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SBS3392A
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200200	BUMPER CORNER - O/S	1	BRG \$318.11
77201118	O/S LIGHT BEZEL	1	CRA \$132.25
77200411	DEFLECTOR CORNER - O/S	1	BRG \$117.48
77200377	SIDE SHETMETAL PANEL	1	BT \$648.97
77200581	Panel Sheet Metal - O/S	1	BT \$213.70
77200590	DOOR BATTERY ASSEMBLY	1	BT \$639.35
77200190	LOWER FRONT DOME	1	CRA \$2,327.92
77200459	HEADLAMP MAIN BEAM	1	CRA \$92.00
-	GREEN WHEEL NUT POINTERS	9	MIS \$27.00
-	TOWER TRANSIT LOGO	1	NE \$46.00
77200572	BRACKET - SHEET METAL ATTACHMENT	2	PAK \$73.95
77200439	FRONT BUMPER LOCK ME	1	PA \$753.85
77040780	LEVEL LATCH NON LOCKING BLACK	1	CRA \$17.25
		7% GST	\$378.55
		FINAL TOTAL COST	\$5,786.39

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	2500 \$3,000.00
	7% GST \$210.00
	FINAL TOTAL COST \$3,210.00