

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100493470

Claims No. 421686865656

Sum Insured: _____ Excess: 4000 13/11/17

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 16810

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 0788/5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ4366Z Yr Regn: 2016 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi Q5 c.c. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 7901 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28RHA033157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 10/11/17

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>00 AIG.</u>
	<u>SLJ 4366Z - CC3 / ALH17018688 / Agb</u> OIA: <u>240917</u>
<u>10/11/17 @ 5.32pm</u>	<u>revert to Victor via Neamen.</u>
<u>13/11/17 @ 11.37am</u>	<u>Victor informed via Neamen.</u>
<u>13/11/17 @ 11.51am</u>	<u>Informed Tony via AEX \$4000 by email.</u>
<u>26/11/18 @ 5.50pm</u>	<u>confirmed with Mr Boo final fig \$8668.64, 7 days. Cred \$70406.36, 70%.</u>

RECEIVED 22 FEB 2018

Date/Time, File Pass to? : Preli. Report

1) 27/2/18 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

<u>200</u>
<u>10</u>
<u>210</u>

Report Format: WER-00

Lump Sum / I.B.I.: (\$ 8668.64)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17021478/Aqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-11-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLJ 4366Z
Policy No.	2100493470	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/11/2017	Inspection Date	10/11/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 26 January 2018 5:50 PM
To: 'Boo seng yak'; SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION SLJ4366Z - OD AIG - SURVEYED 10 NOV 17

Dear Mr Boo,

Confirm final fig \$8,668.64 before excess \$4,000.00 & GST and 7 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Thursday, 21 December 2017 4:54 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION SLJ4366Z - OD AIG - SURVEYED 10 NOV 17

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$8668.64 @ 7 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 13 November, 2017 11:51 AM
To: 'Claims'; SUR
Subject: RE: OD CLAIM FO SLJ 4366 Z (DOA: 03/11/2017)

Dear Tony,

As instructed by our client AIG, please proceed to repair the insured vehicle **SLJ 4366Z (Excess \$4,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 10 November, 2017 10:40 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: OD CLAIM FO SLJ 4366 Z

Dear all,

Survey has been carry out on this morning.

Kindly assist repair approval above mention case.

Thank you and Have a nice day ahead!

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	03 Nov 2017 20:47	CIm Veh Model Changed		[] Merimen Administrator
2	03 Nov 2017 20:47	CIm Created	Reg No: SLJ4366Z. Acct Date: 2017/11/03. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117145649	[I] Merimen Administrator
3	10 Nov 2017 11:34	CIm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	10 Nov 2017 11:34	Adj CIm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	10 Nov 2017 11:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	10 Nov 2017 11:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/21	[A] CATHERINE CHONG KAI LING
7	10 Nov 2017 11:34	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	10 Nov 2017 11:34	CIm Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	10 Nov 2017 11:34	CIm Veh Model Changed	(201613) AUDI Q5 2.0 TFSI Quattro (A).	[A] CATHERINE CHONG KAI LING
10	10 Nov 2017 11:35	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	10 Nov 2017 14:59	Adj Rpt Initiated		[A] SHIAU CHAN
12	10 Nov 2017 14:59	CIm Details Notified		[A] SHIAU CHAN
13	10 Nov 2017 15:18	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/21	[A] SHIAU CHAN
14	10 Nov 2017 15:27	CIm Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 4000.00. 2F Remarks: -> Young Driver. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
15	10 Nov 2017 15:27	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
16	10 Nov 2017 17:31	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/21	[A] SHIAU CHAN
17	10 Nov 2017 17:32	Adj Mandate Request	Cur.Req:10216.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	13 Nov 2017 11:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/21. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	13 Nov 2017 11:37	Adj Mandate Set	Approved:9674.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1635891	10/11/2017 14:59	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLJ4366Z		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 10 Nov 2017

Preliminary Advice

Vehicle No	: SLJ4366Z	Accident Date	: 03/11/2017
Make	: AUDI Q5	Policy No.	: 2100493470
Assignment Date	: 10/11/2017	Excess	: S\$4,000.00
Date of Inspection	: 10/11/2017	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,075.00
Revised Amount	:S\$	9,674.00
Check Items (Estimated)	:S\$	542.00
Total	:S\$	10,216.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	168,000.00
COE / PARF Rebate	:S\$	74,860.00
Salvage Value	:S\$	
Margin for Repair	:S\$	93,140.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Nov 2017

Preliminary Advice

Vehicle No	: SLJ4366Z	Accident Date	: 03/11/2017
Make	: AUDI Q5	Policy No.	: 2100493470
Assignment Date	: 10/11/2017	Excess	: S\$0.00
Date of Inspection	: 10/11/2017	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,075.00
Revised Amount	:S\$	9,424.00
Check Items (Estimated)	:S\$	542.00
Total	:S\$	9,966.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	168,000.00
COE / PARF Rebate	:S\$	74,860.00
Salvage Value	:S\$	
Margin for Repair	:S\$	93,140.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3009H
Vehicle Details	
Vehicle No.	SLJ4366Z
Vehicle to be Exported	No
Intended De-registration Date	10 Nov 2017
Vehicle Make	AUDI
Vehicle Model	Q5 2.0 TFSI QU (180 BHP)
Primary Colour	Black
Manufacturing Year	2016
Engine No.	CNC175466
Chassis No.	WAUZZZ8RXHA033157
Maximum Power Output	132.0 kW (177 bhp)
Open Market Value	\$37,035.00
Original Registration Date	10 Dec 2016
First Registration Date	10 Dec 2016
Transfer Count	0
Actual ARF Paid	\$43,849.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	09 Dec 2026
PARF Rebate Amount	\$32,886.00
Intended COE Rebate Details	
COE Expiry Date	09 Dec 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$46,229.00
COE Rebate Amount	\$41,974.00
Total Rebate Amount	\$74,860.00

The information contained herein is correct as at 10 Nov 2017

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S9772151C**
 Name: **S SINDOORI**

Birth Date: **23 Dec 1997**
 Issue Date: **12 May 2017**

002683173A




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9772151C



Name: **S SINDOORI**

Race: **SRI LANKAN**
 Date of birth: **23-12-1997** Sex: **F**
 Country of birth: **SRI LANKA**

S9772151C



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3A Motor cars without clutch pedals (Auto) with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight =< 2500kg	12 May 2017

NP 428A

Licence No: S9772151C



5060618



NRIC No. **S9772151C**



Date of Issue: **12-05-2012**

Address: **114A ARTHUR ROAD
 #14-03
 SINGAPORE 439626**



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.4

AUDI AUTO PROTECTOR	OWN DAMAGE EXCESS	SS1000.00	(1)
	WINDSCREEN EXCESS	SS100.00	
	(for policies with effect from 1st November 2002)		
CERTIFICATE NO. 2100493470-00000	SUM INSURED	Market Value	
	INSURING WITH COE/PARF	Yes	
1) VEHICLE REGISTRATION NO.	SLJ4366Z		
2) NAME OF INSURED	AMANDEEP ENTERPRISES PTE LTD		
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT	10 Dec 2016		
4) DATE OF EXPIRY OF INSURANCE	9 Dec 2017		
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION All Age Condition	Any person who is driving on the Insured's order or with their permission. This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle			
6) LIMITATION AS TO USE *	Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS			
1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)			
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)			
2. Comfort Deloro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)			
4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only			
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)			
8. Mova Automotive - 1088 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)			
10. SME Motor - 1 Kaki Bukit Ave 6 BJK D (Tel: 67476106)			
LOSS OF USE	Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre		
NAMED DRIVER	NA		
HIRE PURCHASE COMPANY / EMPLOYER'S LOAN	MayBank		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.			

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 12 Dec 2016

AIG Asia Pacific Insurance Pte. Ltd.

504125-250
PREMIUM LEASING - JY
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLLYY.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1092/2017/JT
Date : 6-Nov-17

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Amandeep Enterprises Pte Ltd
Address : 114A Arthur Road
#14-03
Singapore 439826
Telephone : HP +65 6348 6266
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SLJ 4366 Z**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Dec-16
Engine No : CNC 175466
Chassis No : WAUZZZ8RXHA033157
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-17
Place of Accident : Parkway Parade carpark level 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 4366 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓
2	To renew RHS 1/4 quarter glass to facilitate rear fender renewal.	S/N \$ 300.00	✗
3	To remove and transfer RHS rear door's multi lock system and power window devices.	S/N \$ 280.00	✓
4	To dislodge and reinsatll rear wire harness for lights, battery manager, fuse & relay trays, electrical and audio equipment.	S/N \$ 1,400.00	✗
5	To remove and reinstall rear seats, back rest, hat trays, ABCD pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbaqs, etc.	S/N \$ 1,400.00	✗
6	To dismantle RHS rear door, rear bumper, and rear lid. Cut out and weld RHS rear fender. Renew RHS rear fender. Renew RHS rear door and rear bumper assy, align to position. Reinstall all parts removed.	\$ 6,300.00 ¹⁵⁰⁰ 1252	
7	To respray RHS rear door, RHS rear door cover, RHS rear fender, RHS sill panel, RHS drain panel, RHS roof channel, end panelling, rear bumper and lower spoiler. To carry out stone chip treatment and joint sealer works.	\$ 5,800.00 ²¹⁰⁰	3 main pieces. Door Panel 150 Spoiler 300
8	To renew RHS rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
9	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,232.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4366 Z.

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
1	REAR DOOR - RHS <i>Dented</i>	\$ 2,158.00	→ 1776.40
2	REAR DOOR OUTER SEAL - RHS <i>no</i>	\$ 170.00	→ 135.60
3	BONDING AGENT <i>Not nec</i>	\$ 42.00	* ?
4	STONE CHIP FILM <i>no</i>	\$ 66.00	← 52.24
5	REAR DOOR CATCH - RHS <i>rec on</i>	\$ 123.00	+
6	SILL PANEL SEAL - RHS <i>not nec</i>	\$ 181.00	+
7	REAR DOOR COVER - RHS <i>rec</i>	\$ 351.00	✓ 289.40
8	REAR SECTIONAL PIECE (FENDER) - RHS <i>Repair</i>	\$ 3,787.00	+
9	REAR QUARTER GLASS - RHS	\$ 362.00	+
10	PRIMER	\$ 18.00	+
11	REAR QUARTER GLASS CHROME TRIM - RHS	\$ 275.00	+
12	CHROME ROOF MOULDING - RHS	\$ 528.00	+
13	ROOF MOULDING CLIPS	\$ 47.00	+
14	REAR WHEEL HOUSE LINER - RHS	\$ 224.00	+
15	WHEEL HOUSE LINER ATTACHMENT - RHS	\$ 87.00	+
16	REAR BUMPER <i>Delamed</i>	\$ 1,385.00	→ 1108
17	REAR BUMPER SPOILER <i>Repair</i>	\$ 703.00	+
18	REAR BUMPER GUIDE - RHS <i>no</i>	\$ 44.00	+
19	ALUMINIUM RIM - RHS <i>cut</i>	\$ 912.00	→ 779.20
20	1/4 GLASS SEALENT <i>no</i>	S/N \$ 100.00	+
SUB-TOTAL SPARE PARTS		\$11,563.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4366 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ACRYLIC SEALER	S/N \$	180.00 X
22	CAVITY WAX	S/N \$	140.00 X
23	STONE CHIP	S/N \$	180.00 X
24	METAL FILLER POWDER	S/N \$	280.00 X
25	SUNDRIES ?	\$	500.00 ? 4.80 ✓
GRAND TOTAL SPARE PARTS		:	\$ 12,843.00
TOTAL LABOUR CHARGES		:	\$ 16,232.00
GRAND TOTAL		:	\$ 29,075.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 10/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1092/2017/JT
Date : 6-Nov-17

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
We took 7 days - ok - 21 Dec

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Amandeep Enterprises Pte Ltd
Address : 114A Arthur Road
#14-03
Singapore 439826
Telephone : HP +65 6348 6266
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SLJ 4366 Z**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Dec-16
Engine No : CNC 175466
Chassis No : WAUZZZ8RXHA033157
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-17
Place of Accident : Parkway Parade carpark level 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 4366 Z.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To renew RHS 1/4 quarter glass to facilitate rear fender renewal.	S/N \$	300.00	nn
3	To remove and transfer RHS rear door's multi lock system and power window devices.	S/N \$	280.00	\$ 280.00
4	To dislodge and reinsatll rear wire harness for lights, battery manager, fuse & relay trays, electrical and audio equipment.	S/N \$	1,400.00	nn
5	To remove and reinstall rear seats, back rest, hat trays, ABCD pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbags, etc.	S/N \$	1,400.00	nn
6	To dismantle RHS rear door, rear bumper, and rear lid. Cut out and weld RHS rear fender. Renew RHS rear fender. Renew RHS rear door and rear bumper assy, align to position. Reinstall all parts removed.	\$	6,300.00	\$ 1,500.00
7	To respray RHS rear door, RHS rear door cover, RHS rear fender, RHS sill panel, RHS drain panel, RHS roof channel, end panelling, rear bumper and lower spoiler. To carry out stone chip treatment and joint sealer works.	\$	5,800.00	\$ 2,100.00
8	To renew RHS rear rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
9	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 16,232.00	\$ 4,632.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4366 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR - RHS	\$ 2,158.00	\$ 1,726.40
2	REAR DOOR OUTER SEAL - RHS	\$ 170.00	\$ 135.60
3	BONDING AGENT	\$ 42.00	
4	STONE CHIP FILM	\$ 66.00	\$ 52.24
5	REAR DOOR CATCH - RHS	\$ 123.00	
6	SILL PANEL SEAL - RHS	\$ 181.00	
7	REAR DOOR COVER - RHS	\$ 351.00	\$ 280.40
8	REAR SECTIONAL PIECE (FENDER) - RHS	\$ 3,787.00	
9	REAR QUARTER GLASS - RHS	\$ 362.00	
10	PRIMER	\$ 18.00	
11	REAR QUARTER GLASS CHROME TRIM - RHS	\$ 275.00	
12	CHROME ROOF MOULDING - RHS	\$ 528.00	
13	ROOF MOULDING CLIPS	\$ 47.00	
14	REAR WHEEL HOUSE LINER - RHS	\$ 224.00	
15	WHEEL HOUSE LINER ATTACHMENT - RHS	\$ 87.00	
16	REAR BUMPER	\$ 1,385.00	\$ 1,108.00
17	REAR BUMPER SPOILER	\$ 703.00	
18	REAR BUMPER GUIDE - RHS	\$ 44.00	
19	ALUMINIUM RIM - RHS	\$ 912.00	\$ 729.20
20	1/4 GLASS SEALANT	S/N \$ 100.00	
SUB-TOTAL SPARE PARTS		\$ 11,563.00	\$ 4,031.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 4366 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 4,031.84
21	ACRYLIC SEALER	S/N \$ 180.00	
22	CAVITY WAX	S/N \$ 140.00	
23	STONE CHIP	S/N \$ 180.00	
24	METAL FILLER POWDER	S/N \$ 280.00	
25	SUNDRIES	\$ 500.00	\$ 4.80
	GRAND TOTAL SPARE PARTS	\$ 12,843.00	\$ 4,036.64
	TOTAL LABOUR CHARGES	\$ 16,232.00	\$ 4,632.00
	GRAND TOTAL	\$ 29,075.00	\$ 8,668.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLJ 4366 Z

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1092/2017/MAS

17 Feb 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SLJ 4366 Z, Audi Q5 2.0 TFSI QU

With reference to the above-mentioned vehicle no **SLJ 4366 Z**, claimant, **Amandeep Enterprises Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85012135 – S\$4,995.44
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLJ 4366 Z

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2017		10 Nov 2017 11:34 Edit Adj Rpt	S\$8,668.64 Edit Estimates	S\$8,668.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AMANDEEP ENTERPRISES PTE LTD , Co. Reg. No.: 198103009H								
Vehicle Reg. No.:	SLJ4366Z	Date of Loss:	03/11/2017 15:00 - :59						
Claim Type:	OD / 4216868656SG	Policy/Cover Note No.:	2100493470 (Comprehensive)						
		Excess:	S\$4,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/11/2017]								
Driver/Custodian:	SINDOORI (19 / Female), NRIC: S9772151C								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (13/11/2017): Alert - Adj Mandate Approved (S\$9674.00) - SLJ4366Z - Claim Handler: Dally Amri,... AIG_SG (10/11/2017): SLJ4366Z / OD / 03/11/2017 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ4366Z (4216868656SG)
 OD
 Nov 3 2017 3:00PM
 [AMANDEEP ENTERPRISES PTE LTD]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Assessment Reports												1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print											
1	10/11/17 15:18	Adjuster Immediate Advice				Load HTM											
2	10/11/17 17:31	Adjuster Immediate Advice				Load HTM											
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print											
1	10/11/17 17:31	General View				Load JPG											
2	10/11/17 17:31	Chassis Number				Load JPG											
3	10/11/17 17:31	General View				Load JPG											
4	10/11/17 17:31	General View				Load JPG											
5	10/11/17 17:31	General View				Load JPG											
6	10/11/17 17:31	General View				Load JPG											
7	10/11/17 17:31	General View				Load JPG											
8	10/11/17 17:31	General View				Load JPG											
9	10/11/17 17:31	General View				Load JPG											
10	10/11/17 17:31	General View				Load JPG											
11	10/11/17 17:31	General View				Load JPG											
12	10/11/17 17:31	General View				Load JPG											
13	10/11/17 17:31	General View				Load JPG											
14	10/11/17 17:31	General View				Load JPG											
15	10/11/17 17:31	General View				Load JPG											
16	10/11/17 17:31	General View				Load JPG											
17	10/11/17 17:31	General View				Load JPG											
18	10/11/17 17:31	General View				Load JPG											
19	10/11/17 17:31	General View				Load JPG											
20	10/11/17 17:31	General View				Load JPG											
21	10/11/17 17:31	General View				Load JPG											
22	10/11/17 17:31	General View				Load JPG											
23	10/11/17 17:31	General View				Load JPG											
Documentation												1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print											
1	10/11/17 15:07	Singapore Accident Statement				Load PDF											
2	10/11/17 15:07	Drivers Driving License				Load PDF											
3	10/11/17 15:07	WORKSHOP ESTIMATE				Load PDF											
4	10/11/17 15:08	Certificate of Insurance				Load PDF											
5	22/02/18 12:14	WORKSHOP INVOICE				Load PDF											
6	22/02/18 12:14	DISCHARGE VOUCHER				Load PDF											

Linked Accident Report Documents

View Use Viewer															
Assessment Reports												1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)			Thumbnail	Print									
1	03/11/17 20:47	Accident Statement				Load HTM									

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	03/11/17 20:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/11/17 20:42	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	03/11/17 20:42	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid gray; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17021478/AQBN2
Date: 22/02/2018

REFERENCE

Insured/Claimant: AMANDEEP ENTERPRISES PTE LTD Policy No: 2100493470
Date of Loss: 03/11/2017 Nature of Claim: OD Claim No: 4216868656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4366Z	Engine No:	CNC175466
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZ8RXHA033157
Reg. Date:	10/12/2016 (Man. Year: 2016)	Odometer:	7901 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$168,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,843.00	4,036.64	8,806.36	68.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,232.00	4,632.00	11,600.00	71.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,075.00	8,668.64	20,406.36	70.19
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
(S\$)	25,075.00	4,668.64	20,406.36	81.38
+ GST 7.00/7.00% (S\$)	1,755.25	326.80	1,428.45	81.38
Nett Amount (S\$)	26,830.25	4,995.44	21,834.81	81.38

INSPECTION

Date of Assignment: 10/11/2017
Date Inspected: 10/11/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-RHS	Dented	2,158.00 FS	*1,726.40 FS
2	1		*REAR DOOR OUTER SEAL-RHS	Necessary	170.00 FS	*135.60 FS
3	1		*BONDING AGENT	Not Necessary	42.00 FS	*- FS
4	1		*STONE CHIP FILM	Necessary	66.00 FS	*52.24 FS
5	1		*REAR DOOR CATCH-RHS	Not Necessary	123.00 FS	*- FS
6	1		*SILL PANEL SEAL-RHS	Not Necessary	181.00 FS	*- FS
7	1		*REAR DOOR COVER-RHS	Necessary	351.00 FS	*280.40 FS
8	1		*REAR SECTIONAL PIECE (FENDER)-RHS	Repair	3,787.00 FS	*- FS
9	1		*REAR QUARTER GLASS-RHS	Not Necessary	362.00 FS	*- FS
10	1		*PRIMER	Not Necessary	18.00 FS	*- FS
11	1		*REAR QUARTER GLASS CHROME TRIM-RHS	Not Necessary	275.00 FS	*- FS
12	1		*CHROME ROOF MOULDING-RHS	Not Necessary	528.00 FS	*- FS
13	1		*ROOF MOULDING CLIPS	Not Necessary	47.00 FS	*- FS
14	1		*REAR WHEEL HOUSE LINER-RHS	Not Necessary	224.00 FS	*- FS
15	1		*WHEEL HOUSE LINER ATTACHMENT-RHS	Not Necessary	87.00 FS	*- FS
16	1		*REAR BUMPER	Deformed	1,385.00 FS	*1,108.00 FS
17	1		*REAR BUMPER SPOILER	Repair	703.00 FS	*- FS
18	1		*REAR BUMPER GUIDE-RHS	Not Necessary	44.00 FS	*- FS
19	1		*ALUMINIUM RIM-RHS	Cut	912.00 FS	*729.20 FS
20	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
21	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
22	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
23	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
24	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
25	1		*SUNDRIES	Necessary	500.00 FS	*4.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,843.00 4,036.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO RENEW RHS 1/4 QUARTER GLASS TO FACILITATE REAR FENDER RENEWAL	New	300.00	-
3	TO REMOVE AND TRANSFER REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
4	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE & RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	-
5	TO REMOVE AND REINSTALL REAR SEATS,BACK REST,HAT TRAYS,ABCD PILLAR TRIMS,LUGGUAGE COMPARTMENT TRIMS,SEAT BELTS,DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAGS,ETC	New	1,400.00	-
6	TO DISMANTLE RHS REAR DOOR,REAR BUMPER,AND REAR LID.CUT OUT AND WELD RHS REAR FENDER,RENEW RHS REAR FENDER.RENEW RHS REAR DOOR AND REAR BUMPER ASSY,ALIGN TO POSITION.REINSTALL ALL PARTS REMOVED	New	6,300.00	1,500.00
7	TO RESPRAY RHS REAR DOOR,RHS REAR DOOR COVER,RHS REAR FENDER,RHS SILL PANEL,RHS DRAIN PANEL,RHS ROOF CHANNEL,END PANELLING,REAR BUMPER AND LOWER SPOILER.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALERWORKS	New	5,800.00	2,100.00
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			16,232.00	4,632.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >