

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLH3076C
TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991053/YISHUN

Date: 16 Jan 2019

Policy No: 16-MV009797-R00

Veh Reg No: SLH3076C

Make/Model: HONDA HRV 1.5 DX
CVT

Chassis No: JHMRU1810GX200384

Engine No: L15B4530385

Reg. Date: 28/10/2016

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 03/11/2017

TP Veh Reg No: SJU822R

Estimate Repair Cost to Vehicle No :SLH3076C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	508.50	1 PC	508.50	✓
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
3 TAILGATE EMBLEM (HRV)	43.80	1 PC	43.80	✓
4 TAILGATE EMBLEM (E-TECH)	49.80	1 PC	49.80	✓
			623.10	
		Less 20%	124.62	498.48
Special Net				
5 REVERSE SENSOR	200.00	1 PCSET	200.00	?
			200.00	200.00
Labour				
6 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TO KNOCK & REPAIR REAR PANEL, TAILGATE & REALIGN THE SAME	480.00	1 LA	480.00	3000
7 PUTTY & RESPRAY TAILGATE PANEL & REAR BUMPER (TWO TONE)	600.00	1 LA	600.00	4400
			1,080.00	1,080.00
Total				S\$ 1,778.48
Add GST @ 7%				124.49
Total Amount Payable				S\$ 1,902.97

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

AUTHORISED SIGNATURE