



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR LIM SIT GUAN	Cust No/Name /MR LIM SIT GUAN
BLK 130 BISHAN STREET 12	Reg No/Reg Date SLC3499S / 12/05/201
#06-251	Date In/Mileage / 0
SINGAPORE 570130	Chassis No KNAFX411MG5601869
Contact No Mobile: 96370732	Engine No G4FGGH612931
	Make/Model KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/11/2017/ 09:37	TLC	442 / CocoLu	17770			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550.1650.00
TO RENEW REAR BUMPER, REAR BUMPER LOWER COVER, REPAIR REAR END PANEL,								420.1260.00
E PNT98000								60.100.00
TO SPRAY PAINT FOR REAR BUMPER, REAR END PANEL								? 220.00
E PNT88000								✓ 20.00
TO REMOVE & INSTALL REVERSE SENSOR								✓ 200.00
M SUNDRY								✓ 20.00
TO SUPPLY REVERSE SENSOR								
A 90000001								
TO CHECK WIRING & ELECTRICAL SYSTEM								
A 90000001								
TO CONDCUT DISGNOSTIC CHECK FOR THE CAR SYSTEM								
M SUNDRY								
Sundry								
P	COVER-RR BUMPER	de			1.00	768.00	00.00	768.00
M	COVER-RR BUMPER,UPR	de			1.00	221.00	00.00	221.00
M	BEAM-RR BUMPER	?			1.00	360.00	00.00	360.00
M	STAY-RR BUMPER LH	?			1.00	75.00	00.00	75.00
M	BRACKET-RR BUMPER SIDE MTG,LH	?			1.00	33.00	00.00	33.00
M	BRACKET-RR RAIL UPR MTG,LH	?			1.00	4.00	00.00	4.00
M	LAMP ASSY-REAR COMBINATION,LH	X			1.00	788.00	00.00	788.00

SURVEYOR NAME: Tanfah 97495706

SURVEYOR SIGNATURE: [Signature]

DATE: 31/11/17 @ 1150

REMARKS: 3 days Resing before paint

Confirm & accepted by

surc1hkentb.com

KKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: [Signature]

Date: [Date]

7% GST on 5719.00

Nett 5,719.00

400.33

Total Payable

6,119.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.