

22/03/2003

ASS. REC. BY:

REF: CS/MSG17021619/Arbe2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time: 13-11-2017 3:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGE 7037P

Insured:

PA 7765K

at Workshop m/s

Vision Autowork

Tel:

6341 6789

of

8 Kaki Bukit Ave 4 # 08-09

Policy No:

P2878114MKF

Claim No:

536389.

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

13-11-2017 3:44pm

Person Contacted:

Michelle

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGE 7037P - NA/MSG17021619/Y

DOA: 10-11-17

PA 7765K - X

Sent pending estimate through messenger, Chuan Ho

Jilin

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 5487037P Yr Regn: 2006, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c 1794

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 293147 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2NE100287655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15

R: 205/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 13/11/17

Survey held at Vision

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ms/g.
	LS \$11,000 (Red. 23,974.33, 68%)
	MV: 28k
	PV: 17k
	Nett: 11k
	RECEIVED 3 DEC 2017
	RECEIVED 20 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format : TP

Lump Sum / KB! : (\$ 11,000)

350
10
360

Survey Department Check List (Case Handler)

Reference No.: CO/MCG17021619/Arb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Celine 17/05/201
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17021619/Arb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 7765K	Veh. Inspected	SGE 7037P
Policy No.	P28781114MKF	Coverage (\$)	0.00
Claim No.	536389	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	13/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/11/2017	Inspection Date	13/11/2017
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2017		13 Nov 2017 15:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	VICTORY FAMILY CENTRE LTD, Co. Reg. No.: 197802910W								
Main Claimant:	TAN MUN HOWE (CHEN WENHAO), ID: S7618718E								
Vehicle Reg. No.:	SGE7037P	Date of Loss:	10/11/2017 19:00 - :59						
Claim Type:	TP / 536389	Policy/Cover Note No.:	P28781114MKF (Comprehensive) Coverage: 04/08/2017 - 03/08/2018						
Vehicle Reg. No. (Insured):	PA7765K	Policy No. (Claimant):							
	Excess: S\$1,500.00								
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/11/2017]								
Driver/Custodian (Insured):	CHEE KENG YUEN (), NRIC: S2573300B, Tel: +6596641024								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Print Sent Message

This mail is associated with :

***SGE7037P (536389)**

[PA7765K]

TP

TAN MUN HOWE (CHEN WENHAO)

Nov 10 2017 7:00PM

[VICTORY FAMILY CENTRE LTD]

Vision Autowork Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 14/11/2017 16:00 PM.
To christina_wong@sg.msg-asia.com
CC sur@lkkauto.com
Subject SGE7037P (536389)

Dear Chrisina,

Please be informed that we have inspected the vehicle SGE 7037P on 13/11/2017.

We are pending for estimate from repairer.

Thank you.

Regards,
Janice

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8718E

Vehicle Details

Vehicle No.	SGE7037P
Vehicle to be Exported	No
Intended De-registration Date	10 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	WISH 1.8 A
Primary Colour	Grey
Manufacturing Year	2005
Engine No.	1ZZ2476989
Chassis No.	ZNE100287655
Maximum Power Output	97.0 kW (130 bhp)
Open Market Value	\$19,639.00
Original Registration Date	23 Mar 2006
First Registration Date	23 Mar 2006
Transfer Count	4
Actual ARF Paid	\$21,603.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	22 Mar 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	5
PQP Paid	\$25,466.00
COE Rebate Amount	\$17,141.00
Total Rebate Amount	\$17,141.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Nov 2017

COE till 2021



\$12,659


ANNOUNCING Lake View Credit Pte Ltd
 as sgCarMart Premium Dealer for the Sixth Consecutive Year

**Lake View
Credit Pte Ltd**

Username / Email Add

password

Connect

» Sign Up New Account

» Forgot Password

toyota wish 1.8e (coe 2021)

Price Range

Depreciation

Year Reg

Vehicle Type


 Add to Shortlist
 Add to Compare

Home » Used Cars » Karz Konzept » Toyota Wish 1.8A (COE till 03/2021)

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Leasing



Toyota Wish 1.8A (COE till 03/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$29,800	
Depreciation	\$8,790 /yr	
	View models with similar depreciation	
Reg Date	12-Apr-2006	
	(3yrs 4mths 21days COE left)	
Manufactured	2005	
Mileage	110,000 km (9.5k /yr)	
Transmission	Auto	
Engine Cap	1,794 cc	
Road Tax	\$1,069 /yr	
Power	97.0 kW (130 bhp)	
Curb Weight	1,300 kg	
Features	Airbags, ABS, Reliable 1.8L VVTi Engine, Fuel Efficient, Digital Auto Climate Aircon.	
Accessories	Leather Seats, Sports Rims, Audio System.	
Description	Low Down Payment Of \$4800, Monthly Only At \$797. New Paintwork, Wear And Tear All Replaced. 6 Months Warranty Of Engine And Gearbox. Drive With No Worries. Call Now To View This Car Before Its Sold.	
COE	\$25,466	
OMV	\$19,663	
ARF	\$21,630	
Dereg Value	\$17,261 as of today (change)	
No. of Owners	3	
Type of Veh	MPV	
Category	COE Car, Low Mileage Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note



Seller Information

Company	Karz Konzept	
	» dealer's pricelist	
	» 12 vehs sold 5 vehs available	
Address	1 Bukit Batok Crescent #02-44	
	Search cars nearby this location	
Location	WCEGA Plaza	
Contact Person(s)	Kelvin	82513333
	Tan	81173333

Useful Services


 Make sure of this car condition
 with STA Evaluation.

[Vehicle Evaluation](#)

 Find out the market value for your car.
 Get a free Car Valuation.

[Free Valuation](#)

Posted on: 03-Nov-2017 | Last Updated on: 07-Nov-2017

 Tags: Toyota Wish, Toyota Wish, 2006 Toyota Wish, 2006 Toyota Wish, Toyota,
 Wish, Wish, Used Toyota

Upfront Payment

Transfer Fee	\$11	
Down Payment	\$8,940 (change)	Maximum 70% Loan
1st Instalment	\$587	
Total Upfront Payment	\$9,538 (excluding insurance)	

based on 70% loan at 3.75% interest rate. Check with seller for exact figure.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2017 10:19
Date Of Accident	10/11/2017 19:20
Exact Location Of Accident	BKE TOWARDS WOODLANDS(BEFORE DAIRY FARM EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE7037P
Insured/Policyholder	
Name Of Registered Owner	TAN MUN HOWE(CHEN WENHAO)
NRIC No	S7618718E
Email Address	SIMON_MITO@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-87817618
Alternative Phone No	OTHERS-87817618

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00352494
Cover Note Number	

Driver

Name of Driver	TAN MUN HOWE(CHEN WENHAO)
NRIC No	S7618718E
Date Of Birth	23/06/1976
Occupation	INDOOR
Date Of Driving Pass	30/10/1998
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87817618
Fax Number	
Contact Number	OTHERS-87817618
Email Address	SIMON_MITO@HOTMAIL.COM

Address	BLK 48A DORSET ROAD #24-119
Postcode	211048
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA7765K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD1084K
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJE8951H

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name TAN MUN HOWE

Approximate Age

Injuries Sustain BODY PAIN

Injured person in which vehicle? SGE7037P

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

11/6/2017
Reporting Centre Personnel's Signature
Name: Rosli WATOB
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]*
Date & Time: *[Signature]*

Driver's Signature: *[Signature]*
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature: *[Signature]*
Name: *Roshni WATHAR*
NRIC/IN NO: *11/11/2017*

Sketch Plan #3

On 10.11.17 at about 19:20 hours at along BKE towards Woodlands (Before Dairy Farm Exit). While I was travelling on the lane 1 and traffic was heavy, my front vehicle slow down and stop hence I follow suit.

Suddenly, I heard a loud bang from behind and the impact forced my vehicle (A) to move forward to hit onto the rear portion of Vehicle (C). When I alighted I realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle. It was a chain collision of total 4 vehicles involved.

Vehicle (A) : SGE 7037P

Vehicle (B) : PA 7765K

Vehicle (C) : SHD 1084K

Vehicle (D) : SJE 8951H

and 11/11/2017
Simon Tan

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 11.11.17

TO : **MSIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SGE7037P**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : 10.11.17
TIME OF ACCIDENT : 19:20HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rebond</i>	1	\$ 510.00	\$ 510.00
2	FRONT BUMPER LOWER GARNISH <i>new</i>	1	\$ 180.00	\$ 180.00
3	FRONT BUMPER FOG LAMP <i>new</i>	2	\$ 325.00	\$ 650.00
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 130.00	\$ 130.00
5	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
6	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 300.00	\$ 300.00
7	FRONT BUMPER SPONGE <i>new</i>	1	\$ 150.00	\$ 150.00
8	BONNET <i>Buckled.</i>	1	\$ 665.00	\$ 665.00
9	BONNET MOULDING <i>new</i>	1	\$ 205.00	\$ 205.00
10	BONNET LOGO <i>new</i>	1	\$ 60.00	\$ 60.00
11	BONNET LOCK <i>new</i>	1	\$ 90.00	\$ 90.00
12	BONNET LOCK CABLE <i>new</i>	1	\$ 85.00	\$ 85.00
13	BONNET STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00
14	BONNET HINGE <i>new</i>	2	\$ 30.00	\$ 60.00
15	CENTRE GRILLE <i>new</i>	1	\$ 360.00	\$ 360.00
16	HEADLAMP <i>new</i>	2	\$ 1,070.00	\$ 2,140.00
17	FRONT SUPPORT PANEL <i>Buckled.</i>	1	\$ 890.00	\$ 890.00
18	FRONT BRACE PANEL <i>Best</i>	1	\$ 90.00	\$ 90.00
19	HORN <i>new</i>	2	\$ 85.00	\$ 170.00
20	AIRCON CONDENSOR <i>Best</i>	1	\$ 1,600.00	\$ 1,600.00
21	AIRCON PIPE <i>new</i>	2	\$ 460.00	\$ 920.00
22	AIR GUARD GARNISH LH <i>new</i>	1	\$ 120.00	\$ 120.00
23	RADIATOR <i>Best</i>	1	\$ 1,810.00	\$ 1,810.00
24	RADIATOR MOUNTING <i>2</i>	4	\$ 42.00	\$ 168.00
25	RADIATOR BRACKET <i>new</i>	2	\$ 91.00	\$ 182.00
26	RADIATOR FAN COWLING	1	\$ 260.00	\$ 260.00
27	REAR DOOR FRAME WEATHER STRIP LH <i>2</i>	1	\$ 165.00	\$ 165.00
28	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 160.00	\$ 160.00
29	REAR DOOR INNER LOCK LH	1	\$ 320.00	\$ 320.00

30	TAILGATE <i>Dented</i>	1	\$ 1,280.00	\$ 1,280.00	✓
31	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00	✓
32	TAILGATE OUTER MOULDING <i>cracked</i>	1	\$ 240.00	\$ 240.00	✓
33	TAILGATE WIPER HEAD RUBBER <i>missing</i>	1	\$ 90.00	\$ 90.00	✓
34	TAILGATE WIPER ARM <i>at</i>	1	\$ 195.00	\$ 195.00	✓
35	TAILGATE WIPER BLADE <i>new</i>	1	\$ 85.00	\$ 85.00	+
36	TAILGATE WIPER BOLT COVER <i>missing</i>	1	\$ 25.00	\$ 25.00	✓
37	TAILGATE WIPER MOTOR <i>new</i>	1	\$ 745.00	\$ 745.00	+
38	TAILGATE INNER LOCK <i>Dented</i>	1	\$ 445.10	\$ 445.10	✓
39	TAILGATE LOWER LOCK <i>new</i>	1	\$ 35.00	\$ 35.00	+
40	TAILGATE DAMPER <i>Best LH</i>	2	\$ 194.00	\$ 388.00	194
41	TAILGATE STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00	+
42	TAILGATE WEATHER STRIP <i>at</i>	1	\$ 320.00	\$ 320.00	✓
43	TAILGATE INNER TRIM (TOP) <i>at</i>	1	\$ 285.00	\$ 285.00	+
44	TAILGATE INNER TRIM (TOP SIDE) <i>at LH</i>	2	\$ 195.00	\$ 390.00	195
45	TAILGATE INNER TRIM (LOWER) <i>behind</i>	1	\$ 395.00	\$ 395.00	✓
46	TAILGATE WINDSCREEN GLASS <i>shattered</i>	1	\$ 980.00	\$ 980.00	✓
47	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00	✓
48	REAR BUMPER <i>Distorted</i>	1	\$ 590.00	\$ 590.00	✓
49	REAR BUMPER REFLECTOR <i>LH at</i>	2	\$ 68.00	\$ 136.00	68
50	REAR BUMPER BRACKET <i>Dented LH</i>	2	\$ 70.10	\$ 140.20	70.10
51	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00	✓
52	TAILLAMP C/W BRACKET <i>LH cracked, RH at</i>	2	\$ 520.00	\$ 1,040.00	820
53	TAILLAMP INNER PANEL LH <i>Dented</i>	1	\$ 890.00	\$ 890.00	920
54	REAR FENDER LH <i>Buckled</i>	1	\$ 930.00	\$ 930.00	✓
55	REAR FENDER INNER COWLING <i>new</i>	2	\$ 380.00	\$ 760.00	+
56	REAR FENDER AIR VENT <i>behind</i>	1	\$ 95.00	\$ 95.00	✓
57	REAR FENDER INNER TRIM <i>LH cracked</i>	2	\$ 738.10	\$ 1,476.20	738.10
58	REAR FENDER INNER BOTTOM PANEL LH <i>Rpr</i>	1	\$ 455.00	\$ 455.00	+
59	REAR FENDER QUARTER GLASS C/W MOULDING LH <i>new</i>	1	\$ 490.00	\$ 490.00	150
60	FUEL TANK INLET PIPE <i>new</i>	1	\$ 295.00	\$ 295.00	+
61	REAR END PANEL <i>Distorted</i>	1	\$ 480.00	\$ 480.00	✓
62	REAR END PANEL TOP GARNISH <i>behind</i>	1	\$ 245.00	\$ 245.00	✓
63	REAR END PANEL (EXTEND) <i>Rpr</i>	2	\$ 298.70	\$ 597.40	+
64	REAR END PANEL BOTTOM (CENTRE) <i>Rpr</i>	1	\$ 311.10	\$ 311.10	+
65	REAR FLOOR PANEL TOP BOARD (INNER SUPPORT) <i>new</i>	1	\$ 410.10	\$ 410.10	+
66	REAR FLOOR PANEL <i>Rpr</i>	1	\$ 1,150.00	\$ 1,150.00	+
67	REAR FLOOR PANEL TOP BOARD <i>behind</i>	1	\$ 460.00	\$ 460.00	✓
68	REAR FLOOR PANEL SIDE BOARD <i>new</i>	1	\$ 195.00	\$ 195.00	+

1850530

1357897

TOTAL PRICE	\$ 29,979.10
LESS 25%	\$ 7,494.78
SUB TOTAL PRICE	\$ 22,484.33

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>lt</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>m</i>	1	\$ 50.00	\$ 50.00
3	FRONT FENDER COWLING CLIP (SET) <i>men</i>	1	\$ 60.00	\$ 60.00
4	CENTRE GRILLE CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00
5	COOLANT <i>m</i>	1	\$ 60.00	\$ 60.00
6	REAR NUMBER PLATE <i>men</i>	1	\$ 50.00	\$ 50.00
7	REAR BUMPER CLIPS (SET) <i>m</i>	1	\$ 60.00	\$ 60.00
8	TAILLAMP CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00
9	TAILLAMP INNER PANEL SEALANT LH <i>men</i>	1	\$ 80.00	\$ 80.00
10	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>men</i>	1	\$ 60.00	\$ 60.00
11	TAILGATE WINDSCREEN GLASS SOLAR FILM	1	\$ 350.00	\$ 350.00
12	TAILGATE WINDSCREEN SEALANT <i>m</i>	1	\$ 80.00	\$ 80.00
13	TAILGATE WINDSCREEN INNER SHIELD <i>men</i>	1	\$ 60.00	\$ 60.00
14	REAR FENDER LH SEALANT <i>men</i>	1	\$ 80.00	\$ 80.00
15	REAR FENDER INNER TRIM CLIP (SET) <i>m</i>	1	\$ 50.00	\$ 50.00
16	REAR FENDER INNER COWLING CLIP (SET) <i>m</i>	1	\$ 60.00	\$ 60.00
17	REAR FENDER QUARTER GLASS SEALANT LH <i>m</i>	1	\$ 60.00	\$ 60.00
18	REAR FENDER QUARTER GLASS INNER SEAL LH <i>m</i>	1	\$ 40.00	\$ 40.00
19	REAR FENDER QUARTER GLASS SOLAR FILM LH <i>men</i>	1	\$ 250.00	\$ 250.00
20	REAR END PANEL INSULATION SEAL <i>m</i>	1	\$ 150.00	\$ 150.00
21	REAR END PANEL TOP GARNISH CLIP (SET) <i>m</i>	1	\$ 30.00	\$ 30.00
22	REAR FLOOR PANEL INSULATION SEAL <i>men</i>	1	\$ 350.00	\$ 350.00
23	REVERSE SENSOR <i>Ryd</i>	1	\$ 220.00	\$ 220.00
24	REVERSE CAMERA <i>men</i>	1	\$ 450.00	\$ 450.00

790

TOTAL

\$2,760.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600
3	REFOCUS HEADLAMP BEAM	\$ 80.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60

1450

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,800.00	1200

2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1000
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	40
8	REAR CHASSIS ALIGNMENT	\$ 250.00	x
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
13	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	60
14	REMOVE AND REFIX PETROL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	80
15	VACCUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER	\$ 180.00	60
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 9,730.00

2850

ESTIMATE REPORT

TOTAL PARTS COST : \$25,244.33
TOTAL LABOUR COST : \$9,730.00
TOTAL REPAIR COST : \$34,974.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian Lj

1/5 13/11/17

total: 18568.97

HS 11K.

14 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2017		13 Nov 2017 15:21 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VICTORY FAMILY CENTRE LTD, Co. Reg. No.: 197802910W		
Main Claimant:	TAN MUN HOWE (CHEN WENHAO), ID: S7618718E		
Vehicle Reg. No.:	SGE7037P	Date of Loss:	10/11/2017 19:00 - :59
Claim Type:	TP / 536389	Policy/Cover Note No.:	P28781114MKF (Comprehensive) Coverage: 04/08/2017 - 03/08/2018
Vehicle Reg. No. (Insured):	PA7765K	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 14/11/2017]		
Driver/Custodian (Insured):	CHEE KENG YUEN (), NRIC: S2573300B, Tel: +6596641024		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*SGE7037P (536389)

[PA7765K]

TP

TAN MUN HOWE (CHEN WENHAO)

Nov 10 2017 7:00PM

[VICTORY FAMILY CENTRE LTD]

Vision Autowork Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/11/17 15:23	Accident Statement From: SC - Reg. No: PA7765K, Claimant: VICTORY FAMILY CENTRE LTD		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 10:06	General View		Load JPG	☒
2	12/12/17 10:06	General View		Load JPG	☒
3	12/12/17 10:06	Chassis Number		Load JPG	☒
4	12/12/17 10:06	General View		Load JPG	☒
5	12/12/17 10:06	General View		Load JPG	☒
6	12/12/17 10:06	General View		Load JPG	☒
7	12/12/17 10:06	General View		Load JPG	☒
8	12/12/17 10:06	General View		Load JPG	☒
9	12/12/17 10:06	General View		Load JPG	☒
10	12/12/17 10:06	General View		Load JPG	☒
11	12/12/17 10:06	General View		Load JPG	☒
12	12/12/17 10:06	General View		Load JPG	☒
13	12/12/17 10:06	General View		Load JPG	☒
14	12/12/17 10:06	General View		Load JPG	☒
15	12/12/17 10:06	General View		Load JPG	☒
16	12/12/17 10:06	General View		Load JPG	☒
17	12/12/17 10:06	General View		Load JPG	☒
18	12/12/17 10:06	General View		Load JPG	☒
19	12/12/17 10:06	General View		Load JPG	☒
20	12/12/17 10:06	General View		Load JPG	☒
21	12/12/17 10:06	General View		Load JPG	☒
22	12/12/17 10:06	General View		Load JPG	☒
23	12/12/17 10:06	General View		Load JPG	☒
24	12/12/17 10:06	General View		Load JPG	☒
25	12/12/17 10:06	General View		Load JPG	☒
26	12/12/17 10:06	General View		Load JPG	☒
27	12/12/17 10:06	General View		Load JPG	☒
28	12/12/17 10:06	General View		Load JPG	☒
29	12/12/17 10:06	General View		Load JPG	☒
30	12/12/17 10:06	General View		Load JPG	☒
31	12/12/17 10:06	General View		Load JPG	☒
32	12/12/17 10:06	General View		Load JPG	☒
33	12/12/17 10:06	General View		Load JPG	☒
34	12/12/17 10:06	General View		Load JPG	☒

35	12/12/17 10:06	General View		Load JPG	☒
36	12/12/17 10:06	General View		Load JPG	☒
37	12/12/17 10:06	General View		Load JPG	☒
38	12/12/17 10:06	General View		Load JPG	☒
39	12/12/17 10:06	General View		Load JPG	☒
40	12/12/17 10:06	General View		Load JPG	☒
41	12/12/17 10:06	General View		Load JPG	☒
42	12/12/17 10:06	General View		Load JPG	☒
43	12/12/17 10:06	General View		Load JPG	☒
44	12/12/17 10:06	General View		Load JPG	☒
45	12/12/17 10:06	General View		Load JPG	☒
46	12/12/17 10:06	General View		Load JPG	☒
47	12/12/17 10:06	General View		Load JPG	☒
48	12/12/17 10:06	General View		Load JPG	☒
49	12/12/17 10:06	General View		Load JPG	☒
50	12/12/17 10:06	General View		Load JPG	☒
51	12/12/17 10:06	General View		Load JPG	☒
52	12/12/17 10:06	General View		Load JPG	☒
53	12/12/17 10:07	Reinspection Photo		Load JPG	☒
54	12/12/17 10:07	Reinspection Photo		Load JPG	☒
55	12/12/17 10:07	Reinspection Photo		Load JPG	☒
56	12/12/17 10:07	Reinspection Photo		Load JPG	☒
57	12/12/17 10:07	Reinspection Photo		Load JPG	☒
58	12/12/17 10:07	Reinspection Photo		Load JPG	☒
59	12/12/17 10:07	Reinspection Photo		Load JPG	☒
60	12/12/17 10:07	Reinspection Photo		Load JPG	☒
61	12/12/17 10:07	Reinspection Photo		Load JPG	☒
62	12/12/17 10:07	Reinspection Photo		Load JPG	☒
63	12/12/17 10:07	Reinspection Photo		Load JPG	☒
64	12/12/17 10:07	Reinspection Photo		Load JPG	☒
65	12/12/17 10:07	Reinspection Photo		Load JPG	☒
66	12/12/17 10:07	Reinspection Photo		Load JPG	☒
67	12/12/17 10:07	Reinspection Photo		Load JPG	☒
68	12/12/17 10:07	Reinspection Photo		Load JPG	☒
69	12/12/17 10:07	Reinspection Photo		Load JPG	☒
70	12/12/17 10:07	Reinspection Photo		Load JPG	☒
71	12/12/17 10:07	Reinspection Photo		Load JPG	☒
72	12/12/17 10:07	Reinspection Photo		Load JPG	☒
73	12/12/17 10:07	Reinspection Photo		Load JPG	☒
74	12/12/17 10:07	Reinspection Photo		Load JPG	☒
75	12/12/17 10:07	Reinspection Photo		Load JPG	☒
76	12/12/17 10:07	Reinspection Photo		Load JPG	☒
77	12/12/17 10:07	Reinspection Photo		Load JPG	☒
78	12/12/17 10:07	Reinspection Photo		Load JPG	☒
79	12/12/17 10:07	Reinspection Photo		Load JPG	☒
80	12/12/17 10:07	Reinspection Photo		Load JPG	☒
81	12/12/17 10:07	Reinspection Photo		Load JPG	☒
82	12/12/17 10:07	Reinspection Photo		Load JPG	☒
83	12/12/17 10:07	Reinspection Photo		Load JPG	☒
84	12/12/17 10:07	Reinspection Photo		Load JPG	☒
85	12/12/17 10:07	Reinspection Photo		Load JPG	☒

86	12/12/17 10:07	Reinspection Photo		Load JPG	☒
87	12/12/17 10:07	Reinspection Photo		Load JPG	☒
88	12/12/17 10:07	Reinspection Photo		Load JPG	☒
89	12/12/17 10:07	Reinspection Photo		Load JPG	☒
90	12/12/17 10:07	Reinspection Photo		Load JPG	☒
91	12/12/17 10:07	Reinspection Photo		Load JPG	☒
92	12/12/17 10:42	Reinspection Photo		Load JPG	☒
93	12/12/17 10:42	Reinspection Photo		Load JPG	☒
94	12/12/17 10:42	Reinspection Photo		Load JPG	☒
95	12/12/17 10:42	Reinspection Photo		Load JPG	☒
96	12/12/17 10:42	Reinspection Photo		Load JPG	☒
97	12/12/17 10:42	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/11/17 15:21	Survey AGREE ON SJE, Appoint LKK as Surveyor		Load PDF	
2	13/11/17 15:23	Request Pre-Repair Inspection, SGE7037P GIA RPT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021619/ARBE2
Date: 22/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P28781114MKF
Claimant Vehicle No :	SGE7037P	Insured Vehicle No :	PA7765K
Date of Loss:	10/11/2017	Nature of Claim:	TP
		Claim No:	536389

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGE7037P	Engine No:	1ZZ2476989
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100287655
Reg. Date:	23/03/2006 (Man. Year: 2005)	Odometer:	293147 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	25,244.32	14,668.97	10,575.35	41.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,730.00	4,300.00	5,430.00	55.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,974.32	18,968.97	16,005.35	45.76
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	34,974.32	11,000.00	23,974.32	68.55
+ GST 7.00/7.00% (S\$)	2,448.20	770.00	1,678.20	68.55
Nett Amount (S\$)	37,422.52	11,770.00	25,652.52	68.55

INSPECTION

Date of Assignment: 13/11/2017
Date Inspected: 13/11/2017 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4., #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2017)	
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SGE7037P)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	510.00 FL	*510.00 FL
2	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	180.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP	Not Necessary	650.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	130.00 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	300.00 FL	*300.00 FL
7	1		*FRONT BUMPER SPONGE	Cracked	150.00 FL	*150.00 FL
8	1		*BONNET	Buckled	665.00 FL	*665.00 FL
9	1		*BONNET MOULDING	Not Necessary	205.00 FL	*- FL
10	1		*BONNET LOGO	Necessary	60.00 FL	*60.00 FL
11	1		*BONNET LOCK	Damaged	90.00 FL	*90.00 FL
12	1		*BONNET LOCK CABLE	Not Necessary	85.00 FL	*- FL
13	2		*BONNET STOPPER	Not Necessary	40.00 FL	*- FL
14	2		*BONNET HINGE	Not Necessary	60.00 FL	*- FL
15	1		*CENTRE GRILLE	Cracked	360.00 FL	*360.00 FL
16	2		*HEADLAMP	Cracked	2,140.00 FL	*2,140.00 FL
17	1		*FRONT SUPPORT PANEL	Buckled	890.00 FL	*890.00 FL
18	1		*FRONT BRACE PANEL	Bent	90.00 FL	*90.00 FL
19	2		*HORN	Not Necessary	170.00 FL	*- FL
20	1		*AIRCON CONDENSER	Bent	1,600.00 FL	*1,600.00 FL
21	2		*AIRCON PIPE	Not Necessary	920.00 FL	*- FL
22	1		*AIR GUARD GARNISH LH	Not Necessary	120.00 FL	*- FL
23	1		*RADIATOR	Bent	1,810.00 FL	*1,810.00 FL
24	4		*RADIATOR MOUNTING	Not Necessary	168.00 FL	*- FL
25	2		*RADIATOR BRACKET	Not Necessary	182.00 FL	*- FL
26	1		*RADIATOR FAN COWLING	Not Necessary	260.00 FL	*- FL
27	1		*REAR DOOR FRAME WEATHER STRIP LH	Not Necessary	165.00 FL	*- FL
28	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	160.00 FL	*- FL
29	1		*REAR DOOR INNER LOCK LH	Not Necessary	320.00 FL	*- FL
30	1		*TAILGATE	Dented	1,280.00 FL	*1,280.00 FL
31	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
32	1		*TAILGATE OUTER MOULDING	Cracked	240.00 FL	*240.00 FL
33	1		*TAILGATE WIPER HEAD RUBBER	Missing	90.00 FL	*90.00 FL
34	1		*TAILGATE WIPER ARM	Cut	195.00 FL	*195.00 FL
35	1		*TAILGATE WIPER BLADE	Not Necessary	85.00 FL	*- FL
36	1		*TAILGATE WIPER BOLT COVER	Missing	25.00 FL	*25.00 FL
37	1		*TAILGATE WIPER MOTOR	Not Necessary	745.00 FL	*- FL
38	1		*TAILGATE INNER LOCK	Damaged	445.10 FL	*445.10 FL
39	1		*TAILGATE LOWER LOCK	Not Necessary	35.00 FL	*- FL
40	1		*TAILGATE DAMPER	N/S Bent	388.00 FL	*194.00 FL
41	2		*TAILGATE STOPPER	Not Necessary	40.00 FL	*- FL
42	1		*TAILGATE WEATHER STRIP	Cut	320.00 FL	*320.00 FL
43	1		*TAILGATE INNER TRIM (TOP)	Not Necessary	285.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*TAILGATE INNER TRIM (TOP SIDE)	N/S Cut	390.00 FL	*195.00 FL
45	1		*TAILGATE INNER TRIM (LOWER)	Deformed	395.00 FL	*395.00 FL
46	1		*TAILGATE WINDSCREEN GLASS	Shattered	980.00 FL	*980.00 FL
47	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
48	1		*REAR BUMPER	Distorted	590.00 FL	*590.00 FL
49	1		*REAR BUMPER REFLECTOR	N/S Cut	136.00 FL	*68.00 FL
50	1		*REAR BUMPER BRACKET	N/S Dented	140.20 FL	*70.10 FL
51	2		*REAR BUMPER SIDE RETAINER	Necessary	120.00 FL	*120.00 FL
52	2		*TAILLAMP C/W BRACKET	N/S Cracked / O/S Cut	1,040.00 FL	*820.00 FL
53	1		*TAILLAMP INNER PANEL LH	Dented	890.00 FL	*420.00 FL
54	1		*REAR FENDER LH	Buckled	930.00 FL	*930.00 FL
55	2		*REAR FENDER INNER COWLING	Not Necessary	760.00 FL	*- FL
56	1		*REAR FENDER AIR VENT	Deformed	95.00 FL	*95.00 FL
57	1		*REAR FENDER INNER TRIM	N/S Cracked	1,476.20 FL	*738.10 FL
58	1		*REAR FENDER INNER BOTTOM PANEL LH	Repair	455.00 FL	*- FL
59	1		*REAR FENDER QUARTER GLASS C/W MOULDING LH	Necessary	490.00 FL	*150.00 FL
60	1		*FUEL TANK INLET PIPE	Not Necessary	295.00 FL	*- FL
61	1		*REAR END PANEL	Distorted	480.00 FL	*480.00 FL
62	1		*REAR END PANEL TOP GARNISH	Deformed	245.00 FL	*245.00 FL
63	2		*REAR END PANEL (EXTEND)	Repair	597.40 FL	*- FL
64	1		*REAR END PANEL BOTTOM (CENTRE)	Repair	311.10 FL	*- FL
65	1		*REAR FLOOR PANEL TOP BOARD (INNER SUPPORT)	Not Necessary	410.10 FL	*- FL
66	1		*REAR FLOOR PANEL	Repair	1,150.00 FL	*- FL
67	1		*REAR FLOOR PANEL TOP BOARD	Deformed	460.00 FL	*460.00 FL
68	1		*REAR FLOOR PANEL SIDE BOARD	Not Necessary	195.00 FL	*- FL
69	1		*FRONT NUMBER PLATE	Cut	50.00 FS	*50.00 FS
70	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
71	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
72	1		*SET CENTRE GRILLE CLIP	Necessary	30.00 FS	*10.00 FS
73	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
74	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
75	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
76	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*10.00 FS
77	1		*TAILLAMP INNER PANEL SEALANT LH	Not Necessary	80.00 FS	*- FS
78	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Not Necessary	60.00 FS	*- FS
79	1		*TAILGATE WINDSCREEN GLASS SOLER FILM	Necessary	350.00 FS	*200.00 FS
80	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
81	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
82	1		*REAR FENDER LH SEALANT	Not Necessary	80.00 FS	*- FS
83	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
84	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
85	1		*REAR FENDER QUARTER GLASS SEALANT LH	Necessary	60.00 FS	*20.00 FS
86	1		*REAR FENDER QUARTER GLASS INNER SEAL LH	Necessary	40.00 FS	*20.00 FS
87	1		*REAR FENDER QUARTER GLASS SOLAR FILM LH	Not Necessary	250.00 FS	*- FS
88	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
89	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
90	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
91	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS
92	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 32,739.10 19,295.30

- List Item Discount on L Items 25.00/25.00% (\$\$) 7,494.78 4,626.33

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						25,244.32 14,668.97
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,200.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	2,800.00	1,200.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,000.00
8	TUFF COAT	New	250.00	60.00
9	WIRING AND BULB CHECK	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	40.00
13	REAR CHASSIS ALIGNMENT	New	250.00	0.00
14	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
15	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
16	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
17	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
18	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	New	100.00	60.00
19	REMOVE AND REFIX PETROL TANK TO FACILITATE FENDER REPLACEMENT	New	100.00	80.00
20	VACUUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER	New	180.00	60.00
21	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			9,730.00	4,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >