

2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1000
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	40
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
13	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	60
14	REMOVE AND REFIX PETROL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	80
15	VACCUUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER	\$ 180.00	60
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 9,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$25,244.33
TOTAL LABOUR COST : \$9,730.00
TOTAL REPAIR COST : \$34,974.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

LKK Auto-Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 18968.97

Adrian Lj
1/5 13/11/17 H/S HK.

14 Days.