

22/03/2002

ASS. REC. BY:

REF:

CS/MS617021620 / Strb12

Special Instruction:

Surgeon:

Sebastian

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MS61

Date/Time: 13.11.2017 2:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 71447

Insured:

SLF 8423L

at Workshop m/s

World Auto

Tel:

9758 8347

of

No. 1 Kranji Loop

Policy No:

29011746QMY

Claim No:

535656

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05.11.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

13.11.2017 3:37pm

Person Contacted:

Mr. Sim

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 71447 - X

SLF 8423L - X

Submit preli through merimen

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG 7144T Yr Regn: 11/10/2016Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 78663 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GPT 1042095Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15 Giti.R: " Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mmL/Bal. 6 mmD.O.A. 5/11/2017 D.O.I. 13/11/2017Survey held at World AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Confirm \$4273.44, 4 days
Red: \$3975.20, 48%.

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 5305.44 4273.44)200
10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17021620/Srb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 13-11-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 8423L	Veh. Inspected	SLG 7144T	
Policy No.	29011746QMY	Coverage (\$)	0.00	
Claim No.	535656	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	13/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/11/2017	Inspection Date	13/11/2017	
Survey held at	1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main:	06 Nov 2017		13 Nov 2017 14:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

HO JIN XUN, ID: S8621184Z

Main Claimant:

LCRF Pte Ltd, Co. Reg. No.: 201624597K

Vehicle Reg. No.:

SLG7144T

Claim Type:

TP / 535656

Vehicle Reg. No. (Insured):

SLF8423L

Date of Loss:

05/11/2017 12:00 - :59

Policy/Cover Note No.:

29011746QMY (Comprehensive)
Coverage: 13/09/2017 - 12/09/2018

Policy No. (Claimant):

Excess:

Repairer:

World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/11/2017]

Driver/Custodian (Insured):

BRIAN CHIN CHEE KONG (), NRIC: S7901797C, Tel: +6598379084

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 24 Jan 2018

Preliminary Advice

Insured Vehicle No	: SLF8423L	Accident Date	: 05/11/2017
TP Vehicle No	: SLG7144T	Assignment Date	: 13/11/2017
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 4.00
Date of Inspection	: 13/11/2017		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,248.64
Revised Amount	:S\$	5,305.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,305.44

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2017 09:54
Date Of Accident	05/11/2017 11:50
Exact Location Of Accident	CTE (TOWARD ORCHARD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG7144T
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	LEE CHOY JIM RUDY
NRIC No	S6828877J
Date Of Birth	05/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	21/02/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: NO VIDEO TO SHOW
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF8423L
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLT8858S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number


Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/s/orsaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

CTE (towards Orchard)



Sketch Plan #2

Describe Circumstances of the Accident


Driving along CTE, towards CTE. Heavy traffic.
car in front braked suddenly. I braked too.
The car behind me braked as well. The car behind
him rammed into the car behind me who in turn
knocked into me.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time



Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005253

Date : 10/11/2017

Vehicle Num. : SLG 7144T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 05/11/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE (SHUTTLE) ✓ DT		1,850.00 1200
2.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC		88.40
3.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		88.40
4.	1	REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC		195.00
5.	1	REAR TAILGATE LOCK (SHUTTLE) ✓ JM		550.00 200
6.	1	REAR TAILGATE LOCK CATCH (SHUTTLE) ✗ X NN		158.00
7.	1	REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Defang		260.00
8.	1	REAR END PANEL (SHUTTLE) ✗ VBT		950.00 660
9.	1	REAR BUMPER (SHUTTLE) R		1,350.00
List TotalS\$:				5,489.80
20.00% Discount S\$:				1,097.96
				4,391.84
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT nec		160.00 40
2.	8	REAR END PANEL TOP GARNISH CLIPS (SHUTTLE) nec	9.80	78.40 30
3.	8	REAR BUMPER CLIP nec	9.80	78.40 30
4.	1	REVERSE SENSOR Dmg		260.00 200
Special Nett Total S\$:				576.80
LABOUR :				
TRANSFER TAILGATE MECHANISM (SHUTTLE)				160.00 60

CONTINUE / ...

4 days.

Sebastian.
13/11/2017.

- Part by part repair
- Photo Before Paint
90034121
sebastianyong@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES005253**

Date : 10/11/2017

Vehicle Num. : SLG 7144T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 05/11/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)		160.00 ¹²⁰
		To labour charge for removing rear tailgate, end panel rear bumper out to facilitate repairs and replacement of damaged parts		1,200.00 ⁶⁰⁰
		To respray rear tailgate , rear bumper, end panel		1,000.00 ⁶⁰⁰
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions		380.00 ²²⁰
		To conduct a standard of opearting procedure post repairs diagnostic scant test as a requirement for hybrid cars upon completion of collision repairs		380.00 ²²⁰
		Labour Total S\$:		3,280.00

E. & O.E.

Total S\$:

8,248.64

=====

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Attention : Motor Claim Department

Estimate : ES005253

Date : 10/11/2017
 Vehicle Num. : SLG 7144T (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 05/11/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
		REAR TAILGATE (SHUTTLE) ✓ DT		1,850.00 ✓ 1200
		REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC		88.40 ✓
		REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		88.40 ✓
		REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC		195.00 ✓
		REAR TAILGATE LOCK (SHUTTLE) ✓ 3m		550.00 ✓ 200
		REAR TAILGATE LOCK CATCH (SHUTTLE) ✓ X NN		158.00
		REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Defang		260.00 ✓
		REAR END PANEL (SHUTTLE) ✓ BT		260.00 ✓
		REAR BUMPER (SHUTTLE) R		1,350.00 ✓ 660
			2691.80	
			- 20 %	
			1) 2153.44	
		List Total S\$:		5,489.80
		20.00% Discount S\$:		1,097.96
				4,391.84
SPECIAL NETT ITEMS :				
		REAR WINDSCREEN SEALANT		160.00 40
		REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)		78.40 30
		REAR BUMPER CLIP		78.40 30
		REVERSE SENSOR		260.00 200
				576.80
		Special Nett Total S\$:		
		LABOUR :		160.00 60
		TRANSFER TAILGATE MECHANISM (SHUTTLE)		

CONTINUE / ...

4 days.
 Sebastian.
 13/11/2017.
 - Part by part repair
 - Photo Before Paint
 900 K12
 sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Before Paint Survey
 11.12

LD AUTO PTE LTD

mpin #01-02/03
ore 577200
3933 Fax No. : 6455 7576
aut@singnet.com.sg
w.worldauto.com.sg
: 200006765-H Buss. Reg. No. : 200006765H

ANCE (S) PTE LTD

Estimate : ES005253

for Claim Department

Date : 10/11/2017
Vehicle Num. : SLG 7144T (LCR)
Make/Model : HONDA SHUTTLE HYBRID
Chassis/Eng# :
Accident Date : 05/11/2017
Claim No. :
Reference :
Policy No. :

Particular	Unit Price	Amount S\$
REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)		160.00 120
To labour charge for removing rear tailgate, end panel rear bumper out to facilitate repairs and replacement of damaged parts		1,200.00 600
To respray rear tailgate , rear bumper, end panel		1,000.00 600
To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	3) 1820	380.00 220
To conduct a standard of opearting procedure post repairs diagnostic scant test as a requirement for hybrid cars upon completion of collision repairs		380.00 220
Labour Total S\$:		3,280.00

1) Parts : \$ 2153.44
2) S/Netr : \$ 300.00
3) Labour : \$ 1820.00
\$ 4273.44 @ 4 days.

E. & O.E. Total S\$: 8,248.64
=====

LD AUTO PTE LTD

Part 3981.50
Len 20% 796.30
3 185.44
SN- 300.00
Lab 1820.00
Net 5,303.44

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021620/SRBN2

Date: 25/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29011746QMY
Claimant Vehicle No :	SLG7144T	Insured Vehicle No :	SLF8423L
Date of Loss:	05/11/2017	Nature of Claim:	TP
		Claim No:	535656

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7144T	Engine No:	LEB4261717
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71042095
Reg. Date:	11/10/2016 (Man. Year: 2016)	Odometer:	78663 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,968.64	2,453.44	2,515.20	50.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,820.00	1,460.00	44.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,248.64	4,273.44	3,975.20	48.19
+ GST 7.00/7.00% (S\$)	577.40	299.14	278.26	48.19
Nett Amount (S\$)	8,826.04	4,572.58	4,253.46	48.19

INSPECTION

Date of Assignment:	13/11/2017	Inspected At:	World Auto Pte Ltd - Kranji (HQ)
Date Inspected:	13/11/2017		No 1 Kranji Loop
			Singapore 739535

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jan 2018)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7144T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE (SHUTTLE)	Dented	1,850.00 FL	*1,200.00 FL
2	1	*REAR TAILGATE HYBRID EMBLEM (SHUTTLE)	Necessary	88.40 FL	*88.40 FL
3	1	*REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE)	Necessary	88.40 FL	*88.40 FL
4	1	*REAR WINDSCREEN MOULDING (SHUTTLE)	Necessary	195.00 FL	*195.00 FL
5	1	*REAR TAILGATE LOCK (SHUTTLE)	Jammed	550.00 FL	*200.00 FL
6	1	*REAR TAILGATE LOCK CATCH (SHUTTLE)	Not Necessary	158.00 FL	*- FL
7	1	*REAR END PANEL TOP GARNISH (SHUTTLE)	Deformed	260.00 FL	*260.00 FL
8	1	*REAR END PANEL (SHUTTLE)	Bent	950.00 FL	*660.00 FL
9	1	*REAR BUMPER (SHUTTLE)	Repair	1,350.00 FL	*- FL
10	1	*REAR WINDSCREEN SEALANT	Necessary	160.00 FS	*40.00 FS
11	8	*REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)	Necessary	78.40 FS	*30.00 FS
12	8	*REAR BUMPER CLIP	Necessary	78.40 FS	*30.00 FS
13	1	*REVERSE SENSOR	Damaged	260.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,066.60	2,991.80
- List Item Discount on L Items 20.00/20.00% (S\$)	1,097.96	538.36
Total Parts (S\$)	4,968.64	2,453.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)	New	160.00	120.00
2	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE,END PANEL.REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	600.00
3	TO RESPRAY REAR TAILGATE,REAR BUMPER,END PANEL	New	1,000.00	600.00
4	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	380.00	220.00
5	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCANT TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	220.00
6	TRANSFER TAILGATE MECHANISM (SHUTTLE)	New	160.00	60.00
Gross Labour Cost (S\$)			3,280.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >