



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF3611T / 24/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001561
	Engine No	3A92UDG3297
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	10/11/2017/ 20:48		465 / Tay Jian Ye	16656		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER , REAR BOOTLID, WELD AND CUT END PANEL , REAR BOTH FENDER, REAR SPEAKER PANEL, REAR BOTH TAIL LAMP PANEL , REPAIR FLOOR PANEL, REAR BOTH WHEEL ACHE PANEL				✓ 4400			5500.00
E PNT88000 TO REMOVE AND REFIT REAR SEAT AND REAR BOOT TRIM TO FACILIATE REPAIR				✓ 200			200.00
E PNT88000 TO REMOVE AND REFIT FUEL TANK				✓ 180			200.00
E PNT88000 TO REMOVE AND REFIT REAR WINDSCREEN				✓ 200			200.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, BOOTLID, ENDPANEL, FLOOR PANEL, RR SPEAKER PANEL, REAR BOTH FENDER, REAR BOTH TAILLAMP PANEL				✓ 3360			4200.00
E PNT88000 TO RENEW FRT BUMPER AND FRT LH FENDER				✓ 1100			1650.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER , FRT LH FENDER				✓ 840			1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICALSYSTEM				✓ 20			50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200			200.00
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED PORTION				✓ 240			400.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION				✓ 80			150.00
M SUNDRY TO APPLY WINDSCREEN SEALANT				✓ 80			801.00
M SUNDRY TO SUPPLY C&C LOGO				30 new			50.00
M SUNDRY TO SUPPLY PARKING SENSOR				new			220.00
M SUNDRY				70 bt			60.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF3611T / 24/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001561
	Engine No	3A92UDG3297
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	10/11/2017/ 20:48		465 / Tay Jian Ye	16656			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO SUPPLY FRT NUMBER PLATE AND FRAME								
M SUNDRY						10323		50.00
SUNDRIES								
S SPECIALISTJOB						10273		82.00
W/ORDER NO: T139330 ACCIDENT TOWING FROM DAIRY FARM RD TO 209 PANDAN GARDEN								
M BRACKET,RR BUMPER,LH					1.00	27.00	00.00	27.00
M BRACKET,RR BUMPER,RH					1.00	27.00	00.00	27.00
M FACE,RR BUMPER					1.00	740.00	00.00	740.00
M CLIP,FR BUMPER					5.00	3.00	00.00	15.00
M DUCT,RR VENTILATOR					1.00	29.00	00.00	29.00
M COVER,RR VENTILATOR					1.00	38.00	00.00	38.00
M ANT,KEYLESS OPERATION,RR					1.00	91.00	00.00	91.00
M BUZZER,KEYLESS OPERATIO,RR					1.00	88.00	00.00	88.00
M PANEL,RR END					1.00	421.00	00.00	421.00
M TRIM,RR END					1.00	65.00	00.00	65.00
M BOARD,TRUNK ROOM FLOOR					1.00	193.00	00.00	193.00
M PANEL,TRUNK LID					1.00	865.00	00.00	865.00
M HINGE,TRUNK LID,LH					1.00	201.00	00.00	201.00
M HINGE,TRUNK LID,RH					1.00	201.00	00.00	201.00
M WEATHERSTRIP,TRUNK LID					1.00	155.00	00.00	155.00
M LATCH,TRUNK LID					1.00	216.00	00.00	216.00
M GARNISH,RR END PANEL					1.00	332.00	00.00	332.00
M LAMP ASSY,LICENSE PLATE					2.00	50.00	00.00	100.00
M MARK,ATTRAGE					1.00	21.00	00.00	21.00
M MARK,THREE-DIA					1.00	43.00	00.00	43.00
M PANEL,QTR,OTR LH					1.00	748.00	00.00	748.00
M EXTN,QTR PANEL,UPR OTR LH					1.00	117.00	00.00	117.00
P PANEL,RR COMB LAMP HSG,LH					1.00	60.00	00.00	60.00
M TRIM,TRUNK ROOM SIDE,LH					1.00	158.00	00.00	158.00
M LAMP ASSY,COMB,RR LH					1.00	332.00	00.00	332.00
M PANEL,QTR,OTR RH					1.00	756.00	00.00	756.00
M EXTN,QTR PANEL,UPR OTR RH					1.00	117.00	00.00	117.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF3611T / 24/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001561
	Engine No	3A92UDG3297
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	10/11/2017/ 20:48		465 / Tay Jian Ye	16656		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	PANEL,RR COMB LAMP HSG,RH			1.00	60.00	00.00	60.00 ✓
M	TRIM,TRUNK ROOM SIDE,RH			1.00	158.00	00.00	158.00 ✓
M	LAMP ASSY,COMB,RR RH			1.00	332.00	00.00	332.00 ✓
M	PANEL,RR SHELF			1.00	491.00	00.00	491.00 ✓
M	TRIM,RR SHELF			1.00	342.00	00.00	342.00 ✓
M	GLASS,RR WINDOW			1.00	537.00	00.00	537.00 ✓
M	STOPPER,WINDSHIELD GLASS			2.00	3.00	00.00	6.00 ✓
M	SPACER,RR WINDOW			3.00	9.00	00.00	27.00 ✓
M	FACE,FR BUMPER			1.00	696.00	00.00	696.00 ✓
M	REINFORCEMENT,FR BUMPER			1.00	136.00	00.00	136.00 ✓
M	HEADLAMP ASSY,LH			1.00	654.00	00.00	654.00 ✓
M	FENDER,FR LH			1.00	458.00	00.00	458.00 ✓
M	BACK ASSY,FR SEAT,RH			1.00	1999.00	00.00	1999.00 ✓

Estimate

SURVEYOR NAME: Tay Jian Ye 97495749SURVEYOR SIGNATURE: [Signature]DATE: 14/11/17 10:45REMARKS: WP Resurvey before paint
sur @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett 27,325.00
7% GST on 27325.00 1912.75
Total Payable 29,237.75

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.