



FINAL REPORT

Estimate No. : **b1 44783**  
Date Estimated : **09/11/2017**  
Prepared By : **Chua Kee Sin**

Page No. :

**REPAIR FOR -**  
**Soh Siew Ngoh**  
**62 Mei Hwan Drive**  
**#14-06**

**Singapore 568427**

**- ACCOUNT - 303**  
**First Capital Insurance Limited**  
**6 Raffles Quay**  
**#21-00**  
**Singapore 048580**

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SDX8999S	C866507	04/07/2011	523iA	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident			850.00		850.00
To spray paint rear bumper			934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.			150.00		150.00
Sundries.			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER GUIDE BOTTOM CENTRE	57.50	1.00		57.50
RR BUMPER PANEL PRIMED (PDC)	1,431.40	1.00		1,431.40

# SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,488.90
Total Labour & Parts :	3,502.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,502.90
GST @7%:	245.20
Grand Total :	3,748.10