

33063204

ASS: REP. BY

REF: CS/FCI17021651/Tmbn2

Special Instruction:

Surveyor:

Taufik.

ASSIGNMENT (Office)

CWS

From (Person):

Aug 1/12 Min.

of

FCI

Date/Time: 4:24pm @ 10-11-2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDX 8999S

Insured:

SHB 2254R

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

DI7010469MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

wpi

04-12-2017

EOD: Endorsement:

Date/Time:

4:38pm @ 10/11/17

Person Contacted:

Caroline

Vehicle-IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Chua.

SDX 8999S - x

SHB 2254R - NS / INC17012033 / m1ch3m2

DUA: 190617

5/12/17

Email preli revised to FCI

6/2/18

Final fig \$ 3502.90 confirmed by email (Ref 4206.55, 5490)


Signature: Taylin REF: FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SDX 8999S
 at Workshop m/s: Performance Motor
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDX 8999S Yr Regn: 2011 July
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW 523i o.c. 2447
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: 120504 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: B WS A FP 52000 C 86607
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: 6
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 9/11/17 D.O.I. 4/10/17 @ 4:25pm
 Survey held at: RML
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 FEB 2018

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time: File Return to?

6/2- typist

Report Format: CWS

Lump Sum / I.B.I: 3502.90

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐ Site Insp. \$
☐ Interview \$
☐ Tech. Invs \$
☐ Meet and \$

Survey Fee
 Transportation

Photos

Others

150
50
23
223



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021651/T1vb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2254R	Veh. Inspected	SDX 8999S
Policy No.		Coverage (\$)	0.00
Claim No.	D17010469MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/11/2017	Inspection Date	04/12/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010469MFSH
Our ref: CS/FC117021651/T1vb

Date: 5/12/2017

The Motor Claims Department
M/s First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SDX 8999S


We thank you for your instruction on 10/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/12/2017 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,709.45
Revised Estimate Amount	: S\$3,408.45
"Check" Items Amount	: S\$3,320.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No.: CS/FC17021651/Tivb
Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair				
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded				

Check By: VERON 6/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	10-11-2017	Our Ref No. D17010469MFSH
Accident Date	09-11-2017	Claim Type. Third Party
Insured Vehicle	SHB2254R	Third Party Vehicle. SDX8999S
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230049)



PRI Documents



Close



PRI Header Details

Claim No	D17010469MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEN Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2254R	TP Vehicle No	SDX8999S
PRI Recieved Date	10-11-2017 03:43:21 PM	Surveyor Appointed Date	10-11-2017 04:23:12 PM	Surveyor Accept Date	10-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 5 December, 2017 2:17 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010469MFSH/1, SDX 8999S
Attachments: SDX 8999S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SDX 8999S
Date of survey: 4/12/2017
Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 10 November, 2017 4:40 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010469MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 10 November, 2017 4:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010469MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

10 NOV 2017

Estimate No. : b1 44783
Date Estimated : 09/11/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Soh Siew Ngoh
62 Mei Hwan Drive
#14-06

Singapore 568427

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX8999S	C866507	04/07/2011	523ia	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

To replace rear PDC sensor wire harness including reset and checks for proper function.

Sundries.

	VALUE
✓ 850	1,700.00
✓ 934	1,038.00
✓ 150	177.00
nm x 226 ?	266.00
nm ✓ ?	80.00

Total Labour 1: 3,261.00

DESCRIPTION

SET MOUNTS PDC SENSOR REAR (PDC) ?
RR BUMPER GUIDE BOTTOM CENTRE ?
RR BUMPER CTR GUIDE ?
RR BUMPER CTR GUIDE ?
RR BUMPER CTR GUIDE ?
RR BUMPER LH MOUNT ?
RR BUMPER RH MOUNT ?
RR BUMPER CARRIER ?
RR BUMPER PANEL PRIMED (PDC) de ✓
RR BUMPER TOW HOOK COVER PRIMED ✓
LH PROTECTION FOIL ?
RH PROTECTION FOIL ?
PROTECTION FOIL L=55MM ?
PROTECTION FOIL L=55MM ?
RR BUMPER ADAPTER ?
TRIGGER CONTACT ?
DECOUPLING RING PDC TORQUE CONVERTE ✓
BUMPER PDC SENSOR (A72 KASCHMIRSILB) ?

QTY	PRIC	VALUE
1	62.50	62.50
1	57.50	57.50
1	65.75	65.75
1	65.75	65.75
1	65.75	65.75
1	141.65	141.65
1	141.65	141.65
1	696.80	696.80
1	1,431.40	1,431.40
1	23.25	23.25
1	15.15	15.15
1	15.15	15.15
2	4.65	9.30
2	4.65	9.30
1	46.80	46.80
1	128.75	128.75
4	4.95	19.80
4	363.05	1,452.20

Total Parts : 4,448.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44783
Date Estimated : 09/11/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX8999S	C866507	04/07/2011	523iA	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 4/12/12 4:25pm Excess \$ _____
Surveyor's Name Tanphie Sign Tanphie
Surveyor's Tel 97495749 Authorised Yes / No
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PM Yes / No
Surveyor's E-mail tanphie@lkk.com
No. of Working Days Recommend 3 days

[Handwritten signature]
4/12/12

7709.45

Labour 1	:	3,261.00
Parts	:	4,448.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	539.66
Grand Total	:	8,249.11

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44783
Date Estimated : 09/11/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Soh Siew Ngoh
62 Mei Hwan Drive
#14-06

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 568427

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDX8999S	C866507	04/07/2011	523iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER GUIDE BOTTOM CENTRE	57.50	1.00		57.50
RR BUMPER PANEL PRIMED (PDC)	1,431.40	1.00		1,431.40

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,488.90
Total Labour & Parts :	3,502.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,502.90
GST @7%:	245.20
Grand Total :	3,748.10

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 6 February 2018 3:38 PM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SDX89995

Dear Caroline,

Confirmed finalize amount \$3,502.90 before GST

Repair days: 3 days

Final invoice and all supporting documents sent to First Capital Ins Ltd.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]
Sent: Tuesday, 9 January 2018 5:21 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SDX89995

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,488.90
Total Labour & Parts : 3,502.90

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021651/T1vbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2254R	Veh. Inspected	SDX 8999S
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010469MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model	B.M.W 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32000C866507	Colour	GOLD
Odometer	120504	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	6 mm
L/H Front Tyre	225/55 R17	PIRELLI	6 mm
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/11/2017	Inspection Date	04/12/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 8999S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET MOUNTS PDC SENSOR REAR (PDC)(SN)	NOT NECESSARY	62.50	-
1	RR BUMPER GUIDE BOTTOM CENTRE (SN)	NECESSARY	57.50	57.50
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	65.75	-
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	65.75	-
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	65.75	-
1	RR BUMPER LH MOUNT (SN)	NOT NECESSARY	141.65	-
1	RR BUMPER RH MOUNT (SN)	NOT NECESSARY	141.65	-
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	696.80	-
1	RR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	1,431.40	1,431.40
1	RR BUMPER TOW HOOK COVER PRIMED (SN)	NOT NECESSARY	23.25	-
1	LH PROTECTION FOIL (SN)	NOT NECESSARY	15.15	-
1	RH PROTECTION FOIL (SN)	NOT NECESSARY	15.15	-
2	PROTECTION FOIL L-55MM (SN)	NOT NECESSARY	9.30	-
2	PROTECTION FOIL L-55MM (SN)	NOT NECESSARY	9.30	-
1	RR BUMPER ADAPTER (SN)	NOT NECESSARY	46.80	-
1	TRIGGER CONTACT (SN)	NOT NECESSARY	128.75	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	19.80	-
4	BUMPER PDC SENSOR (A72 KASCHMIRSILB)(SN)	NOT NECESSARY	1,452.20	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			4,528.45	1,568.90
LABOUR				
	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.		1,700.00	850.00
	SPRAY PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION.	NOT NECESSARY	266.00	-
			3,181.00	1,934.00
GRAND TOTAL			7,709.45	3,502.90

Report Ref No. CS/FCI17021651/T1vbn2



RECOMMENDED COST OF REPAIRS			3,502.90
-----------------------------	--	--	----------

Report Ref No. CS/FCI17021651/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.