

Source:

AMS REC BY:

REF: ES3/LPC1018108/M0132
3-1

Special Instruction:

Submitter

MO

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of Lonpac

Date/Time:

10-11-2017

Estimated Cost

Bill to

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 766C

Insured:

SJS 6868 E

at Workshop m/s:

Bak Heng Motor

Tel:

9788 8579

or 5032 # 01-291, AMK Ind Park 2, 569 535

Policy No:

Claim No:

17/17/17/VP05/020112

Sum Insured

Excess

Make of Veh:

(Client's Record)

DOA - 16/9/17

CA / REV / REP. / REV 24 HRS

wp!

R.O.D. Endorsement

Date/Time:

10:36 am

Person Contacted:

kelvin

Vehicle IN: OUT

Date/Time	Action/Instruction (X) Estimate
	SJJ 766C - X
	SJS 6868 E - X
	Disburse survey - 25/9/17
	R prev paint - 02/10/17
04/10/17	Submit PRS

06/12/17 Submit US 64650, 5 days (ced \$7150, 61%)

John

6/12/2017

RECEIVED 08 DEC 2017

no bill

Survey Department Check List (Case Handler)

Reference No.: C931PC170181081mjb
Policy Type: OD / TP / RES / TL / EVA

SJT 766C
Typist

Case Handler

Admin (Cat): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Mac.f.): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Chur 06/12/12

Case Handler

Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17018108/M1qb-1

300 BEACH ROAD
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 13-11-2017



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 6868E	Veh. Inspected	SJJ 766C
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020112	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/09/2017	Inspection Date	13/11/2017
Survey held at	BAK HENG MOTOR REPAIRING CO. BLOCK 5032 ANG MO KIO INDUSTRIAL PARK II, #01-291 SINGAPORE 569535		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 November, 2017 11:43 AM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: Our Ref: 17/17/17/VP05/020112 Accident involving SJS6868E & SJJ766C along Jurong Town Hall Rd towards AYE on 16/9/17
Attachments: 10112017113735.pdf, 10112017113801.pdf

Hi Nivitha

Attached are the TP survey report and photographs. (another set of photographs will be sent in a separate email)

Please let us have your surveyor's technical review report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 20 September, 2017 10:38 AM
To: ERIC WOO JUN KIAT; assignments@lkkauto.com
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: Our Ref: 17/17/17/VP05/020112 Accident involving SJS6868E & SJJ766C along Jurong Town Hall Rd towards AYE on 16/9/17

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]
Sent: Wednesday, 20 September, 2017 10:31 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 17/17/17/VP05/020112 Accident involving SJS6868E & SJJ766C along Jurong Town Hall Rd towards AYE on 16/9/17

Dear Catherine,

Kindly refer to our attachment.

Please proceed to appoint Ma Chin Fook to conduct a survey of the vehicle SJJ 766C on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to facilitate the claims process.
2. This Form must be completed by the Policyholder or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of important facts may allow the Insurers to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability or payment of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that subject of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report and will acknowledge that the report will be made available to interested parties.

ACCIDENT STATEMENT

Date Of Report: 18/09/2017 13:25
Date Of Accident: 16/09/2017 12:55
Exact Location Of Accident: JURONG TOWN HALL RD @ AYE INFRT OF GENTING HOTEL
Country/State of Loss: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SJJ766C
Insured/Policyholder
Name Of Registered Owner: TEO WEI HAO JEREMY
NRIC No: S8418458F
Email Address: JEZZA766@GMAIL.COM
Mobile Phone No: (LOCAL) +65-91163500
Alternative Phone No: OFFICE-91163500

Vehicle Particulars

Manufacturer: MERCEDES-BENZ
Model: E200-1.8 CGI (A)

Exact Purpose for which vehicle was being used at time of accident: SELF USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken: THIRD PARTY

Vehicle Category: PRIVATE CAR

Insurance Company

Name of Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) LTD
Type Of Coverage: COMPREHENSIVE
Fleet Policy: NO
Policy Number: DMPCSN3005251700
Cover Note Number: 1101/2017 - 10/01/2018

Driver

Name of Driver: TEO WEI HAO JEREMY
NRIC No: S8418458F
Date Of Birth: 21/06/1984
Occupation: INDOOR
Date Of Driving Pass: 31/12/2002
Driving Experience: 14 YEARS AND 8 MONTHS
Gender: MALE
Mobile Number: (LOCAL) +65-91163500
Fax Number:
Contact Number: OFFICE-91163500
Email Address: JEZZA766@GMAIL.COM

Address 80 CHESTNUT AVE #07-43
 Postcode 679517
 Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured? OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown persons soliciting/offering accident claims assistance? NO
 Number of Passengers (including Driver) 4

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

WAS HEAD STRAIGHT TOWARDS AYE ON JURONG TOWN HALL ROAD. THIRD PARTY CAR SJ6888E HIT MY VEHICLE SJ758C WHILE I AM STATIONARY AS TRAFFIC LIGHT IS RED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by car camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJ6888E
 Vehicle Make/Model/Colour KIA CERATO FORTE
 Details Of Properties
 Name of Driver SOON TEIK LAM
 NRIC/Passport Number
 Contact Number 97564381
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

VEHICLE NO.

INSURER

DATE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation is a breach of material facts that allow insurance companies to reassess policy validity.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy validity on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GAA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, the workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or disclosed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurer(s) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers") the Insurers' lawyers/claim forms, the Monetary Authority of Singapore and any roles and government agencies (including, but not limited to, the police) if:
(i) processing, handling and/or dealing with the claims including the settlement of the claims in order to ascertain investigations relating to the claims;
(ii) investigating the accident and/or the claim;
(iii) carrying out and/or dealing with the claims in order to respond to any enquiries in the;
(iv) administering the claims, including the filing of correspondence, statements, invoices, receipts or copies of the claim form to make disclosure of certain personal data about the claim about delivery of the same, as well as on the external cover of any correspondence received; and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with the claims.
collectively the Purpose(s).
- (b) all insurers who have insured vehicles involved in this accident and the Insurers' lawyers/claim forms, the Monetary Authority of Singapore may be permitted to collect, use, disclose and/or process the Personal Information for one or more of the above Purpose(s) and;
- (c) the Personal Information may also be disclosed by any of the Insurers and/or GIA to third party service providers or agents (including their lawyers/claim forms) which may be used outside of Singapore, for one or more of the above Purpose(s).

Policyholder's Signature (Date & Time)

Driver's Signature (If driver is not the policyholder) (Date & Time)

Witnessed by Reporting Centre's Personnel

Sketch Plan

Sketch Plan #2

Describe Circumstances of the Accident

1. Date: 11/20/2011
 2. Time: 10:00 AM
 3. Location: 1000 1st Ave, 1st Floor, 1st Floor
 4. Vehicle: 2008 Honda Civic
 5. Driver: [Signature]
 6. Witness: [Signature]
 7. Description of Accident: [Handwritten description of the accident involving a car hitting a person]
 8. Name of Person: [Handwritten name]
 9. Address: [Handwritten address]
 10. City: [Handwritten city]
 11. State: [Handwritten state]
 12. Zip: [Handwritten zip]
 13. Phone: [Handwritten phone number]
 14. Email: [Handwritten email address]
 15. Other: [Handwritten notes]

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own policy. Please check with your policy for more information.
 We declare the foregoing particulars are true in every respect.

Policyholder's Signature: [Signature]
 Date: [Date]
 Time: [Time]

Driver's Signature (if driver is not the policyholder): [Signature]
 Date: [Date]
 Time: [Time]

Witnessed by Reporting Centre
 Personnel
 Reporting Only

☐ Claim Own Policy
☐ Claim Third Party
☐ Claim OD (TP at other workshop)

CARLINK CONSULTANCY


60 Hillside Drive
Singapore 549009

Tel : 62856178

Fax : 62874788

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

Our Ref: CL 11941 SJJ 766 C

1 REFERENCE			
Date of request	:	25th September 2017	
Requested by	:	Teo Wei Hao Jeremy C/o Blk 5032 Ang Mo Kio Industrial Park 2, #01-291, Se 569535	
Type of claim	:	Third party	
Workshop	:	M/S Bak Heng Motor Repairing Co Blk 5032 Ang Mo Kio Industrial Park 2, #01-291 Singapore 569535	
Date of survey	:	25th September 2017	
Accident date	:	16th September 2017	
2 DETAILS OF VEHICLE			
Registration No.	:	SJJ 766 C	
Make & Model	:	Mercedes Benz E200CGI	
Date of registration	:	30th December 2010	
Engine No.	:	271860-30167432	
Chassis No.	:	WDD2120482A360408	
Speedometer reading	:	61457 Km	
Transmission	:	Automatic	
Colour	:	Grey	
3 STATIC CHECK			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
4 TYRE CONDITION			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Michelin	6mm/Michelin : 245/45 R17
Rear tyre	:	6mm/Michelin	6mm/Michelin : 245/45 R17
5 POINT OF IMPACT			
See Annex(es) and Motor Accident Reports			
6 REMARK			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Annex A : Assesement / Adjustment on Spare Parts

SJJ 766 C

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
List Items							
1	Rear bumper fascia	Dented/cut/deformed	1	\$1,500.00	10%	\$1,350.00	✓
2	Rear bumper side retainer	Necessary	2	\$70.00	10%	\$63.00	✓
3	Rear bumper attachment	Necessary	2	\$130.00	10%	\$117.00	✓
4	Rear bumper center retainer	Necessary	1	\$85.00	10%	\$76.50	✓
5	Rear bumper chrome (center)	Grazed/dented/bent	1	\$198.00	10%	\$178.20	✓
6	Rear bumper chrome (side)	Slack/bent/distorted	2	\$280.00	10%	\$252.00	✓
7	Rear bumper reinforcement	Dented/bent	1	\$720.00	10%	\$648.00	✓
8	Rear bumper lower spoiler	Distorted/dented/cut	1	\$485.00	10%	\$436.50	✓
9	Rear bumper tow cover	Slack	1	\$75.00	10%	\$67.50	X SVC
10	Rear bumper clips	Necessary	10	\$100.00	10%	\$90.00	✓
11	Rear bumper parking sensor	Slack/distorted/cut	4	\$1,160.00	10%	\$1,044.00	✓
12	Rear bumper parking sensor wire	Cut	1	\$180.00	10%	\$162.00	X SVC
13	Rear bumper lower bracket	Bent	2	\$30.00	10%	\$27.00	✓
14	Tail lamp L/R	Grazed/cut	2	\$1,922.00	10%	\$1,729.80	X SVC
15	Tail lamp clips L/R	Necessary	4	\$40.00	10%	\$36.00	X nn
16	Tail lamp sealant	Necessary	2	\$80.00	10%	\$72.00	X nn
17	Boot lid	Grazed/warped/dented	1	\$2,310.00	10%	\$2,079.00	X R
18	Boot lid lock	Distorted/jammed	1	\$360.00	10%	\$324.00	X SVC
19	Boot lid lock striker	Bent	1	\$18.00	10%	\$16.20	X SVC
20	Boot lid badge	Necessary	1	\$45.00	10%	\$40.50	✓
21	Boot lid E200	Necessary	1	\$68.00	10%	\$61.20	✓
22	Boot lid CGI emblem	Necessary	1	\$51.00	10%	\$45.90	✓
23	Rear end panel	Repair	1	\$1,133.00	100%	\$0.00	
24	Rear end panel top trim	Bent/cut	1	\$115.00	10%	\$103.50	X SVC
25	Rear end panel top trim clips	Necessary	4	\$16.00	10%	\$14.40	X nn
26	Exhaust silencer chrome pipe	Slack/dented	1	\$180.00	10%	\$162.00	X SVC
27	Exhaust silencer rubber mounting	Shifted/cut	1	\$46.00	10%	\$41.40	X SVC
28	Exhaust silencer front mounting bracket	Bent	1	\$198.00	10%	\$178.20	X SVC
29	Exhaust silencer side heat shield	Dented/bent	1	\$201.00	10%	\$180.90	X SVC
30	Rear boot undercarriage splash shield	Grazed/distorted/cut	1	\$512.00	10%	\$460.80	X SVC
31	Rear boot undercarriage splash shield clips	Necessary	6	\$12.00	10%	\$10.80	X nn
S/Nett Items							
32	Boot compartment water proof sealer	Necessary	1	\$150.00		\$150.00	X nn

Total for Spare Parts : \$12,470.00 \$10,218.30

Annex B : Adjustment on Labour and Spray Painting

SJJ 766 C

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	Anti rust treatment	\$150.00	\$100.00 40
2	To check wiring system and light	\$100.00	\$80.00 ✓
3	To remove & refix interior upholstery	\$180.00	\$100.00 ✓
4	To reset electrical module system	\$480.00	\$350.00 X
5	To remove/replace exhaust silencer chrome pipe, exhaust rubber mounting, exhaust silencer front mounting bracket and check, straighten, align exhaust silencer and centre pipe to rectify rattling sound	\$400.00	\$300.00 X
6	To remove/replace parking sensor & parking sensor wire	\$150.00	\$100.00 ✓
7	To putty and respray paint on affected area	\$1,500.00	\$1,250.00 500
8	To remove damaged and necessary parts and attachments; knock, jack, cut, weld, reshape and align all affected portions. Reinstall all undamaged parts and necessary new parts into original positions.	\$1,600.00	\$1,400.00 600
TOTAL FOR LABOUR & SPRAY PAINTING :		\$4,560.00	\$3,680.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$12,470.00	\$10,218.30
TOTAL FOR LABOUR & SPRAY PAINTING :	\$4,560.00	\$3,680.00
TOTAL REPAIR COSTS :	<u>\$17,030.00</u>	<u>\$13,898.30</u>

Swdays

CARLINK CONSULTANCY

SJJ 766 C

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Bak Heng Motor Repairing Co estimated repair cost is **S\$17,030.00** and we have adjusted it to **S\$13,898.30** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$11,800.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,
CARLINK CONSULTANCY


RATHNONG
Automotive Engineer Assessor
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17018108/M1qbs2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 08-12-2017



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 6868E	Veh. Inspected	SJJ 766C
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020112	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2120482A360408	Colour	GREY
Odometer	61457	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45R17	MICHELIN	8 mm
L/H Front Tyre	245/45R17	MICHELIN	8 mm
R/H Rear Tyre	245/45R17	PIRELLI	8 mm
L/H Rear Tyre	245/45R17	PIRELLI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2017	Inspection Date	25/09/2017
Survey held at	BAK HENG MOTOR REPAIRING CO. BLOCK 5032 ANG MO KIO INDUSTRIAL PARK II, #01-291 SINGAPORE 569535		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 766C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA	DENTED / CUT / DEFORMED	1,500.00	1,500.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	70.00	70.00
2	REAR BUMPER ATTACHMENT	NECESSARY	130.00	130.00
1	REAR BUMPER CENTER RETAINER	NECESSARY	85.00	85.00
1	REAR BUMPER CHROME (CENTER)	GRAZED / DENTED / BENT	198.00	198.00
2	REAR BUMPER CHROME (SIDE)	SLACK / BENT / DISTORTED	280.00	280.00
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	720.00	720.00
1	REAR BUMPER LOWER SPOILER	DISTORTED / DENTED / CUT	485.00	485.00
1	REAR BUMPER TOW COVER	SERVICEABLE	75.00	-
10	REAR BUMPER CLIPS	NECESSARY	100.00	100.00
4	REAR BUMPER PARKING SENSOR	SLACK / DISTORTED / CUT	1,160.00	1,160.00
1	REAR BUMPER PARKING SENSOR WIRE	SERVICEABLE	180.00	-
2	REAR BUMPER LOWER BRACKET	BENT	30.00	30.00
2	TAIL LAMP L/R	SERVICEABLE	1,922.00	-
4	TAIL LAMP CLIPS L/R	NOT NECESSARY	40.00	-
2	TAIL LAMP SEALANT	NOT NECESSARY	80.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	2,310.00	-
1	BOOT LID LOCK	SERVICEABLE	360.00	-
1	BOOT LID LOCK STRIKER	SERVICEABLE	18.00	-
1	BOOT LID BADGE	NECESSARY	45.00	45.00
1	BOOT LID E200	NECESSARY	68.00	68.00
1	BOOT LID CGI EMBLEM	NECESSARY	51.00	51.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,133.00	-
1	REAR END PANEL TOP TRIM	SERVICEABLE	115.00	-
4	REAR END PANEL TOP TRIM CLIPS	NOT NECESSARY	16.00	-
1	EXHAUST SILENCER CHROME PIPE	SERVICEABLE	180.00	-
1	EXHAUST SILENCER RUBBER MOUNTING	SERVICEABLE	46.00	-
1	EXHAUST SILENCER FRONT MOUNTING BRACKET	SERVICEABLE	198.00	-
1	EXHAUST SILENCER SIDE HEAT SHIELD	SERVICEABLE	201.00	-

Report Ref No. CS3/LPC17018108/M1qbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT UNDERCARRIAGE SPLASH SHIELD	SERVICEABLE	512.00	-
6	REAR BOOT UNDERCARRIAGE SPLASH SHIELD CLIPS	NOT NECESSARY	12.00	-
	LESS 10% DISCOUNT		-	-492.20
			12,320.00	4,429.80
	SPECIAL NETT ITEMS			
1	BOOT COMPARTMENT WATER PROOF SEALER (SN)	NOT NECESSARY	150.00	-
			150.00	-
	LABOUR			
	ANTI RUST TREATMENT.		150.00	40.00
	TO CHECK WIRING SYSTEM AND LIGHT.		100.00	80.00
	REMOVE & REFIX INTERIOR UPHOLSETRY.		180.00	100.00
	TO RESET ELECTRICAL MODULE SYSTEM.	NOT NECESSARY	480.00	-
	TO REMOVE / REPLACE EXHAUST SILENCER CHROME PIPE, EXHAUST RUBBER MOUNTING, EXHAUST SILENCER FRONT MOUNTING BRACKET AND CHECK, STRAIGHTEN, ALIGN EXHAUST SILENCER AND CENTRE PIPE TO RECTIFY RATTILING SOUND.	NOT NECESSARY	400.00	-
	TO REMOVE / REPLACE PARKING SENSOR & PARKING SENSOR WIRE.		150.00	100.00
	TO PUTTY AND RESPRAY PAINT ON AFFECTED AREA.		1,500.00	500.00
	TO REMOVE DAMAGED AND NECESSARY PARTS AND ATTACHMENTS; KNOCK, JACK, CUT, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS. REINSTALL ALL UNDAAGED PARTS AND NECESSARY NEW PARTS INTO ORIGINAL POSITIONS. INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR END PANEL.		1,600.00	600.00
			4,560.00	1,420.00
	GRAND TOTAL		17,030.00	5,849.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00

Report Ref No. CS3/LPC17018108/M1qbs2-1

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.