

ASS. REC. BY

REF CS3/LPC17019126/Wvb-1⁰²

SUBJECT

Wilson

ASSIGNMENT (Office)

From (Person)

Dng L4

LPC

Date/Time

10.11.2017

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJB 3809 K

Insured

SJQ 4843 A

at Workshop info

Lush Automotive

Tel

97966979

of No. 8 Kaki Bukit Avenue 4, #03-17 Premier, KB 415875

Policy No

Claim No 17/17/17 / VP05/020136

Sum Insured

Excess

Make of Veh

(Client's Record)

DOA 2/10/17

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

5/10/17 11:56am

Person Contacted

Mr. Max

Vehicle (IN) OUT

Date/Time

Action/Inspection (X) Estimate

SJB 3809 K - NA / INC17018473 / NA - DOA 2/10/17

SJQ 4843 A - NA / INC17018473 / NA - DOA 2/10/17

Dismantle : 6/10/17

After paint: 11/10/17

16/10/17 Submit PRS report

Paper survey report reviewed.

Adjustment aligned
to photos provided
and damage on
Vehicle

16/11/2017.

16/11/17 Submit LS \$ 3800, 6 days (Red 450, 1050)

16/11/17

RECEIVED 17 NOV 2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC17019126/Wvb-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 13-11-2017	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJQ 4843A	Veh. Inspected	SJB 3809K
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020136	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/10/2017	Inspection Date	13/11/2017
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 November, 2017 11:27 AM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG; 'SUR'
Subject: RE: Our Ref: 17/17/17/VP05/020136 Accident involving SJQ4843A & SJB3809K along Punggol East on 2/10/17
Attachments: 10112017112122.pdf; 10112017112140.pdf

Hi Nivitha

Attached are the TP survey report and photographs.

Please let us have your surveyor's comment.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 5 October, 2017 12:03 PM
To: ERIC WOO JUN KIAT; assignments@lkkauto.com
Cc: MT_Claim_SG; 'SUR'
Subject: RE: Our Ref: 17/17/17/VP05/020136 Accident involving SJQ4843A & SJB3809K along Punggol East on 2/10/17

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]
Sent: Thursday, 5 October, 2017 10:54 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 17/17/17/VP05/020136 Accident involving SJQ4843A & SJB3809K along Punggol East on 2/10/17

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SJQ 4843A on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/10/2017 17:50
Date Of Accident 02/10/2017 22:05
Exact Location Of Accident SENGKANG EAST SLIP RD INTO PUNGGOL FIELD
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJB3809K
Insured/Policyholder
Name Of Registered Owner CARZONRENT PTE LTD
Co Reg No 201605659R
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-91816096
Vehicle Particulars
Manufacturer TOYOTA
Model AXIO
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5091787071
Cover Note Number -
Driver
Name of Driver YAP GUAN LEONG (YE YUANLONG)
NRIC No S7248610B
Date Of Birth 25/12/1972
Occupation INDOOR
Date Of Driving Pass 04/06/1996
Driving Experience 21 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91816096
Fax Number
Contact Number
Email Address JASONYAPCAR@GMAIL.COM

Address BLK 103A EDGEFIELD PLAINS #12-99
Postcode 821103
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - DIRECTOR
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance? NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJQ4843A
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name YAP GUAN LEONG (YE YUANLONG)
Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

NECK & SHOULDER

SJB3809K

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

PUNGOL FIELD



A = SJB3809K
B = SJQ4843A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG SENKANG EAST ROAD TURNING LEFT TOWARDS PUNGOL FIELD AND STOPPED AT THE GIVE WAY SIGN AS THERE WAS ONCOMING TRAFFIC AND CAR B COLLIDED FROM MY BACK.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Insured	-
Policy No.	-
Sum Insured	-
Excess	-
Our Reference	KAAS/TA/4773/3809/TP/10.17
Date	12 October 2017

To: Carzonrent Pte Ltd
c/o 8 Kaki Bukit Ave 4
#03-47, Premier @ Kaki Bukit
Singapore 415875

VEHICLE APPRAISAL REPORT

Name of Workshop	: Lush Automotive Pte Ltd
Place of inspection	: 8 Kaki Bukit Ave 4 #03-47, Premier @ Kaki Bukit, Singapore 415875
Date of Assignment	: 05 October 2017
Date of Accident	: 02 October 2017
Date of Inspection	: 05 October 2017

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SJB 3809K	Engine No.	: Hidden From View
Make/Model	: Toyota Axio 1.5X (A)	Chassis Frame No.	: NZE141-6063975
Year of Manufacture/Reg	: 2008	Colour	: Gold
Class/Type	: Saloon	Odometer Reading	: 96,177 KM

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition	: Good	Undercarriage (Front)	: Serviceable
Paintwork	: Good	Undercarriage (Rear)	: Serviceable
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front Left	DUNLOP 205 / 60 R15	7mm
Rear Left	DUNLOP 205 / 60 R15	7mm
Front Right	DUNLOP 205 / 60 R15	7mm
Rear Right	DUNLOP 205 / 60 R15	7mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	Rear bumper ✓ CRA	Broken	\$ 876.00	\$ 876.00
2	2 pcs	Rear bumper side retainer @S\$37.00 ✓ NEC	Necessary	\$ 74.00	\$ 74.00
3	2 pcs	Rear bumper side support @S\$32.00 ✓ NEC	Necessary	\$ 64.00	\$ 64.00
4	1 pc	Rear bumper lh bracket ✓ DD	Buckled	\$ 60.00	\$ 60.00
5	1 pc	Rear bumper lh splash shield ✓ DD	Deformed	\$ 79.00	\$ 79.00
6	1 set	Rear bumper fasteners ✓ NEC	Necessary	\$ 35.00	\$ 35.00
7	1 pc	Bootlid ✓ DD	Buckled	\$ 642.00	\$ 642.00
8	1 pc	Bootlid inner lock X R	Shifted	\$ 92.00	Realign
9	1 pc	Bootlid logo emblem ✓ NEC	Necessary	\$ 54.00	\$ 54.00
10	1 pc	Bootlid "x" emblem ✓ NEC	Necessary	\$ 31.00	\$ 31.00
11	1 pc	Bootlid "axio" emblem ✓ NEC	Necessary	\$ 52.00	\$ 52.00
12	1 pc	Bootlid weatherstrip ✓ NEC	Deformed	\$ 182.00	\$ 182.00
13	2 pcs	Taillamp assy @S\$332.00 ✓ CRA/Deformed	Cracked	\$ 664.00	\$ 664.00
14	2 set	Taillamp fasteners @S\$16.00 ✓ NEC	Necessary	\$ 32.00	\$ 32.00
15	1 pc	Rear end panel ✓ DD	Buckled	\$ 582.00	\$ 582.00
16	1 pc	Rear end panel top garnish ✓ CRA	Deformed	\$ 231.00	\$ 231.00
17	1 set	Rear end panel top garnish fasteners ✓ NEC	Necessary	\$ 24.00	\$ 24.00
18	1 pc	Spare tyre panel X R	Buckled	\$ 659.00	Repair
Less 25%				\$ 4,433.00	\$ 3,682.00
					\$ 920.50
				\$ 4,433.00	\$ 2,761.50
SPECIAL NETT ITEMS:-					
19	1 set	Reverse sensor	Broken	\$ 300.00	\$ 250.00
20	1 tube	Rear end panel sealant ✓ NEC	Necessary	\$ 60.00	\$ 40.00
				\$ 360.00	\$ 290.00
Sub - Total				\$ 4,793.00	\$ 3,051.50

APPRAISEMENT SCHEDULE



S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 4,793.00	\$ 3,051.50
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,040.00	\$ 960.00 800
2		To check wiring and rewire		\$ 60.00	\$ 50.00 30
3		To remove and reinstall bootlid components		\$ 80.00	\$ 60.00 ✓
4		To remove and reinstall rear boot upholstery		\$ 120.00	\$ 100.00 60
5		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00 60
6		To anti-rust		\$ 140.00	\$ 120.00 80
7		To putty and spray-paint of affected areas		\$ 960.00	\$ 880.00 800
				\$ 2,540.00	\$ 2,270.00
		Parts (list)		\$ 3456.00	
		Discount 25%		\$ 864.00	
		Parts (Special Net)		\$ 2592.00	
				\$ 240.00	
		Labour		\$ 2832.00	
				\$ 1890.00	
				\$ 4722.00	
		Discount 20% (hump sum)		\$ 944.40	
				\$ 3777.60	
		*hump sum → \$3800			
		*Repair Days → 6-Days			
		Sub - Total		\$ 7,333.00	\$ 5,321.50

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered

Squarely to the Rear

portion of the vehicle.



The general area of damages is at the
(Please refer to the parts list and photographs as attached for more information)

Rear portion

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Lush Automotive Pte Ltd** is \$ 7,333.00 .
We have adjusted the cost to \$ 5,321.50 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 4,250.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **6** working days.

58 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **4773** for our services rendered and
we thank you for engaging our services.

Kelvin Automotive Appraising Services



KELVIN TEO

Licensed Automotive Appraiser

Nitec in Automotive Technology

Dip MS

MSAAA

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC17019126/Wvbe2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 22-11-2017	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 4843A	Veh. Inspected	SJB 3809K	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020136	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	10/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416063975	Colour	SILVER	
Odometer	96177	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R15	DUNLOP	4 mm	
L/H Front Tyre	205/60 R15	DUNLOP	4 mm	
R/H Rear Tyre	195/60 R15	FIREMAX	4 mm	
L/H Rear Tyre	195/60 R15	FIREMAX	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2017	Inspection Date	05/10/2017	
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 3809K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	876.00	650.00
2	REAR BUMPER SIDE RETAINER @\$37.00	NECESSARY	74.00	74.00
2	REAR BUMPER SIDE SUPPORT @\$32.00	NECESSARY	64.00	64.00
1	REAR BUMPER LH BRACKET	DENTED	60.00	60.00
1	REAR BUMPER LH SPLASH SHIELD	DISTORTED	79.00	79.00
1	SET REAR BUMPER FASTENERS	NECESSARY	35.00	35.00
1	BOOTLID	DENTED	642.00	642.00
1	BOOTLID INNER LOCK	TO REPAIR SEE LABOUR	92.00	-
1	BOOTLID LOGO EMBLEM	NECESSARY	54.00	54.00
1	BOOTLID "X" EMBLEM	NECESSARY	31.00	31.00
1	BOOTLID "AXIO" EMBLEM	NECESSARY	52.00	52.00
1	BOOTLID WEATHERSTRIP	NECESSARY	182.00	182.00
2	TAILLAMP ASSY @\$332.00	CRACKED / DEFORMED	664.00	664.00
2	SET TAILLAMP FASTENERS @\$16.00	NECESSARY	32.00	32.00
1	REAR END PANEL	DENTED	582.00	582.00
1	REAR END PANEL TOP GARNISH	CRACKED	231.00	231.00
1	SET REAR END PANEL TOP GARNISH FASTENERS	NECESSARY	24.00	24.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	659.00	-
	LESS 25% DISCOUNT		-	-864.00
			4,433.00	2,592.00
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	BROKEN	300.00	200.00
1	TUBE REAR END PANEL SEALANT (SN)	NECESSARY	60.00	40.00
			360.00	240.00
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID INNER LOCK AND SPARE TYRE PANEL.		1,040.00	800.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL BOOTLID COMPONENTS.		80.00	60.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		120.00	60.00
	TO REMOVE AND REINSTALL REVERSE SENSOR.		140.00	60.00
	TO ANTI-RUST.		140.00	80.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		960.00	800.00
			2,540.00	1,890.00
GRAND TOTAL			7,333.00	4,722.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS3/LPC17019126/Wvbe2-1

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.