

REF: NS/INC17021702 / Srb02

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBA 6683D

Policy No. 5094 850642 11-10-17 - 10-10-18

Claims No. MT/0969224 - 002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 7574.

Yr Regn: 4/2/2015.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

c.c 1798

Colour Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading 500586

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN364805757706.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/11/2017.

D.O.I. 13/11/2017.

Survey held at SMART.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHB 7574 - 03 / 2017 12 353 / Klybs

DIB: JIC 17

TAX/11/17/2017

GBA 6683D - x

Lkr.

NTUC.

Confirmed L/s \$3300, 5 days
Red: \$5533.60, 63%.

RECEIVED 10 JAN 2017

Date/Time, File Pass to?

☐ : Preli. Report

1) typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Report Format: 7P

Lump Sum / H.B.I: (\$ 3300)

Add Fee: ☐ : Site Insp (\$) \$ + RS. \$☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

TOTAL

160

35

195

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0975034-002	COMFORT TRANSPORTATION	SHC 8925T	SIL 9498G	23/12/2017	\$ 3,546.44	\$ 1,615.56
2	MT/0977201-001	COMFORT TRANSPORTATION	SHA 7354H	SGS 4292P	22/12/2017	\$ 2,411.58	\$ 850.00
3	MT/0969224-002	SMRT TAXIS P/L	SHB 757U	GBG 6683D	09/11/2017	\$ 8,833.60	\$ 3,300.00
4	MT/0973642-002	SMRT TAXIS P/L	SHB 5004B	SKC 8591L	13/12/2017	\$ 2,398.00	\$ 638.57
5	MT/0972983-002	SMRT TAXIS P/L	SHB 5494U	SJS 2558B	08/12/2017	\$ 8,366.69	\$ 3,000.00
6	MT/0973821-002	SMRT TAXIS P/L	SHC 4587L	SJQ 2153X	14/12/2017	\$ 10,479.40	\$ 3,100.00

Claim received from LKK Auto



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO. OPERATIVE LTD Ref: NS/INC17021702/Srb

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE SINGAPORE 189556 Date: 14-11-2017



Code: INC4

1.

by Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 668
Policy No.	50948506
Claim No.	
Assign From	

Veh. Inspected	SHB 757U
Coverage (\$)	0.00
Excess (\$)	0.00
Assign Date	13/11/2017

2.

Vehicle Particulars & Condition

Make & Model	
Engine No.	HIDDEN
Chassis No.	
Odometer	-
Brakes	
General	

c.c	0
Year of Reg.	
Colour	
Steering	
Modification	

3.

Conditions of Tyres

	Size
R/H Front Tyre	
L/H Front Tyre	
R/H Rear Tyre	
L/H Rear Tyre	

Make	Balance
	mm
	mm
	mm
	mm

4.

Description of Damages

5.

General Information

Accident Date	09/11/20
Survey held at	SMRT A 60 WOC

Inspection Date 13/11/2017

OTIVE SERVICES PTE LTD

DS INDUSTRIAL P... E4 SINGAPORE 757705

5a.

Remarks

A) THE INSPECTION WAS C
B) IN ACCORDANCE TO YO

JECTED ON A "WITH PREJUDICE" BASIS.
STRUCTURE, WITH NOT AUTHORISED REPAIRS.

eBaoTech

Hello, NAC_PAYA_UBI_800601

[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.

Vehicle No.(For Motor)

GBG6683D

Date of Accident

09/11/2017 13:26

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5094850642	ELH INDUSTRIES LTD	201326252D	GCV	Preferred Workshop Plan	GBG6683D	GBG6683D	11/10/2017	10/10/2018

Continue

General Claim

[Change Language](#)[Change Password](#)[Log Out](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2017 09:41
Date Of Accident	09/11/2017 18:10
Exact Location Of Accident	NORTH BUONA VISTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB757U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
Driver	
Name of Driver	LIM SOON PHENG
NRIC No	S1576251I
Date Of Birth	19/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	10/11/1980
Driving Experience	36 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG NORTH BUONA VISTA ROAD AT THE LEFT LANE AND HAD SLOWED DOWN DUE TO THE FRONT VEHICLE SUDDENLY JAMMED BRAKE AND TURN INTO THE CIVIL SERVICE COLLEGE. AFTER WHICH I FELT AN IMPACT FROM BEHIND. THE VEHICLE GBG6683D FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO LARGE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG6683D

Vehicle Make/Model/Colour TOYOTA VAN

Details Of Properties

Name of Driver PONNAIAH SIVA KUMAR

NRIC/Passport Number F8068272R

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	5369K

Vehicle Details

Vehicle No.	SHB757U
Vehicle to be Exported	No
Intended De-registration Date	14 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2014
Engine No.	2ZR1502051
Chassis No.	JTDKN36U805757706
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$32,920.00
Original Registration Date	04 Feb 2015
First Registration Date	04 Feb 2015
Transfer Count	0
Actual ARF Paid	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Feb 2023
PARF Rebate Amount	\$6,066.00

Intended COE Rebate Details

COE Expiry Date	03 Feb 2023
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$52,904.00
COE Rebate Amount	\$34,528.00
Total Rebate Amount	\$40,594.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Nov 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)


Last updated on 13 Oct 2017 at 07:07 PM

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB757U
 Ref. No : TAX/11/17/2057
 Reg. Date : 04/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LIM SOON PHENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 10/11/2017 08:10:00 AM
 Accident Reported Date / Time : 10/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093023
 Special Instruction to ARC, if any :
 DROVE IN / GBG6683D
 Prepared Date : 10/11/2017 10:01:12 AM



Sebastian
 13/11/2017
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805757706

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	: 1,183.00	850.00
Total Spray Painting Charges	: 1,116.00	500.00
Total Material Charges	: 4,765.18 6054.60	2,698.61
Other Charges	: 480.00	-748.61
TOTAL	: 7,544.18 8033.60	3,300.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	5.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 10/11/2017 03:45:39 AM	13/11/2017 03:54:11 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/11/2017 03:43:39 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1711-0439

Invoice No :

Quotation Date : 18/11

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	850.00 /
Total Labour	1,183.00	850.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
Total Spray Painting & Panel Beating	1,116.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-838.61
Total Other Costs	480.00	-748.61

895' 80

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>CRK</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace <i>S</i>	No <i>BT</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>S</i>	No <i>BT</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X NN</i>
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace <i>S</i>	No <i>DMG</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>DMG</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>NEC</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>X JM</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>X JM</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>Defom</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>cut</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>Defom</i>
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No <i>X NN</i>
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No <i>DMG</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No <i>NEC</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No <i>NEC</i>
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No <i>NEC</i>
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No <i>NEC</i>
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No <i>JM</i>
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.68	Replace	Check	No <i>X JM</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Check	No <i>X NN</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>NEC</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No <i>X NN</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace <i>S</i>	No <i>CRK</i>
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Check	No <i>X</i>
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No <i>X NN</i>
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Check	No <i>X</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58336-12090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Check	No <i>X</i>
TOTAL MATERIALS							4,765.21	2,698.61		
TOTAL MATERIALS(Discounted)							4,765.18	2,698.61		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 2698.60 / \\
 + 850.00 / \\
 + 590.00 / \\
 \hline
 4138.60 / \\
 - 207 \\
 \hline
 3310.88 /
 \end{array}$$

US \$3300/-

Sebastian
27/11/2017.

r

17-11-17 / 11:34 54

17-11-17 / 15:29 54

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

13-11-17/05:34

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No	:	SHB757U
Ref. No	:	TAX/11/17/2057
Reg. Date	:	04/02/2015
Vehicle Type	:	TAXI
Make	:	TOYOTA PRIUS
Model	:	PRIUS
Name of Driver	:	LIM SOON PHENG
Type of Accident	:	HEAD TO REAR
Date / Time of Accident	:	10/11/2017 08:10:00 AM
Accident Reported Date / Time	:	10/11/2017 12:00:00 AM
Surveyor is Required?	:	Yes
Survey by	:	Sebastian
Vehicle is Towed Back?	:	No ✓
Towed Back Date/Time	:	
Replacement Vehicle issued?	:	No
Accident Repair Job Card No	:	000024093023
Special Instruction to ARC, if any	:	



DROVE IN / GBG6683D - NTUC IDAC *HS*
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email :sebastianyeang @lkkauto.com HP:90036121
 LUMPSUM REPAIR

Prepared Date : 10/11/2017 10:01:12 AM

91594104 China 1035 ✓

Recording Camera

Radio Antenna

1st witness

Date _____

13-11-17

2nd witness

Date _____

Qc 17/11/17 9.00 Refect

RR Boot. Lock August

10.26 pgs

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

Vehicle Return Time:

SMRT staff sign:

502584/cm

[illegible]

$\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$
50064

Supplementary

* Refer to the Supplementary part 107

Top up
petrol
\$15

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805757706

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 4,765.15	4,765.15
Other Charges	: 480.00	0.00
TOTAL	: 7,544.15	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sing Off Date	: 10/11/2017 03:45:39 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/11/2017 03:43:39 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 700
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	480.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2159-7905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace ✓ CKK	No
2023-2240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace photo	Replace photo ?	No
2016-7030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
2015-7050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
9997-0070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ DMG	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEC	No
2576-7020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ?	No
2575-7020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
6088-7020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace ✓ Deform	No
6087-7020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace ✓ cut	No
6891-7020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace ✓ Deform	No
8308-7011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace ?	No
7005-7241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace ✓ DT	No
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace ✓ NEC	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace ✓ NEC	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace ✓ NEC	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace ✓ NEC	No
9350-7030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace ✓ Jm	No
9431-7010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace ?	No
7881-7022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace ?	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NEC	No
8307-7060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace ?	No
4718-7031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace ?	No
4716-7031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace ?	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
8311-7071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
8336-2090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Replace	No
TOTAL MATERIALS								4,765.21	4,765.15	
TOTAL MATERIALS(Discounted)								4,765.15	4,765.15	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17021702/Srbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 16-01-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 6683D	Veh. Inspected	SHB 757U
Policy No.	5094850642	Coverage (\$)	0.00
Claim No.	MT/0969224-002	Excess (\$)	0.00
Assign From		Assign Date	13/11/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U805757706	Colour	MAROON
Odometer	500586	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/11/2017	Inspection Date	13/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 757U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	CUT	118.10	88.57
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.92
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR LOCK (DISC 25%)	JAMMED	444.10	333.07
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	CRACKED	46.10	34.58
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	DAMAGED	157.40	141.66
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	END PANEL	NOT NECESSARY	602.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
2	REINFORCEMENT, RR @\$34.60	NOT NECESSARY	69.20	-
			6,172.80	2,698.62

Report Ref No. NS/INC17021702/Srbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,503.00	920.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,116.00	500.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,779.00	1,440.00
	GRAND TOTAL		8,951.80	4,138.62

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,300.00
---	--	--	-----------------

Report Ref No. NS/INC17021702/Srbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.