

ASS. REC. BY:

REF: CS/MSL17021711/Sgbnz

Special Instruction:

Survivor: Sebastian

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of MSLH

Date/Time: 13-11-2017 4:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 8583L

Insured:

SLH 8813J

at Workshop m/s

SC Auto

Tel:

6571 9981

of

51 SONOKO ROAD

Policy No:

A288 50208 AVW

Claim No:

534163

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24-10-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

16.11.2017 @ morning

W.O.D. Endorsement:

Date/Time:

14-11-2017 9:08am

Person Contacted:

Mei Lin

Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	PA 8583L - CS / FC214023056 / Kigbedi
	SLH 8813J ✓


DA: 051214

REF: MS19

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 16/11/17  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: PA8583L  
 at Workshop m/s SC Auto  
 of 51 Senoko Road #03-01, 758133  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Morning



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: PA 8583L Yr Regn: 4/5/2009  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mitsubishi Kosy Bus c.c. 4899  
 Colour: Multi Colour A/C: Insured / Std / NI / NA  
 Sp. Reading: 358646 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 15F 6303F 00150  
 Gen. Cond: Good / Rat / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/75 R17-5  
 R: 205/85 R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Bridgestone  
 Front R/Bal. 6 mm Rear R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 24/10/2017 D.O.I. 16/11/2017  
 Survey held at SC Auto  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>17/11/17</u>	<u>REV preli in memo.</u> <u>45 \$ 4100 (Red: 4339.75, 51%).</u>

RECEIVED 13 DEC 2017

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: TP  
 Lump Sum / I.B.I: (\$ 4100)

Days Of Repair: 4  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) \$ + RS \_\_\_\_\_  
 : Interview (\$ \_\_\_\_\_) ) Photos \_\_\_\_\_  
 : Tech. Invs (\$ \_\_\_\_\_) ) Others \_\_\_\_\_  
 : Weekend (\$ \_\_\_\_\_) )  
 TOTAL 210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17021711/Sgb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 14-11-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 8813J	Veh. Inspected	PA 8583L
Policy No.	A28850208AVW	Coverage (\$)	0.00
Claim No.	534163	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	13/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	24/10/2017	Inspection Date	
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**...CLAIM SUBFOLDER...(New Assignment)**

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Advice	Status
Main	25 Oct 2017		13 Nov 2017 16:28 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
<b>Insured:</b>	ANDREW GAN JIAN WEN, ID: S8521698H, Tel: +6594517951, Email: ANDREW_GAN85@YAHOO.COM.SG	
<b>Main Claimant:</b>	Tong Tar Transport Service Pte Ltd, Co. Reg. No.: 197800458K	
<b>Vehicle Reg. No.:</b>	PA8583L	<b>Date of Loss:</b> 24/10/2017 21:00 - :59
<b>Claim Type:</b>	TP / 534163	<b>Policy/Cover Note No.:</b> A28850208AVW (Comprehensive) Coverage: 31/10/2016 - 30/10/2017
<b>Vehicle Reg. No. (Insured):</b>	SLH8813J	<b>Policy No. (Claimant):</b>
		<b>Excess:</b> S\$500.00
<b>Repairer:</b>	SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road, #03-01, 758133 Woodlands - Tel: 67582222/65719972	
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]	
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/11/2017]	
<b>Driver/Custodian (Insured):</b>	ANDREW GAN JIAN WEN (32 / Male), NRIC: S8521698H, Tel: +6594517951	
<b>ASSOCIATED MAIL RECEIVED</b>		
There are no mail for this case.		<a href="#">View All</a> <a href="#">Compose Case Mail</a>
<b>ALL ASSOCIATED TASKS</b>		
		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>
<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>
<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>
<b>Done?</b>		
No results.		

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 17 Nov 2017

**Preliminary Advice**

Insured Vehicle No	: SLH8813J	Accident Date	: 24/10/2017
TP Vehicle No	: PA8583L	Assignment Date	: 13/11/2017
Make	: MITSUBISHI ROSA	Est. Duration of Repair	: 5.00
Date of Inspection	: 16/11/2017		
Inspection At	: SC AUTO INDUSTRIES (S) PTE LTD (HQ) 51 SENOKO ROAD, #03-01 SINGAPORE 758133		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,439.75
Revised Amount	:S\$	5,181.00
Check Items (Estimated)	:S\$	210.00
Total	:S\$	5,391.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	0458K
Vehicle Details	
Vehicle No.	PA8583L
Vehicle to be Exported	No
Intended De-registration Date	17 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	ROSA BUS 4.9L MT 2WD 6T TURBO
Primary Colour	Multi-Colour
Manufacturing Year	2008
Engine No.	4M50D25601
Chassis No.	BE63DJF00150
Maximum Power Output	-
Open Market Value	\$78,853.00
Original Registration Date	04 May 2009
First Registration Date	04 May 2009
Transfer Count	1
Actual ARF Paid	\$3,943.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	03 May 2019
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$7,326.00
COE Rebate Amount	\$1,173.00
<b>Total Rebate Amount</b>	<b>\$1,173.00</b>

The information contained herein is correct as at 17 Nov 2017

OK



# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133  
 T 65 6758 2222 F 65 6257 6931  
 E sales@scauto.com.sg  
 scauto.com.sg

M/S	Tong Tar Transport Svc Pte Ltd No 8 Soon Lee Road SINGAPORE 628072
Insured	Tong Tar Transport Svc Pte Ltd
Policy	VFX/P0219856/00312

## ESTIMATE Bill

GST Reg. No: 19-9800107D  
 Date: 12/11/2017  
 Our Case Ref. SC17/10/260/4TT-TP  
 Accident Date 24/10/2017

Damaged Vehicle No: PA8583L

S/no	Description	QTY	Price	Disc	Amount
<b>Replaced Parts</b>					
1	VEHICLE NUMBER PLATE X MN	1 PC	\$50.00	-	\$50.00
2	ARTWORK ✓ NEC	1 ST	\$1,800.00	-	\$1,800.00
3	60KM/HR STICKER ✓ NEC	1 PC	\$15.00	-	\$15.00
4	REAR BUMPER ✓ CEX	1 PC	\$2,608.00	25.00%	\$1,956.00
5	BUMPER BRACKET 7X MN	2 PC	\$225.00	25.00%	\$337.50
6	REAR BUMPER LAMP LHS 7X MN	1 PC	\$55.00	25.00%	\$41.25
<b>Labour Charges</b>					
1	LABOUR FOR WIRING	1 30	\$80.00	-	\$80.00
2	SPRAY PAINTING	1 800	\$1,600.00	-	\$1,600.00
3	LABOUR FOR REAR PORTION	1 1280	\$2,560.00	-	\$2,560.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Withhold" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved
- Final invoice is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

4-5 days.  
 Sebastian 16/11/2017.  
 - Long Sun Repair.  
 - Question Mark Iron Photo.  
 - Photo After Paint.  
 [Signature] 22/11/17.

[Signature]  
 \_\_\_\_\_  
 Authorised Signature

**Sub Total** S 8,439.75

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021711/SGBN2

Date: 19/12/2017

#### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28850208AVW
Claimant Vehicle No :	PA8583L	Insured Vehicle No :	SLH8813J
Date of Loss:	24/10/2017	Nature of Claim:	TP
			Claim No: 534163

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA8583L	Engine No:	4M50D25601
Make & Model:	MITSUBISHI ROSA, 4.9 D L MT (M)	Chassis No:	BE63DJF00150
Reg. Date:	04/05/2009 (Man. Year: 2008)	Odometer:	358646 km
Colour:	Multi-colour		
Engine Capacity:	4899 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/75R17.5	Rear Tyre Size:	205/85R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,199.75	3,071.00	1,128.75	26.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,110.00	2,130.00	50.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,439.75</b>	<b>5,181.00</b>	<b>3,258.75</b>	<b>38.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
(S\$)	8,439.75	4,100.00	4,339.75	51.42
+ GST 7.00/7.00% (S\$)	590.78	287.00	303.78	51.42
<b>Nett Amount (S\$)</b>	<b>9,030.53</b>	<b>4,387.00</b>	<b>4,643.53</b>	<b>51.42</b>

#### INSPECTION

Date of Assignment:	13/11/2017	
Date Inspected:	16/11/2017	Inspected At: SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road, #03-01 Singapore 758133
Estimated Period of Repair:	4.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Dec 2017)	
<b>Parts:</b>	N/A	MITSUBISHI ROSA 4.9 D L MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PA8583L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	2,608.00 FL	*2,608.00 FL
2	2		*BUMPER BRACKET	Not Necessary	450.00 FL	*- FL
3	1		*REAR BUMPER LAMP LHS	Not Necessary	55.00 FL	*- FL
4	1		*VEHICLE NUMBER PLATE	Not Necessary	50.00 FS	*- FS
5	1		*ARTWORK	Necessary	1,800.00 FS	*1,100.00 FS
6	1		*60KM/HR STICKER	Necessary	15.00 FS	*15.00 FS
<b>Sub Total (S\$)</b>					<b>4,978.00</b>	<b>3,723.00</b>
- List Item Discount on L Items 25.00/25.00% (S\$)					778.25	652.00
<b>Total Parts (S\$)</b>					<b>4,199.75</b>	<b>3,071.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR WIRING	New	80.00	30.00
2	SPRAY PAINTING	New	1,600.00	800.00
3	LABOUR FOR REAR PORTION	New	2,560.00	1,280.00
Gross Labour Cost (\$\$)			<b>4,240.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >