

ASS: REC. BY REF: CS/FCI17021760 / R/vbnz Special Instructions:

Surveyor: RAW ASSIGNMENT (Office) Date/Time: 3:03pm @ 14/11/17
From (Person): Joanne Yong of FCI Bill to:

Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS Insured: SHD7187H
To Inspect Vehicle No: SJY8668X Tel: 81261237

at Workshop m/s: Wearnes Automotive
of 249 Alexandra Road Claim No: D1701059/MFSH

Policy No: _____ Excess: _____
Sum Insured: _____ D.O.A. 14/11/2017

Make of Veh: _____ H.O.D. Endorsement: _____
(Client's Record) CA / REV / REP. / REV 24 HRS lwp Vehicle-IN/OUT OUT
Date/Time: 5:01pm @ 14/11/17 Person Contacted: Paul

Date/Time	Action/Instruction (✓) Estimate
	<u>SJY8668X-CS/AXA17015459/R7vb-D.O.A.: 1/8/2017</u>
	<u>SHD7187H-CS/FCI17001708/M7gh3m2-D.O.A.: 23/01/2017</u>

7/12/17 Email preli revised to FCI

14/12/17 Final fig \$ 7543.62 confirmed by email (Ref 2999.16, 2870)

Signature: *Paul*

REF: FCL

b230c

ASSIGNMENT

From: _____ Date: 06/12/2017

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SJY 8668X

at Workshop m/s: Wearnes

of: 45 Leng Kee Rd

insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Paul - 8126 1237

Veh No: SJY 8668X Yr Regn: 2016 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: LAND ROVER DISCOVERY 2P2.0 1999

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 024516 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: SALCA2A969H618638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 235/55R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____


Front		Rear	
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>14/11/17</u>	D.O.I. <u>06/12/17</u>	Survey held at: <u>WEARNES</u>	

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

RECEIVED 15 DEC 2017

Date/Time File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 3
Resurvey No. of Trip: 1

Survey Fee
Transportation

Date/Time File Return to?
14/12 - typist

Add Fee: Site Insp \$
 Interview \$
 Tech. Insp \$
 Weekend \$

Photos
Diets

Report Format: aws
Lump Sum / I.B.I: \$ 7543.62

170
50
50
24
294

Survey Department Check List (Case Handler)

Reference No.: CS | FRI 17021760 | RMB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

); Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 14/12/17
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021760/R1vb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7187H	Veh. Inspected	SJY 8668X
Policy No.		Coverage (\$)	0.00
Claim No.	D17010591MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	14/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/11/2017	Inspection Date	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010591MFSH
Our Ref: CS/FCI17021760/R1vb

Date : 7/12/2017

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJY 8668X

We thank you for your instruction on 14/11/2017

Please be informed that we had conducted the inspection of the above mentioned
6/12/2017 at the premises of M/s WEARNES AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$	10,491.30
Revised Estimate Amount	: S\$	7,757.90
"Check" Items Amount	: S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:
The vehicle sustained damages at the
o/s rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-11-2017	Our Ref No. D17010591MFSH
Accident Date	14-11-2017	Claim Type. Third Party
Insured Vehicle	SHD7187H	Third Party Vehicle. SJY8668X
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	PAUL ONG	
Contact No.	63789336/ 81261237	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230193)



PRI Documents



Close



PRI Header Details

Claim No	D17010591MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 63789336 , Fax: 0 EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD7187H	TP Vehicle No	SJY8668X
PRI Recieved Date	14-11-2017 04:36:48 PM	Surveyor Appointed Date	14-11-2017 03:02:29 PM	Surveyor Accept Date	14-11-2017 0.

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	14-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 December, 2017 5:14 PM
To: Paul Ong Qing Yong; Rasul (LKKAuto); SUR
Subject: RE: SJY8668X Finalisation

Sensitivity: Confidential

Dear Paul,

Confirmed finalise amount \$7,543.62 before GST

No of days: 3 days

Final invoice and all supporting documents sent to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Thursday, 14 December, 2017 8:36 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SJY8668X Finalisation
Sensitivity: Confidential

Hi,

Attached for finalisation. Thank you

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 7 December, 2017 3:40 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010591MFSH/1, SJY 8668X
Attachments: SJY 8668X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJY 8668X
Date of survey: 6/12/2017
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 14 November, 2017 5:04 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010591MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 14 November, 2017 3:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010591MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7679353J



Name

ALLINA WANG HSIAO TZU

王孝慈

Race

CHINESE

Date of birth

05-02-1976

Sex

F

Country of birth

TAIWAN

S7679353J

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7679353J

Name:

ALLINA WANG HSIAO TZU

Birth Date: 05 Feb 1976

Issue Date: 21 Jul 2011



9133671



NRIC No: S7679353J

Nationality

AUSTRALIAN

Date of issue

19-07-2011

Address


540A SEMBAWANG ROAD
SINGAPORE 758530

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 23 Apr 2011

NP 428A



Repair
 4p 90000068
 3 days
 06/12/17 @ 1545
 Resin by paint

[Handwritten signature]
 7/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SERVICE ESTIMATE

85586 - C00001 SL: SERVICE SALES - PC
 Mr Ronnie Kong Tzeh Yenn
 540A Sembawang Road
 Sembawang Spring Estate

Singapore 758530

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date : 14/11/2017
 WIP No. : 29306
 Veh.In/Out:
 *Tel.No. : Mobile: 97256680
 Reg.No. : SJY8668X
 Reg.date : 30/06/2016
 Mileage : 0
 Chassis No: SALCA2AG6GH618638

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Ronnie Kong Tzeh

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR RH DOOR, DOOR MOULDING, REPAIR FRT RH DOOR	0	2400.00	0		2,400.00	S 1200 ✓
800	TO PUTTY SPRAYPAINT ON REAR RH DOOR, FRT RH DOOR	0	2000.00	0		2,000.00	S 1000 ✓
802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00	S ✓ ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S ✓ ✓
1	DOOR PANEL REAR RH D	1.0 EA	3333.60			3,333.60	S Price 3000.04
2	MOULDING - DOOR OUTS	1.0 EA	352.10			352.10	S Price 316.59
3	MOULDING ARCH REAR R	1.0 EA	207.20			207.20	S Price 186.48
4	MOULDING - REAR WHEEL	1.0 EA	320.70			320.70	S Price X 500
5	NOISE DEADENING PAD	1.0 EA	500.00			500.00	S Price 450
6	SEAL - DOOR FRONT AN	1.0 EA	212.70			212.70	S Price 191.43
7	SEAL - DOOR FRONT AN	1.0 EA	179.00			179.00	S Price 161.10
Gross Total.						10,491.30	10,542.78
Labour Total			5,386.00	Net.....		10,491.30	
Parts Total			5,105.30	GST @ 7.0%		734.39	
Package Total			0.00	Total.....		11,225.70	
						Paid.....	0.00
						Please Pay..	11,225.70

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01, CITY HOUSE SINGAPORE Singapore 068877	GST Reg.No:M28920628X Inv.No. . . : B&P 0 Page 1 Inv.date. . : 14/12/2017 WIP No. . . : 29306 Veh.In/Out: 06/12/2017 12/12/2017 *Tel.No. . . : Reg.No. . . : SJY8668X Reg.date . . : 30/06/2016 Mileage . . : 16,800 Chassis No: SALCA2AG6GH618638
Closed by : Paul Ong Qing Yong Svc Consultant : ACC Remarks : Mr Ronnie Kong Tzeh	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR RH DOOR, DOOR MOULDING	0	1200.00	0		1,200.00	S
800	TO PUTTY SPRAYPAINT ON REAR RH DOOR	0	1000.00	0		1,000.00	S
802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	DOOR PANEL REAR RH D ①	1.0 EA	3333.60	10		3,000.24	S
	MOULDING - DOOR OUTS ②	1.0 EA	352.10	10		316.89	S
	MOULDING ARCH REAR R ③	1.0 EA	207.20	10		186.48	S
	NOISE DEADENING PAD ⑤	1.0 EA	500.00	10		450.00	S
	base → SEAL - DOOR FRONT AN ⑥	1.0 EA	212.70	10		191.43	S
	SEAL - DOOR FRONT AN ⑦	1.0 EA	179.00	10		161.10	S
	supp BUMPER NUT XF - door	13.0 EA	4.40	10		51.48	S (A) N

Gross Total. 7,543.62

Labour Total 3,186.00
Parts Total 4,357.62
Package Total 0.00

Net..... 7,543.62
 GST @ 7.0% 528.05
 Total..... 8,071.67
 Paid..... 0.00
 Please Pay.. 8,071.67

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021760/R1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7187H	Veh. Inspected	SJY 8668X
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010591MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	14/11/2017
2. Vehicle Particulars & Condition			
Make & Model	LAND ROVER DISCOVERY SP 2.0	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SALCA2AG6GH618638	Colour	BLUE
Odometer	24516	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R19	PIRELLI	6 mm
L/H Front Tyre	235/55 R19	PIRELLI	6 mm
R/H Rear Tyre	235/55 R19	PIRELLI	6 mm
L/H Rear Tyre	235/55 R19	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2017	Inspection Date	06/12/2017
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 8668X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL REAR RH D (SN)	BUCKLED	3,333.60	3,000.24
1	MOULDING-DOOR OUTS (SN)	DEFORMED	352.10	316.89
1	MOULDING ARCH REAR R (SN)	DEFORMED	207.20	186.48
1	MOULDING-REAR WHEEL (SN)	SERVICEABLE	320.70	-
1	NOISE DEADENING PAD (SN)	NECESSARY	500.00	450.00
1	SEAL-DOOR FRONT AN (SN)	NECESSARY	212.70	191.43
1	SEAL-DOOR FRONT AN (SN)	NECESSARY	179.00	161.10
13	BUMPER NUT XF (ADDITIONAL)(SN)	NECESSARY	51.48	51.48
			5,156.78	4,357.62
LABOUR				
	TO REPLACE REAR RH DOOR, DOOR MOULDING, REPAIR FRT RH DOOR.		2,400.00	1,200.00
	TO PUTTY SPRAYPAINT ON REAR RH DOOR, FRT RH DOOR.		2,000.00	1,000.00
	TO TRANSFER REAR RH DOOR PART.		500.00	500.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		486.00	486.00
			5,386.00	3,186.00
GRAND TOTAL			10,542.78	7,543.62
RECOMMENDED COST OF REPAIRS				7,543.62

Report Ref No. CS/FCI17021760/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.