



HKL LIM
TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBE2921D

1. TOWING -\$35 ✓
2. HANDLEBAR -\$120 ?
3. HANDLEBAR FRONT COVER -\$160 cut ✓
4. SIDE MIRROR RH -\$180 cut ✓
5. BRAKE LEVER RH -\$55 cut ✓
6. FRONT WHEEL RIM -\$280 X
7. FRONT WHEEL HALF -\$45 X
8. FRONT BRAKE DISCS -\$110 X
9. HEAD COWLING TOP -\$180 cut ✓
10. HEAD COWLING LOWER -\$220 cut ✓
11. COMPARTMENT -\$150 X
12. FRONT FENDER -\$150 cut ✓
13. LOWER PANEL RH -\$120 cut ✓
14. FRONT FOOT PANEL -\$120 cut ✓
15. PILLON FOOT PANEL RH -\$70 cut ✓
16. SIDE COVER RH -\$180 cut ✓
17. TAIL PANEL RH -\$95 cut ✓
18. EXHAUST PIPE -\$550 RP ✓
19. EXHAUST COVER -\$80 cut ✓
20. FRONT FORK ASSY -\$550 alignment \$150 ✓
21. STEERING CONE BEARING -\$90 ?
22. TOP BOX -\$160 cut ✓
23. LABOUR -\$550 300
- TOTAL -\$4250

Tanpin 97495749.
- WP -

14/11/17 @ 1730.

Tail Cover Cover \$80 de ✓

5 days
Lumpsum
Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: