

12/03/2017

ASS: REC BY

REF: CS/FCI/7021822 / Tlvb 02 Special Instruction

Surveyor: Tauhid ASSIGNMENT (Office)

From (Person): CWS Karen Tan of FCI Date/Time: 11.53 am @ 15/11/17

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 3189G Insured: SH 80462

at Workshop m/s: Shu Fatt Auto Works Tel: 627 30119

of Blk 1009, # 01-90 Bukit Merah Lane 3

Policy No: \_\_\_\_\_ Claim No: D17 010618 MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 12/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp' 20.11.2017 @ before lunch. H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12.45pm @ 15/11/17 Person Contacted: julia Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 3189G - CC6 / AIG 17018541 / T1pb3 - D.O.A : 23/09/2017
	SH 80462 - NS/INC 13022818 / H1gm3c3 - D.O.A : 1/12/2013
21/11/17	Email preli revised to FCI
5/12/17	LS \$ 4450 confirmed by email (Ref 6008.90, 5710)

Signature: *Tan Jiah* REF: **FCI**

**ASSIGNMENT**

From: \_\_\_\_\_ Date: **20/11/2017**

Estimated Cost: \_\_\_\_\_

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SKK 3189G**

at Workshop no: **Shu Fatt Auto Works**

of **Blk 1009 # 01-90 Bkt Merah Lene 3**

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

**Before lunch**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GLA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **'up'**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle IN / OUT

Date / Time Action / Instruction

Veh No: **SKK 3189G** Yr Reg: **2013 June**

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or

Make: **BMW 320I** cc: **1997**

Colour: **Black** A.C. Insured: Std / Nil / NA

Sp. Reading: **70624** 7 Radio: Insured: Std / Nil / NA

Eng No: \_\_\_\_\_

C.No: **WRBAXG12030DX54075**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/R / STD A/Rim or

Tyre Size: F: **225/55R17**

R: \_\_\_\_\_

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R.Bal: **6** mm R.Bal: **6** mm

L.Bal: **6** mm L.Bal: **6** mm

D.O.A: \_\_\_\_\_ D.O: **20/11/17 1120**

Survey held at: **Shu Fatt**

Des. of Damages: Fnt / Rear / ☒ O/S / N/S / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision.

RECEIVED 05 DEC 2017.

Date/Time File Pass to: ☐ Prel. Report

☐ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee

**5/12- typist**

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Ins \$

☐ Other \$

Transport

Report Format: **CWS**

Lump Sum / I.B.I: **4450/-**

170
50
50
57
327

## Survey Department Check List (Case Handler)

Reference No. : CS/17021822/Tlvb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

Case Handler

5/12/17

Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021822/T1vb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-11-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8046Z	Veh. Inspected	SKK 3189G
Policy No.		Coverage (\$)	0.00
Claim No.	D17010618MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	15/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/11/2017	Inspection Date
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

Date	14-11-2017	Our Ref No. D17010618MFSH
Accident Date	12-11-2017	Claim Type. Third Party
Insured Vehicle	SH8046Z	Third Party Vehicle. SKK3189G
Survey Location	BLK 1009 #01-90 BUKIT MERAH LANE 3	
Contact Person.	JULIA WONG	
Contact No.	62730119/ 62730119	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	SHU FATT AUTO WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230229)



PRI Documents



Close X

### PRI Header Details

<b>Claim No</b>	D17010618MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & SHU FATT
<b>Workshop Name</b>	SHU FATT AUTO WORKS (Contact Person : JULIA WONG)	<b>Survey Location &amp; Contact Details</b>	BLK 1009 #01-90 BUKIT MERAH LANE 3 <b>Mobile:</b> 62730119 , <b>Phone:</b> 62730119 , <b>Fax:</b> 0 <b>EmailId:</b> SHUFATT@SINGNET.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SH8046Z	<b>TP Vehicle No</b>	SKK3189G
<b>PRI Recieved Date</b>	14-11-2017 08:46:14 PM	<b>Surveyor Appointed Date</b>	15-11-2017 11:51:51 AM	<b>Surveyor Accept Date</b>	15-11-2017 0

### Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	15-11-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

### Vehicle Particulars

<b>Make</b>	Please Select Make ▼	<b>Model</b>	Please Select Model ▼	<b>Year</b>	Select Year ▼
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

### Multiple Documents Upload

File Name

Action

### Surveyor Job Remarks

Remarks

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 21 November, 2017 2:18 PM  
**To:** 'Claim Workflow System'  
**Cc:** KARENTAN@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17010618MFSH/1,SKK 3189G  
**Attachments:** SKK 3189G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKK 3189G  
Date of survey: 20/11/2017  
Number of days:5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 15 November, 2017 12:48 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D17010618MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Wednesday, 15 November, 2017 11:52 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [KARENTAN@FIRST-INSURANCE.COM.SG](mailto:KARENTAN@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17010618MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010618MFSH  
Our ref: CS/FCI17021822/T1vb

Date: 21/11/2017

The Motor Claims Department  
M/s First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKK 3189G**

We thank you for your instruction on 15/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2017 at the premises of M/s SHU FATT AUTO WORKS and have the following to report:-

Workshop Estimate Amount	: S\$9,930.27
Revised Estimate Amount	: S\$5,033.83
"Check" Items Amount	: S\$2,745.07
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:  
The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/11/2017 11:44
Date Of Accident	12/11/2017 09:30
Exact Location Of Accident	KPE TUNNEL TOWARDS CITY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK3189G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEN FUN GEE@CHEN EDWARD
NRIC No	S1399882E
Email Address	WINHAZ@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96634431
Alternative Phone No	OTHERS-96634431

### Vehicle Particulars

Manufacturer	BMW
Model	BMW 520I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 27539741 SMP
Cover Note Number	

### Driver

Name of Driver	CHEN FUN GEE@CHEN EDWARD
NRIC No	S1399882E
Date Of Birth	01/04/1957
Occupation	INDOOR
Date Of Driving Pass	10/11/1982
Driving Experience	35 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96634431
Fax Number	
Contact Number	OTHERS-96634431
EMail Address	WINHAZ@SINGNET.COM.SG

**Details Of Properties**

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number

SLQ6065S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


**Details of Witness**

Name

Phone Number

Email Address

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

We were driving our car BMW SKK 3189 G on the right lane about 9.30am 12/11/17 Sunday in the KPE tunnel towards the city. A broken down car SLY 6868 J has stopped permanently on the right lane, which caused all the cars in front of us to brake. My husband braked and the taxi no SH 8046 Z banged into the back of our car. The taxi had a passenger in the back seat. Other cars involved SJW 3702 Z & SLQ 6065 S. The taxi driver refused to give his contact number.

Car SKK 3189 G was stationary when the taxi collided behind. There was 1 Bang. The Car in front of my Car was also stationary and there was no collision with the car in front. The car moved off immediately and I did not get the Car Number.

Chm

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

CHEN FUNG GEE  
13.11.2017 1245 PM

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Person's Signature  
Name:  
NRIC/FIN:





# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo  
14<sup>th</sup> November 2017  
TP2

SKK 3189 G BMW 520i

Spare Parts	1	Rear boot.
	1	Rear boot logo.
	1	Rear boot "520i" emblem.
	1	Rear boot lock.
	1	Rear boot rubber.
	1	Set rear boot inner garnish clips.
	1	Rear support panel.
	1	Rear panel inner garnish.
	1	Rt rear tail light.
	1	Rear bumper
	1	Rear bumper reinforcement.
	1	Rear bumper foam.
	2	Rear bumper brackets. @\$151.65
	1	Set rear bumper clips.
	2	Rear bumper side retainers. @\$141.65
	1	Rear bumper tow cover.
	2	Rear bumper reflectors. @\$38.55
	1	Rear lower bumper cover.
	1	Set rear lower engine cover clips.
	2	Rear bumper sensors. @\$252/-

S\$
1653.30 <i>bt ✓</i>
76.80 <i>nei ✓</i>
66.05 <i>nei ✓</i>
445.35 ? <i>x nn</i>
142.25 ? <i>x nn</i>
60.00 ? <i>x nn</i>
871.30 <i>R ✓</i>
130.00 ? <i>x nn</i>
572.25 <i>x ✓</i>
1631.40 <i>de ✓</i>
696.80 ? <i>x</i>
78.50 ? <i>x</i>
7303.30 ? <i>x</i>
60.00 <i>nei ✓</i>
283.30 ? <i>x nn</i>
25.30 <i>de ✓</i>
77.10 <i>LH-? RH-ann</i>
157.50 ? <i>x</i>
50.00 ? <i>x</i>
504.00 ? <i>x</i>

7884.50

Less 5% 394.22

7490.27

Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, left rear panel, rt rear panel, renew rear boot, rear support panel, rear lights, rear bumper and assembly.
	To respray damaged parts.
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.
	To remove rear electronics to facilitate repairs and assembly.
	To reseal joints, reinsulate, anti rust panels and assembly.
	To check and reset ECU.

900.00 *700*

980.00 *700*

180.00 *60*

150.00 *40*

80.00 *40*

150.00 *120*

9930.27 10,458.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price subject to confirmation
- Third party claim on a subject to insurance basis
- No illegal modification(s) is allowed
- Supplier's warranty must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749  
-wp

20/11/17 @ 1115

sw @ lkkauto.com

5 days

Lump sum

Revised after repair

*[Signature]*  
20/11/17

Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 5 December, 2017 3:28 PM  
**To:** 'Pat-Shu Fatt Auto Works'; Rasul (LKKAUTO); SUR  
**Subject:** RE: SKK 3189 G - finalise

Dear Pat,

Confirmed Lump Sum \$4,450.00 before GST.

No of days: 5 days

**Kindly send invoice direct to First Capital Insurance.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Pat-Shu Fatt Auto Works [mailto:shufatt@singnet.com.sg]  
**Sent:** Tuesday, 5 December, 2017 12:50 PM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** SKK 3189 G - finalise

Dear Rasul,

Please see attached after paint photos and finalized calculations.

Cost of repair: \$4450.00 lump sum before GST.  
5 days.

Thanks & regards,  
Pat  
Shu Fatt Auto Works



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo  
14<sup>th</sup> November 2017  
TP2

SKK 3189 G BMW 520i

		S\$
Spare Parts	1 Rear boot.	1653.30 <i>bt✓</i>
	1 Rear boot logo.	76.80 <i>rel✓</i>
	1 Rear boot '520i' emblem.	66.05 <i>rel✓</i>
	1 Rear boot lock.	445.35 <i>?x</i>
	1 Rear boot rubber.	142.25 <i>?x</i>
	1 Set rear boot inner garnish clips.	60.00 <i>?x</i>
	1 Rear support panel.	871.30 <i>R✓</i>
	1 Rear panel inner garnish.	130.00 <i>?x</i>
	1 Rt rear tail light.	572.25 <i>x</i>
	1 Rear bumper.	1631.40 <i>de✓</i>
	1 Rear bumper reinforcement.	696.80 <i>?x</i>
	1 Rear bumper foam.	78.50 <i>?x</i>
	2 Rear bumper brackets. @\$151.65	7303.30 <i>x</i>
	1 Set rear bumper clips.	60.00 <i>rel✓</i>
	2 Rear bumper side retainers. @\$141.65	283.30 <i>?x</i>
	1 Rear bumper tow cover.	25.30 <i>de✓</i>
	2 Rear bumper reflectors. @\$38.55	77.10 <i>38.55 LH-?, RH-ana</i>
	1 Rear lower bumper cover.	157.50 <i>?x</i>
	1 Set rear lower engine cover clips.	50.00 <i>?x</i>
	2 Rear bumper sensors. @\$252/-	504.00 <i>TV</i>
		-----
		7884.50
	Less 5%	394.22
		-----
Labour		7490.27
	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, left rear panel, rt rear panel, renew rear boot, rear support panel, rear lights, rear bumper and assembly.	900.00 <i>700</i>
	To respray damaged parts.	980.00 <i>700</i>
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	180.00 <i>60</i>
	To remove rear electronics to facilitate repairs and assembly.	150.00 <i>40</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	80.00 <i>40</i>
	To check and reset ECU.	150.00 <i>120</i>
		-----
		9930.27
		=====

Pirelli 225/55R17  
WBAXG12030DX54075  
70293

Tan Jiah 97495749  
-wp

20/11/17 @ 1115

sw @ lkkanto.com

5 days

Lump sum

Reborn after repair



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo  
14<sup>th</sup> November 2017

TP2  
SUPPLEMENTARY

SKK 3189 G BMW 520i

Spare Parts	1	Sensor wire for smart opener (top)
	1	Sensor wire for smart opener (bottom)
	1	Control unit smart opener.

	S\$
	dis 49.50 -
	dis 49.50 -
	dis 457.45 -
	-----
	556.45
Less 5%	(27.82)
	-----
	528.63
	=====

Parts: 4107.85 (incl. supp.)  
- 5%: (205.39)  
-----  
3902.46  
labour: 1660.00  
-----  
5562.46  
- 20%: (1112.49)  
-----  
4449.96

L11: 4450






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021822/T1vbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2017	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8046Z	Veh. Inspected	SKK 3189G	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010618MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	15/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W 520I	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAXG12030DX54075	Colour	BLACK	
Odometer	70624	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/11/2017	Inspection Date	20/11/2017	
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3189G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT	BENT	1,653.30	1,653.30
1	REAR BOOT LOGO	NECESSARY	76.80	76.80
1	REAR BOOT '520I' EMBLEM	NECESSARY	66.05	66.05
1	REAR BOOT LOCK	NOT NECESSARY	445.35	-
1	REAR BOOT RUBBER	NOT NECESSARY	142.25	-
1	SET REAR BOOT INNER GARNISH CLIPS	NOT NECESSARY	60.00	-
1	REAR SUPPORT PANEL	TO REPAIR SEE LABOUR	871.30	-
1	REAR PANEL INNER GARNISH	NOT NECESSARY	130.00	-
1	RT REAR TAIL LIGHT	NOT NECESSARY	572.25	-
1	REAR BUMPER	DEFORMED	1,631.40	1,631.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	696.80	-
1	REAR BUMPER FOAM	NOT NECESSARY	78.50	-
2	REAR BUMPER BRACKETS @\$151.65	NOT NECESSARY	303.30	-
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
2	REAR BUMPER SIDE RETAINERS @\$141.65	NOT NECESSARY	283.30	-
1	REAR BUMPER TOW COVER	DEFORMED	25.30	25.30
2	REAR BUMPER REFLECTORS @\$38.55	N/S NOT NECESSARY / O/S CRACKED	77.10	38.55
1	REAR LOWER BUMPER COVER	NOT NECESSARY	157.50	-
1	SET REAR LOWER ENGINE COVER CLIPS	NOT NECESSARY	50.00	-
2	REAR BUMPER SENSORS @\$252.00	NOT NECESSARY	504.00	-
1	SENSOR WIRE FOR SMART OPENER (TOP) (ADDITIONAL)	DISTORTED	49.50	49.50
1	SENSOR WIRE FOR SMART OPENER (BOTTOM) (ADDITIONAL)	DISTORTED	49.50	49.50
1	CONTROL UNIT SMART OPENER (ADDITIONAL)	DISTORTED	457.45	457.45
	LESS 5% DISCOUNT		-422.05	-205.39
			8,018.90	3,902.46

Report Ref No. CS/FC117021822/T1vbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO KNOCK, STRAIGHTEN REAR INNER PANEL, REAR LOWER PANEL, REAR SIDE PANEL, REAR FLOOR BOARD, REAR SPARE WHEEL BASE, LEFT REAR PANEL, RT REAR PANEL, RENEW REAR BOOT, REAR SUPPORT PANEL, REAR LIGHTS, REAR BUMPER AND ASSEMBLY. INCLUSIVE OF THE REPAIR OF REAR SUPPORT PANEL.		900.00	700.00
	TO RESPRAY DAMAGED PARTS.		980.00	700.00
	TO REMOVE REAR GARNISHES, CARPETS, UPHOLSTERY TO FACILITATE REPAIRS AND ASSEMBLY.		180.00	60.00
	TO REMOVE REAR ELECTRONICS TO FACILITATE REPAIRS AND ASSEMBLY.		150.00	40.00
	TO RESEAL JOINTS, REINSULATE, ANTI RUST PANELS AND ASSEMBLY.		80.00	40.00
	TO CHECK AND RESET ECU.		150.00	120.00
			2,440.00	1,660.00
	<b>GRAND TOTAL</b>		<b>10,458.90</b>	<b>5,562.46</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,450.00</b>

Report Ref No. CS/FCI17021822/T1vbe2

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.