

ASS: RES BY:

REF: CS/FCI/17021835 / Grbnz Special Instruction

Surveyor

GR

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of

FCI

Date/Time: 9.30am @ 15/11/17

Estimated Cost:

Bill to:

OD: TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STR 6584E

Insured: SHA 70994

at Workshop m/s

Kah Motor

Tel: 6514 5687

of

15 Ubi Road 4

Policy No:

Claim No: D17010580MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

21.11.2017 @ morning

H.O.D. Endorsement

Date/Time: 9.39am @ 15/11/17

Person Contacted:

Faiz

Vehicle IN: OUT

Date/Time	Action/Instruction (✓) Estimate
	STR 6584E - X
	SHA 70994 - CS/FCI/16007898 / Kah 302 - D.O.A.: 26/04/2016
	Sent preli to Serene
	Confirmed \$3628.76, 4 days
	Red: \$1231.70, 25%.

Xnl

REF: FCL

ASSIGNMENT

Form Date: 21.11.2017
Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SLR 6584E

at Workshop no. Kah Motor

at 15 Ubi Rd 4

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

New

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value

IDAO Accident Report: Consistent? : Yes or No

IGIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date Time Action / Instruction

Gen No SLR 6584E Yr Regn 23 Aug 2017

Type: M / G / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make

Honda HRV

1496

Colour

Black

A/C Insured / Std / NI / NA

So. Reading

5258

T/Prior Insured / Std / NI / NA

Eng No

C.No

JHMRU1810GX202878

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In / Out / Jammed / Leaked / Burnt or

Brake: In / Out / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / J/Rim or

Tyre Size

F:

215 / 60R16

R:

11

BS / DUX / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

9

mm

R/Bal

9

mm

L/Bal

9

mm

L/Bal

9

mm

D.O.A.

D.O.A.

21-11-17

Survey held at:

W/S

10AM

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

O/S rear

The ~~Chassis~~ Chassis frame / Body Structure affected due to collision

RECEIVED 15 DEC 2017

Date Time File Pass to:



Prel. Report

typist



Final Report

Date Time File Return to:

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee

Transport

135

50

50

24

Add Fee:



Site Insd \$



Interd \$



Repd \$



Week end \$

Report Format

7P 76)

Lump Sum / IB

3628.76)

259



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021835/Grb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7099U	Veh. Inspected	SLR 6584E
Policy No.		Coverage (\$)	0.00
Claim No.	D17010580MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	15/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/11/2017	Inspection Date
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010580MESH

Our Ref: CS/FCI17021835/Grb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 6584E .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/11/2017 at the premises of M/s KAH MOTOR CO. SDN BHD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,860.48</u> .
Revised Estimate Amount	: S\$ <u>3,628.78</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s rear portion.



Yours faithfully

XING GUO QIANG
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-11-2017	Our Ref No. D17010580MFSH
Accident Date	11-11-2017	Claim Type. Third Party
Insured Vehicle	SHA7099U	Third Party Vehicle. SLR6584E
Survey Location	15 UBI ROAD 4	
Contact Person.	TW LIEW	
Contact No.	65145687/ 0	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230182)



PRI Documents



Close X

PRI Header Details

Claim No	D17010580MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KAH MOTC
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : TW LIEW)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 0 , Phone: 65145687 , Fax: 67480770 EmailId: TWLIEW@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7099U	TP Vehicle No	SLR6584E
PRI Recieved Date	14-11-2017 04:21:58 PM	Surveyor Appointed Date	15-11-2017 09:29:09 AM	Surveyor Accept Date	15-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	15-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Janice Lee (LKKAUTO)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Wednesday, December 13, 2017 4:55 PM
To: Guo Qiang (LKKAUTO)
Cc: SUR
Subject: Pre-Invoice Of Vehicle No: SLR6584E For Finalising
Attachments: 2003_001.pdf

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLR6584E
Final Repair Costs (include GST) \$3,882.75
Repair Period*(Working Day) 04
*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong
Contact No: 81006303 HP
KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
15 Ubi Road 4 Singapore 408610
Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

From: Lim Chou Siong
Sent: Thursday, 7 December, 2017 8:25 AM
To: 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>
Cc: 'sur@lkkauto.com' <sur@lkkauto.com>
Subject: Pre-Invoice Of Vehicle No: SLR6584E For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLR6584E

Final Repair Costs (include GST) \$3,882.75

Repair Period*(Working Day) 04

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

From: Lim Chou Siong

Sent: Saturday, 25 November, 2017 12:58 PM

To: 'guoqiang@lkkauto.com' <guoqiang@lkkauto.com>

Cc: 'sur@lkkauto.com' <sur@lkkauto.com>; Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: Pre-Invoice Of Vehicle No: SLR6584E For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLR6584E

Final Repair Costs (include GST) \$3,882.75

Repair Period*(Working Day) 04

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

From: Printer Service

Sent: Saturday, 25 November, 2017 12:58 PM

To: Lim Chou Siong <cslim@honda.com.sg>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Enquire Transfer Fee

Vehicle Details			
Vehicle No.	SLR6584E		
Vehicle Type	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1	No Attachment		
Vehicle Scheme	Normal		
Vehicle Make	HONDA		
Vehicle Model	HRV 1.5 DX CVT		
Chassis No.	JHMRU1810GX202878		
Propellant	Petrol		
Engine No.	L15B4532878		
Engine Capacity	1496 cc		
Maximum Power Output	96.0 kW (128 bhp)		
Maximum Laden Weight	1760 kg		
Unladen Weight	1185 kg		
Year Of Manufacture	2017		
Original Registration Date	23 Aug 2017		
Lifespan Expiry Date	-		
COE Category	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium	\$46,778.00		
COE Expiry Date	22 Aug 2027		
Road Tax Expiry Date	22 Feb 2018		
PARF Eligibility Expiry Date	22 Aug 2027		
Inspection Due Date	22 Aug 2020		
Intended Transfer Date	22 Nov 2018		
CO2 Emission	129.00 (g/km)		
CEVS Rebate Utilised Amount	\$5,000.00		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 23 Feb 2018 to 22 Aug 2018)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLR6584E
Chassis No : JHMRU1810GX202878
Model : HRV DX-SIN CVT YM 2016
Owner's Name : LIM TECK KENG ADELIN
Ins Policy No. :
Date of Accident : 11/11/2017

Document No. : SQT17004645 Page 1
Date : 13. Nov 2017
Customer No. : WZF002
Svc Advisor : LIEW THYE WEI
Engine No : L15B4532878
Date | Time : 13. Nov 2017 2:09:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM TECK KENG ADELIN OWNER INSURER: TOKIO MARINE INS. ACC DATE: 11/11/17 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL TP VEH: SHA7099U						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	Sum Ext. Service				180.00	12.60	192.60
74475-T7A-N00	X STRAKER.RR. X <i>MC</i> <i>3 NN</i>	1	12.90	25	9.67	0.68	10.35
74552-T7A-010	X FENDERR.RR INNER X	1	90.40	25	67.80	4.75	72.55
91501-T2A-003	/ CLIPINNER FENDER <i>MC</i>	3	0.40	25	0.90	0.06	0.96
91501-TR0-003	/ CLIPINNER FENDER	4	2.30	25	6.90	0.48	7.38
74410-T7B-003	/ PROTECTOR.RR.WHEEL ARCH <i>cut</i>	1	172.10	25	129.07	9.03	138.10
04717-T7A-000ZZ	/ FACER.RR.BUMPER CORNER <i>MC</i>	1	92.20	25	69.15	4.84	73.99
71501-T7B-000	/ FACE RR.BUMPER <i>cut</i>	1	762.70	25 <i>341.71</i>	572.02	40.04	612.06
71593-T7A-000	/ SPACERR.RR.BUMPER SIDE <i>MC</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	/ CLIPBUMPER <i>MC</i>	8	2.00	25	12.00	0.84	12.84
42700-T7A-J91	/ DISKALUMINIUM WHEEL <i>cut</i>	1	765.80	25	574.35	40.20	614.55
	Sum Item				1450.48	101.52	1,552.00
BOSUN	/ SUNDRIES <i>MC</i>	1	30.00 <i>10</i>		30.00	2.10	32.10
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	280.00 <i>150</i>		280.00	19.60	299.60
BKFE22K	STRAIGHTEN ALIGN RR R FENDER. REPLACE DAMAGED <i>parts</i>	1	1400.00 <i>1120</i>		1400.00	98.00	1498.00



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLR6584E
Chassis No : JHMRU1810GX202878
Model : HRV DX-SIN CVT YM 2016
Owner's Name : LIM TECK KENG ADELIN
Ins Policy No. :
Date of Accident : 11/11/2017

Document No. : SQT17004645 Page 2
Date : 13. Nov 2017
Customer No. : WZF002
Svc Advisor : LIEW THYE WEI
Engine No : L15B4532878
Date | Time : 13. Nov 2017 2:09:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1400.00	900	1400.00	98.00	1498.00
Sum Labor					3230.00	226.10	3,456.10

Survey By Guo Qianf - 82880282

Date & Time 21/11/17

Excess _____

Status _____

Signature _____

Total Amount 4,860.48 340.22 5,200.70

Total (Inclusive of GST) 5,200.70

before paint photos.
4 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/11/2017 2:56:35 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Attn: Guo Qiang (L.L.L.L.) Company Ref. No.: S60FC1380G
4 days

Customer: WZF002 / FIRST CAPITAL
 Chassis No: JHMRU1810GX202878
 License No: SLR6584E
 Mileage: 5258
 Engine No: L15B4532878

Document No: SVO17073142
 Printed By: TWLIEW
 Order Date: 21. November 2017
 Order Time: 10:21:28 AM
 Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69447) OWNER: LIM TECK KENG ADELIN OWNER INSURER: TOKIO MARINE INS. ACC DATE: 11/11/17 SURVEYED BY: GUO QIANG DATE: 21/11/17 @ 10.15AM REF NO: D17010580MFSH TP INSURER: FIRST CAPITAL TP VEH: SHA7099U						
91501-T2A-003	CLIPINNER FENDER	3	0.40	25	0.90	0.06	0.96
91501-TR0-003	CLIPINNER FENDER	4	2.30	25	6.90	0.48	7.38
74410-T7M-H01	PROTECTORR.RR.WHEEL ARCH	1	172.10	25	129.07	9.03	138.10
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	92.20	25	69.15	4.84	73.99
04716-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
42700-T7A-J91	DISKALUMINIUM WHEEL	1	765.80	25	574.35	40.20	614.55
	SUM PARTS:				1,148.76	80.39	1,229.15
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BA02R	EXT-YJ	1	120.00		120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BMI02D	EXT-YJ	1	150.00		150.00	10.50	160.50
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)						
BKFE22K	EXT-YJ	1	1,120.00		1,120.00	78.40	1,198.40
	STRAIGHTEN ALIGN RR R FENDER. REPLACE DAMAGED PARTS.						
BP02R	EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				2,300.00	161.00	2,461.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				3,628.76	253.99	3,882.75
	Total Payable (SGD)						3,882.75

GST Amount is calculated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021835/Grbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7099U	Veh. Inspected	SLR 6584E	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010580MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	15/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1810GX202878	Colour	BLACK	
Odometer	5258	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	9 mm	
L/H Front Tyre	215/60 R16	DUNLOP	9 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/11/2017	Inspection Date	21/11/2017	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6584E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	STRAKER,RR (SN)	NOT NECESSARY	9.67	-
1	FENDERR.RR INNER (SN)	NOT NECESSARY	67.80	-
3	CLIPINNER FENDER (SN)	NECESSARY	0.90	0.90
4	CLIPINNER FENDER (SN)	NECESSARY	6.90	6.90
1	PROTECTOR,R,RR WHEEL ARCH (SN)	CUT	129.07	129.07
1	FACE,RR BUMPER CORNER (SN)	DEFORMED	69.15	69.15
1	FACE RR BUMPER (SN)	CUT	572.02	347.77
1	SPACERR RR BUMPER SIDE (SN)	NECESSARY	8.62	8.62
8	CLIPBUMPER (SN)	NECESSARY	12.00	12.00
1	DISKALUMINIUM WHEEL (SN)	CUT	574.35	574.35
1	SUNDRIES (SN)	NECESSARY	30.00	10.00
			1,480.48	1,158.76
<u>LABOUR</u>				
	REMOVE & RENEW REVERSE SENSOR-4 PCS.		120.00	120.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		280.00	150.00
	STRAIGHTEN ALIGN RR R FENDER.REPLACE DAMAGED PARTS.		1,400.00	1,120.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P).		1,400.00	900.00
	WHEEL ALIGNMENT X4.		180.00	180.00
			3,380.00	2,470.00
GRAND TOTAL			4,860.48	3,628.76
RECOMMENDED COST OF REPAIRS				3,628.76

Report Ref No. CS/FC117021835/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.