



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving

1 2009 TOYOTA WISH 1.8 (SJV6602P)

Date of Loss

November 10, 2017

Time of Loss

19.00

Loss Description

Please refer to Police report

Comment

Workshop Details

Total Rebate Amount

17006

Nett Loss Amount

\$21,994.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

02/15/2018



Days of work completion *

80



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
SJV6602P

Registration State
SINGAPORE

Mileage
331569

Purchase Date
mm/dd/yyyy

Registration Date *
02/04/2010

Age of Vehicle
7

CATEGORY	Manufacturing Year
POLICY INFORMATION	2009
ASSESSMENT INFORMATION	2009
CATEGORY	Make
POLICY INFORMATION	TOYOTA

CATEGORY Model

POLICY INFORMATION WISH 1.8

ASSESSMENT INFORMATION WISH 1.8X A

CATEGORY Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Chassis No

POLICY INFORMATION ZGE200025625

ASSESSMENT INFORMATION ZGE200025625

CATEGORY Engine No

POLICY INFORMATION 2ZR0473067

ASSESSMENT INFORMATION 2ZR0473067

CATEGORY Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION 1797

POLICY INFORMATION	0
ASSESSMENT INFORMATION	0

CATEGORY Market Value

POLICY INFORMATION	0
ASSESSMENT INFORMATION	39000

Driver Details

CATEGORY	Driver Name
FNOL INFORMATION	KAMSIDIN AHAMADI BIN
POST SURVEY INFORMATION	

CATEGORY	Date of Birth
FNOL INFORMATION	June 19, 1955
POST SURVEY INFORMATION	mm/dd/yyyy 

CATEGORY	Age
FNOL INFORMATION	62

POST SURVEY INFORMATION	
CATEGORY	Occupation
FNOL INFORMATION	Unknown

POST SURVEY INFORMATION	
-------------------------	--



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

11/16/2017

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

900

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

275/45R17

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Spare wheel

Rear Tyre Size

275/45R17



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Discount%

Salvage%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

2

1

Tailgate Emblem Centre

Necessary

0

0

Reviewing



3

1

Rear Windscreen Moulding

Necessary

0

0

Reviewing



4

1

Tailgate Emblem "Valve Matic"

Necessary

0

0

Reviewing





5

1

Tailgate Lock

Damaged

0

0

Reviewing



6

1

Tailgate Inner Trim (Lower)

Cut

0

0

Reviewing



7

1

Tailgate Rubber

Twisted

0

0

Reviewing





8

1

Tailgate Lamp LH

Cracked

0

0

Reviewing



9

1

Tailgate Lamp RH

Serviceable

0

0

0

0

0

Deny



10

1

Tailgate Chrome Garnish

Deformed

0

0

Reviewing



11

1

Rear Lamp Outer LH

Cracked

0

0

Reviewing



12

1

Rear Lamp Outer RH

Serviceable

0

0

0

0

0

Deny



13

1

Rear Bumper

Deformed

0

0

Reviewing



14

10

Rear Bumper Clips

Necessary

0

0

Reviewing



15

1

Rear Bumper Side Retainer LH

Necessary

0

0

Reviewing



16

1

Rear Bumper Side Retainer RH

Necessary

0

0

Reviewing



17

1

Rear Bumper Inner Bracket LH

Necessary

0

0

Reviewing





18

1

Rear Bumper Inner Bracket RH

Necessary

0

0

Reviewing



19

1

Rear Bumper Reflector LH

Serviceable

0

0

0

0

0

Deny



0



20

1

Rear Bumper Reflector RH

Serviceable

0

0

0

0

0



Deny



21

1

Rear Bumper Arm LH

Serviceable

0

0

0

0

0

Deny



22

1

Rear Bumper Arm RH

Serviceable

0

0

0

0

0

Deny



23

1

Rear End Panel

Bent

0

0

Reviewing



24

1

Rear End Panel Top Garnish

Deformed

0

0

Reviewing





25

1

Rear Fender Inner Lower Trim LH

Serviceable

0

0

0

0

0

Deny



26

1

Rear Fender Inner Lower Trim RH

Serviceable

0

0

0

0

0

Deny



27

1

Spare Tyre Panel

Serviceable

Repair

0

0

0

0

0

Deny



28

1

Rear Fender LH

Serviceable

Repair

0

0

0

0

0

Deny



29

1

Rear Fender RH

Serviceable

Repair

0

0

0

0

0

Deny



30

1

Rear Number Plate (SN)

Bent

35

35

Reviewing



31

1

Reverse Sensor (SN)

Shorted

200

200

Reviewing





32

1

Windscreen Sealant (SN)

Necessary

60

60

Reviewing



Labour

Add

Approve

Deny



1

Labour to carry out rear repair

700

Reviewing



2

To check and reconnect all necessary wirings

30

Reviewing



3

To spray painting on rear affected area

600

Reviewing



4

To remove & install all rear bootlid components to faciliate repairs

50

Reviewing



5

To remove & install rear windscreen glass

120

Reviewing



6

To remove & re-install spare compartment trims

50

Reviewing



General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio

Parts & Labour Miscellaneous Summary Add Approve Deny



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount	
\$1,245.00	
CATEGORY	Labour
ESTIMATE	\$1,985.00
REVISED AMOUNT	\$1,550.00
CATEGORY	Spare Parts
ESTIMATE	\$2,920.00
REVISED AMOUNT	\$295.00
CATEGORY	Miscellaneous
ESTIMATE	\$300.00
REVISED AMOUNT	\$300.00
CATEGORY	Excess
ESTIMATE	-\$900.00
REVISED AMOUNT	-\$900.00

