

REF CS3/LCN7021848/Sb2v

ASSIGNMENT (Officer)

Date/Time 15/11/17 @ 11:06am

ASS. REC BY

Minister

Sebastian
Chin Lee Ying

LCR

Estimated Cost

9E 7682S

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured

9423 5006

To Inspect Vehicle No

SKW 6217B

at Workshop no

Eng Hup Auto parts

of Blk No. 1, 387 J Woodlands Road, 677954

Policy No

0999995059

Claim No

425858471386

Excess

D.O.A. 9/11/2017

Sum Insured

Make of Vehl

(Client's Record)

H.O.D. Endorsement

Vehicle ☒ OUT

CA / REV / REP. / REV 24 HRS

'wp'

Ah Soon

Date/Time 12:09pm @ 15/11/17

Person Contacted

Date/Time

Action/Instruction (X) Estimate

81E7682S - X

SKW 6217B - CS3 / AIG 7021591 / Sb - D.O.A. : 9/11/2017

Diagnosis: 16/11/2017

After repair: 1/12/2017

DAR

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop no:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKW6217B.

Yr Regn: 2/11/2006

Type: MC: r / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic

CC 1595

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 158257

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMFD 462065200444

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Five Stone

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/11/2017

D.O.I. 13/11/17

Survey held at

Eng Hup

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 30 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

DAR

Lump Sum / I.B.I: (\$)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

3 S-PS \$1

1 Photos:

3 Other:



TOTAL

180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLE7682S AND SKW6217B ON 9/11/2017**

From: Chin, Lee-Ying
To: 'assignments', 'Admin A'
Cc: Fong, Andy-SY
Sent: Wednesday, 15 November, 2017 11:06:55 AM
Attachments:  Fax1508.tif  FaxD08.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

K. K. CHENG & CO

Advocates and Solicitors
101 Upper Cross Street #05-21
People's Park Centre
Singapore 058357
Tel: 6227 1272 Fax: 6227 5563

Our Ref: EHA/SKW 6217B
Your Ref: SLE 7682S
(Please quote our reference number when replying)

13 November 2017

AIG ASIA
Singapore

By fax only: 6835-7416

Attention: Motor Claims Department

Dear Sirs

NOTICE OF ACCIDENT
Claimant: LEE SIEW BEE

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or before 1st April 2016 ["Protocol"]

We refer to your email dated 13 November 2017.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 13 November 2017.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 13 November 2017.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:

Name of Workshop	:	Eng Hup Auto Parts Accessories Co
Address	:	Blk 1 No. 387J Woodlands Road Yew Tee Industrial Estate Singapore 677954
Contact person	:	Ah Soon
Telephone No.	:	94235006

Yours faithfully

CHENG KIM KUAN

cc Workshop (REF: SKW 6217B)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8535H
Vehicle Details	
Vehicle No.:	SKW6217B
Vehicle to be Exported:	No
Intended De-registration Date:	25 May 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L VTI AUTO
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	R16A11000517
Chassis No.:	JHMFD46206S200444
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$18,696.00
Original Registration Date:	02 Nov 2006
First Registration Date:	02 Nov 2006
Transfer Count:	2
Actual ARF Paid:	\$20,566.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,821.00
COE Rebate Amount:	\$17,741.00
Total Rebate Amount:	\$17,741.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/11/2017 13:34
Date Of Accident 09/11/2017 10:30
Exact Location Of Accident BKE TOWARDS PIE (CHANGI)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW6217B
Insured/Policyholder
Name Of Registered Owner LEE SIEW BEE
NRIC No S7218535H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-94512621
Alternative Phone No OFFICE-94512621

Vehicle Particulars

Manufacturer HONDA
Model CIVIC-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number 5075487281-02
Cover Note Number

Driver

Name of Driver LEE SIEW BEE
NRIC No S7218535H
Date Of Birth 22/04/1972
Occupation INDOOR
Date Of Driving Pass 20/02/1995
Driving Experience 22 YEARS AND 8 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-94512621
Fax Number
Contact Number OFFICE-94512621
Email Address NOEMAIL

Address 451 CHOA CHU KANG AVE 4
 #03-147
 Postcode S680451
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG BKE GOING TOWARDS PIE(CHANGI) ON THE 3RD LANE, THE VEHICLE INFRONT OF ME BRAKE AND I FOLLOWED TO BRAKE AND STOPPED, ALL OF A SUDDEN, I FELT A GREAT IMPACT COMING FROM BEHIND MY VEHICLE AND MY VEHICLE WAS BEING PUSHED FORWARD AND THUS THE FRONT PORTION OF MY VEHICLE HIT ONTO THE REAR PORTION OF THE VEHICLE INFRONT OF ME. I THEN ALIGHTED TO CHECK AND REALISED THAT IT WAS A CHAIN COLLISION INVOLVING 4 VEHICLES (INCLUDING MINE). I AM FEELING A STIFF N AND BODY PAIN, I WILL BE CONSULTING A DOCTOR LATER. MY VEHICLE SUSTAINED SERIOUS DAMAGE TO THE REAR PORTION AS COMPARED TO THE FRONT PORTION. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA1844C
 Vehicle Make/Model/Colour HONDA
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name

- Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBD39U

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLE7682S

Vehicle Make/Model/Colour

HONDA

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten signature: *E. H. Lee*

1DAC BUKIT BATOK (VAC)

511 Bukit Batok St 23

Singapore 659545

Tel: 6567 9427 / 6560 3312

Fax: 6569 0722

Email: vacbb@singnet.com.sg

DECLARATION

I/We declare the foregoing particulars are true in every respect.

9 NOV 2017

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

DAC BUKIT BATOK (VAC)

511 Bukit Batok St 23

Singapore 659545

Tel: 6567 9427 / 6560 3312

Fax: 6569 0722

Email: vacbb@singnet.com.sg

- 9 NOV 2017

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ven SKW 6217 B

DOI 13.1.17

1. Rear bumper - Bu
2. Rear bootlid - Bu
3. Rear fender - Bu
4. Front bonnet - Bt
5. Front bumper - dm

Rear End

1. Rear light assembly x2 - br
2. Bootlid reflector lamp x2 br
3. Reverse sensors x1 dm
4. Rear bumper clip set - nec
5. Rear bumper bracket - dm
6. Rear bumper side retainers x2 dm
7. Rear panel - di
8. Rear panel lock - dm
9. Rear panel garnish - dm
10. Rear panel garnish clips - nec
11. Rear bootlid H emblem - nec
12. Rear bootlid CIVIC emblem - nec
13. Rear bootlid I-VTEC emblem - nec
14. Rear bootlid mechanism lock - dm
15. Rear bootlid hinge x2 bt
16. Spare wheel panel di
17. Rear panel top garnish di
18. Rear bootlid lock dm

SKW 6217 B

DOL 13.1.17

Front End

- | | |
|--------------------------------|-------|
| 1. Front bumper reinforcement | - di |
| 2 Front windscreen - | cr |
| 3 Front headlight assy X 2 | br |
| 4 Front grille - | br |
| 5 Front grille clips set - | nec |
| 6. Front windscreen moulding | - nec |
| 7. Front bumper side retainers | - nec |
| 8. | |

Painting 6 panels

labour 7 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

























PRI























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018 Edit Reg		15 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case







































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	LEE SIEW BEE, ID: S7218535H								
Vehicle Reg. No.:	SKW6217B	Date of Loss:	09/11/2017 10:00 - :59 [132 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4258584713SG	Policy/Cover Note No.:	0999995059 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLE76825	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Hup Auto Parts Accessories Co (HQ) BLK 1, NO. 387J WOODLANDS ROAD, YEW TEE INDUSTRIAL ESTATE, 677954 Woodlands - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 30/05/2018]								
Claimant's Solicitor:	K. K. Cheng & Co								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (21/05/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents




*SKW6217B (4258584713SG)
[SLE7682S]
TP
LEE SIEW BEE
Nov 9 2017 10:00AM
[LCRF PTE LTD]
Eng Hup Auto Parts Accessories Co

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
26	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
27	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
28	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
29	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
30	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
31	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
32	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
33	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
34	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
35	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
36	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>
37	25/05/18 16:07	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/05/18 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	25/05/18 16:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	25/05/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/05/18 16:22	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR17021848/SBE2

Date: 31/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995059
 Claimant Vehicle No: SKW6217B Insured Vehicle No: SLE7682S
 Date of Loss: 09/11/2017 Nature of Claim: TP Claim No: 4258584713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW6217B Engine No: R16A11000517
 Make & Model: HONDA CIVIC, 1.6 (A) Chassis No: JHMFD46206S200444
 Reg. Date: 02/11/2006 (Man. Year: 2006) Odometer: 158257 km
 Colour: Blue
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Firestone 6 mm Rear Left Side: Firestone 6 mm
 Front Right Side: Firestone 6 mm Rear Right Side: Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/11/2017
 Date Inspected: 13/11/2017 Inspected At: Eng Hup Auto Parts Accessories Co (HQ)
 BLK 1, NO. 387J WOODLANDS ROAD,
 YEW TEE INDUSTRIAL ESTATE
 Singapore 677954

Estimated Period of Repair: 7.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	0.00 F	*- F
2	1		*REAR BOOTLID	Buckled	0.00 F	*- F
3	1		*REAR FENDER	Buckled	0.00 F	*- F
4	1		*FRONT BONNET	Bent	0.00 F	*- F
5	1		*FRONT BUMPER	Damaged	0.00 F	*- F
6	2		*REAR LIGHT ASSEMBLY	Broken	0.00 F	*- F
7	2		*BOOTLID REFLECTOR LAMP	Broken	0.00 F	*- F
8	1		*REVERSE SENSORS	Damaged	0.00 F	*- F
9	1		*SET REAR BUMPER CLIP	Necessary	0.00 F	*- F
10	1		*REAR BUMPER BRACKET	Damaged	0.00 F	*- F
11	2		*REAR BUMPER SIDE RETAINERS	Damaged	0.00 F	*- F
12	1		*REAR PANEL	Distorted	0.00 F	*- F
13	1		*REAR PANEL LOCK	Damaged	0.00 F	*- F
14	1		*REAR PANEL GARNISH	Damaged	0.00 F	*- F
15	1		*REAR PANEL GARNISH CLIPS	Necessary	0.00 F	*- F
16	1		*REAR BOOTLID H EMBLEM	Necessary	0.00 F	*- F
17	1		*REAR BOOTLID CIVIC EMBLEM	Necessary	0.00 F	*- F
18	1		*REAR BOOTLID I-VTEC EMBLEM	Necessary	0.00 F	*- F
19	1		*REAR BOOTLID MECHANISM LOCK	Damaged	0.00 F	*- F
20	2		*REAR BOOTLID HINGE	Bent	0.00 F	*- F
21	1		*SPARE WHEEL PANEL	Distorted	0.00 F	*- F
22	1		*REAR PANEL TOP GARNISH	Distorted	0.00 F	*- F
23	1		*REAR BOOTLID LOCK	Damaged	0.00 F	*- F
24	1		*FRONT BUMPER REINFORCEMENT	Distorted	0.00 F	*- F
25	1		*FRONT WINDSCREEN	Cracked	0.00 F	*- F
26	2		*FRONT HEADLIGHT ASSY	Broken	0.00 F	*- F
27	1		*FRONT GRILLE	Broken	0.00 F	*- F
28	1		*SET FRONT GRILLE CLIPS	Necessary	0.00 F	*- F
29	1		*FRONT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
30	1		*FRONT BUMPER SIDE RETAINERS	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >