

ASS. REC. BY

REF CS/MSG17021875/T19602

Special Insurance

By/To/At

Taufik

ASSIGNMENT (Office)

Menmen

From (Person)

Monica Chung

MSG

Date/Time 16/11/17 @ 9:31am

Estimated Cost

Bill to

OD / HP / WS / TP RLS / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STD 8645Z

Insured:

FBJ 428Z

at Workshop/ins:

Ethos Group

Tel:

9624 8656

of 30 Bukit Batok Crescent

Policy No MSD/VMS/16-355295-CA

Claim No MSC/V/17-001768

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A 11/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time 9:37am @ 16/11/17

Person Contacted

Shah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

STD 8645Z-X

FBJ 428Z-X

REF: MS19

ASSIGNMENT

From: Date: 16/11/17

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 86452

at Workshop m/s Ethoz Group
of 30 Bukit Batok Crescent, 658075

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Shah

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

1wp

Date: Person Contacted:

Vehicle: IN / OUT

Shah

Veh No: SLD 86452 Yr Regn: 2016 June
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1496

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

29310

T/Radio: Insured / Std / NI / NA

Eng/No:

JM 6BM42A860343413.

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16/11/2017

Survey held at

Ethoz Bukit Khat

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/11/17 REV preli in merimen.

5/12/17 confirmed P/P \$ 4535.92 with Shah.
(Red: 1273.24, 22%).

RECEIVED 03 DEC 2017

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

)

TOTAL

200
10
210

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format: TP

Lump Sum / ☒ B: (\$ 4535.92)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17021875/T1gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBJ 428Z	Veh. Inspected	SLD 8645Z
Policy No.	MSD/VMS/16-355295-CA	Coverage (\$)	0.00
Claim No.	MSC/V/17-001768	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	16/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/11/2017	Inspection Date	16/11/2017
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2017		16 Nov 2017 09:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM TONG TECK, ID: S1131374D, Tel: +6590259018, Email: NOEMAIL		
Main Claimant:	ETHOZCAB LTD, Co. Reg. No.: 201613943G		
Vehicle Reg. No.:	SLD8645Z	Date of Loss:	11/11/2017 18:00 - :59
Claim Type:	TP / MSC/V/17-001768	Policy/Cover Note No.:	MSD/VMS/16-355295-CA (TP, Fire & Theft) Coverage: 13/12/2016 - 12/12/2017
Vehicle Reg. No. (Insured):	FBJ428Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/11/2017]		
Driver/Custodian (Insured):	LIM TONG TECK (62 / Male), NRIC: S1131374D, Tel: +6590259018		
Adj Asg. Remarks:	CAR IN WORKSHOP. Pls call Shah @ 96248656		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Nov 2017

Preliminary Advice

Insured Vehicle No : FBJ428Z
TP Vehicle No : SLD8645Z
Make : MAZDA 3
Date of Inspection : 16/11/2017
Inspection At : ETHOZ GROUP LTD (HQ)
30 BUKIT BATOK CRESCENT
SINGAPORE 658075

Accident Date : 11/11/2017
Assignment Date : 16/11/2017
Est. Duration of Repair : 6.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,809.16
Revised Amount	:S\$	4,423.76
Check Items (Estimated)	:S\$	335.36
Total	:S\$	4,759.12

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2017 10:15
Date Of Accident	11/11/2017 18:20
Exact Location Of Accident	CTE AMK TWDS CITY 400M BEFORE BALESTIER EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8645Z
Insured/Policyholder	
Name Of Registered Owner	ETHOZCAB LTD
Co Reg No	201613943G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66547777
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D17MTRENT000050
Cover Note Number	

Driver

Name of Driver	KHOO THOW SUI
NRIC No	S0105973D
Date Of Birth	30/10/1952
Occupation	OUTDOOR
Date Of Driving Pass	02/10/1974
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90903431
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 340 HOUGANG AVE 7 #03-431
Postcode	530340
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO ATTACH NOTICE OF COMPLIANCE & SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ428Z
Vehicle Make/Model/Colour	MOTOR CYCLE
Details Of Properties	
Name of Driver	LIM TONG TECK
NRIC/Passport Number	S1131374D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	TIM TIMOO
Phone Number	93372745

Email Address

DETAILS OF INJURED PERSON 1

Name

LIM TONG TECK

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBJ428Z

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

13/11/2017

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/11/2017, I was driving Vehicle (SLD8645Z) with one passenger on board from Woodlands to Jalan Bahagia and traffic was heavy. While traveling along CTE towards City on the 2nd lane, the traffic moved very slowly so I on my Signal change to 3rd lane before the Tuas exit. After driving for a distance about 400m before the Balestier exit, suddenly I heard a loud bang sound on my rear right door, I immediately stopped and alighted to check and I saw one motor cycle (FBJ428Z) was fell next to my car on my right (2nd lane) and damaged onto my rear right door & driver door portion. Both party exchange particulars

Accident happened Time : 6:20 pm

[Signature]

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE** WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

13/11/2017

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 16/11/2017

To : MSIG INSURANCE (SINGAPORE) PTE.LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000050

Accident Date : 11/11/2017

Vehicle No : SLD-8645-Z

Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

- 1 FRONT DOOR RH
- 1 FRONT DOOR FRAME STICKER SET RH
- 1 REAR DOOR RH
- 1 REAR DOOR FRAME STICKER SET RH
- 1 REAR DOOR OUTER GLASS MOULDING RH
- 1 REAR DOOR WINDOW REGULATOR RH
- 1 REAR DOOR WEATHERSTRIP RH
- 1 REAR SPORTS RIM RH
- 1 REAR FENDER RH

RESTORE

1,143.20 del
64.70 ner
999.40 bt
84.20 ner
140.20 ? de
279.00 ? X m
120.70 ner
980.00 cut
NPA

Date : 16/11/2017

To : MSIG INSURANCE (SINGAPORE) PTE.LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000050

Accident Date : 11/11/2017

Vehicle No : SLD-8645-Z

Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER	RESTORE	
1	ROCKER PANEL RH	RESTORE	
	Sub Total	3811.40	
	Discount 20% On Parts	(762.28)	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,000.00	700/
	TO RESPRAY AFFECTED AREAS	1,000.00	800/
	TO REMOVE AND TRANSFER BOTH RH DOOR COMPONENTS	200.00	120/
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30/
	TO REMOVE AND BALANCE REAR TYRE RH	80.00	30/

Date : 16/11/2017

To : MSIG INSURANCE (SINGAPORE) PTE.LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000050

Accident Date : 11/11/2017

Vehicle No : SLD-8645-Z

Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RUST PROOFING	50.00	30/
	Sub Total	2380.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5,429.12

Remarks:

SUB TOTAL

GST 7.0 % 380.04

TOTAL 5,809.16

Surveyor's name:

Tanpin 97195749

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

16/11/2017 1450

6 days.
wp.
Resurvey before paint
sur e lkkauto.com

22/11/17

PAGE : 3

Date : 04/12/2017
To : MSIG INSURANCE (SINGAPORE) PTE.LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000050 Accident Date : 11/11/2017
Vehicle No : SLD-8645-Z Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT DOOR RH	1143.20	1143.20
1	FRONT DOOR FRAME STICKER SET RH	64.70	64.70
1	REAR DOOR RH	999.40	999.40
1	REAR DOOR FRAME STICKER SET RH	84.20	84.20
1	REAR DOOR OUTER GLASS MOULDING RH	140.20	140.20
1	REAR DOOR WINDOW REGULATOR RH	279.00	0.00
1	REAR DOOR WEATHERSTRIP RH	120.70	120.70
1	REAR SPORTS RIM RH	980.00	980.00
1	REAR FENDER RH RESTORE	0.00	0.00
1	REAR BUMPER RESTORE	0.00	0.00
1	ROCKER PANEL RH RESTORE	0.00	0.00



Date : 04/12/2017
To : MSIG INSURANCE (SINGAPORE) PTE.LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000050 Accident Date : 11/11/2017
Vehicle No : SLD-8645-Z Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	3811.40	3532.40
	Discount 20% On Parts	(0.00)	(762.28)
			(706.48)
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1000.00	700.00
	TO RESPRAY AFFECTED AREAS	1000.00	800.00
	TO REMOVE AND TRANSFER BOTH RH DOOR COMPONENTS	200.00	120.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.00
	TO REMOVE AND BALANCE REAR TYRE RH	80.00	30.00
	RUST PROOFING	50.00	30.00

PAGE : 2



Date : 04/12/2017
To : MSIG INSURANCE (SINGAPORE) PTE.LTD

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000050 Accident Date : 11/11/2017
Vehicle No : SLD-8645-Z Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 2,000.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
Sub Total		2380.00	1710.00
Sub Total		5,429.12	4,535.92
GST 7.0 %		380.04	317.51
Total		5,809.16	4,853.43

Surveyor Name : TAUFIK - LKK

Date & Time : 16/11/2017 2:50:00 PM

Salamatshahh

CLAIM DEPARTMENT

DID : 66547519

FAX :

PAGE: 3

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2017		16 Nov 2017 09:34 Edit Adj Rpt	S\$4,535.92 Edit Estimates	S\$4,535.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

LIM TONG TECK, ID: S1131374D, Tel: +6590259018, Email: NOEMAIL

Main Claimant:

ETHOZCAB LTD, Co. Reg. No.: 201613943G

Vehicle Reg. No.:

SLD8645Z

Date of Loss:

11/11/2017 18:00 - :59

Claim Type:

TP / MSC/V/17-001768

Policy/Cover Note No.:

MSD/VMS/16-355295-CA (TP, Fire & Theft)
Coverage: 13/12/2016 - 12/12/2017

Vehicle Reg. No. (Insured):

FBJ428Z

Policy No. (Claimant):

Excess:

Repairer:

Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 16/12/2017]

Driver/Custodian (Insured):

LIM TONG TECK (62 / Male), NRIC: S1131374D, Tel: +6590259018

Adj Asg. Remarks:

CAR IN WORKSHOP. Pls call Shah @ 96248656

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD8645Z (MSC/V/17-001768)

[FBJ428Z]

TP

ETHOZCAB LTD

Nov 11 2017 6:00PM

[LIM TONG TECK]

Ethoz Group Ltd

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	16/11/17 09:35	Accident Statement From: SC - Reg. No: FBJ428Z, Claimant: LIM TONG TECK		Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	17/11/17 14:49	Adjuster Immediate Advice		Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
2	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
3	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
4	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
5	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
6	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
7	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
8	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
9	17/11/17 14:34	General View		Load JPG	<input checked="" type="checkbox"/>			
10	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
11	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
12	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
13	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
14	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
15	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
16	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
17	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
18	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
19	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
20	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
21	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
22	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
23	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
24	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
25	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
26	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
27	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
28	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
29	17/11/17 14:35	General View		Load JPG	<input checked="" type="checkbox"/>			
30	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>			
31	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>			
32	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>			
33	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>			

34	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
35	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
36	05/12/17 12:53	RE-SURVEY PHOTO		Load JPG	<input checked="" type="checkbox"/>
Documentation					
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		1 per page	<input checked="" type="checkbox"/>
1	16/11/17 09:35	PRI FROM ETHOZ & TP GIA REPORT		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Load PDF	
1	06/12/17 12:34	Workshop Invoice		Thumbnail	Print
				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021875/T1GBE2

Date: 06/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/16-355295-CA
Claimant Vehicle No :	SLD8645Z	Insured Vehicle No :	FBJ428Z
Date of Loss:	11/11/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001768

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8645Z	Engine No:	P520369347
Make & Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Chassis No:	JM6BM42A8G0343413
Reg. Date:	29/06/2016 (Man. Year: 2016)	Odometer:	79340 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,049.12	2,825.92	223.20	7.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,710.00	670.00	28.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,429.12	4,535.92	893.20	16.45
+ GST 7.00/7.00% (\$\$)	380.04	317.51	62.53	16.45
Nett Amount (\$\$)	5,809.16	4,853.43	955.73	16.45

INSPECTION

Date of Assignment:	16/11/2017		
Date Inspected:	16/11/2017	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2017)
Parts: 143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD8645Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,143.20 FL	*1,143.20 FL
2	1		*SET FRONT DOOR FRAME STICKER RH	Necessary	64.70 FL	*64.70 FL
3	1		*REAR DOOR RH	Bent	999.40 FL	*999.40 FL
4	1		*SET REAR DOOR FRAME STICKER RH	Necessary	84.20 FL	*84.20 FL
5	1		*REAR DOOR OUTER GLASS MOULDING RH	Deformed	140.20 FL	*140.20 FL
6	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	279.00 FL	*- FL
7	1		*REAR SPORT RIM RH	Cut	980.00 FL	*980.00 FL
8	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
10	1		*ROCKER PANEL RH (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR DOOR WEATHERSTRIP RH	Necessary	120.70 FL	*120.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,811.40	3,532.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	762.28	706.48
Total Parts (\$\$)	3,049.12	2,825.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	1,000.00	700.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
3	TO REMOVE AND TRANSFER BOTH RH DOOR COMPONENTS	New	200.00	120.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
5	TO REMOVE AND BALANCE REAR TYRE RH	New	80.00	30.00
6	RUST PROOFING	New	50.00	30.00
Gross Labour Cost (S\$)			2,380.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >