ASS REC EY	EEE CS3/MSG17021881/MI	ber range.
Marinan MA	ASSIGNMENT (Office	-
Merimen Irene Tan		15/11/17 8 4-26pm
Estimated Cost	Billing	12/11/14 6 1 9
OD TP WS/TP RES / OD I	RESTEVATING MVTCS	
To Inspect Vehicle No.	SIM 6685Z	Inned GBF 9722 K
at Workshop mus Sz	e Kana Antomobile	9 201 0070
- Inc to the Wall	K - 2 A # 13-14 . 56 x 044	-0001 1111
Policy No. 28948698	MKC Claim No	
Sum insured	Excess	
Make of Veh		DOA 13/11/2017
(Client's Record	'wp' After	lpm
CA / REV / REP. / REV 24	HRS	N.O.D. Encorrectors.
Date/Time 4.56pm @ 15/	1117 Person Contacted Amhory	Vehicle IX OUT
	ot (X) Estimate	2
	85 <u>Z</u> -×	
OF 1+	22 K - NA İMSG1700928 / F	3-DOA : 5/5/2017
M1247 210 5 6 1	7	
01.1217 219pm Emill to	brene tan thiu marinen	

CHANGE THE PARTY OF THE PARTY O		MSU			
gansgor		ASS	IGNMENT		
		2300	The second secon	2 Yr Regn: 2009	Anc M
From:	Date:				
Estimated Cost:			Type: M.Car / M.Cycle / Bus / Van / L	orry / Taxi / Prime Mov	er/
OD/TP/WS/TF	PRES / OD RES / EVA / INV / MV		Truck / Trailer or		2000
To Inspect Vehicle	e No:	- D	Make: LOYOTHA G	FMITIS CC	2207
at Workshop m/s			Colour SILYED	A/C: Insured / S	
of			Sp.Reading (9300-)	T/Radio: Insured / S	Std / NI / NA
Insured:			Eng/No:	7 _	
Policy No.			C/No: WRO538K)		
Claims No.			Gen. Cond Good / Fair / Poor / Burn		
Sum Insured:	Excess:		Steering: Inorder / Jammed / Leaked		
(Client's Record	d)		Brake: Inorder / Jammed / Leaked		
Make of Veh:			Modi: Nil /(S/Rim / STD A/Rim o	1120	
		· ·	Tyre Size: F: & 1	2/22/154	
(Policy Conditio	nn) - •		R:		
	had commenced its	N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA	A / MIC / OHTSU / PIR / S	SUMI /
repair a	at the time of inspection.		TOYOTYOKO or		- 1
Bal. or Market Va	alue:		Front	Rear	
IDAC Accident R	port: Consistent? : Ye	es or No	R/Bal. mm	. R/Bal.	mm
GIA / PR Seen:	Consistent? : Ye	es or No	L/Bal. mm	L/Bal.	mm
GIA / PK Seell.	Condictional	00 01 110	- 11111		1
Est. Repairs:	days Res.: Ye		D.O.A.	D.O.I. (Etu	120170
		es or No	D.O.A. Survey held at	D.O.I. (Elu	
Est. Repairs: Lum Sum:	days Res.: Ye	es or No	D.O.A.	D.O.I. (Elu	
Est. Repairs: Lum Sum: CA / REV /	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS	es or No	D.O.A. Survey held at Des. of Damages : Frt / Rear O/S	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date:	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted:	es or No	D.O.A. Survey held at Des. of Damages : Frt / Rear O/S	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear O/S	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Sec. V	es or No es or No Vehicle: IN / OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Yee % 3 Val.: Yee REP. / 24 HRS Person Contacted: Action / Instruction Action / Sec. V	es or No Vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages : Frt / Rear / O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Sto? Prelli. Report	es or No Vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Box	D.O.I. (Clui	p or
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Sto? Preli. Report : Final Report	es or No Vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Both	D.O.I. (Clui	p or ue to collision.
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time Date/Time, File Pass 1) (15-17-20)	days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Sto? Preli. Report : Final Report	es or No Vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Both	D.O.I. (Cluidade) 20 Yang 3 / N/S / U/C / Roofto dy Structure affected de . Survey Fee:	p or ue to collision.
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time Date/Time, File Pass 1) (\(\)5-12-20(days Res.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Sto? Preli. Report : Final Report	vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Both	D.O.I. (Cluidade) 20 Yang 3 / N/S / U/C / Roofto dy Structure affected do . Survey Fee: Transportation:	p or ue to collision.
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time Date/Time, File Pass 1) (15-12-201) Date/Time, File Returns	days Res.: Ye % 3 Val.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Instruction Person Contacted: Action / Instruction Action / Instruction Final Report In Preli. Report In Preli. Report In Preli. Report	vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Both Days Of Repair: Resurvey No. of Trip:	Survey Fee: Transportation: S+RS,_SI	p or ue to collision.
Est. Repairs: Lum Sum: CA / REV / Date: Date / Time Date/Time, File Pass 1) 05-12-20(Date/Time, File Retu	days Res.: Ye % 3 Val.: Ye % 3 Val.: Ye REP. / 24 HRS Person Contacted: Action / Instruction Action / Instruction Preli. Report Contacted: Action / Instruction Final Report Contacted: Action / Instruction Action / Instruction Final Report Contacted: Action / Instruction Action / Instruction Action / Instruction FRS.	vehicle: IN/OUT	D.O.A. Survey held at Des. of Damages: Frt / Rear O/S The U/C / Chassis frame / Bo Days Of Repair: Resurvey No. of Trip: Pe: : Site Insp (\$: Interview (\$	Survey Fee: Transportation: S+RS,_SI Photos	p or ue to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Automo	bile
MSI	G INSURANCE (S	INGAPORE) PTE LTD	Ref : CS3/MSG17021	881/M1b
	AFFLES QUAY 01 HONG LEONG	BLDG SINGAPORE 048581	Date: 16-11-2017 Code: MSG	
1.		Policy Particulars	:- (THIRD PARTY CLAIN	n)
	Insured Veh.	GBF 9722K	Veh. Inspected	SLM 6685Z
	Policy No.	28948698MKC	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	MERIMEN (IRENE TAN)	Assign Date	16/11/2017
2.		Vehicle Parti	culars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	5	Steering	
	Brakes		Modification	
	General			
3.		Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre		25	mm
	L/H Rear Tyre			mm
4.		Descripti	on of Damages	
5.		Genera	al Information	
٠.	Accident Date	13/11/2017	Inspection Date	16/11/2017
	Survey held at	SZE KANG AUTOMOBILE SPR		7.57 (11) 2.5.15
		BLK 10 ANG MO KIO INDUSTR SINGAPORE 568047		AUTO POINT
5a.	A CONTRACTOR	R	temarks	
	B) THE REPAIR E THE REPAIRER V	ON WAS CONDUCTED ON A "W STIMATE WAS NOT PRESENTE VAS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	D AT THE TIME OF INSPE STIMATE.	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	Adi Rot	Adj Submit	ted Ins Auti	Court 1	President Control	
Main	15 Nov 2017		15 Nov 2017 16:26 Assign		Asj Submit	ted Its Add	r.ed	New As: Cancel C	signment Case
-1077-107-007	Main	Refere	nce	Claim	Details	Docume	nts)	Show All
CLAIM S	JBFOLDER DET	AILS		AND RESIDENCE	AND DEPOSIT OF THE PARTY OF	[Cros	ited by in:	An I wall when	-
Insured:		BUDGETCARS	PTE LTD, Co	. Reg. No.: 2	016182397	Lcrea	ited by in	surer	
Main Claim	417.41	ONG BENG H	ONG, ID: S17						
Vehicle Re	g. No.:	SLM6685Z		Date	e of Loss:	13/11	/2017 10:0	0 - :59	
Claim Type:		TP		TP Policy/Cover Note I		28948	28948698MKC (Comprehensive)		
Vehicle Reg. No. (Insured):		GBF9722K		Polic	y No. (Claimant):	Cover	Coverage: 29/04/2017 - 28/04/20		
				Exce	255:	\$\$500	\$\$500.00		
Repairer:		Sze Kang Aut 568047 Ang M	omobile Spray o Kio - Tel: 648	ing Services	(HQ) BLK 10 AND	MO KIO INDUS	TRIAL PAR	K 2A, #0	3-17,
Handling In	surer:	MSIG Insura 6594 2541]	nce (Singapore	e) Pte. Ltd. (HQ) - Tel: +65 68	27 7888 [Har	ndled by Ire	ene Tan	Gek Ing -
Adjuster:			sultants Pte L	td (HQ) - Te	: 6256-3561 [I	mm.Advice	due 16/11	/20171	
ASSOCIA	TED MAIL RECE							-	
There are r	o mall for this ca	se.					View All	Compose	Case Mail
ALL ASS	CIATED TASKS								
					View All	Search Tasks	Create Ne	w Task	Complete
Due Date No results.	Priority T	ype Task Grou	p Subject	Handler	Assigned By	Completed C	n Cre	ated On	Done?



REG/CS/PAY/FA 1 5 NOV 2017

ADVOCATES AND SOLICITORS COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER: 200911678H

15/11/2017

Our Ref: SLM 6685Z (H) Your Ref: GBF 9722K

RIAZ QAYYUM (LLB HONS) NUS (DIRECTOR)

TAN KOK SIANG ILLB HONS LON (ASSOCIATE)

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS (ASSOCIATE)

TO:

MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Attn: Motor Claims Department

BY FAX ONLY (6225-7402)

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to notify you of a road traffic accident on 13 NOVEMBER 2017 at about 1030 hours along Eng Neo Avenue involving our client's vehicle registration number SLM 6685Z and vehicle registration number GBF 9722K driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop

SZE KANG AUTOMOBILE SPRAYING SERVICES

Address

AMK AUTOPOINT

10 ANG MO KIO INDUSTRIAL PARK 2A

#03-17/09

SINGAPORE 568047

Telephone no.

6481 2712/8201 9979

: Please let us hear from you by the stipulated time.

Yours faithfully

FOR SURVEYOR

Please initial here after completion of prerepair inspection, Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection

encs

cc. client



Survey Department Check List (Case Handler)

dmin (): Case handler to make sure all Infor	mation created	hy the assi		oist am are Δ
	Assign Form		N-Date	Y-Date	
C	Reference No.	V	IV-Date	1-Date	is Date
C	Customer Code				
	Assign From	7			
		1			
	Assign Date	V .			
	Veh No (Inspected)		-	-	
С	Veh No (Insured)	1		-	
С	D.O.A	V			
С	Policy No	V			
С	Claim No				-
С	Insurance Authorisation (CA /REV/REP)				
С	Report Type	~			
С	Weekend Charges	,			
Ν	Survey held at/Repairer				
С	Excess				
urveyo	r (): Case handler to make sure	the survervor c	ompleted a	Il required	informa
	nment Form			est tituling between 1800	
_, r.ss.g.	Vehicle No				
C	Regn Month/Year	1		-	1
	Vehicle Type	1			
N.	Make & Model	1	+	-	+
C		1	-		-
	Engine Capacity. (C.C) Colour	V	-		-
N	The state of the s	-	-	-	-
C	Odometer. (Sp.Reading) Chassis No	-	-	-	+
- 10	General Condition				
N		1	+		-
N	Steering		+	_	-
N	Brake	/	+	-	-
N	Modification (Modi)				-
С	Tyre Size	1	-	-	-
N	Tyre Make	V	-		+
С	Tyre Balance	-			-
С	Date of Inspection				-
N	Survey held		-		+
N	Des.of Damages				4
2) Syste	m - (Views/Merimen)				
С	Damaged Vehicle Photographs Uploaded	V			
3) Work	shop Estimate/Assignment Form				
N	ALL Parts condition				9 - 37220
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
c	Days of repair		1		
C	Finalised Amount				711-11
c	Re-inspection Cases to Finalize within 5 Days				-
	m - (Views/Merimen)				
C	Resurvey photo Uploaded		1	1	T

*C: Critical *N: Non-Critical

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1271J
Vehicle Details	
Vehicle No.	SLM6685Z
Vehicle to be Exported	No
Intended De-registration Date	01 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour	Silver
Manufacturing Year	2007
Engine No.	2AZE072948
Chassis No.	MR053BK4007020141
Maximum Power Output	123.0 kW (164 bhp)
Open Market Value	\$28,797.00
Original Registration Date	07 Apr 2008
First Registration Date	07 Apr 2008
Transfer Count	2
Actual ARF Paid	\$28,797.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	06 Apr 2018
PARF Rebate Amount	\$14,398.00
Intended COE Rebate Details	
COE Expiry Date	06 Apr 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$19,001.00
COE Rebate Amount	\$659.00
Total Rebate Amount	\$15,057.00

The information contained herein is correct as at 01 Dec 2017

ОК

View Sent Message

This mail is associated with:

"SLM6685Z (536909) [GBF9722K]

TP ONG BENG HONG Nov 13 2017 10:00AM [BUDGETCARS PTE LTD] Sze Kang Automobile Spraying Services

View Recipients

Print Message

Delete Message

Forward

From Subject LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/12/2017 14:19 PM. ${\sf MSI_TTAN}$

Pre-repair Inspection

Dear Irene,

Refer to your assignment on 15.11.2017 at 4.26PM.

Please be informed that we have inspected the vehicle SLM 6685Z on 16.11.2017 at 1.28PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2017		15 Nov 2017 16:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case
	Main	Refer	ence]	Claim Deta	ls	Documents	Show All
CLAIM S	UBFOLDER DET	AILS			1000	[Created by in	nsurer]
Insured:		The State of the S	The second secon	eg. No.: 20161823	9Z		
Main Clai Vehicle R		ONG BENG HO	NG, ID: S1721	Date of L	oss:	13/11/2017 10:	00 - +59
Claim Ty	pe:	TP / 536909		0.0000000000000000000000000000000000000	ver Note No.:	28948698MKC (Comprehensive) 4/2017 - 28/04/2018
Vehicle Reg. No. (Insured):		GBF9722K		Policy No	Policy No. (Claimant):		72017 20,0472010
(11)11(05) -1-1 (1				Excess:		S\$500.00	
Repairer:		Sze Kang Auto 568047 Ang Mo	mobile Sprayin Kio - Tel: 64812	g Services (HQ) 8 712	BLK 10 ANG MO K	IO INDUSTRIAL P	ARK 2A, #03-17,
Handling	Insurer:			The second secon	el: +65 6827 788	8 [Handled by	Irene Tan Gek Ing -
Adjuster:	L.	LKK Auto Cons [Imm.Advic	sultants Pte Ltd e due 16/11/2	(HQ) - Tel: 6256- 017]	3561 [Handled	by MA CHIN FO	OK]
ASSOCIA	TED MAIL REC	EIVED				View All	Compose Case Mail
There are	no mail for this c	ase.					
8							
ALL ASS	OCIATED TASK	s		View All	Search Tasks	Create Nev	v Task Complete
Due Dat	the constant of	ype Task Gro	up Subject	Handler Assi	gned By Cor	npleted On	Created On Done?

Claim Documents

*SLM6685Z (536909) [GBF9722K] ONG BENG HONG Nov 13 2017 10:00AM [BUDGETCARS PTE LTD] Sze Kang Automobile Spraying Services

ho	tos/Images		3 per p	3 per page ▼	
No		LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/17 19:09	General View	0	Load JPG	V
2	05/12/17 19:09	Chassis Number	0	Load JPG	V
3	05/12/17 19:09	General View	0	Load JPG	V
4	05/12/17 19:09	Odometer Reading	0	Load JPG	V
5	05/12/17 19:09	General View	0	Load JPG	
6	05/12/17 19:09	General View	0	Load JPG	V
7	05/12/17 19:09	General View	0	Load JPG	V
8	05/12/17 19:09	General View	0	Load JPG	V
9	05/12/17 19:09	General View	0	Load JPG	7
10	05/12/17 19:09	General View	0	Load JPG	J
11	05/12/17 19:09	General View	0	Load JPG	V
12	05/12/17 19:09	General View	0	Load JPG	V
13	05/12/17 19:09	General View	0	Load JPG	7
14	05/12/17 19:09	General View	0	Load JPG	J
15	05/12/17 19:09	General View	0	Load JPG	7
16	05/12/17 19:09	General View	0	Load JPG	V
17	05/12/17 19:09	General View	0	Load JPG	V
18	05/12/17 19:09	General View	ð	Load JPG	7
19	05/12/17 19:09	General View	0	Load JPG	V
20	05/12/17 19:09	General View	0	Load JPG	V
21	05/12/17 19:09	General View	0	Load JPG	V
22	05/12/17 19:09	General View	0	Load JPG	V
23	05/12/17 19:09	General View	0	Load JPG	V
24	05/12/17 19:09	General View	0	Load JPG	V
25	05/12/17 19:09	General View	0	Load JPG	V
26	0.000	General View	0	Load JPG	V
27		General View	0	Load JPG	V
28	- 102 100 102 10 10 10 10 10 10 10 10 10 10 10 10 10	General View	0	Load JPG	V
29		General View	0	Load JPG	V
200	CONTRACTOR STORY	General View	0	Load JPG	V
30	Control of the Contro	General View	0	Load JPG	V
31	A Description of the second	General View	0	Load JPG	V
32	05/12/17 19:09	General View			
Do	cumentation		1 per	page 🕶	V
	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
1	15/11/17 16:26	PRI	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		Neset Save Print
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HO	
	*	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		
Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG17021881/M1BE2

Date:

06/12/2017

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28948698MKC

Claimant

SLM6685Z

Insured Vehicle No:

GBF9722K

Vehicle No: Date of Loss:

13/11/2017

Nature of Claim:

TP

Claim No: 536909

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLM6685Z

Make & Model:

TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Engine No:

2AZE072948

Reg. Date:

07/04/2008 (Man. Year: 2007)

Chassis No:

MR053BK4007020141

Colour:

Silver

2362 cc **Engine Capacity:**

Market Value/New Car Price: Sum Insured (S\$):

N/A

Odometer:

193007 km

Market Value/New Car Price

Yes Engine Modification:

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side:

Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side:

Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

15/11/2017

Date Inspected:

16/11/2017 Inspected At:

Sze Kang Automobile Spraying

Services (HQ)

BLK 10 ANG MO KIO INDUSTRIAL

PARK 2A, #03-17 Singapore 568047

Estimated Period of Repair:

0.0 days

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,000.00

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Dec 2017)

Parts: 143 TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM6685Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >