

INS. CASE OWNER:

CC 4 / AIG 1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$:

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age: MOHAMMED FADEL BIN SAPI'EM

Driver Tel No.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLS 41424



INSRS:

WSP:

Tel:

Liability:

RMKS:

EM-1



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
7/11/17	SLS 41424 - 4	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
21/11/17	email letter to O2	Call OI:	21/11/17 email
24/9/18	File pass to typist to type report (urgent)	After call ltr to OI:	vivian
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 21/10/18	Confirm with: CHIA
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	\$5 9560.00		
Costs of Rental (LOR):	\$5 749.00	(7 days) x 100 + 637	
Costs of Use (LOU):	\$5 (\$ x days)		
Costs of Income (LOI):	\$5 (\$ x days)		
Or only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
LTA Search:	\$5 5-35		
Medical:	\$5		
Reimbursement:	\$5	(e.g. Tow/ Independent)	
Initial Cost:	\$5		
Total:	\$5 9314.35	Global Sum \$5:	
FINAL PAYMENT		Date/Time:	Confirm with:
Fee 1:	\$5 9314.35	Name 1:	EM-1 Auto Pte Ltd
Fee 2: (Strike if N.A.)	\$5	Name 2:	
Fee 3: (Strike if N.A.)	\$5	Name 3:	

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s EMI

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No**CA / REV / REP. / 24 HRS**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS 91424Yr Regn: JUL 2011Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VECKSWAGEN TOURAN1390Colour: GREY

A/C: Insured / Std / NI / NA

Sp. Reading: 13381

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG 22217 BW 104110Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55/R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MICFrontRearR/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 14/11/2017D.O.I. 16/11/2017

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/11/18 Confirm LL \$8000.00 with 7 working days(Red. \$238.00 51%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee: _____

Transportation: _____

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR17021925/M1wb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 16-11-2017		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 7054A	Veh. Inspected	SLS 9142Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/11/2017	Inspection Date	16/11/2017	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

1,750.00	469.50	40.00	800.00
137.00	293.70	40.00	800.00
125.00	30.00	220.00	30.00
87.00	495.70	80.00	40.00
	191.00		120.00
60.00			60.00
65.00	652.40		60.00
	76.00		60.00
76.00	356.70		
	60.00		

557.10
4.00
319.70
175.00
356.00

1,200.00
180.00
162.00
50.00
129.10
650.00
65.00
550.00
35.00

File No: 5140

Vehicle No.
SLS 9142Y

Model
VK TOURAN

Rental 7 days

Total List Price	\$	9,357.90
Discount		10%
List Price	\$	8,422.11
Total Nett Price	\$	-
Discount		10%
Nett Price	\$	-
Total Special Nett	\$	380.00
Total Labour	\$	1,970.00
Grand Total	\$	10,772.11
Discount 20%		20%
Lump Sum	\$	8,617.69

Columns	List Price
A	Nett Price
C	Special Nett
D	Labour
E	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLS 9142Y
Vehicle Model : VOLKSWAGEN TOURAN
Accident Date : 14.11.2017
Original Reg Date : 11.07.2011

Date : 15.11.2017
Chassis : WVZZZ1TZBW104110
TP Ins. : AIG

ESTIMATE

1	1 pc	Tailgate	✓	dt	✓	1,750.00	
2	1 pc	Tailgate Badge	✓	u4	✓	137.00	
3	1 pc	Tailgate Emblem Touran	✓	u4	✓	125.00	
4	1 pc	Tailgate Emblem TSI	✓	u4	✓	87.00	
5	1 pc	Tailgate Windscreen	X		X	950.00	NN
6	1 pc	Tailgate Windscreen Inner Seal	✓	u4	✓	60.00	
7	2 pcs	Tailgate Number Plate Lamps LH, RH - NEW	✓	u4 (65.00)	✓	130.00	
8	1 pc	Tailgate Opener Switch	X		X	127.50	NN
9	2 pcs	Tailgate Lamps	X	256.30	X	512.60	NN
10	2 pcs	Tailgate Lamps Inner Sealer	✓	38.00	7	76.00	NEC
11	2 set	Tailgate Lamps Clips	X	25.00	X	50.00	NN
12	2 pcs	Tailgate Stopper	X	21.00	u4	42.00	
13	1 pc	Tailgate Inner Trim	✓		7	557.10	CRA
14	1 pc	Tailgate Inner Trim Clips	✓		✓	40.00	NEC
15	1 pc	Tailgate Inner Lock	✓	u4	✓	319.70	
16	1 pc	Tailgate Auto Lock Actuator	✓		7	175.00	DM
17	1 pc	Tailgate Lock Catch	X	u4	X	46.00	NN
18	1 pc	Tailgate Weatherstrip	✓	u4	✓	356.00	
19	2 pcs	Tailgate Hinges	u4 X	111.00	X	222.00	
20	2 pcs	Tailgate Absorber	u4 X	219.00	X	438.00	
21	1 pc	Rear Bumper	✓	u4	✓	1,200.00	
22	2 pcs	Rear Bumper Side Retainers	u4	90.00	✓	180.00	
23	2 pcs	Rear Bumper Attachment Retainers LH-CRA, RH-NN	u4	81.00	7	162.00	✓
24	1 set	Rear Bumper Clips	✓	u4	✓	50.00	
25	1 pc	Rear Bumper Apron Garnish	✓		7	129.10	CRA
26	1 pc	Rear Bumper Reinforcement	✓		7	650.00	DD
27	2 pcs	Rear Bumper Reinforcement Bracket	X	171.00	7	342.00	NN
28	2 pcs	Rear Bumper Reflectors LH-CRA, RH-NN	u4	65.00	u4 7	130.00	
29	1 pc	Rear Bumper Lower Skirt	✓		7	550.00	CRA
30	1 pc	Rear Bumper Tow Cover	✓	u4	✓	35.00	

C/F

9,629.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLS 9142Y

B/F

9,629.00

1	1 pc	End Panel Outer	✓	7	469.50	BUC
2	1 pc	End Panel Top Trim	✓	7	293.70	CRA
3	1 set	End Panel Top Trim Clips	✓	h2	30.00	
4	1 pc	Rear Floor Panel Top Tray Box	✓	7	495.70	CRA
5	1 pc	Rear Floor Panel Top Sponge	✓	7	191.00	CRA
6	1 pc	Rear Key Antenna Sensor	X	7	178.10	NN
7	2 pcs	Taillamps LH-CRA, RH-NN	✓	326.20	7	652.40
8	2 pcs	Taillamps Inner Sealer LH-NEC, RH-NN	✓	38.00	7	76.00
9	2 set	Taillamps Clips	X	25.00	X	50.00
10	2 pcs	Rear Fender Inner Trim LH-CRA, RH-NN	✓	356.70	X	713.40
11	2 set	Rear Fender Inner Trim Clips	✓	30.00	✓	60.00
					12,838.80	NEC

Special Nett

1	1 pc	Rear Windscreen Sealant	40	80.00	40 NEC
2	1 pc	Rear Number Plate with Cover	40	70.00	40 DIS
3	1 set	Reverse Camera Sensor	200	250.00	52
4	1 set	Body Panel Joint Sealant	80	120.00	80 NEC

Labour charge

Panel Beating	800	1,200.00	800
Spray painting	800	1,200.00	800
Check Wiring	30	50.00	30
Anti rust	40	100.00	40
Remove and install rear winscreen.	120	140.00	120
Remove and install tailgate parts.	60	90.00	60
Remove and install carpet and seat.	60	120.00	60
Remove and install reverse sensor	60	90.00	60
		\$ 16,328.80	

Not Authorised
 4/5 Repairs
 After paint work
 16/11/2017 @
 7 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3779I

Vehicle Details

Vehicle No.	SL59142Y
Vehicle to be Exported	Yes
Intended De-registration Date	15 Nov 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	TOURAN 1.4 TSI AT 1T32B4 FL HID
Primary Colour	Grey
Manufacturing Year	2011
Engine No.	CAV309937
Chassis No.	WVGZZZ1TZBW104110
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$20,635.00
Original Registration Date	11 Jul 2011 ✓
First Registration Date	11 Jul 2011
Transfer Count	1
Actual ARF Paid	\$20,635.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	10 Jul 2021
PARF Rebate Amount	\$13,412.00

Intended COE Rebate Details

COE Expiry Date	10 Jul 2021 ✓
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$38,889.00
COE Rebate Amount	\$14,201.00
Total Rebate Amount	\$27,613.00 ✓

The information contained herein is correct as at 14 Nov 2017

OK

- Michelin Pilot Sport 4
- How to spend your time as a retiree
- Porsche

Username / Email Addr
 password
 Sign Up New Account

Volkswagen Touran Price Range Depreciation 2011 Vehicle Type Advanced Search

Home » Used Cars » Car Lingual » Volkswagen Touran 1.4A TSI

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle



Manulife
 Family comes first.
 Grow your wealth and
 leave a legacy for them.

Learn

Volkswagen Touran 1.4A TSI

Overview Financial Accessories Similar Research Photos Map



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share


Car Details

Price	\$50,800	1
Depreciation	\$10,590 /yr View models with similar depreciation	1
Reg Date	29-Aug-2011 (3yrs 9mths 14days COE left)	2
Manufactured	2011	2
Mileage	91,000 km (14.6k /yr)	2
Transmission	Auto	2
Engine Cap	1,390 cc	2
Road Tax	\$620 /yr	2
Power	103.0 kW (138 bhp) View specs of the Volkswagen Touran (2010-2016)	2
Curb Weight	1,536 kg	2
Features	Efficient 1.4L Twin Charged TSI Engine With 138Bhp, DSG 7 Speed Tiptronic Transmission, Auto Headlight, ABS, 6 Airbags, Cruise Control, Rain Sensors.	2
Accessories	Leather Seats, Sports Rims, Retractable Side Mirrors With Indicator, Reverse Sensors And Camera, Rear Knockdown Seats, Steering Control.	2
Description	The Best Selling And Most Popular Mid Size European Style MPV. Ultra Smooth And Quiet Engine. Spacious Head/Leg Room, Ideal For Family And Voted Most Economical Car In Singapore. Please Feel Free To Call Our Friendly Sales Consultants Now To Check Out The Latest Offer!	2
COE	\$42,999	2
OMV	\$21,383	2
ARF	\$21,383	2
Derog Value	\$30,191 as of today (change)	2
No. of Owners	2	2
Type of Veh	MPV	2
Category	PARF Car	2
Availability	Available	2

Add to Shortlist Add to Compare Add a Note

Posted on: 21-Sep-2017 | Last Updated on: 13-Nov-2017

Tags: Volkswagen Touran, Vo
 Volkswagen Touran, Volkswag
 wagen Touran, 2011
 volkswagen



Seller Information

Company	Car Lingual • dealer's pricelist • 7 vehs sold 34 vehs available
Address	1 Bukit Batok Crescent #04-58/59 /60/61 Search cars nearby this location
Location	WCEGA Plaza
Office No	64633777

Compare

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLS 9142Y
Vehicle Model : VOLKSWAGEN TOURAN
Accident Date : 14.11.2017
Original Reg Date : 11.07.2011

Date : 15.11.2017
Chassis : WVGZZZ1TZBW104110
TP Ins. : AIG

ESTIMATE

1	1 pc	Tailgate	dt	✓	1,750.00
2	1 pc	Tailgate Badge	ue	✓	137.00
3	1 pc	Tailgate Emblem Touran	ue	✓	125.00
4	1 pc	Tailgate Emblem TSI	ue	✓	87.00
5	1 pc	Tailgate Windscreen		X	950.00
6	1 pc	Tailgate Windscreen Inner Seal	ue	✓	60.00
7	2 pcs	Tailgate Number Plate Lamps	over 65.00		130.00
8	1 pc	Tailgate Opener Switch		X	127.50
9	2 pcs	Tailgate Lamps	256.30	X	512.60
10	2 pcs	Tailgate Lamps Inner Sealer	38.00	7	76.00
11	2 set	Tailgate Lamps Clips	25.00	X	50.00
12	2 pcs	Tailgate Stopper	21.00	me x	42.00
13	1 pc	Tailgate Inner Trim		7	557.10
14	1 pc	Tailgate Inner Trim Clips		✓	40.00
15	1 pc	Tailgate Inner Lock	wa	✓	319.70
16	1 pc	Tailgate Auto Lock Actuator		7	175.00
17	1 pc	Tailgate Lock Catch	tl	X	46.00
18	1 pc	Tailgate Weatherstrip	dis	✓	356.00
19	2 pcs	Tailgate Hinges	me	X	222.00
20	2 pcs	Tailgate Absorber	me	X	438.00
21	1 pc	Rear Bumper	def	✓	1,200.00
22	2 pcs	Rear Bumper Side Retainers	dis	✓	180.00
23	2 pcs	Rear Bumper Attachment Retainers		7	162.00
24	1 set	Rear Bumper Clips	ue	✓	50.00
25	1 pc	Rear Bumper Apron Garnish		7	129.10
26	1 pc	Rear Bumper Reinforcement		7	650.00
27	2 pcs	Rear Bumper Reinforcement Bracket	171.00	7	342.00
28	2 pcs	Rear Bumper Reflectors	65.00	7	130.00
29	1 pc	Rear Bumper Lower Skirt		7	550.00
30	1 pc	Rear Bumper Tow Cover	def	✓	35.00

C/F

9,629.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLS 9142Y

B/F

9,629.00

1	1 pc	End Panel Outer		7	469.50
2	1 pc	End Panel Top Trim		7	293.70
3	1 set	End Panel Top Trim Clips	Wz	✓	30.00
4	1 pc	Rear Floor Panel Top Tray Box		7	495.70
5	1 pc	Rear Floor Panel Top Sponge		7	191.00
6	1 pc	Rear Key Antenna Sensor		7	178.10
7	2 pcs	Taillamps	326.20	7	652.40
8	2 pcs	Taillamps Inner Sealer	38.00	7	76.00
9	2 set	Taillamps Clips	25.00	X	50.00
10	2 pcs	Rear Fender Inner Trim	356.70	2	713.40
11	2 set	Rear Fender Inner Trim Clips	30.00	✓	60.00

12,838.80

Special Nett

1	1 pc	Rear Windscreen Sealant			-60.00
2	1 pc	Rear Number Plate with Cover			70.00
3	1 set	Reverse Camera <i>Sensor</i>		220 ✓	250.00
4	1 set	Body Panel Joint Sealant			120.00

Labour charge

Panel Beating		1,200.00
Spray painting		1,200.00
Check Wiring		50.00
Anti rust		100.00
Remove and install rear winscreen.		140.00
Remove and install tailgate parts.		90.00
Remove and install carpet and seat.		120.00
Remove and install reverse sensor		90.00

\$ **16,328.80**

Not Anthony
 4/5 Repur
 After paint
 WLC Auto (M)
 16/11/2021 @
 7 days

Svy-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3779I

Vehicle Details

Vehicle No.	SL59142Y
Vehicle to be Exported	Yes
Intended De-registration Date	15 Nov 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	TOURAN 1.4 TSI AT 1T32B4 FL HID
Primary Colour	Grey
Manufacturing Year	2011
Engine No.	CAV309937
Chassis No.	WVGZZZ1TZBW104110
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$20,635.00
Original Registration Date	11 Jul 2011
First Registration Date	11 Jul 2011
Transfer Count	1
Actual ARF Paid	\$20,635.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	10 Jul 2021
PARF Rebate Amount	\$13,412.00

Intended COE Rebate Details

COE Expiry Date	10 Jul 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$38,889.00
COE Rebate Amount	\$14,201.00
Total Rebate Amount	\$27,613.00

The information contained herein is correct as at 14 Nov 2017

OK

View Received Message

This mail is associated with :

***SLS9142Y (6293319035SG)**
[SLF7054A]
TP
TIEW KIM TECK
Nov 14 2017 12:00AM
[LCRF Pte Ltd]
Em-1 Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on **26/09/2018 16:02 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9314.35) - SLS9142Y - Claim Handler: Yong, Ivy-AV

Approved:9314.35.

DOCUMENTS SUMMARY

There are no documents.

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Tuesday, 21 November, 2017 12:57 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLF 7054A AND SLS 9142Y ON 14/11/2017

Our Ref: CC4/LCR17021925/M1wb3

21 November 2017

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 7054A AND SLS 9142Y ON 14/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Tiew Kim Teck ("the third party claimant")
of Blk 786B #06-85 WOODLANDS DRIVE 60 (S) 732786 (address),
owner of SL89142Y (vehicle no.) hereby authorize
EM-1 Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SL89142Y that was
damaged pursuant to the accident which occurred on 14/11/17 (date) along
SLE (BKE) before Mandai Exit (location)
involving vehicle no/s SLF 7054A ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 14 day of NOV (month) 20 17 (year)



Signed by "the third party claimant"

Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, EM-1 Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 8560.00 (repair costs), S\$ 749.00 (loss of use/rental) S\$ 5.35 (search fees) for vehicle no. SLS9142Y that was damaged pursuant to the accident which occurred on 14/11/17 (date) along SVE LKFF DEPOKO MANDAI EXIT (location) involving vehicle no/s SLF7054A.

This is pursuant to the inspection conducted on 16/11/17 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tiew Kim Teck ("third party claimant") of vehicle no. SLS9142Y to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLS9142Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 2 day of Oct (month) 20 18 (year)

mif



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY/ GST REG. NO: 201316380R

TAX INVOICE

M/S TIEW KIM TECK

Invoice No : 18/00246/5140TP

Date : 02-Oct-2018

AIG Asia Pacific Insurance Pte. Ltd.

Motor Claim Department

AIG Building

78 Shenton Way

#07-16 Singapore 079120

Date of Accident : 14-Nov-2017
Our Client's Vehicle Number : SLS 9142Y
Vehicle Make / Model : VOLKSWAGEN TOURAN
Your Insurer : SLF 7054A

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	8,000.00	560.00	8,560.00 SR


SGD (Eight Thousand Five Hundred Sixty only)

GRAND TOTAL

8,560.00

Subject to 7% GST

560.00



Authorised Signature and Company Stamp



友立旅遊服務私人有限公司
UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Centre, # 02-574,
Singapore 0718.
Tel: 2927656
Fax: (65) 2939720
STPB LIC TA/076

GST Reg. No.: M2-0019671-6

Mr Tiew Kim Teck
Blk 786B Woodlands Drive 60
06-85
Singapore 732786

20, Sin Ming Lane,
#08-51, Midview City
Singapore 573968
Tel: 6292 7656

TAX INVOICE

WP2017252
NO.

22.11.2017

Singapore, _____ 19

DATE	PARTICULARS	@	\$	cts
	Rental of one unit Toyota Picnic 2.0 Auto Registration no. SJF 748 B self driven as from 14.11.2017 to 21.11.2017.			
	7 days at \$140.00 per day	\$	980.00	
		\$	980.00	
	Add GST at 7%	\$	68.60	
	Amount Due	\$	1048.60	
(SIN DOLLARS: ONE THOUSAND FORTY EIGHT AND SIXTY CENTS ONLY)				
	Standard Rated Supplies:\$		980.00	
	Total Amount of GST:\$		68.60	

AUTHORISED SIGNATURE



友立旅遊服務私人有限公司
UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Centre, # 02-574,
Singapore 0718.
Tel: 2927656
Fax: (65) 2939720
STPB LIC TA076

GST Reg. No.: M2-0019671-6

Mr Tiew Kim Teck
Blk 786B Woodlands Drive 60
06-85
Singapore 732786

20, Sin Ming Lane,
#06-51, Midview City
Singapore 573968
Tel: 6292 7658

22.11.2017

Singapore,

19

TAX INVOICE

NO. **WP2017252**

DATE

PARTICULARS

@

\$

cts

Rental of one unit Toyota Picnic 2.0 Auto
Registration no. SJF 748 B self driven
as from 14.11.2017 to 21.11.2017.

7 days at \$140.00 per day

\$ 980.00

Add GST at 7%

\$ 980.00

Amount Due

\$ 68.60

\$ 1048.60

(SIN DOLLARS: ONE THOUSAND FORTY EIGHT AND SIXTY CENTS ONLY)

Standard Rated Supplies:\$

980.00

Total Amount of GST:\$

68.60

AUTHORISED SIGNATURE



UNIQUE TOURIST SERVICE (PTE) LTD.

20, Sin Ming Lane, #08-51, Midview City, Singapore 573968

TEL: 6292 7656 EMAIL: uniqtour@singnet.com.sg

COMPANY REG NO: 197401067R

GST REG NO: M2-0019671-6

CAR RENTAL AGREEMENT

RA No. 21252

VEHICLE NO.

SJF 748B

MAKE/MODEL

TOYOTA PILLIC

NAME OF HIRER	Tiew Kim Teck		
ADDRESS	BLK 788B #06-85 Wilands Dr 60		
	SINGAPORE 730786		
OFFICE TEL	RES TEL	HP	
NAMED DRIVER	Tiew Kim Teck		
OCCUPATION	NATIONALITY		
PASSPORT / NRIC	57883779I		
DATE OF BIRTH	7/8/78		
DRIVING LIC NO.	57883779I		
PLACE OF ISSUE	DATE PASS/EXPIRY 14/3/07		

DATE OUT	14/11/7	TIME OUT	1755		
PETROL OUT	E	1/4	1/2	3/4	1
DATE IN	21/11/7	TIME IN	1245		
PETROL IN	E	1/4	1/2	3/4	F
RENTAL RATES					
MONTHLY	@ \$				
WEEKLY	@ \$				
DAILY	7 @ \$ 140/p 980.00				
C.O.W. FEE					
PETROL CONSUMPTION					
DELIVERY CHARGE					
COLLECTION CHARGE					
SUB-TOTAL					
GST @ 7%	68.60				
RENTAL DEPOSIT					
TOTAL:	1048.60				

ADDITIONAL NAMED DRIVER			
ADDRESS			
	SINGAPORE		
OFFICE TEL	RES TEL	HP	
OCCUPATION	NATIONALITY		
PASSPORT / NRIC	DATE OF BIRTH		
DRIVING LIC NO.			
PLACE OF ISSUE	DATE PASS/EXPIRY		

BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS

A. COLLISION DAMAGE WAIVER (CDW) AT \$ _____ PER DAY / WEEK / MONTH "X"

B. SURCHARGE OF \$ _____ FOR USE IN MALAYSIA FROM _____ TO _____ "X"

* THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY.

COMPULSORY EXCESS, DOLLAR	\$ 1200/p
NOTE:	HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS.
	YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS
	PRINTED OVERLEAF.

FOR SINGAPORE DRIVE ONLY

DEPOSIT REFUND
PAYMENT BY: BILL CO / CREDIT CARD / CASH
ATTENDED BY:
OF UNIQUE TOURIST SERVICE (PTE) LTD.

DECLARATION

I HEREBY DECLARE THAT NO MOTOR ACCIDENT HAD OCCURED DURING MY HIRE OF YOUR MOTOR VEHICLE AS STATED IN THE ABOVE MENTIONED SCHEDULE * OR TO ANY SUBSTITUTED VEHICLE AS STATED IN THE MEMORANDUM DATED.

REPLACEMENT VEHICLE NO:

1. _____ ON _____ TIME _____
2. _____ ON _____ TIME _____
3. _____ ON _____ TIME _____

DATE:

SIGNATURE OF HIRER

DATE:

SIGNATURE OF HIRER

SLF 9142Y



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 14 Nov 2017 / 17:30:35

Receipt Date/Time : 14 Nov 2017 / 17:30:35

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171114-001739

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
-----	--	--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SLF7054A

As at 14 Nov 2017/16:30:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1	Insurance Enquiry - SLF7054A Enquiry Fee 20171114172926755082	5.00	0.35	5.35
---	---	------	------	------

Sub-Total	5.00	0.35	5.35
------------------	------	------	------

Total Before Rounding	5.00	0.35	5.35
------------------------------	------	------	------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			5.35
-----------------------------	--	--	------

Paid By

20171114172935961	Direct Debit: eNETS Debit (Internet Banking)	5.35
-------------------	---	------

Total		5.35
--------------	--	------

Cash Change		0.00
--------------------	--	------

Tendered Amount		5.35
------------------------	--	------

Excess Refundable Amount		0.00
---------------------------------	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt	OK	Save as PDF
-------------------------------	--------------------	-----------------------------

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017 Edit Reg		15 Nov 2017 00:00 Edit Adj Rpt	S\$8,000.00 Edit Estimates	S\$8,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF Pte Ltd. Co. Reg. No.: NA									
Main Claimant: TIEW KIM TECK, ID: S78837791									
Vehicle Reg. No.:	SLS9142Y	Date of Loss:	14/11/2017 00:00 - :59 [76 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6293319035SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLF7054A	Policy No. (Claimant):	5095789562						
		Excess:							
Repairer: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/11/2017]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (26/09/2018): Alert - Adj Mandate Approved (S\$9314.35) - SLS9142Y - Claim Handler: Yong, Ivy-A... - AIG_SG (17/11/2017): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS9142Y (6293319035SG)
[SLF7054A]
TP
TIEW KIM TECK
Nov 14 2017 12:00AM
[LCRF Pte Ltd]
Em-1 Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	{Draft}		Third Party Express Settlement – Payment Breakdown												1	Edit				
															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	25/09/18 19:04		General View												1	Load JPG				
2	25/09/18 19:04		General View												1	Load JPG				
3	25/09/18 19:04		General View												1	Load JPG				
4	25/09/18 19:04		General View												1	Load JPG				
5	25/09/18 19:04		General View												1	Load JPG				
6	25/09/18 19:04		General View												1	Load JPG				
7	25/09/18 19:04		General View												1	Load JPG				
8	25/09/18 19:04		General View												1	Load JPG				
9	25/09/18 19:04		General View												1	Load JPG				
10	25/09/18 19:04		General View												1	Load JPG				
11	25/09/18 19:04		General View												1	Load JPG				
12	25/09/18 19:04		General View												1	Load JPG				
13	25/09/18 19:04		General View												1	Load JPG				
14	25/09/18 19:04		General View												1	Load JPG				
15	25/09/18 19:04		General View												1	Load JPG				
16	25/09/18 19:04		General View												1	Load JPG				
17	25/09/18 19:04		General View												1	Load JPG				
18	25/09/18 19:04		General View												1	Load JPG				
19	25/09/18 19:04		General View												1	Load JPG				
20	25/09/18 19:04		General View												1	Load JPG				
21	25/09/18 19:04		General View												1	Load JPG				
22	25/09/18 19:04		General View												1	Load JPG				
23	25/09/18 19:04		General View												1	Load JPG				
24	25/09/18 19:04		General View												1	Load JPG				
25	25/09/18 19:04		General View												1	Load JPG				
26	25/09/18 19:04		General View												1	Load JPG				
27	25/09/18 19:04		General View												1	Load JPG				
28	26/09/18 09:44		Reinspection Photo												1	Load JPG				
29	26/09/18 09:44		Reinspection Photo												1	Load JPG				
30	26/09/18 09:44		Reinspection Photo												1	Load JPG				
31	26/09/18 09:44		Reinspection Photo												1	Load JPG				
32	26/09/18 09:44		Reinspection Photo												1	Load JPG				
33	26/09/18 09:44		Reinspection Photo												1	Load JPG				
34	26/09/18 09:44		Reinspection Photo												1	Load JPG				

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
36	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
37	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
38	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
39	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
40	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
41	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
42	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
43	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
44	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
45	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
46	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
47	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
48	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
49	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
50	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
51	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
52	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
53	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
54	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
55	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
56	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
57	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
58	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
59	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
60	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
61	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
62	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
63	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
64	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
65	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
66	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
67	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
68	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
69	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
70	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
71	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
72	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
73	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
74	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
75	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
76	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
77	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
78	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
79	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
80	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
81	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
82	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
83	26/09/18 09:44	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
85	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
86	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
87	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
88	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
89	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
90	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
91	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
92	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
93	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
94	26/09/18 09:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/11/17 15:57	EMAIL FROM AIG DD 15112017	 Load PDF	
2	16/11/17 15:57	WKSP NOTICE	 Load PDF	
3	21/11/17 09:00	TP ESTIMATE- MARKED	 Load PDF	
4	21/11/17 09:00	TP GIA REPORT	 Load PDF	
5	21/11/17 12:57	Email letter to OI ACCIDENT INVOLVING SLF 7054A AND SLS 9142Y ON 14.11.2017	 Load PDF	
6	24/09/18 16:13	RENTAL RECEIPT	 Load PDF	
7	24/09/18 16:13	LTA SEARCH	 Load PDF	
8	26/09/18 10:13	Email to AIG to seek mandate 26.9.18	 Load PDF	
9	04/10/18 08:33	WORKSHOP INVOICE	 Load PDF	
10	04/10/18 08:33	AUTHORISATION TO ACT FORM	 Load PDF	
11	04/10/18 08:33	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/11/17 08:30	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF7054A (Insd veh)	Model:	VOLKSWAGEN TOURAN 1.4
	SLS9142Y (TP veh)		TSI (A)
Date of Accident:	14/11/2017		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	17,471.82	
Final Repair Cost	:	\$	8,560.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	749.00	7 days
LTA / GIA Search Fee	:	\$	5.35	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	9,314.35	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 9,314.35
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

04 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17021925/M1WB3Q2

Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLS9142Y

Insured Vehicle No : SLF7054A

Date of Loss: 14/11/2017

Nature of Claim: TP

Claim No: 6293319035SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS9142Y**

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A)

Engine No: CAV309937

Reg. Date: 11/07/2011 (Man. Year: 2011)

Chassis No: WVGZZZ1TZBW104110

Colour: Grey

Odometer: 133881 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,338.80	8,179.63	5,159.17	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,970.00	1,020.00	34.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,328.80	10,149.63	6,179.17	37.84
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	16,328.80	8,000.00	8,328.80	51.01
+ GST 7.00/7.00% (S\$)	1,143.02	560.00	583.02	51.01
Nett Amount (S\$)	17,471.82	8,560.00	8,911.82	51.01
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		9,314.35		

INSPECTION

Date of Assignment: 15/11/2017

Date Inspected: 16/11/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,

#01-68
Singapore 575643

Estimated Period of Repair: 7.0 days

Adjuster: MA CHIN FOOK

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,750.00 F	*1,750.00 FL
2	1		*TAILGATE BADGE	Necessary	137.00 F	*137.00 FL
3	1		*TAILGATE EMBLEM TOURAN	Necessary	125.00 F	*125.00 FL
4	1		*TAILGATE EMBLEM TSI	Necessary	87.00 F	*87.00 FL
5	1		*TAILGATE WINDSCREEN	Not Necessary	950.00 F	*- FL
6	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 F	*60.00 FL
7	1		*TAILGATE NUMBER PLATE LAMPS	N/S Not Necessary /N/S Cracked	130.00 F	*65.00 FL
8	1		*TAILGATE OPENER SWITCH	Not Necessary	127.50 F	*- FL
9	2		*TAILGATE LAMP	Not Necessary	512.60 F	*- FL
10	2		*TAILGATE LAMP INNE SEALER	Necessary (1 PCS ONLY)	76.00 F	*38.00 FL
11	2		*SET TAILGATE LAMPS CLIPS	Not Necessary	50.00 F	*- FL
12	2		*TAILGATE STOPPERS	Serviceable	42.00 F	*- FL
13	1		*TAILGATE INNER TRIM	Cracked	557.10 F	*557.10 FL
14	1		*TAILGATE INNER TRIM CLIPS	Necessary	40.00 F	*40.00 FL
15	1		*TAILGATE INNER LOCK	Bent	319.70 F	*319.70 FL
16	1		*TAILGATE AUTO LOCK ACTUATOR	Damaged	175.00 F	*175.00 FL
17	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 F	*- FL
18	1		*TAILGATE WEATHERSTRIP	Distorted	356.00 F	*356.00 FL
19	2		*TAILGATE HINGES	Serviceable	222.00 F	*- FL
20	2		*TAILGATE ABSORBER	Serviceable	438.00 F	*- FL
21	1		*REAR BUMPER	Deformed	1,200.00 F	*1,200.00 FL
22	2		*REAR BUMPER SIDE RETAINERS	Distorted	180.00 F	*180.00 FL
23	1		*REAR BUMPER ATTACHMENT RETAINERS	N/S Cracked / O/SNot Necessary	162.00 F	*81.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
25	1		*REAR BUMPER APRON GARNISH	Cracked	129.10 F	*129.10 FL
26	1		*REAR BUMPER REINFORCEMENT	Dented	650.00 F	*650.00 FL
27	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	342.00 F	*- FL
28	1		*REAR BUMPER REFLECTORS	N/S Cracked / O/SNot Necessary	130.00 F	*65.00 FL
29	1		*REAR BUMPER LOWER SKIRT	Cracked	550.00 F	*550.00 FL
30	1		*REAR BUMPER TOW COVER	Deformed	35.00 F	*35.00 FL
31	1		*END PANEL OUTER	Buckled	469.50 F	*469.50 FL
32	1		*END PANEL TOP TRIM	Cracked	293.70 F	*293.70 FL
33	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 F	*30.00 FL
34	1		*REAR FLOOR PANEL TOP TRAY BOX	Cracked	495.70 F	*495.70 FL
35	1		*REAR FLOOR PANEL TOP SPONGE	Cracked	191.00 F	*191.00 FL
36	1		*REAR KEY ANTENNA SENSOR	Not Necessary	178.10 F	*- FL
37	1		*TAILLAMPS	N/S Cracked / O/SNot Necessary	652.40 F	*326.20 FL
38	1		*TAILLAMPS INNER SEALER	N/S Necessary/O/SNot Necessary	76.00 F	*38.00 FL
39	2		*SET TAILLAMPS CLIPS	Not Necessary	50.00 F	*- FL
40	1		*REAR FENDER INNER TRIM	N/S Cracked/ O/S Not Necessary	713.40 F	*356.70 FL
41	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 F	*60.00 FL
42	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR NUMBER PLATE WITH COVER	Distorted	70.00 FS	*40.00 FS
44	1		*SET REVERSE SENSOR	Serviceable	250.00 FS	*- FS
45	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	13,338.80	9,070.70
- List Item Discount on L Items 0.00/10.00% (\$\$)		0.00	891.07
	Total Parts (\$\$)	13,338.80	8,179.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	40.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
7	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
Gross Labour Cost (S\$)			2,990.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >