

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLS 9142Y
Vehicle Model : VOLKSWAGEN TOURAN
Accident Date : 14.11.2017
Original Reg Date : 11.07.2011

Date : 15.11.2017
Chassis : WVGZZZ1TZBW104110
TP Ins. : AIG

ESTIMATE

1	1 pc	Tailgate	dt	✓	1,750.00
2	1 pc	Tailgate Badge	uu	✓	137.00
3	1 pc	Tailgate Emblem Touran	uu	✓	125.00
4	1 pc	Tailgate Emblem TSI	uu	✓	87.00
5	1 pc	Tailgate Windscreen		X	950.00
6	1 pc	Tailgate Windscreen Inner Seal	uu	✓	60.00
7	2 pcs	Tailgate Number Plate Lamps	avg (65.00)		130.00
8	1 pc	Tailgate Opener Switch		X	127.50
9	2 pcs	Tailgate Lamps	256.30	X	512.60
10	2 pcs	Tailgate Lamps Inner Sealer	38.00	?	76.00
11	2 set	Tailgate Lamps Clips	25.00	X	50.00
12	2 pcs	Tailgate Stopper	21.00	mx	42.00
13	1 pc	Tailgate Inner Trim		?	557.10
14	1 pc	Tailgate Inner Trim Clips		✓	40.00
15	1 pc	Tailgate Inner Lock	ht	✓	319.70
16	1 pc	Tailgate Auto Lock Actuator		?	175.00
17	1 pc	Tailgate Lock Catch	tl	X	46.00
18	1 pc	Tailgate Weatherstrip	dis	✓	356.00
19	2 pcs	Tailgate Hinges	711.00	X	222.00
20	2 pcs	Tailgate Absorber	219.00	X	438.00
21	1 pc	Rear Bumper	def	✓	1,200.00
22	2 pcs	Rear Bumper Side Retainers	90.00	✓	180.00
23	2 pcs	Rear Bumper Attachment Retainers	81.00	?	162.00
24	1 set	Rear Bumper Clips	uu	✓	50.00
25	1 pc	Rear Bumper Apron Garnish		?	129.10
26	1 pc	Rear Bumper Reinforcement		?	650.00
27	2 pcs	Rear Bumper Reinforcement Bracket	171.00	?	342.00
28	2 pcs	Rear Bumper Reflectors	65.00	?	130.00
29	1 pc	Rear Bumper Lower Skirt		?	550.00
30	1 pc	Rear Bumper Tow Cover	def	✓	35.00

C/F

9,629.00

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLS 9142Y

B/F

9,629.00

1	1 pc	End Panel Outer		7	469.50
2	1 pc	End Panel Top Trim		7	293.70
3	1 set	End Panel Top Trim Clips	WZ	✓	30.00
4	1 pc	Rear Floor Panel Top Tray Box		7	495.70
5	1 pc	Rear Floor Panel Top Sponge		7	191.00
6	1 pc	Rear Key Antenna Sensor		7	178.10
7	2 pcs	Taillamps	326.20	7	652.40
8	2 pcs	Taillamps Inner Sealer	38.00	7	76.00
9	2 set	Taillamps Clips	25.00	X	50.00
10	2 pcs	Rear Fender Inner Trim	356.70	X	713.40
11	2 set	Rear Fender Inner Trim Clips	30.00	✓	60.00

12,838.80

Special Nett

1	1 pc	Rear Windscreen Sealant			60.00
2	1 pc	Rear Number Plate with Cover			70.00
3	1 set	Reverse Camera <i>Sensor</i>		220	250.00
4	1 set	Body Panel Joint Sealant			120.00

40
40
52
80

Labour charge

Panel Beating		1,200.00
Spray painting		1,200.00
Check Wiring		50.00
Anti rust		100.00
Remove and install rear winscreen.		140.00
Remove and install tailgate parts.		90.00
Remove and install carpet and seat.		120.00
Remove and install reverse sensor		90.00

800
201
30
40
120
60
60
60

\$ 16,328.80

Not Authorised
4/5 Repur
After paint Plak
WCC Authorised
16/11/2017 @
7w days