

ASS: RFO BY:

REF: CS/EG17021931/ A7b⁰² Special Instructions

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Veepei Li

of

GGI

Date/Time 16/11/17 @ 3.25pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL4680E

Insured:

PC6512U

at Workshop m/s

Borneo Motors (Inch Cape)

Tel:

98476209

of

17 ubi Road 4

Policy No:

Claim No:

PC6512U / SE / PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

1/11/2017

(Client's Record)

1up

18.12.17 @ morning.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.11pm @ 16/11/17

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL4680E-X

PC6512U-X

Part by Part \$3852.62 (Red. 6164.30; 61%)

REF: EGI

ASSIGNMENT

From: _____
Estimated Cost: _____

Date: 18/12/17

OD / ☒ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLL 4680 E
at Workshop m/s Borneo Motors (Inchape)
of 17 Ubi Road 4, 408611

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL4680 E. Yr Regn: 2017 Feb.

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius. C.C. 1497

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: 13219. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTOKD3B3901593003

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ergo.

RECEIVED 0 0 MAR 2018

Date/Time: File Pass to?

1) 8/5 Typist

Date/Time: File Return to?

2) _____

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RE - SI

Photos

Others

Add Fee:

☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 3852.62)

TOTAL

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17021931/Atb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 16-11-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 6512U	Veh. Inspected	SLL 4680E
Policy No.		Coverage (\$)	0.00
Claim No.	PC6512U/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	01/11/2017	Inspection Date	18/12/2017
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 16 November, 2017 3:25 PM
To: 'admin-d@lkkauto.com'
Subject: OI : PC6512U / TP : SLL4680E/LKK / DOA : 01/11/2017
Attachments: PC6512U - SAS.pdf; SLL4680E - SAS.pdf; SLL4680E - ESTIMATE.pdf; SLL4680E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD**,

ADDRESS : 17 UBI ROAD 4

PERSON TO CONTACT : SAM JOI @ 9847 6209 / 6631 1687

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured, Third Parties SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 16.11.2017
Our Reference: PC 6512U/SE/pl
Your Reference: SLL 4680E

Sent via Fax

or

Email

Siti.Nabilah@inchcape.com.sg

To: INCHCAPE - BORNEO MOTORS (S) PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLL 4680E
Insured's Vehicle: PC 6512U
Date Of Accident: 01.11.2017


We acknowledge receipt of your request for PRS on: 15.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us today.
- ☒ Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - STEVE

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7886 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

MOTOR INSURANCE COVER NOTE

Cover Note No. 52000457

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 156351
Name of Insured : YAP AH SENG
Make and Description of Vehicle : TOYOTA PRIUS C 1.5A
Vehicle Registration No. :
Year of Manufacture : 2017
Engine No. : 1NZR492932
Chassis No. : JTDKD3B3901593003
Capacity : 1,498 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : One year from Date of Registration of the vehicle with LTA
Excess (SGD) : As Agreed
Finance Company : UNITED OVERSEAS BANK LIMITED

I/We hereby certify that this Covering note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative



Assure Pte Ltd

MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers

Amy Ler
Senior Vice President, Agencies

Date of Issue : 20/02/2017

This covering note is valid for 30 days from the date of issue.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8628689J**

Name: **YAP JIE HAN, JARON**

Birth Date: **03 Oct 1986**

Issue Date: **07 Jul 2006**

001430670K




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8628689J**

Name: **YAP JIE HAN, JARON**

叶杰汉

Race: **CHINESE**

Date of Birth: **03-10-1986**

Sex: **M**

Country of Birth: **SINGAPORE**

S8628689J




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars ≤ 3000kg with ≤ 7 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg

PASS DATE: **07 Jul 2006**



NP 428A

A0074362

S8628689J

APT BLK 265C PUNGOL WAY #09-344

SINGAPORE 823265

NRIC No: S8628689J

Date: 18/03/2014






Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

17 Ubi Road 1

Singapore 40871

Tel no: 6431 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No S1000010/ICN13	Customer Detail
Eigo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		Document No 0	Mr Yap Ah Song 2035 Compassvale Road #14-71 Singapore 543203 Mobile: 97421161
		Document Date 19/12/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ASCVB	E4	27/02/2017	SLL4680E	11188	15439	7DS/SLL4680E/01111
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTKKD3B3901593003	1N22J92932	20	Sap San Joo	02/12/2017	0.00	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDAY BUNKERIES TP-DIRECT SETTLEMENT TP-PC6512U DRIVE IN: 01/11/2017 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				330.00
		BP-SUBLET SEALANT - BONNET				80.00
		BP-SUBLET CHECK LIGHTING & WIRING SYSTEM				104.72
		BP-SUBLET FRT NUMBER PLATE				90.00
		BP-SUBLET REPLACE FRT BUMPER, BONNET, ETC				1232
		STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREA				1012
		BP-SUBLET RESPRAY JOB ON FRT ACCIDENT AFFECTED AREA				263.90
		AS				
	1	T52119-52996 COVER, FR BUMPER	1.00	452.40		452.40
	2	T52536-52110 RETAINER, BUMPER LH	1.00	58.30		58.30
	3	T52536-52150 RETAINER, BUMPER RH	1.00	58.30		58.30
	4	T53395-52050 SEAL, HOOD	1.00	23.60		23.60
	5	T52521-52040 RETAINER, FR BUMPER	1.00	79.20		79.20
	6	T52611-52150 ABSORBER, FR BUMPER	1.00	70.30		70.30
	7	T53141-52080 GARNISH, RADIATOR	1.00	263.90		263.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3566845

TO SECURITY GUARD

3566845

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 19/12/2017
TIME 08:55

VEHICLE NO SLL4680E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingapore.com.sg

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1122

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
Siga Insurance Pte Ltd 5 Temasek Boulevard #01-01 Suntec Tower Five Singapore 038989 Attn: Motor Claims Dept	S1000010 / IONIS Document No 0 Document Date 18/12/2017	Mr Yap Ah Beng 2035 Compassvale Road #14-71 Singapore 549203 Mobile: 97421161

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ARKVB	E4	NHPIOR	27/02/2017	SLL4680E	11148	15409 /DS/ SLL4680E/ 01111
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDK33B3901693003	1NR492912	00	SAN SAN JOI	02/11/2017	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	2	T53111-52780 GRILLE, RADIATOR <i>Set of 2 x 1 m</i>	1.00	227.00		227.00 X
13	9	T52114-52120 BRACKET, FR BUMPER <i>Ango</i>	1.00	97.40		97.40 ✓
14	0	T53301-52370 HOOD SUB-ASSY <i>Set of 2</i>	1.00	740.50		740.50 ✓
17	1	T53208-52901 SUPPORT S/A, HOOD <i>m m</i>	1.00	170.00		170.00 X
18	2	T81150-52K60 HEADLAMP ASSY, LH <i>Not m</i>	1.00	2993.30		2993.30 X

LKK Auto Consultants hereby notify the Reparer of the following:

- To resolve, replace or repair damaged
- To display damaged damaged vehicle
- Parts prices are correct
- Third party survey is to be completed
- No illegal modification is made
- Supplementary estimate will be issued

is subject to final approval from LKK Auto Consultants

Acknowledged by Reparer
Signature: _____
Date: _____

Adrian Ling
18/12/17.
04 Days

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	10,016.92
	Please acknowledge receipt of vehicle	Parts 5,234.20	GST 7.00%	701.18
		Labour 10.00		
		Materials 4,752.72	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	10,718.10

PLEASE TEAR ALONG PERFORATED LINE

3566846

TO SECURITY GUARD

3566846

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE
TIME18/12/2017
05:55

VEHICLE NO

SLL4680E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Attn: Motor Claims Dept

S1000010 / ICN13

39006143

12/02/2018

Mr Yap Ah Seng
203E Compassvale Road
#14-71
Singapore 545203
Mobile: 97421161

17 AHXVB E4 NHP10R 27/02/2017 SLL4680E 11148 15439 7DS/SLL4680E/01111

JTDK3B3901593003 1NZR492932 60 Sam San Joi 02/11/2017 11.24 --/--/---- 0.00

1	Z	BP-SUNDRY	SUNDRIES	TP-DIRECT SETTLEMENT		30.00
		TP-PC6512U		ACC DATE:01/11/2017		
		DRIVE IN:01/11/2017				
		DATE-IN:18/12/2017		DATE SURVEY:18/12/2017		
		NO OF REPAIR DAYS:5 DAYS				
		BY:ADRIAN(LKK)				
2	S	BP-SUBLET	SEALANT - BONNET	A45		80.00
3	S	BP-SUBLET	CHECK LIGHTING & WIRING SYSTEM	A45		104.72
4	S	BP-SUBLET	FRT NUMBER PLATE	E33		80.00
5	S	BP-SUBLET	REPLACE FRT BUMPER, BONNET, ETC	A45		1232.00
		STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				
6	S	BP-SUBLET	RESPRAY JOB ON FRT ACCIDENT AFFECTED AREAS	A45		1012.00
		AS				
7	1	T52119-52996	COVER, FR BUMPER	1.00	452.40	452.40
8	2	T53395-52050	SEAL, HOOD	1.00	23.60	23.60
9	3	T53301-52370	HOOD SUB-ASSY	1.00	740.50	740.50
10	4	T52114-52120	BRACKET, FR BUMPER	1.00	97.40	97.40

3,852.62

1,313.90 GST 7.00% 269.68

30.00

2,508.72 0.00

0.00

0.00

4,122.30

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

12/02/2018

16:23


SLL4680E

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17021931/Atbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 09-05-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6512U	Veh. Inspected	SLL 4680E	
Policy No.		Coverage (\$)	0.00	
Claim No.	PC6512U/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	16/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKD3B3901593003	Colour	SILVER	
Odometer	13219	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2017	Inspection Date	18/12/2017	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4680E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER,FR BUMPER (SN)	DEFORMED	452.40	452.40
1	RETAINER,BUMPER LH (SN)	NOT NECESSARY	58.30	-
1	RETAINER,BUMPER RH (SN)	NOT NECESSARY	58.30	-
1	SEAL,HOOD (SN)	NECESSARY	23.60	23.60
1	RETAINER,FR BUMPER (SN)	NOT NECESSARY	79.20	-
1	ABSORBER,FR BUMPER (SN)	NOT NECESSARY	70.30	-
1	GARNISH,RADIATOR (SN)	NOT NECESSARY	263.90	-
1	GRILLE,RADIATOR (SN)	NOT NECESSARY	227.00	-
1	BRACKET,FR BUMPER (SN)	DAMAGED	97.40	97.40
1	HOOD SUB-ASSY (SN)	DENTED	740.50	740.50
1	SUPPORT,S/A HOOD (SN)	NOT NECESSARY	170.00	-
1	HEADLAMP ASSY,LH (SN)	NOT NECESSARY	2,993.30	-
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	FRT NUMBER PLATE (SN)	BENT	80.00	80.00
1	SEALANT-BONNET (SN)	NECESSARY	80.00	80.00
			5,424.20	1,503.90
LABOUR				
CHECK LIGHTING & WIRING SYSTEM.			104.72	104.72
REPLACE FRT BUMPER,BONNET,ETC.STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS.			2,464.00	1,232.00
RESPRAY JOB ON FRT ACCIDENT AFFECTED AREAS.			2,024.00	1,012.00
			4,592.72	2,348.72
GRAND TOTAL			10,016.92	3,852.62
RECOMMENDED COST OF REPAIRS				3,852.62

Report Ref No. CS/EGI17021931/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.