















































P&R Automotive Consultancy

Regn No: S29869741

Thomson Rd Post Office PO Box 029 Singapore 913701 Tel: 645 31173, Fax: 645 36131.

Report No: 0164-16-N51

28 March 2016

ACCIDENT VEHICLE SURVEY REPORT

Neo & Cheong Engineering Svs
1017 Yishun Ind Park A #01-240
Singapore 768759

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	GBD8118Y	<i>Odometer:</i>	18905km
<i>Make & Model:</i>	Toyota Hiace 3.0 DX A	<i>Colour:</i>	White
<i>Chassis number:</i>	KDH2015017850	<i>Date of accident:</i>	08/01/2016
<i>Year of Regn.:</i>	26/06/2015	<i>Date inspected:</i>	11/01/2016
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

