



SINGAPORE
POLICE FORCE



J/20171116/2165

POLICE REPORT (NP322)

CONTINUATION OF REPORT

2 of 2

Report No. J/20171116/2165

S/N	Item	Type	Brand/ Account/ Property/ Security- Type	Make/ Model/ Bank/ Address/ Counter	Serial No./ IMEI/ Acct No.	Quantity	Value	Description
1	Licence	Lost	Qualified Driving Licence			1		One driving licence bearing Ang Yeow Honh of S7013836J

Signature Of Officer Recording The Report:

J / Sgt 2 SIAU JING YANG

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp CHIEW YAN LIN
Contact No.: 63167654

Authentication Stamp

Signature Of Informant

Date/Time:
16/11/2017 19:53

Classification Of Case:

FUPO hotline number: 68429645

Sketch Plan #5



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MX.1

MERCEDES-BENZ MOTOR INSURANCE

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00

(For policies with effect from 1st November 2002)

CERTIFICATE NO. 2100489527-00000

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SJL332K

Ang Yeow Hong

1 Dec 2016

30 Nov 2017

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MERCEDES-BENZ AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Loop Service Center - 188 Pandan Loop (Tel: 6777 8388)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ebuoz - 30 Bukit Batok Cres (Tel: 66547777)

4. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Hunt (Meng Kee) Motor - 21 Sin Ming Rd (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE 15 Days Replacement Car only for repairs at C & C - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN MERCEDES-BENZ FINANCIAL SERVICES (S) LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 6 Dec 2016

AIG Asia Pacific Insurance Pte. Ltd.

S04380-258
CYCLE & CARRIAGE - TT
239 ALEXANDRA ROAD SINGAPORE 159930

AUTHORISED REPRESENTATIVE

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Transfer Fee

Vehicle Details	
Vehicle No.	SJL332K
Vehicle Type	P10 - Passenger Motor Car
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	MERCEDES BENZ
Vehicle Model	E200 AVG (R18 LED)
Chassis No.	WDD2130422A078906
Propellant	Petrol
Engine No.	27492030779813
Engine Capacity	1991 cc
Maximum Power Output	135.0 kW (181 bhp)
Maximum Laden Weight	2265 kg
Unladen Weight	1605 kg
Year Of Manufacture	2016
Original Registration Date	01 Dec 2016
Lifespan Expiry Date	-
COE Category	B - Car above 1600cc or 97kW (130bhp)
Quota Premium	\$56,500.00
COE Expiry Date	30 Nov 2026
Road Tax Expiry Date	30 Nov 2017
PARF Eligibility Expiry Date	30 Nov 2026
Inspection Due Date	30 Nov 2019
Intended Transfer Date	29 Nov 2017
CO2 Emission	142.00 (g/km)
CEVS Rebate Utilised Amount	-
The current road tax expiry is 30 Nov 2017. You may renew the road tax from 01 Sep 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 30 Nov 2017, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable (From 01 Dec 2017 to 31 May 2018)	

Enquiry on Vehicle Recall - Vehicle Specific

ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	3836J
Vehicle Details	
Vehicle Registration number	SJL332K
Make	MERCEDES BENZ
Vehicle Model	E200 AVG (R18 LED)
Engine No.	27492030779813
Chassis No.	WDD2130422A078906
Recall Details	
1	Recall No. R2017090433
	Manufacturer Recall Date 30 Jan 2017
	Estimated Completion Year of Recall 2018
	Brief Description (As Provided by Motor Dealer) The wiring harness to the front windshield wiper motor in the area of the windshield wiper linkage may have been routed in a manner that does not correspond to the specification
	Date Rectified -
	For more details, contact DAIMLER SOUTH EAST ASIA PTE. LTD.
	Hotline Information CYCLE&CARRIAGE CUSTOMER ASSISTANCE CENTRE at 6471 9111

OK



Auto
Consultants
Pte Ltd

STATEMENT

PARTICULARS

Name : ANG YEOW HONG
 NRIC / Passport No. : S7013836 J
 Address : BLK 12 TECK WHYE LANE #12-220 S 680012
 Telephone : (R) _____ (O) _____
 (HP) 86852332, 81047212
 Sex / Age : M / 47
 Occupation / Name of Company : HAWKER / ANG ENTERPRISE (SELF EMPLOYED)
 Nationality : SINGAPOREAN

Recorded By : MUHAMMAD NAZRIL Date : 29/11/17 Time: 1430
 Place Recorded: BLK 10 TECK WHYE LANE
 Language Spoken: ENGLISH Interpreted By: N/A

FACTS OF CASE:


I am the owner and driver of vehicle no. SJL 332K involved in the accident on 16/11/17 at 0300 hours. I was from JB with my friend. I dropped him off near BLK 12 Teck Whye Lane at 0300 hours. So I proceeded to exit the carpark. It was a very open carpark. As I turned left I hit a parked van. The impact caused the van to hit the vehicle beside it. I don't know how I hit the van. I was travelling at 20kmph. After I hit the van I waited for 10 minutes for the owner to show up. After nobody came, I left and went to Yew Tee as my friend who owns a car servicing workshop. I tried calling him as I wanted to repair my car there. He told me that my car is only 11 months old and told me to go to Cycle and Carriage to make an insurance report. I called my worker and told him to meet me at the carpark at my house. As I was driving back home along Choa Chu Kang Drive I got stopped by a police road block just before Choa Chu Kang Avenue 1 junction. I told the police officer that I had hit a van. He conducted a breathalyzer test on me to see if I had been drinking. The test proved negative for alcohol. I reached my carpark and my worker was there. I parked my car and asked my worker to drive me to the

Signed: [Signature]

Recorded by: [Signature]

S7013836 J

MUHAMMAD NAZRIL
 LKK AUTO CONSULTANTS



Auto
Consultants
Pte Ltd

STATEMENT

accident site. I reached at about 0415 am. 2 traffic police officers were there and also the owner of car no. SKG 6535. The owner of the van no. GX 4227C was not there. I took photos of the accident scene and of the 2 vehicles I hit. I told the TP officer what had happened. He asked if I was drinking and I said no. The TP officer then said there was no case and told me to put my contact number on the windshield of the van. The owner of SKG 6535 wanted to report his car at his own workshop. I suggested using my workshop but he refused. So I told him to claim against my insurance. The TP officers left at about 0450 hours.

The next day I made an insurance report at Cycle & Carriage at Garden Lane at 1738 hours. C & C towed my car there by the time I was done.

During the police road block the police officer asked for my IC & driving licence but I could not find it in my wallet or in my car. So he told me to make a police report which I did at the Chea Chin Kang NPP on 16/11/17 at 1953 hours.

I then returned to C & C and submitted my police report for my lost IC on 16/11/17 in the afternoon.

The owner of GX 4227C called me on 17/11/17 and told me that he will claim against my insurance for the damages to the van.

I affirm that I did not consume any alcohol or medication that may cause drowsiness and impair my ability to drive.

I ~~to~~ confirm that the above statement is true and correct at the time it was written.

Signed: 

Recorded by: 

SJ0138365

MIND NOZEL
LCC AUTO CONSULTANTS

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2017 Edit Reg		16 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	Ang Yeow Hong, ID: S7013836J	[Created by adjuster]
Main Claimant:	CHENG FARM, Co. Reg. No.: 30476800J	
Vehicle Reg. No.:	GX4227C	
Claim Type:	TP / 1126214345SG	Date of Loss: 16/11/2017 02:00 - :59
Vehicle Reg. No. (Insured):	SJL332K	Policy/Cover Note No.: 2100489527 (Comprehensive) Coverage: 01/12/2016 - 30/11/2017
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271	Policy No. (Claimant): Excess:
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 30/11/2017]	
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026	

ASSOCIATED MAIL RECEIVED

- AIG_SG (22/11/2017): Request To Upload TP GIA Report [View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									Done?

Claim Documents

*GX4227C (1126214345SG)
[SJL332K]
TP
CHENG FARM
Nov 16 2017 2:00AM
[Ang Yeow Hong]
Eng Soon Painting Services

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Assessment Reports			1 per page v ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	22/11/17 11:19	Accident Statement From:OD - Reg. No: SJL332K, Claimant: ANG YEOW HONG	☒ Load HTM	☐ Print
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	16/01/18 17:43	General View	☒ Load JPG	☒ Print
2	16/01/18 17:43	General View	☒ Load JPG	☒ Print
3	16/01/18 17:43	General View	☒ Load JPG	☒ Print
4	16/01/18 17:43	General View	☒ Load JPG	☒ Print
5	16/01/18 17:43	General View	☒ Load JPG	☒ Print
6	16/01/18 17:43	General View	☒ Load JPG	☒ Print
7	16/01/18 17:43	General View	☒ Load JPG	☒ Print
8	16/01/18 17:43	General View	☒ Load JPG	☒ Print
9	16/01/18 17:43	General View	☒ Load JPG	☒ Print
10	16/01/18 17:43	General View	☒ Load JPG	☒ Print
11	16/01/18 17:43	General View	☒ Load JPG	☒ Print
12	16/01/18 17:43	General View	☒ Load JPG	☒ Print
13	16/01/18 17:43	General View	☒ Load JPG	☒ Print
14	16/01/18 17:43	General View	☒ Load JPG	☒ Print
15	16/01/18 17:43	General View	☒ Load JPG	☒ Print
16	16/01/18 17:43	General View	☒ Load JPG	☒ Print
17	16/01/18 17:43	General View	☒ Load JPG	☒ Print
18	16/01/18 17:43	General View	☒ Load JPG	☒ Print
19	16/01/18 17:43	General View	☒ Load JPG	☒ Print
20	16/01/18 17:43	General View	☒ Load JPG	☒ Print
21	16/01/18 17:43	General View	☒ Load JPG	☒ Print
22	16/01/18 17:43	General View	☒ Load JPG	☒ Print
23	16/01/18 17:43	General View	☒ Load JPG	☒ Print
24	16/01/18 17:43	General View	☒ Load JPG	☒ Print
25	16/01/18 17:43	General View	☒ Load JPG	☒ Print
26	16/01/18 17:43	General View	☒ Load JPG	☒ Print
27	16/01/18 17:43	General View	☒ Load JPG	☒ Print
28	16/01/18 17:43	General View	☒ Load JPG	☒ Print
29	16/01/18 17:43	General View	☒ Load JPG	☒ Print
30	16/01/18 17:43	General View	☒ Load JPG	☒ Print
31	16/01/18 17:43	General View	☒ Load JPG	☒ Print

32	16/01/18 17:43	General View		Load JPG	☒
33	16/01/18 17:43	General View		Load JPG	☒
34	16/01/18 17:43	General View		Load JPG	☒
35	16/01/18 17:43	General View		Load JPG	☒
36	16/01/18 17:43	General View		Load JPG	☒
37	16/01/18 17:43	General View		Load JPG	☒
38	16/01/18 17:43	General View		Load JPG	☒
39	16/01/18 17:43	General View		Load JPG	☒
40	16/01/18 17:43	General View		Load JPG	☒
41	16/01/18 17:43	General View		Load JPG	☒
42	16/01/18 17:43	General View		Load JPG	☒
43	16/01/18 17:43	General View		Load JPG	☒
44	16/01/18 17:43	General View		Load JPG	☒
45	16/01/18 17:43	General View		Load JPG	☒
46	16/01/18 17:43	General View		Load JPG	☒
47	16/01/18 17:43	General View		Load JPG	☒
48	16/01/18 17:43	General View		Load JPG	☒
49	16/01/18 17:43	General View		Load JPG	☒
50	16/01/18 17:43	General View		Load JPG	☒
51	16/01/18 17:43	General View		Load JPG	☒
52	16/01/18 17:43	General View		Load JPG	☒
53	16/01/18 17:43	General View		Load JPG	☒
54	16/01/18 17:43	General View		Load JPG	☒
55	16/01/18 17:43	General View		Load JPG	☒
56	16/01/18 17:43	General View		Load JPG	☒
57	16/01/18 17:43	General View		Load JPG	☒
58	16/01/18 17:43	General View		Load JPG	☒
59	16/01/18 17:43	General View		Load JPG	☒
60	16/01/18 17:43	General View		Load JPG	☒
61	16/01/18 17:43	General View		Load JPG	☒
62	16/01/18 17:43	General View		Load JPG	☒
63	16/01/18 17:43	General View		Load JPG	☒
64	16/01/18 17:43	General View		Load JPG	☒
65	16/01/18 17:43	Odometer Reading		Load JPG	☒
66	16/01/18 17:43	General View		Load JPG	☒
67	16/01/18 17:43	Chassis Number		Load JPG	☒
68	16/01/18 17:46	Photo After Spray		Load JPG	☒
69	16/01/18 17:46	Photo After Spray		Load JPG	☒
70	16/01/18 17:46	Photo After Spray		Load JPG	☒
71	16/01/18 17:46	Photo After Spray		Load JPG	☒
72	16/01/18 17:46	Photo After Spray		Load JPG	☒
73	16/01/18 17:46	Photo After Spray		Load JPG	☒
74	16/01/18 17:46	Photo After Spray		Load JPG	☒
75	16/01/18 17:46	Photo After Spray		Load JPG	☒
76	16/01/18 17:46	Photo After Spray		Load JPG	☒
Documentation				1 per page ☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/12/17 11:33	SJL 332K INTERVIEW REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	16/01/18 16:39	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17021962/SBE2
 Date: 29/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100489527
 Claimant Vehicle No: GX4227C Insured Vehicle No: SJL332K
 Date of Loss: 16/11/2017 Nature of Claim: TP Claim No: 1126214345SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GX4227C**
 Make & Model: NISSAN URVAN, 3.0 D (A)
 Reg. Date: 04/05/2004 (Man. Year: 2004) Engine No: ZD30039457
 Colour: Silver Chassis No: JN1MG4E25Z0711235
 Engine Capacity: 2953 cc Odometer: 320006 km
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15
 Front Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm
 Rear Tyre Size: 195 R15
 Rear Left Side: Bridgestone 6 mm
 Rear Right Side: Bridgestone 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/11/2017
 Date Inspected: 17/11/2017 Inspected At: Eng Soon Painting Services (HQ)
 393J WOODLANDS ROAD
 Singapore 677978
 Estimated Period of Repair: 7.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT RH BUMPER FOG LAMP	Damaged	0.00 F	*- F
6	1		*FRT GRILLE	Cut	0.00 F	*- F
7	1		*FRT CORNER PANEL LH	Dented	0.00 F	*- F
8	1		*FRT SIGNAL LAMP LH	Cracked	0.00 F	*- F
9	1		*FRT SIGNAL LAMP RH	Cracked	0.00 F	*- F
10	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
11	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*AIR CON LIQUID PIPE	Bent	0.00 F	*- F
13	1		*FRT LH DOOR	Dented	0.00 F	*- F
14	1		*FRT LH DOOR HINGE	* Check	0.00 F	*- F
15	1		*FRT STEP PANEL	Dented	0.00 F	*- F
16	1		*FRT STEP PANEL TOP GARNISH	Cracked	0.00 F	*- F
17	1		*FRT RH BUMPER FOG LAMP COVER	Deformed	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >