ASS: REC. BY:	REF. CS/EG117021977/AVbelloperial Internation
SURVEYOF:	Addiun ASSIGNMENI (Office)
Estimated Cost	Yeu Pei di on EGI DeterTime 15/11/17 @ 4.24pm
OD (IP) WS	TP RES / OD RES / EVA / INV / MV / CS
To Inspect Veh	icle No: SKM 9278 H Insured: SGY 2022J
at Workshop m	JD Motorsports To 9023 4180
or 110.55 k	caki Bukit Ave 4 # 06-38 Synergy > 417800
	Claim No: S(M) 20127 / SE/p1
Sum Insured _	Excess.
Make of Veh: (Client's Record)	D.O.A. 9/11/2017
	REP. / REV 24 HRS 407 1117 117 117 117 117 117 117 117 117
Date/Time 4	S6pm O S/II/14 Person Contacted Mr - 800 Vehicle DOUT
Date/Time	Action/Instruction () Estimate
	SKM 9278H-X
	39420225-CC6/A1916022318/Uyb3g2-D.O.A:20/11/2016
भागाम	Informed Pei Li pending workshop est by email
SIXIA	Adrian Confirmed LS \$ 7200 (Red 18 893, 729)
म्।	Email preli revised to Pei Li

		ASSIGNMENT	
	20/11/17	SKM9278H. 2016 FM	Q,
From Estimated Cost		Type M.Cay / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /	
•	DD RES / EVA / INV / MV	Truck / Traller or	
OD (P) WS / TP RES / C	SKM 9278 H	BMW 3181 1499.	
et Workshop mis	JD Motorsports	Colour Red . AC Insured Std NI NA	
	okt the 4 # 06-38 Sy	Vineral St. Reading 40208 / TPacs Insured Std NI NA	
	JK4 1106 4 11 00 30 -1		
insured Policy No.		CNO WBASE360504.789411	
Diams No		Gen Gond Wood / Fair / Poor / Burnt	
Sum Insured	Excess	Steering Inopto Jammed / Leaked / Burnt of	
(Client's Record)		Brake Ingger / Jammad / Leaked / Burnt or	
Make of Veh	Mr-500	Modi NII SiRim STD A/Rim of	
11.	im owner	Tyre Size F: 225/508-17.	
	waiting	R 225/50R17.	
Remark: The veh had co	ommenced its N.S.	O/S B DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI	
repair at the ti	me of inspection.	TOYO / YOKO or	
Sal, or Market Value:		<u>Front</u> <u>Eear</u>	
DAC Accident Room	Consistent? Yes or No.	R/Bal of mm P.Bal 0.6 mm	
GIA / PR Seen.	Consistent? Yes or No.	LBal 96 mm LBal 06	-
Est Repairs:	days Res Yes or No	5.0 A 50 1 20 11 17	
Lum Sum	s _b 3 Val. Yes or No.	Survey held as JD Molors golf.	
CA / REV / REP.	1 24 HRS Wp)	Des of Damages Frt (Res) O/S N/S U/C Rooftop or	
	• Vehicle	IN / OUT	
	Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collisi	
Date Time Action	n instruction TP Ecgo.		
	0		
	RECEIVE	D 0 0 1 2017	
	11-0-0		
		Days Of Repair: 5	
Deserve Fie Passiti	: Prell. Report	Resurvey No. of Trip: 2 Sune Fee 39	0
Date Time File Return to	: Final Report	Resulted to the second	
		Add Fee: Steinsc S1+81_1	
typish	1	Telephon 8 Post	
Report Format :		Test of St	
Lump Sum / LB II		Nas and 3	
Anna Anna		29	()

Survey Department Check List (Case Handler)
Reference No.: (S) EGエレオのメタオナ Avb
Policy Type: OD / TP / TP RES / TL / EVA

Typist

dmin (): Case handler to make sure all Info Assign Form	Y-Date	N-Date	<u>Y-Date</u>	N-Date
C	Reference No.	~			
С	Customer Code				
N	Assign From				
С	Assign Date	_			
С	Veh No (Inspected)	~			-
С	Veh No (Insured)	~			-
c	D.O.A	~			
c	Policy No				
c	Claim No	~			
c	Insurance Authorisation (CA /REV/REP)				
c	Report Type	~			
c	Weekend Charges				
N	Survey held at/Repairer	~			
c	Excess				
	nment Form	e the surveryor c	ompleted a	all required	informa
С	Vehicle No	7	+		1
С	Regn Month/Year	-			+
N	Vehicle Type	- VECT	-		+
N	Make & Model				+
C	Engine Capacity. (C.C)	~			+
N	Colour	~			1
С	Odometer. (Sp.Reading)	~	-		+
С	Chassis No	~	1		-
N	General Condition	7		-	
N	Steering	~			-
N	Brake	~		-	-
N	Modification (Modi)			-	-
С	Tyre Size	~		-	+
N	Tyre Make	~		-	+-
С	Tyre Balance	V		-	
С	Date of Inspection	~		-	_
N	Survey held	~		-	
N	Des.of Damages	~		J L	
(2) Syst	em - (Views/Merimen)				
C	Damaged Vehicle Photographs Uploaded	~			
(3) Wo	rkshop Estimate/Assignment Form			1	
N	ALL Parts condition	V		-	
С	Market Value for OD cases			-	
С	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
С	Days of repair	~		-	
С	Finalised Amount	~		-	
	Re-inspection Cases to Finalize within 5 Days				
С					
	tem - (Views/Merimen) Resurvey photo Uploaded				

Date

Case Handler



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

是不是Brett,以由19	Affiliated to Federation Internal		
RGO INSURANCE PT	E LTD	Ref : CS/EGI170219	77/Avb
TEMASEK BOULEVA 104-01 SUNTEC TOWE SINGAPORE 038985	ARD ER FIVE	Date: 17-11-2017 Code: EGI	
l.	Policy Particular	rs :- THIRD PARTY CLA	IM
Insured Veh.	SGY 2022J	Veh. Inspected	SKM 9278H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	17/11/2017
2.	Vehicle Pa	rticulars & Condition	
Make & Model	A STATE OF THE STA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	•	Steering	
Brakes		Modification	
General			
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4.	Descri	iption of Damages	
	Gon	eral Information	
5.	09/11/2017	Inspection Date	
Accident Date			
Survey held at	25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800	· ·	
5a.	Salata Control Control	Remarks	

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

To:

Tuesday, 5 December, 2017 3:01 PM 'Survey Report (ERGO Insurance Pte. Ltd.)'

Cc:

Subject: Attachments: RE: SGY2022J / TP : SKM9278H/LKK / DOA : 09.11.2017

SKM 9278H PRELI REVISED.pdf

Dear Pei Li.

Enclosed preliminary revised of vehicle SKM 9278H

Date of survey: 20/11/2017 Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 21 November, 2017 9:22 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Dear Pei Li,

Please be informed that we have inspected the vehicle SKM 9278H on 20/11/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 17 November, 2017 10:59 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' < Survey Report@ergo.com.sg>; assignments

<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>

Subject: RE: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Wednesday, 15 November, 2017 4:24 PM

To: 'admin-d@lkkauto.com'

Subject: OI: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from RIAZ LLC,

ADDRESS

: JD MOTORSPORTS PTE LTD NO 25 KAKI BUKIT AVENUE 4

#06-38 SYNERGY @ KB SINGAPORE 417800

PERSON TO CONTACT

: RONNIE TAY @ 9237 3644

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.



Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

SGY2022J/SE/pl

Our ref:

CS/EGI17021977/Avb

Date: 5/12/2017

Without Prejudice

The Motor Claims Department

M/s: ERGO Insurance Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.SKM 9278H

We thank you for your instruction on 15/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2017 at the premises of M/s

JD MOTORSPORTS PTE LTD and have the following to report:-

Workshop Estimate Amount	: \$\$26,093.00
Revised Estimate Amount	: S\$7,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the

rear portion.

nearside

offside

rear

front

Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 21 November, 2017 9:22 AM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'

Cc:

SUR

Subject:

RE: SGY2022J / TP : SKM9278H/LKK / DOA : 09.11.2017

Dear Pei Li,

Please be informed that we have inspected the vehicle SKM 9278H on 20/11/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 17 November, 2017 10:59 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments

<assignments@lkkauto.com> Cc: SUR <sur@lkkauto.com>

Subject: RE: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Wednesday, 15 November, 2017 4:24 PM

To: 'admin-d@lkkauto.com'

Subject: OI: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from RIAZ LLC,

: JD MOTORSPORTS PTE LTD ADDRESS

> NO 25 KAKI BUKIT AVENUE 4 #06-38 SYNERGY @ KB SINGAPORE 417800

PERSON TO CONTACT

RONNIE TAY @ 9237 3644

ERGO OFFICER-IN-CHARGE

STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor) ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Nivitha (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Wednesday, 15 November, 2017 4:24 PM

To:

'admin-d@lkkauto.com'

Subject:

OI: SGY2022J / TP: SKM9278H/LKK / DOA: 09.11.2017

Attachments:

SGY2022J - SAS.pdf; SKM9278H - SAS.pdf; SKM9278H - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from RIAZ LLC,

ADDRESS

: JD MOTORSPORTS PTE LTD

NO 25 KAKI BUKIT AVENUE 4

#06-38 SYNERGY @ KB SINGAPORE 417800

PERSON TO CONTACT

RONNIE TAY @ 9237 3644

ERGO OFFICER-IN-CHARGE

STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor) ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Tel.: 65 6829 9199 DID: 65 6829 9194 Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

atu:	14.11.2017		Sent via Fax	6534 0220
ur Reference:	SGY 2022J/SE/pl	vertex and	L	
	SKM 9278H(H)		or —	
our Reference;	SKINI SES CITICIS		Email	2
o:	RIAZ LLC			1 145
re-Repair St	urvey (PRS) Acknowledgement	F		
ehicle For Insp				
sured's Vehic	4.0V.0001			
ate Of Accident: 09.11.2017				
		14.11.2017	i)	
	ge receipt of your request for PRS on: with "State Courts Practice Direction			
	and indicate your selection in the box			* LKK Auto Consuctant
AIS	Automobile Inspection Services Pte L	td LBS		sultants Pte Ltd
MIZ			LKK Auto Cons	ultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK		
	Infiniti Appraisal Service	PS	Priority Service	15
FTA IAS JPK V Yourreq	Infiniti Appraisal Service JP Knights Pte Ltd uest for inspection does not have your c	PS VAC	Vicom Ltd	
FTA IAS JPK V Yourreq Yourreq We ackn Ourless	infiniti Appraisal Service JP Knights Pte Ltd uest for inspection does not have your clust for inspection does not have your clowledge your interest for direct settlements driver has not reported the accident	PS VAC lient's cost of repair as lient's GIA report, kindlent, we will assess & re	Vicom Ltd timate, kindly forward a copy.	vard a copy.
FTA IAS JPK V Yourreq Yourreq We ackn	infiniti Appraisal Service JP Knights Pte Ltd uest for inspection does not have your cluest for inspection does not have your cluest for inspection does not have your clowledge your interest for direct settlements.	PS VAC lient's cost of repair as lient's GIA report, kindlent, we will assess & re	Vicom Ltd timate, kindly forward a copy.	vard a copy.
V Your req Your req We ackn Our insu V Others:	infiniti Appraisal Service JP Knights Pte Ltd uest for inspection does not have your clust for inspection does not have your clowledge your interest for direct settlements driver has not reported the accident	PS VAC lient's cost of repair as lient's GIA report, kindlent, we will assess & re	Vicom Ltd timate, kindly forward a copy.	vard a copy. celpt of estimate.
FTA IAS JPK V Yourreq Yourreq We ackn Ourless	infiniti Appraisal Service JP Knights Pte Ltd uest for inspection does not have your clust for inspection does not have your clowledge your interest for direct settlements driver has not reported the accident	PS VAC VAC lient's cost of repair as lient's GIA report, kindli ent, we will assess & re at to us todate.	Vicom Ltd Umate, kindly forw y forward a copy.	vard a copy.

MOR117148995 / ETHOZ Protect Pte Ltd - Bukit Batok ENTRY DATE & TIME: 10/11/2017 15:19

DENT STATEMENT

SS. \$10950 ER TO CTP.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

10/11/2017 15:19 Date Of Report 09/11/2017 19:20

Date Of Accident ALONG BKE TWDS SLE Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SKM9278H Vehicle Registration Number

Insured/Policyholder

FAN LIHUA Name Of Registered Owner S7367585E NRIC No

LIHUAFAN73@GMAIL.COM Email Address (LOCAL) +65-97327788 Mobile Phone No OFFICE-97327788 Alternative Phone No.

Vehicle Particulars

BMW Manufacturer

318I SEDAN LED NAV Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No. Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

MT/00389751 Policy Number

02/06/2017-01/06/2018 Cover Note Number

Driver

FAN LIHUA Name of Driver S7367585E NRIC NO 29/12/1973 Date Of Birth OUTDOOR Occupation 10/06/2009 Date Of Driving Pass

8 YEARS AND 4 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-97327788 Mobile Number

Fax Number

OFFICE-97327788 Contact Number

LIHUAFAN73@GMAIL.COM **FMail Address**

Address

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

NO YES

NO

NO

NO

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Details Of Froperties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SGY2022J

TOYOTA RUSH

KOO SU XIN JASMIN

S8809070E

96709910

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposets) of "...
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Service agree

Driver's Signature

(If driver is not the policyholder)

- Non-Armin

Date & Time:


eporting Centre Personnel's Signature

Name NRIC/FIN No

The second second

SKETCH PLAN

Ven A-> SKM9278 H Ven B-> SGY 2002J



I was driving along BKE towards SLE, suddruly the velocity brake. I managed to slowdown and slop. After whout 2 see huge impart from the rear. I alighted from my vehicle to	
bugg tupped from the seas. I dighted from mus vehicle to	
male mides the ten the ten	realise velise hed
but onto the rear of my vehicle.	
	Reporting Only
ou had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause	Claim OD
whereby the claim must be made within the stipulated timeframe from the day of occurance.	Claim TP Claim OD/TP at other workshop

Policyholder's Signature Date & Time:

Survivada -

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Ceptre Personnel's Signature

NRIC/FIN No



Vehicle Number: - SKM 9278 H

Model Number: - BMW 3181

Chassis Number: - WBA8E36050NT89411

Surveyor: -

Insurance: - Direct Asia vs. Ergo

TP Erys Veron

List Items:

	Olpes Rear Bootlid Dented	\$2650.00 1650
	02pcs Rear Bootlid lamp (LH)(RH)@\$825.00 x 2 LH Condiced	\$1659.00 325
	02pcs Rear Tail Lamp (LH)(RH) @ \$550.00 x 2 ⊢H ⇔t	\$1100.00 550
-	02pcs Rear Tail Lamp Rubber Garnish (LH)(RH) @ \$76.00 x 2	\$152.00 ×
	01pcs Rear Bootlid Emblem (BMW)	\$97.50
	01pcs Rear Bootlid Logo (3181)	\$85.00
,	01pcs Rear Bootlid Weatherstrip Cot	\$160.00
	01pcs Rear Bootlid Lock	\$287.50
	Olpes Rear Bumper Delind	\$1850.00 /350
	01pcs Rear Bumper Tow Cover Octob	\$95.00
	Olpes Rear Bumper Black Moulding De	\$195.00 /
0	Olset Rear Bumper Inner Bracket Center couled	\$175.00
	04pcs Rear Bumper Sensor @ \$350.00 x 4 3 pieces degd	\$1400.00 750
	Olset Rear Bumper Inner Bracket Holder Delora	\$185.00
	02pcs Rear Bumper Reflector (LH)(RH)@\$78.00 x 2 LH Lt	\$156.00 78
	Olpes Rear End Panel Rvis	\$762.50 ¥
	Olpes Rear End Panel Top Garnish Ht M	\$130.00 \(\tau\)
	Olpes Rear End Panel Insulator	\$185.00 ×
	Olpes Rear Spare Tyre Panel Ref M	\$262.50 🗼
	Olpes Rear Spare Tyre Board	\$475.00 ×

JD MOTORSPORTS

	01pcs Rear Bumper Reinforcement Inner Center E	Bracket Repended \$350.00 X	
•	01pcs Rear Bumper Reinforcement Best		85
•	01pcs Rear Bumper Heat Shield Insulator	µ ~ \$160.00 ₹	
	02pcs Rear Bumper Side Inner Garnish (LH)(R	H)@\$495.00 x 2 ペイ~ \$990.00 火	
	Olpes Rear Exhaust Pipe Assy Best	\$3850.00	1480
	02pcs Rear Exhaust Pipe Mounting @ \$185.00 x	2 Hem \$370.00 X	
	7948	Sub-Total: \$18,648.00	
ecia	al Net Items:		
	Olpes Rear Number Plate Carnish	\$45.00 ×	
	01pcs Rear Number Plate Garnish	\$50.00 🖈	
4.5.6.	To supply labour to putty & re spray accident To supply labour to re-wire electrical parts: To supply labour to remove and refit upholste To supply labour to transfer boot component: To supply labour to conduct diagnosis report	\$450.00 80 ry for repair works :- \$300.00 50 - \$250.00 60	1440.
	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Total Labour: \$7,350.00 Total Special Net: \$95.00 Total Parts: \$18,648.00 Total: \$26,093.00 Less Discount 20%: \$5,218.60	total 8590.60 L/s=7.214 05 pays.
	Signature:	Total: S20,874.40	
	The state of the s	 Control of the control of the control	

JD Motorsports PTE LTD
25 Kaki Bukit road 4 #06-38 Synergy @ KB Singapore 417800
Tel: 92373644 Fax: 64514516

Lumpsum: \$20,000.00

Date:



ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	ationale Des Experts En Autom	
RGO INSURANCE PT	E LTD	Ref : CS/EGI1702197	77/Avbe2
TEMASEK BOULEVA 04-01 SUNTEC TOWE SINGAPORE 038985	ARD ER FIVE	Date: 20-12-2017	
		Code: EGI	
	Policy Particula	ars :- THIRD PARTY CLAI	
Insured Veh.	SGY 2022J	Veh. Inspected	SKM 9278H
Policy No.		Coverage (\$)	0.00
Claim No.	SGY2022J/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	15/11/2017
2.	Vehicle Pa	articulars & Condition	
Make & Model	B.M.W 318I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA8E36050NT89411	Colour	RED
Odometer	40208	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Cor	nditions of Tyres	
J.	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
4.	Desc	ription of Damages	
	JSTAINED DAMAGES AT THI DETAILS.	E REAR PORTION.	
5.		neral Information	
Accident Date	09/11/2017	Inspection Date	20/11/2017
Survey held at	JD MOTORSPORTS PTE I	LTD	
	25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		
5a.		Remarks	
A)THE INSPECT	ION WAS CONDUCTED ON A NCE TO YOUR INSTRUCTION	A"WITHOUT PREJUDICE" BA NS. WE HAVE NOT AUTHOR	ASIS. ISED REPAIRS.
5b.	Esti	mate Days of Repair	

5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 9278H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	DENTED	2,650.00	1,650.00
2	REAR BOOTLID LAMP (LH) (RH) @\$825.00	N/S CRACKED	1,650.00	325.00
	REAR TAIL LAMP (LH) (RH) @\$550.00	N/S CUT	1,100.00	550.00
2		NOT NECESSARY	152.00	
1	REAR BOOTLID EMBLEM (BMW)	NECESSARY	97.50	97.50
1	REAR BOOTLID LOGO (318I)	NECESSARY	85.00	85.00
4	REAR BOOTLID WEATHERSTRIP	CUT	160.00	160.00
,	REAR BOOTLID LOCK	DAMAGED	287.50	287.50
1	REAR BUMPER	DEFORMED	1,850.00	1,350.00
4	REAR BUMPER TOW COVER	DEFORMED	95.00	95.00
1	REAR BUMPER BLACK MOULDING	DEFORMED	195.00	195.00
	REAR BUMPER INNER BRACKET CENTER	CRACKED	175.00	175.0
- 05	REAR BUMPER SENSOR @\$350.00	DAMAGED-3 PCS ONLY	1,400.00	750.0
	SET REAR BUMPER INNER BRACKER HOLDER	DEFORMED	185.00	185.0
	REAR BUMPER REFLECTOR (LH) (RH) @\$78.00	N/S CUT	156.00	78.0
	REAR END PANEL	TO REPAIR SEE LABOUR	762.50)
19	REAR END PANEL TOP GARNISH	NOT NECESSARY	130.00	
	REAR END PANEL INSULATOR	NOT NECESSARY	185.00	
	REAR SPARE TYRE PANEL	NOT NECESSARY	262.50	
	REAR SPARE TYRE BOARD	NOT NECESSARY	475.00	
	1 REAR BUMPER REINFORCEMENT INNER CENTER BRACKET	REPEATED	350.00	
	1 REAR BUMPER REINFORCEMENT	BENT	875.00	485.0
	1 REAR BUMPER HEAT SHIELD INSULATOR	NOT NECESSARY	160.0	0
	2 REAR BUMPER SIDE INNER GARNISH (LH) (RH) @\$495.00	NOT NECESSARY	990.0	
	1 REAR EXHAUST PIPE ASSY	BENT	3,850.0	
	2 REAR EXHAUST PIPE MOUNTING @\$185.00	NOT NECESSARY	370.0	\$15,000,000
	LESS 5% DISCOUNT			397.4
			18,648.0	0 7,550.6

Report Ref No. CS/EGI17021977/Avbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR NUMBER PLATE GARNISH (SN)	NOT NECESSARY	50.00	
			95.00	
	LABOUR			200 123 103 123
	TO SUPPLY LABOUR & PARTS TO REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		2,500.00	500.00
	TO SUPPLY LABOUR TO STRAIGHTEN CHASSIS FRAME.	NOT NECESSARY	1,500.00	
	TO SUPPLY LABOUR TO PUTTY & RE-SPRAY ACCIDENT AFFECTED AREA.		1,800.00	00.0000
	TO SUPPLY LABOUR TO RE-WIRE ELECTRICAL PARTS.	V	450.00	80.00
	TO SUPPLY LABOUR TO REMOVE AND REFIT UPHOLSTERY FOR REPAIR WORKS.		300.00	50.00
	TO SUPPLY LABOUR TO TRANSFER BOOT COMPONENT.		250.00	60.00
	TO SUPPLY LABOUR TO CONDUCT DIAGNOSIS REPORT FOR REPROGRAMMING.		550.00	100.00
			7,350.00	1,440.00
	GRAND TOTAL		26,093.00	8,990.60

RECOMMENDED COST OF LUMP SUM REPAIRS	7,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EGI17021977/Avbe2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.