

REF: CSI/LAW17021978/Tlvbe2

Special Instructions:

US: \$ 11,100.00

Third Parties:

Claimant:

Surveyor: PAR Automotive & H-51 Auto

Workshop: N-51 Automotive

From (Person): Angelina of Tam Kik Wuen Date/Time: 10.10.2017
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To inspect Vehicle No: 933 76198 Insured: SKU 770501

at Workshop m/s N-51 Automobile Tel: 6842 0051

of 2 Kalsi Bukit Ave 2 # 01-17

Policy No: TWK/AR/0966/17/qiq/ml/PP Claim No: 1210898655S6

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06-04-2016

(Client's Record)

STL

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 26/12 Confirmed with 1.1.10 Final Fig days (Red S / %; Original 9 days)

Date/Time: 28/12/17 Submit Final Fig 4/5/3610, 5 days (Red \$ 7500 / 67 %; Original days)

Date/Time	Action/Instruction
-----------	--------------------

303 76198 - CS3 / LPC13019598 / Gmzd1-1
SKU 7765m - x

DUA: 18-10-13

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 28 DEC 2017

\$350.00

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time 28/12-14:14 File Pass to

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to

Survey Department Check List (Case Handler)

Reference No.: CSI | LAW 17021928 | Tivb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON | 28/12/17
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS1/LAW17021978/T1vb

C/O: TAN KOK QUAN PARTNERSHIP
1 WALLICH STREET #07-02
GUOCO TOWERS SINGAPORE 078881

Date : 17-11-2017



Code : AIG

1. Policy Particulars :- PAPER SURVEY

Insured Veh.	SKU 7705M	Veh. Inspected	SJS 7619B
Policy No.	TWK/AR/0966/17/aig/ml/PD	Coverage (\$)	0.00
Claim No.	1210898659SG	Excess (\$)	0.00
Assign From	ANGELINE	Assign Date	10/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/04/2016	Inspection Date	17/11/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

--

Catherine Chong (LKK Auto)

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Tuesday, 10 October, 2017 6:51 PM
To: Angeline Rajoo
Cc: assignments
Subject: RE: MC Suit No. 8977/2017 - AIG Ref: 1210898659SG II Oref TKQP Ref: TWK/AR/0966/17/aig/ml/PD

Dear Angeline,

Refer to our tele-conversation today.

We confirm the charges as at below.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angeline Rajoo [mailto:angeline@tkqp.com.sg]
Sent: Tuesday, 10 October, 2017 11:48 AM
To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: FW:MC Suit No. 8977/2017 - AIG Ref: 1210898659SG II Oref TKQP Ref: TWK/AR/0966/17/aig/ml/PD
Importance: High

Dear Celine,

We act for AIG, the insurers of motor vehicle no. SKU 7705M, in respect of a claim by the owner of motor vehicle no. SJS 7619B for claims arising from the above captioned accident.

The Court has directed for parties to engage a single joint expert to conduct a paper survey report for this matter.

We proposed Mr Taufikh. I have your charges and CV from an earlier email on a another matter. We understand from your email below, that your charges are \$350 for a paper survey.

Please confirm. We look forward to hearing from you on an urgent basis.

Upon your confirmation, we shall appoint your surveyor, Mr Taufikh. as the SJE for this matter and will forward all documents.

Thanks.

Best Regards

Angeline Rajoo

TKQP

Tan Kok Quan Partnership
Advocates & Solicitors, Singapore
1 Wallich Street #07-02 Guoco Tower Singapore 078881
T (65) 6225 9333
D (65) 6496 9525
F (65) 6225 0111
E angelina@tkqp.com.sg
W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

From: Celine Fong (LKKAuto) [<mailto:celinefong@lkkauto.com>]
Sent: Tuesday, June 20, 2017 9:46 AM
To: Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>; assignments <assignments@lkkauto.com>
Cc: Angeline Rajoo <angelina@tkqp.com.sg>
Subject: RE: SJE - MC Suit No. 2197/2017 - TKQP Ref: TWK/AR/0519.17/ml/PD

Dear Michelle,
Attached herewith CV of our surveyor Mr Mohamad Taufikh Bin Hamid for your attention.
We are pleased to submit our Professional Fee Charges (Single Joint Expert) as follows:
Paper Survey - \$350.00
Physical Re-inspection - \$500.00
Court Attendance Expert Witness Fee :
(a) State Courts
i) Half day \$400.00
ii) Full day \$800.00
All above charges are subject to GST 7%.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax:

6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Michelle Liew on behalf of Angeline Rajoo [<mailto:michelleliew@tkqp.com.sg>]
Sent: Friday, 16 June, 2017 4:51 PM
To: assignments
Cc: Angeline Rajoo
Subject: SJE - MC Suit No. 2197/2017 - TKQP Ref: TWK/AR/0519.17/ml/PD
Importance: High

LKK Auto Consultants Pte Ltd

Dear Sir

MC Suit No. 2197 of 2017 – Claimant: Koh Kock Leong Enterprise Pte Ltd
Accident involving XB 6016X & SHD 9953A on 28.10.16 along Lower Delta Road

We act for AXA Insurance Singapore Pte Ltd, the insurers of motor vehicle no. SHD 9953A in respect of a claim by the owner of motor vehicle no. XB 6016X for claims arising from the above captioned accident.

The Court has directed for parties to engage a single joint expert to conduct a re-inspection in this matter. As such, we write to request for your quotation for preparing such a single joint expert re-inspection report and your charges for attending ½ day trial in Court.

Please also let us have a copy of your surveyor's CV.

We look forward to hearing from you soonest possible.

Best Regards

Michelle Liew

Secretary

For and on behalf of Ms Angeline Rajoo

Tan Kok Quan Partnership

Advocates & Solicitors, Singapore

1 Wallich Street #07-02 Guoco Tower Singapore 078881

T (65) 6225 9333

D (65) 6496 9569

F (65) 6225 0111

E michelleliew@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

-----Original Message-----

From: IT Admin

Sent: Friday, June 16, 2017 4:46 PM

To: Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>

Subject: Message from "RICOH24"

This E-mail was sent from "RICOH24" (MP C6502).

Scan Date: 06.16.2017 16:45:40 (+0800)

Queries to: it_admin@tkqp.com.sg



Catherine Chong <catherinechong90.cc@gmail.com>

RE: SJE - MC Suit No. 8977/2017 - LKK Ref: TBA II TKQP Ref: TWK/AR/0966.17/aig/ml/PD

2 messages

Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>
To: "catherinechong90.cc@gmail.com" <catherinechong90.cc@gmail.com>
Cc: Angeline Rajoo <angeline@tkqp.com.sg>

17 November 2017 at 10:54

Hi Catherine

As spoken, please find attached our letter of 10 October 2017 together with the supporting documents for your necessary action.

Please let us urgently have the report, as there is Court mention on 21.11.17.

Thank you.

Best Regards

Michelle Liew

Secretary

For and on behalf of Ms Angeline Rajoo

TKQP

Tan Kok Quan Partnership

Advocates & Solicitors, Singapore

1 Wallich Street #07-02 Guoco Tower Singapore 078881

T (65) 6225 9333

D (65) 6496 9569

F (65) 6225 0111

E michelleliew@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of internet transmission.

From: Michelle Liew on behalf of Angeline Rajoo
Sent: Wednesday, October 11, 2017 7:22 PM
To: LKK (assignments@lkkauto.com) <assignments@lkkauto.com>
Subject: SJE - MC Suit No. 8977/2017 - LKK Ref: TBA II TKQP Ref: TWK/AR/0966.17/aig/ml/PD
Importance: High

LKK Auto Consultants Pte Ltd

Ref: TBA

Dear Sirs

MC SUIT NO. 8977 OF 2017 - CLAIMANT: LOH MUN ONN

ACCIDENT INVOLVING SJS 7619B & SKU 7705M ON 06.04.16 AT JUNCTION OF HILLVIEW AVENUE AND BUKIT BATOK EAST AVENUE 2

Attached please find our letter dated 10 October 2017 for your urgent attention.

Please let us have the report on an urgent basis.

Best Regards

Michelle Liew

Secretary

For and on behalf of Ms Angeline Rajoo

TKQP

Tan Kok Quan Partnership

Advocates & Solicitors, Singapore

1 Wallich Street #07-02 Guoco Tower Singapore 078881

T (65) 6225 9333

D (65) 6496 9569

F (65) 6225 0111

E michelleliew@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

3 attachments

 **ltr 0966.17.pdf**
128K

 **Repair bill + RI rpt 0966.17.pdf**
5955K

 **Survey report 0966.17.pdf**
10001K

Catherine Chong <catherinechong90.cc@gmail.com>

17 November 2017 at 12:10

To: Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>

Cc: Angeline Rajoo <angeline@tkqp.com.sg>

Dear Michelle,

Received with thanks.

Catherine

Sent from my iPhone

On 17 Nov 2017, at 10:54 AM, Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg> wrote:

Hi Catherine

As spoken, please find attached our letter of 10 October 2017 together with the supporting documents for your necessary action.

Please let us urgently have the report, as there is Court mention on 21.11.17.

Thank you.

Best Regards

Michelle Liew

Secretary

For and on behalf of Ms Angeline Rajoo

<image001.jpg>

[Quoted text hidden]

[Quoted text hidden]

[Quoted text hidden]

<image001.jpg>

Tan Kok Quan Partnership

Advocates & Solicitors, Singapore

1 Wallich Street #07-02 Guoco Tower Singapore 078881

T (65) 6225 9333

D (65) 6496 9569

F (65) 6225 0111

E michelleliew@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

<ltr 0966.17.pdf>

<Repair bill + RI rpt 0966.17.pdf>

<Survey report 0966.17.pdf>

TKQP

Advocates & Solicitors

Your Ref : New matter
Our Ref : **TWK/AR/0966.17/ml/PD**

Direct Line : 6496 9525
Direct Fax : 6227 6116
Writer's E-mail : angeline@tkqp.com.sg
Secretary's DID : 6496 9569
To Fax No: 6256 4315

Service of Court
Documents by Fax
Is Not Accepted

Date: 10 October 2017

BY EMAIL & POST

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Dear Sirs

**MC SUIT NO. 8977 OF 2017 – CLAIMANT: LOH MUN ONN
ACCIDENT INVOLVING SJS 7619B & SKU 7705M ON 06.04.16 AT JUNCTION OF
HILLVIEW AVENUE AND BUKIT BATOK EAST AVENUE 2**

We act for AIG Asia Pacific Insurance Pte Ltd, the insurers of motor vehicle no. SKU 7705M.

Plaintiff's solicitors are M/s Vision Law LLC in respect of a claim by the owner of motor vehicle no. SJS 7619B for the captioned accident.

The Court has now directed for parties to engage a Single Joint Expert (SJE) to conduct a paper survey in this matter.

The Court has further appointed, our proposed surveyor, namely Mr Mohammad Taufikh Bin Hamid, as the Court appointed SJE, for this matter and fixed the fees from the paper re-survey at \$350.00, as the Plaintiff's vehicle has been sold.

We enclose all the supporting documents:-

- 1) Plaintiff's survey report and photos
- 2) Our resurvey report and photos
- 3) Final repair bill

The Court has further directed that the report us to be completed before 1 November 2017.

We will need to disclose the report to M/s Vision Law LLC by 1 November 2017.

Page 1 of 2

This fax is for the addressee only and may contain confidential information and/or may be subject to legal privilege. If it has reached you in error, please inform us immediately by telephone, reversing the charges if necessary.

TKQP

Advocates & Solicitors

As such, please let us have the paper resurvey report by 1 November 2017 latest, to enable us to then forward it to the Plaintiff's solicitors.

Please note that our clients, AIG Asia Pacific Insurance Pte Ltd, will be paying you your charges. Kindly therefore direct your bill to them. However, you can care-of your bill to us and we will forward it to our clients for their payment. Please state our clients' reference no. 1210898659SG and our file reference no. TWK/AR/0966.17/ml/PD in your bill.

Yours faithfully



ANGELINE RAJOO

Enc. (By Email Only)

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LOH MUN ONN
BLK 386 BUKIT BATOK WEST AVE 5 #11-360
SINGAPORE 650386

Contact : 62751221 98263538

TAX INVOICE

Date : 22/09/2016

Date in : 06/04/2016

Vehicle Num. : SJS7619B

Make/Model : TOYOTA COROLLA AXIO 1.5X A-2008

Chassis/Eng# : NZE1416104827/1NZD267198

Accident Date : 06/04/2016

Claim No : CLM13460

Reference : APR-13/2016

Policy No. : D15MTPV01005393 (01/09/2016)

LUMP SUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0446-16-N51 DATED 19/09/2016
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

11,100.00



for N-51 AUTOMOTIVE PTE LTD

E. & O.E. Sub S\$: 11,100.00

Add GST (7 %) S\$: 777.00

Total Amount S\$: 11,877.00





FORMTEAM ADJUSTERS PTE LTD

No.33, Ubi Ave 3
#02-13, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

Co.Reg No: 201212134W

GST Reg No: 201212134W

Our Reference : FTA/AHA/1610/5725/RI

Your Reference: 1210898659SG

Date : 07-Nov-2016

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Attention : Ms Pauline Tham

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO . SJS 7619B

Pursuant to your instructions on 13 Oct 2016 , we have conducted a reinspection of the above vehicle at 2 Kaki Bukit Ave 2 Autohub #01-18 S'417921 on 01 Nov 2016.


We recommend a repair cost of **\$2,900.00** (see report) based on lump sum repair and the estimated duration of repairs would take **04 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Adjusters Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

(Email : frankie@fta.com.sg)

Encl. Re-inspection Report

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : FTA/AHA/1610/5725/RIYour Reference : 1210898659SG

Date : 07-Nov-2016

Attention : Ms Pauline Tham

TO : Motor Claims Department

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Singapore 079120

Dear Sir/Madam,

Vehicle No : SJS 7619BModel : Toyota AxioMileage : 11976 kmChassis No : NZE1416104827Workshop : M/S N-51 Automotive Pte Ltd

Pursuant to your instructions on **13 Oct 2016**, we have conducted a reinspection of the above vehicle at **2 Kaki Bukit Ave 2 Autohub #01-18 S'417921** on **01 Nov 2016**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Rear Boot Lid	Not Replaced		727.00	-
1	Rear Boot Lid 'Logo' Emblem	Necessary		52.30	52.30
2	Rear Boot Lid Hinges L/R	Repair		-	-
1	Rear Boot Lid Inner Upholstery Trim	Not Consistent		672.50	
	Rear Boot Lid Mechanism Lock	Not Consistent		181.10	-
2	Rear Boot Lid Number Plate Lamp L/R	Not Consistent		192.40	-
1	Rear Boot Lid Outer Garnish	Not Consistent		289.80	-
4	Rear Boot Lid Outer Garnish Clips	Not Necessary		26.00	-
4	Rr Boot Lid Rubber Guide Stopper L/R	Not Necessary		35.20	-
1	Rear Boot Lid Weatherstrip	Not Consistent		191.40	-
1	Rear Bumper	Squashed		1,101.70	1,101.70
2	Rear Bumper Impact Bracket L/R	Bent		132.00	132.00
6	Rr Bumper Inner Side Shield Clips L/R	Necessary		39.00	39.00
2	Rear Bumper Inner Side Shield L/R	Warped		110.00	110.00
2	Rear Bumper Side Retainer L/R	Necessary		274.80	274.80
1	Rear End Panel	Repairable		591.40	-
1	Rear End Panel Inner Top Garnish	Warped		281.40	281.40

FORMTEAM ADJUSTERS PTE LTD

PAGE : 2

Our Reference : FTA/AHA/1610/5725/RI

Your Reference : 1210898659SG

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
4	Rear End Panel Inner Top Garnish Clips	Necessary		26.00	26.00
1	Rear End Panel Lock Striker	Not Consistent		49.00	-
1	Rear Exhaust Aluminium Heat Shield	Reuse		-	-
1	Rear Exhaust Gasket	Not Necessary		23.00	-
2	Rear Exhaust Rubber Mounting	Not Necessary		127.40	-
1	Rear Exhaust Silencer Box	Not Consistent		971.00	-
2	Rear Fender Inner Air Vent L/R	Reuse		-	-
	Rear Fender Inner Upholstery Trim L/R	Not Consistent		979.20	-
1	Rear LH Tail Lamp	Not Consistent		283.10	-
1	Rear LH Tail Lamp Back Rubber Gasket	Not Necessary		43.70	-
1	Rear LH Tail Lamp Clip	Not Necessary		6.50	-
1	Rear LH Tail Lamp Inner Panel	Repair		-	-
1	Rear LH Tail Lamp Lower Bracket	Not Necessary		121.35	-
1	Rear RH Tail Lamp	Not Consistent		398.70	-
1	Rear RH Tail Lamp Back Rubber Gasket	Not Necessary		43.70	-
1	Rear RH Tail Lamp Clip	Not Necessary		6.50	-
1	Rear RH Tail Lamp Inner Panel	Repair		-	-
1	Rear RH Tail Lamp Lower Bracket	Not Necessary		121.35	-
1	Rear Sub RH Chassis Frame	Repair		-	-
1	Spare Tyre Panel	Repair		-	-
1	Spare Tyre Panel Inner Top Upholstery Board	Not Consistent		232.00	-
1	Spare Tyre Retainer Lock	Reuse		-	-
1	Spare Tyre Side Panel Inner Top Tray L/R	Not Consistent		743.70	-
2	Spare Tyre Side Panel L/R	Repair		-	-
	Sub-Total			9,074.20	2,017.20
	Discount Percentage 25%			2,268.55	504.30
	Total Parts List Items			6,805.65	1,512.90
	<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>				
1 set	Rr Boot Lid Inner Upholstery Trim Clips	Not Consistent		30.00	-
1	Rear Boot Lid Insulator Sound Mat	Not Consistent		350.00	-
1	Rear Boot Lid Number Plate	Not Consistent		25.00	-
1	Rear Boot Lid Number Plate Holder	Not Consistent		50.00	-
1	Rear Boot Lid Reverse Camera	Not Consistent		800.00	-

FORMTEAM ADJUSTERS PTE LTD

PAGE : 3

Our Reference : FTA/AHA/1610/5725/RI

Your Reference : 1210898659SG

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Rear Boot Lid Spoiler 'Top'	Reuse		-	-
1 set	Rear Bumper Clips	Necessary		30.00	30.00
1	Rear Bumper Lower Lip 'TRD'	Deformed		1,200.00	1,000.00
1 set	Rear Bumper Reverse Sensor	Shorted		350.00	200.00
2 set	Rear Fender Inner Upholstery Trim Clips L/R	Not Necessary		60.00	-
2	Rear Fender Insulator Mat L/R	Reuse		-	-
1	Rear LH Tail Lamp 'Brake' Bulb	Not Consistent		12.00	-
1	Rear LH Tail Lamp 'Reverse' Bulb	Not Consistent		12.00	-
1	Rear LH Tail Lamp 'Signal' Bulb	Not Consistent		12.00	-
1	Spare Tyre	Reuse		-	-
1	Spare Tyre Panel Inner Jacking Tool	Reuse		-	-
1	Spare Tyre Panel Insulator Mat	Not Necessary		350.00	-
Total Parts Special Nett Items				3,281.00	1,230.00
Total Parts				10,086.65	2,742.90

FORMTEAM ADJUSTERS PTE LTD

PAGE : 4

Our Reference : FTA/AHA/1610/5725/RI

Your Reference: 1210898659SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00	20.00
2	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60.00	60.00
3	To re-spray painting on the rear boot lid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,200.00	400.00
4	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	120.00	-
5	To provide labour, workmanship to change the above damaged body parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. (including all repair parts)	1,100.00	400.00
6	To mount vehicle on to Car 'O' Liner.	400.00	-
7	To apply anti-rust chemical on repaired and replaced panel.	60.00	30.00
	Total Labour Amount	3,020.00	910.00
	Total Parts and Labour	13,106.65	3,652.90

FORMTEAM ADJUSTERS PTE LTD

PAGE : 5

Our Reference : FTA/AHA/1610/5725/RI

Your Reference: 1210898659SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$11,100.00	\$2,900.00


REMARKS :

Our recommended Lump Sum Repair Cost is **\$2,900.00** (instead of the submitted repair cost of **\$11,100.00** .In normal circumstances, repairs to the vehicle would take approximately **04 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FORMTEAM ADJUSTERS PTE LTD** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,
FORMTEAM ADJUSTERS PTE LTD



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

FormTeam Adjusters Pte Ltd

Vehicle No: SJS 7619B

Workshop: N-51 Automotive Pte Ltd

Accident Date: 06 April 2016

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

www.fta.com.sg

Co. Reg No: 201212134W

GST Reg. No: 201212134W

























PAR Automotive Consultancy

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 11,100.00
and the recommended number of working days for the repairs is within 9 day(s).



B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0446-16-N51

19 September 2016

ACCIDENT VEHICLE SURVEY REPORT

Loh Mun Onn
Blk 386 Bukit Batok West Ave 5 #11-360
Singapore 650386

VEHICLE INFORMATION:

Vehicle Reg No.:	SJS7619B	Odometer:	105181km
Make & Model:	Toyota Axio 1.5X A	Colour:	Silver
Chassis number:	NZE1416104827	Date of accident:	06/04/2016
Year of Regn.:	02/09/2009	Date inspected:	11/04/2016
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Firestone	5mm/Firestone	215/45R17
Rear:	5mm/Firestone	5mm/Firestone	215/45R17

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BOOTLID	1	buckled	727.00	727.00 <i>Rx</i>
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	52.30	52.30
REAR BOOTLID HINGES L/R	2	repair	179.70	0.00
REAR BOOTLID INNER UPHOLSTERY TRIM	1	deformed	672.50	672.50 <i>X H N</i>
REAR BOOTLID MECHANISM LOCK	1	bent	181.10	181.10 <i>X H N</i>
REAR BOOTLID NUMBER PLATE LAMP L/R	2	fractured	192.40	192.40 <i>X H N</i>
REAR BOOTLID OUTER GARNISH	1	warped	289.80	289.80 <i>X H N</i>
REAR BOOTLID OUTER GARNISH CLIPS	4	necessary	26.00	26.00 <i>X H N</i>
REAR BOOTLID RUBBER GUIDE STOPPER L/R	4	deformed	35.20	35.20 <i>X H N</i>
REAR BOOTLID WEATHERSTRIP	1	deformed	191.40	191.40
REAR BUMPER	1	squashed	1,101.70	1,101.70
REAR BUMPER IMPACT BRACKET L/R	2	bent	132.00	132.00
REAR BUMPER INNER SIDE SHIELD CLIPS L/R	6	necessary	39.00	39.00
REAR BUMPER INNER SIDE SHIELD L/R	2	warped	110.00	110.00
REAR BUMPER SIDE RETAINER L/R	2	necessary	274.80	274.80
REAR END PANEL	1	buckled	591.40	591.40
REAR END PANEL INNER TOP GARNISH	1	warped	281.40	281.40
REAR END PANEL INNER TOP GARNISH CLIPS	4	necessary	26.00	26.00
REAR END PANEL LOCK STRIKER	1	bent	49.00	49.00 <i>X H N</i>
REAR EXHAUST ALUMINIUM HEAT SHIELD	1	reuse	182.20	0.00
REAR EXHAUST GASKET	1	necessary	23.00	23.00 <i>X H N</i>
REAR EXHAUST RUBBER MOUNTING	2	distorted	127.40	127.40 <i>X H N</i>
REAR EXHAUST SILENCER BOX	1	bent	971.00	971.00 <i>X H N</i>
REAR FENDER INNER AIR VENT L/R	2	reuse	364.20	0.00
REAR FENDER INNER UPHOLSTERY TRIM L/R	2	deformed	979.20	979.20 <i>X H N</i>
REAR LH TAILLAMP	1	fractured	283.10	283.10 <i>X H N</i>
REAR LH TAILLAMP BACK RUBBER GASKET	1	necessary	43.70	43.70 <i>X H N</i>
REAR LH TAILLAMP CLIPS	1	necessary	6.50	6.50 <i>X H N</i>
REAR LH TAILLAMP INNER PANEL	1	repair	231.35	0.00
REAR LH TAILLAMP LOWER BRACKET	1	bent	121.35	121.35 <i>X H N</i>
REAR RH TAILLAMP	1	fractured	398.70	398.70 <i>X H N</i>
REAR RH TAILLAMP BACK RUBBER GASKET	1	necessary	43.70	43.70 <i>X H N</i>
REAR RH TAILLAMP CLIPS	1	necessary	6.50	6.50 <i>X H N</i>
REAR RH TAILLAMP INNER PANEL	1	repair	287.70	0.00 <i>Rx</i>
REAR RH TAILLAMP LOWER BRACKET	1	bent	121.35	121.35 <i>X H N</i>
REAR SUB RH CHASSIS FRAME	1	repair	731.40	0.00 <i>R</i>
SPARE TYRE PANEL	1	repair	987.72	0.00 <i>R</i>
SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	1	deformed	232.00	232.00 <i>X H N</i>
SPARE TYRE RETAINER LOCK	1	reuse	171.80	0.00
SPARE TYRE SIDE PANEL INNER TOP TRAY L/R	2	deformed	743.70	743.70 <i>X H N</i>

PAR Automotive Consultancy

Annex A: Page 2
Report No: 0446-16-N51-SJS7619B

SPARE TYRE SIDE PANEL L/R

2 repair

220.50

0.00

Subtotal before discount

S\$ 12,430.77

S\$ 9,074.20

Percentage discount 25% and 25%

S\$ 3,107.69

S\$ 2,268.55

Sub-total 1

S\$ 9,323.08

S\$ 6,805.65

RR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET

1 necessary

30.00

30.00 x an

REAR BOOTLID INSULATOR SOUND MAT

1 necessary

350.00

350.00 x an

REAR BOOTLID NUMBER PLATE

1 bent

25.00

25.00 x an

REAR BOOTLID NUMBER PLATE HOLDER

1 bent

50.00

50.00 x an

REAR BOOTLID REVERSE CAMERA

1 shorted

800.00

800.00 x an

REAR BOOTLID SPOILER 'TRD'

1 reuse

800.00

0.00

REAR BUMPER CLIPS - SET

1 necessary

30.00

30.00

REAR BUMPER LOWER LIP 'TRD'

1 deformed

1,200.00

1,200.00 900

REAR BUMPER REVERSE SENSOR - SET

1 shorted

350.00

350.00 200

REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET

2 necessary

60.00

60.00 x an

REAR FENDER INSULATOR MAT L/R

2 reuse

700.00

0.00

REAR LH TAILLAMP 'BRAKE' BULB

1 fused

12.00

12.00 x an

REAR LH TAILLAMP 'REVERSE' BULB

1 fused

12.00

12.00 x an

REAR LH TAILLAMP 'SIGNAL' BULB

1 fused

12.00

12.00 x an

SPARE TYRE

1 reuse

280.00

0.00

SPARE TYRE PANEL INNER JACKING TOOL

1 reuse

180.00

0.00

SPARE TYRE PANEL INSULATOR MAT

1 necessary

350.00

350.00 x an

Subtotal before discount

S\$ 5,241.00

S\$ 3,281.00

Sub-total 2

S\$ 5,241.00

S\$ 3,281.00

Parts-total

S\$ 14,564.08

S\$ 10,086.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

150.00

80.00 30

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00

60.00 ✓

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1,500.00

1,200.00 600

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

160.00

120.00 x an

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00

1,100.00 600

To mount vehicle on to Car 'O' Liner.

400.00

400.00 x an

To apply anti-rust chemical on repaired and replaced panel.

120.00

60.00 40

Labour Total

S\$ 3,970.00

S\$ 3,020.00

Parts & Labour Total

S\$ 18,534.08

S\$ 13,106.65

4560
2583600
5 days

Your Ref: TWK/AR/0966/17/aig/ml/PD

Date: 28th December 2017

Our Ref: CS1/LAW17021978/T1vbe2

M/s TAN KOK QUAN PARTNERSHIP

1 WALLICH STREET #07-02

GUOCO TOWER

SINGAPORE 078881

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SJS 7619B

INSURED VEHICLE: SKU 7705M

ACCIDENT DATE: 06/04/2016

We thank you for your instruction on 10/10/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 7619B from M/s Formteam Adjusters Pte Ltd.
- b) Survey report by PAR Automotive Consultancy with colour photographs.
- c) Final Repair Bill of SJS 7619B from M/s N-51 Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SJS 7619B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJS 7619B
Make & Model	: Toyota Axio 1.5X A
Year of Registration	: 2009
Chassis Number	: NZE1416104827

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7619B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	REPAIRED SEE LABOUR	727.00	-
1	REAR BOOTLID 'LOGO' EMBLEM	REPLACED	52.30	52.30
2	REAR BOOTLID HINGES L/R	REPAIRED SEE LABOUR	179.70	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	NOT NECESSARY	672.50	-
1	REAR BOOTLID MECHANISM LOCK	NOT NECESSARY	181.10	-
2	REAR BOOTLID NUMBER PLATE LAMP L/R	NOT NECESSARY	192.40	-
1	REAR BOOTLID OUTER GARNISH	NOT NECESSARY	289.80	-
4	REAR BOOTLID OUTER GARNISH CLIPS	NOT NECESSARY	26.00	-
4	REAR BOOTLID RUBBER GUIDE STOPPER L/R	NOT NECESSARY	35.20	-
1	REAR BOOTLID WEATHERSTRIP	REPLACED	191.40	191.40
1	REAR BUMPER	REPLACED	1,101.70	1,101.70
2	REAR BUMPER IMPACT BRACKET L/R	REPLACED	132.00	132.00
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	REPLACED	39.00	39.00
2	REAR BUMPER SIDE RETAINER L/R	REPLACED	274.80	274.80
1	REAR END PANEL	REPLACED	591.40	591.40
1	REAR END PANEL INNER TOP GARNISH	REPLACED	281.40	281.40
4	REAR END PANEL INNER TOP GARNISH CLIPS	REPLACED	26.00	26.00
1	REAR END PANEL LOCK STRIKER	NOT NECESSARY	49.00	-
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	REUSE	182.20	-
1	REAR EXHAUST GASKET	NOT NECESSARY	23.00	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	127.40	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	971.00	-
2	REAR FENDER INNER AIR VENT L/R	REUSE	364.20	-
2	REAR FENDER INNER UPHOLSTERY TRIM L/R	NOT NECESSARY	979.20	-
1	REAR LH TAILLAMP	NOT NECESSARY	283.10	-
1	REAR LH TAILLAMP BACK RUBBER GASKET	NOT NECESSARY	43.70	-
1	REAR LH TAILLAMP CLIPS	NOT NECESSARY	6.50	-
1	REAR LH TAILLAMP INNER PANEL	REPAIRED SEE LABOUR	231.35	-
1	REAR LH TAILLAMP LOWER BRACKET	NOT NECESSARY	121.35	-

Report Ref No. CS1/LAW17021978/T1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH TAILLAMP	NOT NECESSARY	398.70	-
1	REAR RH TAILLAMP BACK RUBBER GASKET	NOT NECESSARY	43.70	-
1	REAR RH TAILLAMP CLIPS	NOT NECESSARY	6.50	-
1	REAR RH TAILLAMP INNER PANEL	REPAIRED SEE LABOUR	287.70	-
1	REAR RH TAILLAMP LOWER BRACKET	NOT NECESSARY	121.35	-
1	REAR SUB RH CHASSIS FRAME	REPAIRED SEE LABOUR	731.40	-
1	SPARE TYRE PANEL	REPAIRED SEE LABOUR	987.72	-
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	NOT NECESSARY	232.00	-
1	SPARE TYRE RETAINER LOCK	REUSE	171.80	-
2	SPARE TYRE SIDE PANEL INNER TOP TRAY L/R	NOT NECESSARY	743.70	-
2	SPARE TYRE SIDE PANEL L/R	REPAIRED SEE LABOUR	220.50	-
2	REAR BUMPER INNER SIDE SHIELD L/R	REPLACED	110.00	110.00
	LESS 25% DISCOUNT		-3,107.69	-700.00
			9,323.08	2,100.00
	SPECIAL NETT ITEMS			
1	SET RR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR BOOTLID INSULATOR SOUND MAT (SN)	NOT NECESSARY	350.00	-
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR BOOTLID REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	REAR BOOTID SPOILER 'TRD' (SN)	REUSE	800.00	-
1	SET REAR BUMPER CLIPS (SN)	REPLACED	30.00	30.00
1	REAR BUMPER LOWER LIP 'TRD' (SN)	REPLACED	1,200.00	900.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	REPLACED	350.00	200.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R (SN)	NOT NECESSARY	60.00	-
2	REAR FENDER INSULATOR MAT L/R (SN)	REUSE	700.00	-
1	REAR LH TAILLAMP 'BRAKE' BULB (SN)	NOT NECESSARY	12.00	-
1	REAR LH TAILLAMP 'REVERSE' BULB (SN)	NOT NECESSARY	12.00	-
1	REAR LH TAILLAMP 'SIGNAL' BULB (SN)	NOT NECESSARY	12.00	-

Report Ref No. CS1/LAW17021978/T1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE (SN)	REUSE	280.00	-
1	SPARE TYRE PANEL INNER JACKING TOOL (SN)	REUSE	180.00	-
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-
			5,241.00	1,130.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		150.00	30.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	600.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	160.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID HINGES L/R, REAR LH TAILLAMP INNER PANEL, REAR RH TAILLAMP INNER PANEL, REAR SUB RH CHASSIS FRAME, SPARE TYRE PANEL AND SPARE TYRE SIDE PANEL L/R.		1,500.00	600.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,970.00	1,330.00
GRAND TOTAL			18,534.08	4,560.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS1/LAW17021978/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.