

22/05/2002

ASS: REC BY:

REF: CS/FCI17021985/Kltbnz Special Instructions

Surveyor:

ASSIGNMENT (Office)

CWS
From (Person): Eileen Lee

of FCI

Date/Time 16/11/17 @ 5pm

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD1711J

Insured:

SH9528T

at Workshop m/s:

Premier Automotive

Tel:

6214 8880

of 23 Changi South Ave 2# 03-02

Policy No:

Claim No:

D17010683 MFSH

Sum Insured:

Excess:

D.O.A.

14/11/2017

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wpr'

H.O.D. Endorsement:

Date/Time

5:18pm @ 16/11/17

Person Contacted:

Gary

Vehicle IN ☒ OUT

Date/Time	Action/Instruction
	(<input checked="" type="checkbox"/> Estimate
	SHD 1711J - CC3/AIG17011571/H1eb3q2-D.O.A.: 12/06/2017
	SH9528T - NS/INC10007941/Fg7-D.O.A.: 22/04/2010
29/11-	Revert preli via email

SIRVUIC

Kahar

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD1711JYr Regn: 29 Dec 2011Type: M.Car / M.Cycle / Bus / Van / Lorry / Tr / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1582Colour: BlueA/C: Ins / Std / NI / NASp. Reading: 504258T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KM HPC815LC4140933Gen. Cond: Good / Fair / Poor / BurntSteering: Ins / Jammed / Leaked / Burnt orBrake: Ins / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 14/11/12D.O.I. 20/11/12Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11/12Call PR \$380 / 2 days (Red: 1226.80 76%)

F.C.I

RECEIVED 29 NOV 2011

Date/Time, File Pass to?

29/11/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

100

50

50

15

215

Report Format: TPLump Sum / (B): \$ 380/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021985/K1tb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9528T	Veh. Inspected	SHD 1711J
Policy No.		Coverage (\$)	0.00
Claim No.	D17010683MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/11/2017	Inspection Date
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	16-11-2017	Our Ref No.	D17010683MFSH
Accident Date	14-11-2017	Claim Type.	Third Party
Insured Vehicle	SH9528T	Third Party Vehicle.	SHD1711J
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	GARY SHI		
Contact No.	62148880/ 65446671	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230315)



PRI Documents



Close X

PRI Header Details

Claim No	D17010683MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PREMIER , LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446671 , Phone: 62148880 , Fax: 62141511 EmailId: GARY.SHI@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9528T	TP Vehicle No	SHD1711J
PRI Recieved Date	16-11-2017 04:03:22 PM	Surveyor Appointed Date	16-11-2017 04:59:04 PM	Surveyor Accept Date	17-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	17-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 29 November, 2017 11:49 AM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010683MFSH/1
Attachments: PRELI ADVISED SHD 1711J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 1711J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 17 November, 2017 10:25 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010683MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 16 November, 2017 4:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010683MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010683MFSH

Date: 29/11/2017

Our Ref: CS/FCI17021985/K1tb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1711J

Please be informed that we had conducted the inspection of the abovementioned vehicle
20/11/2017 at the premises of M/s Premier Automotive at and have the following to
report:-

Workshop Estimate Amount	: S\$ 1,606.80
Revised Estimate Amount	: S\$ 380.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
At front rear n/s portion.



Repair days: 2

Yours faithfully

Kalvin Ang

Motor Surveyor

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	SHD1711J	Vehicle Scheme:	Taxi (Company)
Vehicle Type:	H11 - Public Transport Taxi (Station Wagon)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	HYUNDAI	Vehicle Model:	FD I30CW 1.6 MT 5DR TURBO 2WD
Chassis No.:	KMHDC81SLCU140933	Engine No.:	D4FBBU041423
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Diesel	Passenger Capacity:	4
Engine Capacity:	1582 cc	Power Rating:	-
Unladen Weight:	1334 kg	Maximum Laden Weight:	1860 kg
Primary Colour:	Silver	Secondary Colour:	-
First Registration Date:	29 Dec 2011	Original Registration Date:	29 Dec 2011
Manufacturing Year:	2011	Open Market Value:	\$11,810.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$7,086.00
No. of Transfers:	0		

Owner Particulars

Owner Name:	PREMIER TAXIS PTE. LTD.
Owner ID Type:	Company
Owner ID:	200304975H
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	11
Registered Street Name:	KUNG CHONG ROAD
Registered Unit No.:	-
Registered Building Name:	ALEXANDRA INDUSTRIAL ESTATE
Registered Postal Code:	159147
COE No. / Expiry Date:	2011090101000877K / 28 Dec 2019
COE Bld Category:	A - Car (1600cc & below) & Taxi
QP Paid:	\$39,441.00

Transaction Details

Business Transaction Ref. No.:	20111229090435334959
Business Transaction Date:	29 Dec 2011
Business Transaction Time:	09:04:35

Message

The above vehicle has been successfully registered.

Please note that \$44,451.00 will be deducted from your GIRO account.

OK

Land Transport Authority

Please read through the Privacy Statement, Conditions of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 8.0 SP3 and above, 800 X 600 resolution
Copyright © 2005 LTA | [Privacy Statement](#) | [Conditions of Use](#) | [Disclaimer](#)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-Nov-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1711 J

1 pc	Rear bumper <i>Xhp</i>	\$	447.00
2 pcs	Rear bumper o/s & n/s side bracket @ \$16.00 <i>X jcc</i>	\$	32.00
2 pcs	Rear bumper o/s & n/s side upper bracket @ \$15.20 <i>X jcc</i>	\$	30.40
2 pcs	Rear bumper o/s & n/s upper bracket @ \$13.30 <i>X jcc</i>	\$	26.60
		\$	536.00
	Less 20%	\$	107.20
		\$	428.80

S/NETT

1 set	Rear bumper clips <i>X "</i>	\$	48.00
1 set	Reverse sensor <i>X "</i>	\$	280.00

To dismantle and replace reverse sensor and test system

\$ 80.00 *X "*

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape and adjust of same, etc.

\$ 350.00 *200*

To putty and spray painting on rear bumper

\$ 300.00 *180*

To apply rustproofing on the repaired and replaced panels

\$ 120.00 *X "*

Total

\$ 1,606.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K. L. (C/C)
20/11/17 1335h.
2 Days.
L15
After Repair photo




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021985/K1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9528T	Veh. Inspected	SHD 1711J	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010683MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	16/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHDC81SLCU140933	Colour	SILVER	
Odometer	504358	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2017	Inspection Date	20/11/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1711J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	447.00	-
2	REAR BUMPER O/S & N/S SIDE BRACKET @\$16.00	SERVICEABLE	32.00	-
2	REAR BUMPER O/S & N/S SIDE UPPER BRACKET @\$15.20	SERVICEABLE	30.40	-
2	REAR BUMPER O/S & N/S UPPER BRACKET @\$13.30	SERVICEABLE	26.60	-
	LESS 20% DISCOUNT		-107.20	-
			428.80	-
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			328.00	-
LABOUR				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF SAME.ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		350.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER.		300.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			850.00	380.00
GRAND TOTAL			1,606.80	380.00
RECOMMENDED COST OF REPAIRS				380.00

Report Ref No. CS/FCI17021985/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.