

ASSIGNMENT (Office)

AGI

17/11/17 @ 9.09am

(OD) Tr/WS/IF RES/OD RES/EVA/INV/MV/C

To inspect Vehicle No. FD 5557

at Workshop in: Komoco Motryeles

Tel: 9824 7879

of 253, Alexandra Rd, # 01-04 159936

Policy no. P20020245R00

Claim No. C20001116

Summary

Exerc. IBA 500

Make of Veh.
(Client's Record)

DOA 3/11/2017

CA / (REV) / REP. / REV 24 HRS

Date/Time: 10:38am @ 17/11/17 Person Coordinated: Razali

THE OUT

<u>Date/Time</u>	<u>Action/Instruction</u> (✓) <u>Estimate</u>
------------------	---

[illegible]

Signature

REF:

2847A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FO 5552at Workshop m/s HARLEY DAVIDSONof @ Komoco motorcycles #01-04Insured: AGI / DO

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 49k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FO 5552 Yr Regn: 2015 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HARLEY DAVIDSON CVO STGL cc 1801Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 017557 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5401PXNCSFB954601Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 130/60R19R: 180/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 63/11/17 D.O.I. 17/11/17Survey held at HARLEY DAVIDSONDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/11/17	email preli REV to Albert - pending COR from wksp.
23/11/17	wksp agree COR not more \$44000
23/11/17	Albert email approved CA, ex: 500
23/11/17	@ 2.30PM email to Razali, CA, ex: 500 - COR not more \$44k
16/3/2018	Confirmed \$39,694.24, repair 4 days (\$3,955.52, 0.090%)
	Submit final fig \$39,181.10 and 5 days (Red-12,571.86, 232).

Date/Time, File Pass to?

☐

Preli. Report

1) Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2Survey Fee: 150

Transportation:

) S + RS) \$

) Photos

) Others

TOTAL

Report Format: ODLump Sum / (B.I.): (\$ \$39,181.10)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI17021997/R1nb	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 17-11-2017	
			Code : AGI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		FD 555Z
Policy No. P20020245R00		Coverage (\$)		0.00
Claim No. C2000116		Excess (\$)		500.00
Assign From ALBERT HONG		Assign Date		17/11/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 03/11/2017		Inspection Date 17/11/2017		
Survey held at		KOMOCO MOTORCYCLES PTE LTD		
		253 ALEXANDRA ROAD		
		#01-04		
		SINGAPORE 159936		
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

From: Mohamad Razali Bin Hassan [<mailto:razali.hassan@harleysingapore.com>]
Sent: Thursday, 23 November, 2017 12:40 PM
To: Rasul (LKKAuto)
Cc: Ai Phing (LKKAuto); Ian Lim (ianlimth@gmail.com)
Subject: RE: FD 555Z DOA : 03/11/2017

Hi Rasul,

Attached is the amended repair assessment. Do let me know if we can proceed to order, thanks.

BR
Razali

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Thursday, 23 November, 2017 10:04 AM
To: Mohamad Razali Bin Hassan
Cc: Ai Phing (LKKAuto)
Subject: FD 555Z DOA : 03/11/2017

Hi Razali,

As spoken, the NETT amount repair limit is 44K. Meant that repair cost should not beyond 44K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Celine Fong (LKKAUTO)

From: Norrita (LKKAUTO)
Sent: Friday, 2 February 2018 3:13 PM
To: Mohamad Razali Bin Hassan
Cc: Rasul (LKKAUTO); SUR
Subject: RE: FD555Z supplementary
Attachments: FD 555Z- SUPPLEMENTARY.tif

Dear Mr Razali,

As per your tele-conversation with Mr Simon , please find the attached file of Vehicle No : FD 555 .

Please proceed to repair on the Supplementary on the markings , please .

Thank you very much.

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norrita (LKKAUTO)
Sent: Friday, 2 February 2018 2:23 PM
To: Mohamad Razali Bin Hassan <razali.hassan@harleysingapore.com>; SUR <sur@lkkauto.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: FD555Z supplementary

Dear Razali

Thank you and noted.

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamad Razali Bin Hassan [<mailto:razali.hassan@harleysingapore.com>]
Sent: Friday, 2 February 2018 2:14 PM
To: SUR <sur@lkkauto.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: FW: FD555Z supplementary

Hi,

As requested, thanks.

BR
Razali

From: Mohamad Razali Bin Hassan
Sent: Thursday, 1 February, 2018 1:32 PM
To: 'Rasul (LKKAUTO)'
Subject: FD555Z supplementary

Hi Rasul,

As requested, thanks.

BR

RAZALI HASSAN
SERVICE CONSULTANT

Harley-Davidson of Singapore
253 Alexandra Road, #01-04
Singapore 159936

Phone: (65) 6475 0123 Ext(907)
Mobile: (65) 98247879
Fax: (65) 6472 8900
Email: razali.hassan@harleysingapore.com
Web: www.harleysingapore.com

Norrita (LKKAUTO)

From: Mohamad Razali Bin Hassan <razali.hassan@harleysingapore.com>
Sent: Wednesday, 14 March 2018 11:55 AM
To: Admin-D (LKKAUTO); Norrita (LKKAUTO); Rasul (LKKAUTO)
Cc: SUR
Subject: RE: FD 555Z DOA : 03/11/2017

Hi,

May I know what time will you be here today?

BR
Razali

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 9 March, 2018 3:38 PM
To: 'Norrita (LKKAUTO)'; Mohamad Razali Bin Hassan; 'Rasul (LKKAUTO)'
Cc: 'SUR'
Subject: RE: FD 555Z DOA : 03/11/2017

Dear Rita,

Noted, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norrita (LKKAUTO) [mailto:norrita@lkkauto.com]
Sent: Friday, 9 March 2018 3:37 PM
To: Mohamad Razali Bin Hassan <razali.hassan@harleysingapore.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FD 555Z DOA : 03/11/2017

Dear Mr Razali

Contents noted.

Dear Nivitha - kindly assist on the after repair survey on 14/3.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamad Razali Bin Hassan [<mailto:razali.hassan@harleysingapore.com>]

Sent: Friday, 2 February 2018 2:14 PM

To: SUR <sur@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: FW: FD555Z supplementary

Hi,

As requested, thanks.

BR

Razali

From: Mohamad Razali Bin Hassan

Sent: Thursday, 1 February, 2018 1:32 PM

To: 'Rasul (LKKAuto)'

Subject: FD555Z supplementary

Hi Rasul,

As requested, thanks.

BR

RAZALI HASSAN

SERVICE CONSULTANT

Harley-Davidson of Singapore

253 Alexandra Road, #01-04

Singapore 159936

Phone: (65) 6475 0123 Ext(907)

Mobile: (65) 98247879

Fax: (65) 6472 8900

Email: razali.hassan@harleysingapore.com

Web: www.harleysingapore.com

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Thursday, 23 November, 2017 2:31 PM
To: 'Mohamad Razali Bin Hassan'
Subject: RE: FD 555Z DOA : 03/11/2017 AGI-OD

Dear Razali,

As instructed by our client, please proceed to repair the insured vehicle **FD 555Z (Excess \$500)** and **repair cost not more than \$44,000.00.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Ai Phing (LKKAUTO)
Sent: Thursday, 23 November, 2017 12:58 PM
To: 'Mohamad Razali Bin Hassan' <razali.hassan@harleysingapore.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Ian Lim (ianlimth@gmail.com) <ianlimth@gmail.com>
Subject: RE: FD 555Z DOA : 03/11/2017

Dear Razali,

We noted that the repair cost is not more than \$44K.

We have to seek the approval to insurance. Once approve will email to you.

Ai Phing (LKKAUTO)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Thursday, 23 November, 2017 2:27 PM
To: Ai Phing (LKKAUTO)
Cc: Lincoln Yeo
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116

Excess is \$500.

Thanks.

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Ai Phing (LKKAUTO) [mailto:aiphing@lkkauto.com]
Sent: Thursday, 23 November, 2017 2:26 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Cc: Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116

Dear Albert,

Please advise the excess.

Ai Phing (LKKAUTO)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Thursday, 23 November, 2017 2:19 PM
To: Ai Phing (LKKAUTO)
Cc: Lincoln Yeo
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116

Hi Ai Phing,

Please authorise repair for this bike.

We refer to our conversation earlier, do inform your surveyors to avoid sending any documents to our insured in the event of negotiating with workshop. Should the repairer cc our insured in the loop, the reply should leave our insured out and to inform repairer about it to avoid all sort of implication.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Ai Phing (LKKAUTO) [mailto:aiphing@lkkauto.com]
Sent: Thursday, 23 November, 2017 1:57 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116

Dear Albert,

Repairer agree the repair cost not more than \$44,000.00.

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Thursday, 23 November, 2017 12:58 PM
To: 'Mohamad Razali Bin Hassan'; Rasul (LKKAuto)
Cc: Ian Lim (ianlimth@gmail.com)
Subject: RE: FD 555Z DOA : 03/11/2017

Dear Razali,

We noted that the repair cost is not more than \$44K.

We have to seek the approval to insurance. Once approve will email to you.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Mohamad Razali Bin Hassan [<mailto:razali.hassan@harleysingapore.com>]
Sent: Thursday, 23 November, 2017 12:40 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Ian Lim (ianlimth@gmail.com) <ianlimth@gmail.com>
Subject: RE: FD 555Z DOA : 03/11/2017

Hi Rasul,

Attached is the amended repair assessment. Do let me know if we can proceed to order, thanks.

BR
Razali

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Thursday, 23 November, 2017 10:04 AM
To: Mohamad Razali Bin Hassan
Cc: Ai Phing (LKKAuto)
Subject: FD 555Z DOA : 03/11/2017

Hi Razali,

As spoken, the NETT amount repair limit is 44K. Meant that repair cost should not beyond 44K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Wednesday, 22 November, 2017 11:26 AM
To: 'Albert Hong'
Cc: SUR
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116
Attachments: FD 555Z.pdf

Dear Albert,

Enclosed herewith preliminary advise of vehicle FD 555Z.
We have not authorise repair.

Pending repair cost from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 17 November, 2017 10:41 AM
To: 'Albert Hong' <albert.hong@budgetdirect.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Appoint LKK to conduct OD survey; Our Ref: C20001116

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Albert Hong [<mailto:albert.hong@budgetdirect.com.sg>]
Sent: Friday, 17 November, 2017 9:09 AM
To: assignments
Cc: SUR; Lincoln Yeo
Subject: Appoint LKK to conduct OD survey; Our Ref: C20001116
Importance: High

Hi LKK,

Please accept assignment and liaise with Harley-Davidson.

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Friday, 17 November, 2017 9:09 AM
To: assignments
Cc: SUR; Lincoln Yeo
Subject: Appoint LKK to conduct OD survey; Our Ref: C20001116
Attachments: FD555Z(RA).xls; FD555Z(GR).pdf

Importance: High

Hi LKK,

Please accept assignment and liaise with Harley-Davidson.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Mohamad Razali Bin Hassan [<mailto:razali.hassan@harleysingapore.com>]
Sent: Thursday, 16 November, 2017 3:16 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Cc: Ian Lim <ianlimth@gmail.com>
Subject: RE: Claim: C20001116 , Claimed Policy: P20020245R00 , Policy Holder: Teng Han Ian Lim

Hi Albert,

Please arrange to survey the bike tomorrow at 11am, thanks.

BR

RAZALI HASSAN
SERVICE CONSULTANT

Harley-Davidson of Singapore
253 Alexandra Road, #01-04
Singapore 159936

Phone: (65) 6475 0123 Ext(907)
Mobile: (65) 98247879
Fax: (65) 6472 8900
Email: razali.hassan@harleysingapore.com
Web: www.harleysingapore.com

From: Ian Lim [<mailto:ianlimth@gmail.com>]
Sent: Monday, 6 November, 2017 2:01 PM
To: Mohamad Razali Bin Hassan; albert.hong@budgetdirect.com.sg
Subject: Fwd: Claim: C20001116 , Claimed Policy: P20020245R00 , Policy Holder: Teng Han Ian Lim

----- Forwarded message -----

From: **Albert Hong** <albert.hong@budgetdirect.com.sg>
Date: 6 November 2017 at 13:41
Subject: Claim: C20001116 , Claimed Policy: P20020245R00 , Policy Holder: Teng Han Ian Lim
To: "ianlimth@gmail.com" <ianlimth@gmail.com>

Dear Mr Lim,

We refer to our conversation earlier.

You can reach me at this email or contact me at 6540 2182.

Please feel free to call me should you require any assistance.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182

F +65 6725 0853

E albert.hong@budgetdirect.com.sg



Customer Care: +65 6221 2111

Claims: +65 6221 2199

Claims (Int.): +65 6540 2199

190 Clemenceau Avenue

#03-01, Singapore Shopping Centre

Singapore 239924

budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

--
Regards,

Cheers!
Ian

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: C2000116

Date: 22-11-2017

Our Ref: CS/AGI17021997/R1gb

The Motor Claims Department
Auto & General Insurance (Singapore)

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. FD 555Z


We thank you for the instruction on 17-11-2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17-11-2017 at the premises of M/s KOMOCO MOTORCYCLES and have the following to report:-

Workshop Estimate Amount	: S\$ <u>49,728.06</u>
Revised Estimate Amount	: S\$ <u>40,605.06</u>
"Check" Items Amount	: S\$ <u>8,818.00</u>
Market Value	: S\$ <u>49,000.00</u>
LTA Reimbursement Value	: S\$ <u>4,155.00</u>
Nett Value	: S\$ <u>44,845.00</u>

Description of Damage:

The vehicle sustained damages at the o/s and n/s portion.



Comments/ Present Status:

Damages Consistent.

We have not authorize repair.

Pending repair cost from repairer.

Yours faithfully
Mohamed Rasul
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2947A
Vehicle Details	
Vehicle No.	FD555Z
Vehicle to be Exported	No
Intended De-registration Date	20 Nov 2017
Vehicle Make	HARLEY DAVIDSON
Vehicle Model	CVO STREET GLIDE
Primary Colour	Silver
Manufacturing Year	2014
Engine No.	PXNF954601
Chassis No.	5HD1PXNC5FB954601
Maximum Power Output	-
Open Market Value	\$33,891.00
Original Registration Date	04 Apr 2015
First Registration Date	04 Apr 2015
Transfer Count	1
Actual ARF Paid	\$5,084.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	03 Apr 2025
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$5,610.00
COE Rebate Amount	\$4,155.00
Total Rebate Amount	\$4,155.00

The information contained herein is correct as at 20 Nov 2017

OK

49,000
4,155
44,845

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of this accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/11/2017 14:54
Date Of Accident	03/11/2017 12:00
Exact Location Of Accident	NORTH SOUTH HIGHWAY 280KM MARK AFT SEREMBAN TO KUL
Country/State of Loss	MALAYSIA/NEGERI SEMBILAN DARUL KHUSUS

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FD555Z
Insured/Policyholder	
Name Of Registered Owner	LIM TENG HAN IAN
NRIC No	S6842947A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98801884
Alternative Phone No	OFFICE-98801884

Vehicle Particulars

Manufacturer	HARLEY-DAVIDSON
Model	CVO STREET GLIDE

Exact Purpose for which vehicle was being used at time of accident	PRIVATE
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P20020245R00
Cover Note Number	

Driver

Name of Driver	LIM TENG HAN IAN
NRIC No	S6842947A
Date Of Birth	30/12/1968
Occupation	INDOOR
Date Of Driving Pass	29/07/1987
Driving Experience	30 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98801884
Fax Number	
Contact Number	OFFICE-98801884
EMail Address	NOEMAIL

Address	BLK 495E TAMPINES STREET 43 #10-370
Postcode	524495
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	POLIS DIRAJA MALAYSIA, JALAN CAMPBELL, SEREMBAN
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE MALAYSIA POLICE REPORT NO. : TRAFIK NILAI/008042/17 ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	LIM TENG HAN IAN
Approximate Age	48
Injuries Sustain	LEFT WRIST FRACTURE AND ABRASION ON SEVERAL PARTS OF THE BODY
Injured person in which vehicle?	FD555Z
Were seat belts worn?	NO
Was injured conveyed to hospital by ambulance?	YES
Address	BLK 495E TAMPINES STREET 43 #10-370
Postcode	524495

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

Refer to Police Report No. TRAFIK NITAI/00300207/1 attached

Sketch Plan #2

Salinan Repot Polis


POLIS DIRAJA MALAYSIA
 REPOT POLIS

COPY

Balai : JALAN CAMPBELL
 Daerah : SEREMBAN
 Kontinjen : NEGERI SEMBILAN
 No Repot : TRAFIK NILAI/008042/17
 Tarikh : 03/11/2017
 Waktu : 2341 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R185930

Butir-butir Penerima Repot

Nama : MUHAMMAD SHAFIQ BIN MOHD SHAFIE No Personal : R185930 Pangkat : L/KPL
 Butir-butir Jurubahasa (Jika Ada)
 Nama : — No K/P (Baru) : — No Polis/Tentera : —
 No Pasport : — Bahasa Asal : —
 Alamat : —

Butir-butir Pengadu

Nama : LIM TENG HAN IAN
 No K/P (Baru) : — No Polis/Tentera : — No Pasport : E5375810H
 No Sijil Beranak : —
 Jantina : Lelaki Tarikh Lahir : 30/12/1968 Umur : 48 tahun 10 bulan
 Keturunan : Cina Warganegara : Singapore
 Pekerjaan : MANAGER
 Alamat Tempat Tinggal : APT BLK 495E TAMPINES STREET 43#10-370 SINGAPORE, 524495
 Alamat Ibu/Bapa : —
 Alamat Pejabat : —
 No Tel (Rumah) : — No Tel (Pejabat) : — No Tel (HP) : 6596601884
 Emel : —

Pengadu Menyatakan:-

REPOT DITAIIP SENDIRI OLEH PENGADU.

ON 3RD November 2017, at 1200hrs, I was riding my Harley Davidson Motorbike with registration number FD555Z along North South Highway 280km mark after Seremban towards Kuala Lumpur, and I noticed a white Malaysian Registered Car swerved towards my bike and I just avoided the collision with the car and such I skidded and lost control of the bike.

Condition of road was wet with light rain.

This is all I can remember and my motorbike had substantial damages and missing mobile phone.
 I suffered Left wrist fracture and abrasion on several parts of my body.

This report is made for the purpose of Insurance Claim. Thank You.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):


Tandatangan Penerima Repot

ID Pencetak | Tarikh @ Masa Cetak : R185930 | 03/11/2017 11:53:03 PM

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Driving License



Accident Photo



Accident Photo





KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04, Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500364-4
Business Reg. No. : 198800033H

Budget Direct Insurance
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
BIKE NO / MODEL: FD555Z FLHXSE 2015
VIN NO: 5HD1PXNC5F8954601

INSURANCE : BUDGET DIRI
DATE : 08.11.17

S/N	Part #	Description	Quantity	Unit Price	Price
1	10344	(H) CLAMP, HOSE	1	\$7.80	\$7.80
2	59900116DXX	FF, HC MRCRY W/SMOKY QURTZ FLMS	1	\$2,408.00	\$2,408.00
3	61400224	WINDSHIELD TRIM, GROOVED, CHROME, BILLET	1	\$309.00	\$309.00
4	57000418DXX	KIT, FRNG/FLH, HC MRCRY W/SMOKY QURTZ	1	\$2,479.00	\$2,479.00
5	57000417DYE	FRNG ASY, INR, SMOKY QURTZ	1	\$2,479.00	\$2,479.00
6	57200017	SKIRT, FRT-FRNG	1	\$188.10	\$188.10
7	57200012	AIR DEFLECTOR ASY,LH	1	\$169.00	\$169.00
8	2583	SCREW	6	\$3.00	\$18.00
9	57400263	WINDSPLITTER,MED,SMOKE..177	1	\$391.00	\$391.00
10	48050-09A	: GLOSS BLACK ENGINE GUARD KIT, TOURING	1	\$525.50	\$525.50
11	57100107	GLOVE BOX ASY,LH,PC	1	\$141.00	\$141.00
12	7415A	WASHER RUBBER	2	\$2.60	\$5.20
13	57100099	PANEL ASY,GLOVEBOX,PC	2	\$33.50	\$67.00
14	57100154	HINGE, TORQUE	2	\$36.10	\$72.20
15	57100151	SCREEN,RADIATOR,LH-PC	1	\$28.50	\$28.50
16	47200275	CLAMP	2	\$2.60	\$5.20
17	12200025	CLIP,PANEL	6	\$2.00	\$12.00
18	57100155	DOOR,VENT	2	\$135.80	\$271.60
19	57100275DXX	FRNG ASY,LWR,LH, HC MRCRY W/SMOKY QURTZ	1	\$1,132.30	\$1,132.30
20	8175	BOLT,RETAINER	2	\$7.90	\$15.80
21	26800008	DUCT,LH-RADIATOR	1	\$27.10	\$27.10
22	57100200	PIN,DOOR,VENT	2	\$15.00	\$30.00
23	57100242DYO	CAP,FRNG LWR,LH, HC MRCRY	1	\$601.50	\$601.50
24	7716	(20) LOCK NUT	6	\$2.60	\$15.60
25	57100109	GLOVE BOX ASY,RH,PC	1	\$141.00	\$141.00
26	26800009	DUCT,RH-RADIATOR	1	\$27.10	\$27.10
27	11519	BUSHING,AIRBOX MOUNTING	1	\$2.50	\$2.50
28	57100153	GASKET,LH/RH,RADIATOR SCREEN	2	\$23.00	\$46.00
29	57100276DXX	FRNG ASY,LWR,RH, HC MRCRY W/SMOKY QURTZ	1	\$1,132.30	\$1,132.30
30	57100243DYO	CAP,FRNG LWR,RH, HC MRCRY	1	\$601.50	\$601.50
31	57100152	SCREEN,RADIATOR,RH-PC	1	\$28.50	\$28.50
32	61000168DXX	F/T, HC MRCRY W/SMOKY QURTZ FLMS	1	\$4,371.80	\$4,371.80
33	81402-08	GASKET, TOP PLATE	1	\$13.10	\$13.10
34	63028-06	CHROME TRIM RING	1	\$29.90	\$29.90
35	42102-08D	MSTR CYL ASY,FRT,DUAL/CHRM	1	\$804.30	\$804.30
36	41751-06A	GASKET, BRAKELINE	2	\$2.80	\$5.60
37	41800219	DOT 4 BRAKE FLUID	1	\$21.50	\$21.50
38	71500160A	COVER ASY,RH/RR,CHROME	1	\$221.00	\$221.00
39	71500086	COVER,RH/FRT,CHROME	1	\$221.00	\$221.00
40	71500168	VERTICAL KEY CAP,START/HAZARD	1	\$33.40	\$33.40
41	50500343	FOOTBOARD ASY,RH,RIDER	1	\$245.50	\$245.50
42	50600142	FOOTBRAKE LEVER ASY	1	\$426.50	\$426.50
43	50600134	FRAME INSERT,BRAKEPEDAL	1	\$66.90	\$66.90
44	50600135	INSERT,BRAKEPEDAL,RUBBER	1	\$28.00	\$28.00
45	3340	SCREW	1	\$2.50	\$2.50
46	6416	WASHER	1	\$1.20	\$1.20
47	50500055B	FTBRD,SUPPORT BRKT,FRONT,CHRM	2	\$203.50	\$407.00
48	50500051	BRACKET,LH/RR,FTBRD SUPRT/CHRM	1	\$203.20	\$203.20



KOMOCO Motorcycles Pte Ltd
 253, Alexandra Road, # 01-04, Singapore 159936
 Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500984-4
 Business Reg. No. : 186800933H

Budget Direct Insurance
 190 Clemenceau Avenue
 #03-01, Singapore Shopping Centre
 Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
 BIKE NO / MODEL: FD555Z FLHXSE 2015
 VIN NO: 5HD1PXNC5FB954601

INSURANCE : BUDGET DIRI
 DATE : 06.11.17

S/N	Part #	Description	Quantity	Unit Price	Price
49	50500052A	FTBRD,SUPPORT BRKT,RH/RR,CHRM	1	\$164.50	\$164.50
50	4668	SCREW,HEX SCKT,SEMS,3/8-16X1-1	2	\$6.70	\$13.40
51	4032A	HEX SOCKET HD CAP SCREW	2	\$2.80	\$5.60
52	7038	LOCKWASHER	2	\$0.80	\$1.60
53	7601	FLANGE LOCKING NUT	2	\$2.60	\$5.20
54	50500348	BOTTOM,RH-FOOTBOARD	1	\$90.70	\$90.70
55	50500349	BOTTOM,LH-FOOTBOARD	1	\$90.70	\$90.70
56	33130-07A	WEAR PEG	2	\$12.10	\$24.20
57	50674-05	BOLT, SHOULDER, GRADE 8	4	\$3.00	\$12.00
58	8835	(10) CLAMP SHIELD	1	\$5.80	\$5.80
59	66219-06	HEATSHIELD, EXHAUST, RH, CHROME	1	\$238.00	\$238.00
60	66220-06	HEATSHIELD, EXHAUST, LH, CHROME	1	\$238.00	\$238.00
61	90201143DYO	S/B COV ASY RH, HC MRCRY	1	\$1,265.50	\$1,265.50
62	90200520	LATCH ASY,RH S'BAG	1	\$625.20	\$625.20
63	76000418	GRILLE ASY,BOOM,RH-S'BAG	1	\$130.90	\$130.90
64	90200979	HANDLE,RH-S'BAG,SPEAKER	1	\$58.50	\$58.50
65	90200467	CUSHION,S'BAG SUPPORT	4	\$7.60	\$30.40
66	76000333	SPEAKER ASY,SADDLEBAG,TIER 2	2	\$467.00	\$934.00
67	90200415	GASKET,S/BAG COVER	2	\$17.00	\$34.00
68	90201137DXX	KIT, S/B BOT, RH, HC MRCRY W/SMOKY QURTZ	1	\$2,579.50	\$2,579.50
69	10900040	KIT,STUD,SADDLEBAG,CLIPS	4	\$68.90	\$275.60
70	90200984DYO	FACEPLATE,RH S/B, HC MRCRY	1	\$454.50	\$454.50
71	67900068	REFLECTOR, SIDE, RH, AMBER	1	\$17.90	\$17.90
72	60900058A	KING TWO-UP LUGGAGE RACK, BLACK	1	\$494.50	\$494.50
73	52300361	BACKREST PAD,15 FLHXSE	1	\$266.20	\$266.20
74	54248-09A	SISSY BAR UPRIGHT, SHORT, GLOSS BLACK	1	\$375.00	\$375.00
75	90201142DYO	S/B COV ASY LH, HC MRCRY	1	\$1,265.50	\$1,265.50
76	90201136DXX	KIT, S/B BOT, LH, HC MRCRY W/SMOKY QURTZ	1	\$2,579.50	\$2,579.50
77	90200680	HANDLE,LH-S'BAG,SPEAKER	1	\$59.00	\$59.00
78	90200521	LATCH ASY,LH S'BAG	1	\$625.50	\$625.50
79	76000417	GRILLE ASY,BOOM,LH-S'BAG	1	\$130.90	\$130.90
80	90200983DYO	FACEPLATE,LH S/B, HC MRCRY	1	\$454.50	\$454.50
81	67900066	REFLECTOR, SIDE, LH, AMBER	1	\$18.70	\$18.70
82	38700050	CLUTCHLEVER ASY,CHRM	1	\$185.00	\$185.00
83	11143	EXT. RETAINING RING	1	\$2.60	\$2.60
84	57485-11	BAT WING APE HANGER HANDLEBAR BLACK	1	\$454.00	\$454.00
85	56000081	KIT-MIRROR,ILLUMINATED,BLACK	1	\$687.50	\$687.50
86	50500187	ADJ HWY PEG MNT,LONG,BLACK	1	\$249.50	\$249.50
87	60500367	KIT-FOOTPEG,BURST,RECTANGULAR	1	\$328.80	\$328.80
88	61400028	KIT-TRIM,MID FRM AIR DEFLCTR,TOURING	1	\$151.30	\$151.30
89	45600018	COVER ASY,FORK TUBE,LH,PEM	1	\$105.90	\$105.90
90	45600017	COVER ASY,FORK TUBE,RH,PEM	1	\$105.90	\$105.90
91	68000082	KIT-FOG LAMP,BULLET,BLACK	1	\$823.80	\$823.80
92	69201109	KIT-WIRE HARNESS,FOG LAMP,FLT	1	\$50.90	\$50.90
93	68000142	KIT-MNTG, FOG LT, TOURING W/LWRS, BLK	1	\$103.00	\$103.00
94	69200172	SWITCH ASY,DASH/PANEL MTND,FOG	1	\$118.00	\$118.00
95	76000535	SPEAKER ASY,RH TWEETER,MID-RANGE	1	\$363.50	\$363.50
96	56100098A	BURST HAND GRIPS, ETC	1	\$287.60	\$287.60



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04. Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500364-4
Business Reg. No. : 198800933H

Budget Direct Insurance
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
BIKE NO / MODEL : FD555Z FLHXSE 2015
VIN NO : 5HD1PXXNC8FB954601

INSURANCE : BUDGET DIRI
DATE : 06.11.17

S/N	Part #	Description
		<u>SUPPLEMENTARY</u>
97	57000172	SPEAKER ENCLOSURE SUB-ASSY, LH
98	57000175	SPEAKER ENCLOSURE SUB-ASSY, RH
99	12200063	CLIP, ANTENNA
100	50500347	FOOTBOARD ASY, LH, RIDER
101	42271-08A	BRAKELEVER ASY, CHRM
102	26800119	H-D EXTENDED LIFE COOLANT, ANTIFREEZE, PINT
103	10200060	SCREW, TORX SCKT, 6TN HD X 2.83
104	76000513	KIT-ANTENNA, HIDDEN

Quantity	Unit Price	Price
1	\$255.20	\$255.20
1	\$255.20	\$255.20
1	\$12.70	\$12.70
1	\$245.60	\$245.60
1	\$210.70	\$210.70
3	\$29.50	\$88.50
1	\$3.20	\$3.20
1	\$146.40	\$146.40

SUB TOTAL PARTS : \$39,280.60

LESS : 10% DISCOUNT \$3,928.06

\$35,352.54

LESS EXCESS PAYMENT \$500.00

\$34,852.54

ADD : LABOUR \$2,800.00

1 \$190.00 \$190.00

1 \$90.00 \$90.00

1 \$8.56 \$8.56

1 \$180.00 \$180.00

IJ-UNIT IJ ASSEMBLY
I.U. I.U. BRACKET
NOPLATE-F FRONT NUMBER PLATE(STICKER)
SUBLET TPMS

SUBLET 3RD PARTY EXHAUST HEATSHEILD
WORKSHOP MISCELLANEOUS SALES

1 \$560.00 \$560.00

\$38,681.10

GST 7% \$2,707.68

TOTAL PAYABLE (SGD) : \$41,388.78



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04, Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 64728900
REPAIR ASSESSMENT

OWNER'S NAME : LIM TENG HAN IAN
BIKE NO / MODEL : FD555Z FLHXSE 2015
VIN NO : 5HD1PXNC5FB954601

INSURANCE :
DATE : 15/11/2017

S/N	PART NO.	DESCRIPTION	QTY	AMOUNT	
1	58900116DXX	FF, HC MRCRY W/SMOKY QURTZ FLMS	1	\$ / 2,408.00	HT -
2	61400224	WINDSHIELD TRIM, GROOVED, CHROME, BILLET	1	\$ / 309.00	CRH -
3	57000416DXX	KIT, FRNG/FLH, HC MRCRY W/SMOKY QURTZ	1	\$ / 2,479.00	CRH -
4	57000417DYB	FRNG ASY, INR, SMOKY QURTZ	1	\$ / 2,479.00	CRH -
5	61400063	TRIM, LH-INR FRNG	1	\$ / 17.40	CRH -
6	61400064	TRIM, RH-INR FRNG	1	\$ / 17.40	CRH -
7	57200017	SKIRT, FRT-FRNG	1	\$ / 188.10	CRH -
8	57200012	AIR DEFLECTOR ASY, LH	1	\$ / 169.00	MIS -
9	2563	SCREW	7	\$ / 3.00	NEE -
10	11100038	FOAM TAPE	1	\$ / 7.80	NEE -
11	57400253	WINDSPITTER, MED SMOKE	1	\$ / 391.00	SCA -
12	NOPLATE-F	FRONT NUMBER PLATE(STICKER)	1	\$ / 8.56	NE -
13	49050-09A	GLOSS BLACK ENGINE GUARD KIT, TOURING	1	\$ / 525.50	PT -
14	57100107	GLOVE BOX ASY, LH, PC	1	\$ / 141.00	DE -
15	10200052	SCREW, BTN HD, TORX	4	\$ / 2.60	AA -
16	57100256	CLAMP, PC, LH, LWR-FRNG	1	\$ / 61.70	AA -
17	57100170	LWR FASCIA ASY, LH	1	\$ / 70.50	DE -
18	7415A	WASHER RUBBER	2	\$ / 2.60	NE -
19	57100099	PANEL ASY, GLOVEBOX, PC	2	\$ / 33.50	SCA -
20	57100154	HINGE, TORQUE	2	\$ / 36.10	NE -
21	3655A	PAN HEAD TORX SCREW	2	\$ / 1.00	AA -
22	57100151	SCREEN, RADIATOR, LH-PC	1	\$ / 26.50	MIS -
23	47200275	CLAMP	2	\$ / 2.60	NE -
24	12200025	CLIP, PANEL	10	\$ / 2.00	NE -
25	57100155	DOOR, VENT	2	\$ / 135.80	SCA -
26	57100275DXX	FRNG ASY, LWR, LH, HC MRCRY	1	\$ / 1,132.30	SCA -
27	12600049	SCREW, CAP, SEMS, W/LOCKPATCH	1	\$ / 1.50	AA -
28	8175	BOLT, RETAINER	2	\$ / 7.90	NE -
29	7576	NUT FLANGE	2	\$ / 2.60	NE -
30	26800008	DUCT, LH-RADIATOR	1	\$ / 27.10	MIS -
31	57100200	PIN, DOOR, VENT	2	\$ / 15.00	NE -
32	57100242DYO	CAP, FRNG LWR, LH, HC MRCRY	1	\$ / 601.50	SCA -
33	57100187	RETAINER, U-BOLT	2	\$ / 5.70	AA -
34	7716	(20) LOCH NUT	8	\$ / 2.60	NE -
35	57100153	GASKET, LH/RH, RADIATOR SCREEN	1	\$ / 23.00	AA -
36	57100109	GLOVE BOX ASY, RH, PC	1	\$ / 141.00	SCA -
37	12600049	SCREW, CAP, SEMS, W/LOCKPATCH	8	\$ / 1.20	AA -
38	26800009	DUCT, RH-RADIATOR	1	\$ / 27.10	NE -
39	11519	BUSHING, AIRBOX MOUNTING	1	\$ / 2.50	NE -
40	57100153	GASKET, LH/RH, RADIATOR SCREEN	2	\$ / 23.00	NE -
41	57100276DXX	FRNG ASY, LWR, RH, HC MRCRY	1	\$ / 1,132.30	SCA -
42	57100243DYO	CAP, FRNG LWR, RH, HC MRCRY	1	\$ / 601.50	SCA -
43	57100171	LWR FASCIA ASY, RH	1	\$ / 70.50	SCA -
44	57100152	SCREEN, RADIATOR, RH-PC	1	\$ / 26.50	MIS -
45	61000168DXX	F/T, HC MRCRY W/SMOKY QURTZ FLMS	1	\$ / 4,371.80	HT -
46	70901-09	BOOT, RH/FRT TANK MNT	1	\$ / 21.60	AA -
47	70999-09	BOOT, LH/FRT TANK MNT	1	\$ / 21.60	AA -
48	61402-08	GASKET, TOP PLATE	1	\$ / 13.10	NE -
49	83028-06	CHROME TRIM RING	1	\$ / 29.90	NE -
50	56100098A	BURST HAND GRIPS, ETC	1	\$ / 287.60	SCA -
51	42102-06D	MSTR CYL ASY, FRT, DUAL/CHRM	1	\$ / 804.30	SCA -
52	41751-06A	GASKET, BRAKELINE	2	\$ / 2.80	NE -
53	41800219	DOT 4 BRAKE FLUID	1	\$ / 21.50	NE -

117		KIT-MIRROR, ILLUMINATED, BLACK	1		\$ 687.50
118		ADJ HWY PEG MNT, LONG, BLACK	1		\$ 249.50
119		KIT-FOOTPEG, BURST, RECTANGULAR	1		\$ 328.80
120		TPMS	1		\$ 250.00
121		COVER ASY, FORK TUBE, LH, PEM	1		\$ 105.90
122		COVER ASY, FORK TUBE, RH, PEM	1		\$ 105.90
123		KIT-FOG LAMP, BULLET, BLACK	1		\$ 823.80
124		KIT-WIRE HARNESS, FOG LAMP, FLT	1		\$ 50.90
125		KIT-MNTG, FOG LT, TOURING W/LWRS, BLK	1		\$ 103.00
126		SWITCH ASY, DASH PANEL MTND, FOG	1		\$ 118.00
127		SPEAKER ASY, RH TWEETER, MID-RANGE	1		\$ 363.50
128		KIT-TRIM, MID FRM AIR DEFLECTR, TOURING	1		\$ 151.30
129		SUPPLEMENTARY			
130		SPEAKER ENCLOSURE SUB-ASSY, LH	1		\$ 255.20
131		SPEAKER ENCLOSURE SUB-ASSY, RH	1		\$ 255.20
132		SEMS, HEX SOCKET CAP	6	\$ 6.80	\$ 40.80
133	(A)	SCREW, 1/4-20, HEX BTN, SEMS, 50 LG	6	\$ 1.00	\$ 6.00
134		CLIP, ANTENNA	1	12.30	\$ 13.30
135		3RD PARTY EXHAUST HEATSHEILD SN	1		\$ 560.00
136		FOOTBOARD ASY, LH, RIDER	1		\$ 245.60
			LABOUR		\$ 2,996.00
					\$ 43,649.76

} (CR)
 X NEE NN
 X NEE NN
 NEC
 CUT
 CUT

*** Estimation is based on visual inspection and should there be unforeseen additional damage found during repair, supplementary parts may have to be ordered.

*** Prices are subject to change.

$$43,649.76 - 39,694.24 = 3955.52$$

$$3955.52 \div 43,649.76 = 0.09\%$$



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04, Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500364-4
 Business Reg. No. : 199800033H

Budget Direct Insurance
 190 Clemenceau Avenue
 #03-01, Singapore Shopping Centre
 Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
 BIKE NO / MODEL : FD555Z FLHXSE 2015
 VIN NO : 5HD1PXNC5FB954601

INSURANCE :
 DATE :
 BUDGET DIRI
 06.11.17

S/N	Part #	Description	Quantity	Unit Price	Price
1	10344	CLAMP, HOSE	1	\$7.80	\$7.80
2	58900116DXX	FF, HC MRCRY W/SMOKY QURTZ FLMS	1	\$2,408.00	\$2,408.00
3	61400224	WINDSHIELD TRIM, GROOVED, CHROME, BILLET	1	\$309.00	\$309.00
4	57000416DXX	KIT, FRNG/FLH, HC MRCRY W/SMOKY QURTZ	1	\$2,479.00	\$2,479.00
5	57000417DYB	FRNG ASY, INR, SMOKY QURTZ	1	\$2,479.00	\$2,479.00
6	57200017	SKIRT, FRT-FRNG	1	\$188.10	\$188.10
7	57200012	AIR DEFLECTOR ASY,LH	1	\$169.00	\$169.00
8	2563	SCREW	6	\$3.00	\$18.00
9	57400253	WINDSPITTER,MED,SMOKE..177	1	\$391.00	\$391.00
10	48050-09A	: GLOSS BLACK ENGINE GUARD KIT, TOURING	1	\$525.50	\$525.50
11	57100107	GLOVE BOX ASY,LH,PC	1	\$141.00	\$141.00
12	7415A	WASHER RUBBER	2	\$2.60	\$5.20
13	57100089	PANEL ASY,GLOVEBOX,PC	2	\$33.50	\$67.00
14	57100154	HINGE, TORQUE	2	\$36.10	\$72.20
15	57100151	SCREEN,RADIATOR,LH-PC	1	\$28.50	\$28.50
16	47200275	CLAMP	2	\$2.60	\$5.20
17	12200025	CLIP,PANEL	6	\$2.00	\$12.00
18	57100155	DOOR,VENT	2	\$135.80	\$271.60
19	57100275DXX	FRNG ASY,LWR,LH, HC MRCRY W/SMOKY QURTZ	1	\$1,132.30	\$1,132.30
20	8175	BOLT,RETAINER	2	\$7.90	\$15.80
21	26800006	DUCT,LH-RADIATOR	1	\$27.10	\$27.10
22	57100200	PIN,DOOR,VENT	2	\$15.00	\$30.00
23	57100242DYO	CAP,FRNG LWR,RH, HC MRCRY	1	\$601.50	\$601.50
24	7716	(20) LOCH NUT	8	\$2.60	\$15.60
25	57100109	GLOVE BOX ASY,RH,PC	1	\$141.00	\$141.00
26	26800009	DUCT,RH-RADIATOR	1	\$27.10	\$27.10
27	11519	BUSHING,AIRBOX MOUNTING	1	\$2.50	\$2.50
28	57100153	GASKET,LH/RH,RADIATOR SCREEN	2	\$23.00	\$46.00
29	57100276DXX	FRNG ASY,LWR,RH, HC MRCRY W/SMOKY QURTZ	1	\$1,132.30	\$1,132.30
30	57100243DYO	CAP,FRNG LWR,RH, HC MRCRY	1	\$601.50	\$601.50
31	57100152	SCREEN,RADIATOR,RH-PC	1	\$28.50	\$28.50
32	61000168DXX	F/T, HC MRCRY W/SMOKY QURTZ FLMS	1	\$4,371.80	\$4,371.80
33	61402-08	GASKET, TOP PLATE	1	\$13.10	\$13.10
34	63028-06	CHROME TRIM RING	1	\$29.90	\$29.90
35	42102-08D	MSTR CYL ASY,FRT,DUAL/CHRM	1	\$804.30	\$804.30
36	41751-06A	GASKET, BRAKELINE	2	\$2.60	\$5.60
37	41800219	DOT 4 BRAKE FLUID	1	\$21.50	\$21.50
38	71500160A	COVER ASY,RH/RR,CHROME	1	\$221.00	\$221.00
39	71500086	COVER,RH/FRT,CHROME	1	\$221.00	\$221.00
40	71500168	VERTICAL KEY CAP,START/HAZARD	1	\$33.40	\$33.40
41	50600343	FOOTBOARD ASY,RH,RIDER	1	\$245.60	\$245.60
42	50600142	FOOTBRAKE LEVER ASY	1	\$426.50	\$426.50
43	50600134	FRAME INSERT,BRAKEPEDAL	1	\$66.90	\$66.90
44	50600135	INSERT,BRAKEPEDAL,RUBBER	1	\$28.00	\$28.00
45	3340	SCREW	1	\$2.50	\$2.50
46	6416	WASHER	1	\$1.20	\$1.20
47	50500065B	FTBRD,SUPPORT BRKT,FRONT,CHRM	2	\$203.50	\$407.00
48	50600051	BRACKET,LH/RR,FTBRD SUPRT/CHRM	1	\$203.20	\$203.20



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04, Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500364-4
 Business Reg. No. : 198800933H

Budget Direct Insurance
 190 Clemenceau Avenue
 #03-01, Singapore Shopping Centre
 Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
 BIKE NO / MODEL: FD555Z FLHXSE 2015
 VIN NO: 5HD1PXNC5FB954601

INSURANCE :
 DATE :
 BUDGET DIRI
 06.11.17

S/N	Part #	Description	Quantity	Unit Price	Price
49	50500052A	FTBRD,SUPPORT BRKT,RH/RR,CHRM	1	\$164.50	\$164.50
50	4688	SCREW,HEX SCKT,SEMS,3/8-16X1-1	2	\$6.70	\$13.40
51	4032A	HEX SOCKET HD CAP SCREW	2	\$2.80	\$5.60
52	7038	LOCKWASHER	2	\$0.80	\$1.60
53	7601	FLANGE LOCKING NUT	2	\$2.60	\$5.20
54	50500348	BOTTOM,RH-FOOTBOARD	1	\$90.70	\$90.70
55	50500349	BOTTOM,LH-FOOTBOARD	1	\$90.70	\$90.70
56	33130-07A	WEAR PEG	2	\$12.10	\$24.20
57	50574-05	BOLT, SHOULDER, GRADE 8	4	\$3.00	\$12.00
58	9955	(10) CLAMP SHIELD	1	\$5.80	\$5.80
59	66219-06	HEATSHIELD, EXHAUST, RH, CHROME	1	\$238.00	\$238.00
60	66220-06	HEATSHIELD, EXHAUST, LH, CHROME	1	\$238.00	\$238.00
61	90201143DYO	S/B COV ASY RH, HC MRCRY	1	\$1,265.50	\$1,265.50
62	90200520	LATCH ASY,RH S'BAG	1	\$625.20	\$625.20
63	76000418	GRILLE ASY,BOOM,RH-S'BAG	1	\$130.90	\$130.90
64	90200879	HANDLE,RH-S'BAG,SPEAKER	1	\$58.50	\$58.50
65	90200467	CUSHION,S'BAG SUPPORT	4	\$7.60	\$30.40
66	76000333	SPEAKER ASY,SADDLEBAG,TIER 2	2	\$467.00	\$934.00
67	90200415	GASKET,S/BAG COVER	2	\$17.00	\$34.00
68	90201137DXX	KIT, S/B BOT, RH, HC MRCRY W/SMOKY QURTZ	1	\$2,579.50	\$2,579.50
69	10900040	KIT,STUD,SADDLEBAG,CLIPS	4	\$68.90	\$275.60
70	90200984DYO	FACEPLATE,RH S/B, HC MRCRY	1	\$454.50	\$454.50
71	67900068	REFLECTOR, SIDE, RH, AMBER	1	\$17.90	\$17.90
72	50300058A	KING TWO-UP LUGGAGE RACK, BLACK	1	\$494.50	\$494.50
73	52300381	BACKREST PAD,15 FLHXSE	1	\$268.20	\$268.20
74	54248-09A	SISSY BAR UPRIGHT, SHORT, GLOSS BLACK	1	\$375.00	\$375.00
75	90201142DYO	S/B COV ASY LH, HC MRCRY	1	\$1,265.50	\$1,265.50
76	90201136DXX	KIT, S/B BOT, LH, HC MRCRY W/SMOKY QURTZ	1	\$2,579.50	\$2,579.50
77	90200980	HANDLE,LH-S'BAG,SPEAKER	1	\$59.00	\$59.00
78	90200521	LATCH ASY,LH S'BAG	1	\$625.50	\$625.50
79	76000417	GRILLE ASY,BOOM,LH-S'BAG	1	\$130.90	\$130.90
80	90200983DYO	FACEPLATE,LH S/B, HC MRCRY	1	\$454.50	\$454.50
81	67900066	REFLECTOR, SIDE, LH, AMBER	1	\$18.70	\$18.70
82	36700050	CLUTCHLEVER ASY,CHRM	1	\$185.00	\$185.00
83	11143	EXT. RETAINING RING	1	\$2.60	\$2.60
84	57485-11	BAT WING APE HANGER HANDLEBAR BLACK	1	\$454.00	\$454.00
85	56000081	KIT-MIRROR,ILLUMINATED,BLACK	1	\$687.50	\$687.50
86	50500167	ADJ HWY PEG MNT,LONG,BLACK	1	\$249.50	\$249.50
87	50500367	KIT-FOOTPEG,BURST,RECTANGULAR	1	\$328.80	\$328.80
88	61400028	KIT-TRIM,MID FRM AIR DEFLCTR,TOURING	1	\$151.30	\$151.30
89	45600018	COVER ASY,FORK TUBE,LH,PEM	1	\$105.90	\$105.90
90	45600017	COVER ASY,FORK TUBE,RH,PEM	1	\$105.90	\$105.90
91	68000092	KIT-FOG LAMP,BULLET,BLACK	1	\$823.80	\$823.80
92	60201109	KIT-WIRE HARNESS,FOG LAMP,FLT	1	\$50.90	\$50.90
93	68000142	KIT-MNTG, FOG LT, TOURING W/LWRS, BLK	1	\$103.00	\$103.00
94	69200172	SWITCH ASY,DASH/PANEL MTND,FOG	1	\$118.00	\$118.00
95	76000535	SPEAKER ASY,RH TWEETER,MID-RANGE	1	\$363.50	\$363.50
96	58100098A	BURST HAND GRIPS, ETC	1	\$287.60	\$287.60



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04, Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 6472-8900

TAX INVOICE

GST Reg no. MR-8500364-4
Business Reg. No. : 199800939H

Budget Direct Insurance
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

INVOICE NO. : RO2017/11/030

OWNER'S NAME : LIM TENG HAN IAN
BIKE NO / MODEL: FD555Z FLHXSE 2015
VIN NO: 5HD1PXNC5FB954601

INSURANCE : BUDGET DIRI
DATE : 06.11.17

S/N	Part #	Description
		<u>SUPPLEMENTARY</u>
97	57000172	SPEAKER ENCLOSURE SUB-ASSY, LH
98	57000175	SPEAKER ENCLOSURE SUB-ASSY, RH
99	12200063	CLIP, ANTENNA
100	50900347	FOOTBOARD ASY, LH, RIDER
101	42271-06A	BRAKELEVER ASY, CHRM
102	26800119	H-D EXTENDED LIFE COOLANT, ANTIFREEZE, PINT
103	10200060	SCREW, TORX SCKT, STN HD X 2.63
104	76000513	KIT-ANTENNA, HIDDEN

Quantity	Unit Price	Price
1	\$255.20	\$255.20
1	\$255.20	\$255.20
1	\$12.70	\$12.70
1	\$245.60	\$245.60
1	\$210.70	\$210.70
3	\$29.50	\$88.50
1	\$3.20	\$3.20
1	\$146.40	\$146.40

SUB TOTAL PARTS : \$39,280.60

LESS : 10% DISCOUNT \$3,928.08

\$35,352.54

LESS EXCESS PAYMENT \$500.00

\$34,852.54

ADD : LABOUR \$2,800.00

1 \$190.00 \$190.00

1 \$90.00 \$90.00

1 \$8.56 \$8.56

1 \$180.00 \$180.00

IJ-UNIT	IJ ASSEMBLY
I.U.	I.U. BRACKET
NOPLATE-F	FRONT NUMBER PLATE(STICKER)
SUBLET	TPMS

SUBLET	3RD PARTY EXHAUST HEATSHIELD
	WORKSHOP MISCELLANEOUS SALES

1 \$560.00 \$560.00

\$36,681.10

GST 7% \$2,707.88

TOTAL PAYABLE (SGD) : \$41,388.78



KOMOCO Motorcycles Pte. Ltd.

253 Alexandra Road

#01-04 Singapore 159936

Tel: 6475-0123 Fax: 6479-7061

DISCHARGE VOUCHER

I, IAN LIM TENG HAN hereby acknowledge having received my motorcycle, bearing registration no. FD555Z from my/our repairers **KOMOCO Motorcycles Pte. Ltd.** in good running order which has been repaired to my satisfaction. In addition, I have no further claim on the above repairs in respect thereof from **KOMOCO Motorcycles Pte. Ltd** or Budget Direct Insurance

* 7 days Warranty from 27/Mar/18

Signature

NRIC No.

S6842947/A

Date

27/Mar/18

Witnessed By

Name

RAZALI HASSAN

NRIC No.

S81079524

Date

27/3/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI17021997/R1rbe2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 21-09-2018



Code : AGI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	FD 555Z
Policy No. P20020245R00	Coverage (\$)	0.00
Claim No. C2000116	Excess (\$)	500.00
Assign From ALBERT HONG	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model	HARLEY DAVIDSON CVO STREET GLIDE	c.c	1801
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	5HD1PXNC5FB954601	Colour	MULTI COLOUR
Odometer	17557	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	130/60 R19	DUNLOP	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 R18	DUNLOP	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/11/2017	Inspection Date	17/11/2017
Survey held at	KOMOCO MOTORCYCLES PTE LTD 253 ALEXANDRA ROAD #01-04 SINGAPORE 159936		

5a. Remarks

A)THE MARKET VALUE IS S\$49,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR.	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FD 555Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FF, HC MRCRY W/SMOKY QURTZ FLMS	BENT	2,408.00	2,408.00
1	WINDSHIELD TRIM, GROOVED, CHROME, BILLET	CRACKED	309.00	309.00
1	KIT, FRNG/FLH, HC MRCRY W/SMOKY QURTZ	CRACKED	2,479.00	2,479.00
1	FRNG ASY, INR,SMOKY QURTZ	CRACKED	2,479.00	2,479.00
1	TRIM, LH-INR FRNG	SERVICEABLE	17.40	-
1	TRIM, RH-INR FRNG	SERVICEABLE	17.40	-
1	SKIRT, FRT-FRNG	CRACKED	188.10	188.10
1	AIR DEFLECTOR ASY, LH	MISSING	169.00	169.00
7	SCREW @\$3.00	NECESSARY	21.00	18.00
1	FOAM TAPE	NOT NECESSARY	7.80	-
1	WINDSPLITTER, MED, SMOKE	SCRATCHED	391.00	391.00
1	GLOSS BLACK ENGINE GUARD KIT, TOURING	BENT	525.50	525.50
1	GLOVE BOX ASY, LH, PC	DEFORMED	141.00	141.00
4	SCREW, BTN HD, TORX @\$2.60	NOT NECESSARY	10.40	-
1	CLAMP, PC, LH, LWR-FRNG	NOT NECESSARY	61.70	-
1	LWR FASCIA ASY, LH	NOT NECESSARY	70.50	-
2	WASHER RUBBER @\$2.60	NECESSARY	5.20	5.20
2	PANEL ASY, GLOVEBOX, PC @\$33.50	SCRATCHED	67.00	67.00
2	HINGE, TORQUE @\$36.10	NECESSARY	72.20	72.20
2	PAN HEAD TORX SCREW @\$1.00	NOT NECESSARY	2.00	-
1	SCREEN, RADIATOR, LH-PC	MISSING	28.50	28.50
2	CLAMP @\$2.60	NECESSARY	5.20	5.20
10	CLIP, PANEL @\$2.00	NECESSARY	20.00	12.00
2	DOOR, VENT @\$135.80	JAMMED	271.60	271.60
1	FRNG ASY, LWR LH, HC MRCRY	SCRATCHED	1,132.30	1,132.30
1	SCREW, CAP, SEMS, W/LOCKPATCH	NOT NECESSARY	1.50	-
2	BOLT, RETAINER @\$7.90	NECESSARY	15.80	15.80
2	NUT FLANGE	NOT NECESSARY	5.20	-
1	DUCT, LH-RADIATOR	MISSING	27.10	27.10
2	PIN, DOOR, VENT @\$15.00	NECESSARY	30.00	30.00
1	CAP, FRNG LWR, LH, HC MRCRY	SCRATCHED	601.50	601.50

Report Ref No. CS/AGI17021997/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RETAINER, U-BOLT @\$5.70	NOT NECESSARY	11.40	-
8	(20) LOCH NUT @\$2.60	NECESSARY	20.80	15.60
1	GASKET, LH/RH, RADIATOR SCREEN	NOT NECESSARY	23.00	-
1	GLOVE BOX ASY, RH, PC	SCRATCHED	141.00	141.00
8	SCREW, CAP, SEMS, W/LOCKPATCH @\$1.20	NOT NECESSARY	9.60	-
1	DUCT, RH-RADIATOR	MISSING	27.10	27.10
1	BUSHING, AIRBOX MOUNTING	NECESSARY	2.50	2.50
2	GASKET, LH / RH, RADIATOR SCREEN @\$23.00	NECESSARY	46.00	46.00
1	FRNG ASY, LWR, RH, HC MRCRY	SCRATCHED	1,132.30	1,132.30
1	CAP, FRNG LWR RH, HC MRCRY	SCRATCHED	601.50	601.50
1	LWR FASCIA ASY RH	SERVICEABLE	70.50	-
1	SCREEN, RADIATOR, RH-PC	MISSING	28.50	28.50
1	F/T, HC MRCRY W/SMOKY QURTC FLMS	BENT	4,371.80	4,371.80
1	BOOT, RH/ FRT TANK MNT	NOT NECESSARY	21.60	-
1	BOOT, LH/FRT TANK MNT	NOT NECESSARY	21.60	-
1	GASKET, TOP PLATE	NECESSARY	13.10	13.10
1	CHROME TRIM RING	NECESSARY	29.90	29.90
1	BURST HAND GRIPS, ETC	CUT	287.60	287.60
1	MSTR CYL ASY, FRT, DUAL / CHRM	SCRATCHED	804.30	804.30
2	GASKET, BRAKELINE @\$2.80	NECESSARY	5.60	5.60
1	DOT 4 BRAKE FLUID	MISSING	21.50	21.50
1	COVER ASY, RH/RR, CHROME	SCRATCHED	221.00	221.00
1	COVER, RH /FRT, CHROME	SCRATCHED	221.00	221.00
1	VERTICAL KEY CAP, START/HAZARD	SCRATCHED	33.40	33.40
1	FOOTBOARD ASY, RH, RIDER	MISSING	245.60	245.60
1	FOOTBRKE LEVER ASY	BROKEN	426.50	426.50
1	FRAME INSERT BRAKEPEDAL	MISSING	66.90	66.90
1	INSERT, BRAKEPEDAL, RUBBER	MISSING	28.00	28.00
1	OFFSET WASHER	NOT NECESSARY	5.50	-
1	SCREW	NECESSARY	2.50	2.50
2	SCREW @\$1.20	NOT NECESSARY	2.40	-
1	WASHER	NECESSARY	1.20	1.20
1	NUT, FLEX	NOT NECESSARY	2.60	-

Report Ref No. CS/AGI17021997/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FTBRD, SUPPORT BRKT, FRONT, CHRM @\$203.50	BENT	407.00	407.00
1	BRACKET, LH/RR, FRBRD SUPPT/CHRM	BENT	203.20	203.20
1	FRBRD, SUPPORT BRKT, RH/RR, CHRMM	BENT	164.50	164.50
2	SCREW, HEX SCKT, SEMS, 3/8-16X1-1 @\$6.70	NECESSARY	13.40	13.40
2	HEX SOCKER HD CAP SCREW @\$2.80	NECESSARY	5.60	5.60
2	LOCKWASHER	NECESSARY	1.60	1.60
2	FLANGE LOCKING NUT @\$2.60	NECESSARY	5.60	5.20
1	BOTTOM, RH-FOOTBOARD	MISSING	90.70	90.70
1	BOTTOM, LH-FOOTBOARD	SCRATCHED	90.70	90.70
2	WEAR PEG @\$12.10	NECESSARY	24.20	24.20
4	(20) LOCH NUT @\$2.60	NOT NECESSARY	10.40	-
4	BOLT, SHOULDER, GRADE 8 @\$3.00	NECESSARY	12.00	12.00
1	HEATSHIELD, RH, FRT, LWR	SERVICEABLE	423.80	-
1	HEATSHIELD, RH, RR, UPR	SERVICEABLE	305.00	-
1	HEATSHIELD, RH, RR, LWR	SERVICEABLE	305.00	-
5	(10) CLAMP SHIELD @\$5.80	NECESSARY	29.00	5.80
1	CLAMP	NOT NECESSARY	4.30	-
4	CLAMP, WORM DRIVE, 3.5-4.5 INCH @\$7.20	NOT NECESSARY	28.80	-
1	HEATSHIELD, EXHAUST, RH, CHROME	BENT	238.00	238.00
1	HEATSHIELD, EXHAUST, LH, CHROME	BENT	238.00	238.00
1	S/B COV ASY RH, HC MRCRY	SCRATCHED	1,265.50	1,265.50
1	LATCH ASY, RH S'BAG	BENT	625.20	625.20
1	GRILLE ASY, BOOM, RH-S'BAG	SCRATCHED	130.90	130.90
1	HANDLE, RH-S'BAG, SPEAKER	SCRATCHED	58.50	58.50
4	CUSHION, S'BAG SUPPORT @\$7.60	NECESSARY	30.40	30.40
2	SPEAKER ASY, SADDLEBAG, TIER 2 @\$467.00	CRACKED	934.00	934.00
2	GASKET, S/BAG COVER @\$17.00	NECESSARY	34.00	34.00
4	STRIKE, S'BAG @\$19.50	SERVICEABLE	78.00	-
2	GASKET, SPEAKER, S'BAG @\$13.60	NOT NECESSARY	27.20	-
1	KIT, S/B BOT, RH, HC MRCRY	SCRATCHED	2,579.50	2,579.50
4	KIT, STUD, SADDLEBAG, CLIPS @\$68.90	SCRATCHED	275.60	275.60
1	FACEPLATE, RH S/B, HC MRCRY	SCRATCHED	454.50	454.50
1	REFLECTOR, SIDE, RH, AMBER	SCRATCHED	17.90	17.90

Report Ref No. CS/AGI17021997/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KING TWO-UP LUGGAGE RACK, BLACK	SCRATCHED	494.50	494.50
1	BACKREST PAD ,15 FLHXSE	TORN	266.20	266.20
1	SISSY BAR UPRIGHT, SHORT, GLOSS BLACK	BENT	401.60	375.00
1	S/B COV ASY LH, HC MRCRY	BROKEN	1,265.50	1,265.50
1	KIT, S/B BOT, LH, HC, MRCRY	SCRATCHED	2,579.50	2,579.50
1	HANDLE, LH-S'BAG, SPEAKER	CUT	59.00	59.00
1	LATCH ASSY, LH S'BAG	CUT	625.50	625.50
1	HINGE ASSY, LH -S'BAG	NOT NECESSARY	52.50	-
1	GRILLE ASY BOOM, LH-S'BAG	BURNT	130.90	130.90
8	SCREW, HI-LOW @\$2.40	NOT NECESSARY	19.20	-
8	SCREW,HI-LO, TORX @\$2.80	NOT NECESSARY	22.40	-
1	FACEPLATE, LH S/B, HC, MRCRY	SCRATCHED	454.50	454.50
1	REFLECTOR, SIDE, LH AMBER	SCRATCHED	18.70	18.70
1	CLUTCH LEVER ASY, CHRM	BENT	185.00	185.00
1	PIVOT PIN	NOT NECESSARY	12.50	-
1	EXT. RETAINING RING	NECESSARY	2.60	2.60
1	S/C LH, HC MRCRY W/SMOKY QURTZ FLMS	SERVICEABLE	1,668.70	-
1	S/C RH, HC MRCRY W/SMOKY QURTZ FLMS	SERVICEABLE	1,668.70	-
1	BAT WING APE HANGER HANDLEBAR BLACK	BENT	454.00	454.00
1	KIT-MIRROR, ILLUMINATED, BLACK	MISSING	687.50	687.50
1	ADJ HWY PEG MNT, LONG, BLACK	BENT	249.50	249.50
1	KIT-FOOTPEG, BURST, RECTANGULAR	CRACKED	328.80	328.80
1	COVER ASY, FORK TUBE, LH , PEM	BENT	105.90	105.90
1	COVER ASY, FORK TUBE, RH, PEM	BENT	105.90	105.90
1	FORK ASY, LH/CHRM	SERVICEABLE	1,253.50	-
1	FORK ASY, RH/CHRM	SERVICEABLE	1,253.50	-
1	BEARING KIT, STEERING HEAD	SERVICEABLE	87.50	-
1	KIT-FOG LAMP, BULLET, BLACK	MISSING	823.80	823.80
1	KIT-WIRE HARNESS FOG LAMP, FLT	BENT	50.90	50.90
1	KIT-MNTG, FOG IT, TOURING W/LWRS, BLK	MISSING	103.00	103.00
1	SWICTH ASY, DASHPANEL MTND, FOG	SCRATCHED	118.00	118.00
1	SPEAKER ASY, RH TWEETER MID-RANGE	MISSING	363.50	363.50
1	KIT-TRIM, MID FRM AIR DEFLCTR, TOURING	DISTORTED	151.30	151.30

Report Ref No. CS/AGI17021997/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MID FRAME AIR DEFLECTOR	SERVICEABLE	189.10	-
1	CLAMP HOSE (ADDITIONAL)	NECESSARY	7.80	7.80
1	SPEAKER ENCLOSURE SUB-ASSY, LH (ADDITIONAL)	CRACKED	255.20	255.20
1	SPEAKER ENCLOSURE SUB-ASSY, RH (ADDITIONAL)	CRACKED	255.20	255.20
6	SEMS, HEX SOCKER CAP (ADDITIONAL) @\$6.80	NOT NECESSARY	40.80	-
6	SCREW, 1/4-20, HEX BTN, SEMS, 50LG (ADDITIONAL) @\$1.00	NOT NECESSARY	6.00	-
1	CLIP, ANTENNA	NECESSARY	13.30	12.70
1	FOOTBOARD ASY, LH, RIDER (ADDITIONAL)	CUT	245.60	245.60
1	BRAKELEVER ASY, CHRM (ADDITIONAL)	SCRATCHED	210.70	210.70
3	H-D EXTENDED LIFE COOLANT, ANTIFREEZE, PINT (ADDITIONAL) @\$29.50	NECESSARY	88.50	88.50
1	SCREW, TORX SCKT, BTN HD X 2.63 (ADDITIONAL)	NECESSARY	3.20	3.20
1	KIT-ANTENNA, HIDDEN (ADDITIONAL)	NECESSARY	146.40	146.40
	LESS 10% DISCOUNT		-	-3,928.06
			47,166.60	35,352.54
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (STICKER) (SN)	NECESSARY	8.56	8.56
1	IU ASSEMBLY (SN)	BROKEN	190.00	190.00
1	I.U. BRACKET (SN)	BENT	90.00	90.00
1	TPMS (SN)	SCRATCHED	250.00	180.00
1	3RD PARTY EXHAUST HEATSHIELD (SN) (ADDITIONAL)	CUT	560.00	560.00
			1,098.56	1,028.56
	<u>LABOUR</u>			
	LABOUR.		3,295.60	2,800.00
			-	-
			-	-
			-	-
			-	-
			-	-
			3,295.60	2,800.00
GRAND TOTAL			51,560.76	39,181.10

Report Ref No. CS/AGI17021997/R1rbe2



RECOMMENDED COST OF REPAIRS			39,181.10
LESS EXCESS			-500.00
NETT LIABILITY			38,681.10

Report Ref No. CS/AGI17021997/R1rbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.