

VEHICLE NO.: SKE9105R
 MAKE: VOLKSWAGEN
 MODEL: GOLF
 YEAR OF MAKE: 2008
 CHASSIS NO.: WVVZZZ1KZ9U007340
 SUPPLIERS : HEXING

Not Authorized
hkh
20/11/17 *Excess \$500*
Sday. T. hup h. before party.

S/N	Items Description	QTY	Remarks
1	FRT BONNET	1	SVC \$460.00 ✓
2	FRT BONNET RUBBER	1	To. 1 \$25.00 ✓
3	FRT BONNET INSULATOR	1	D.S \$155.00 ✓
4	FRT BONNET INSULATOR CLIP	8	NRC \$28.00 ✓
5	FRT BONNET LOCK	1	Yw1 \$75.00 ✓
6	FRT BONNET LOCK CATCH	1	Yw1 \$75.00 ✓
7	FRT GRILLE	1	320 \$300.00 ✓
8	FRT GRILLE LOGO	1	NH \$55.00 ✓
9	FRT GRILLE CLIP	4	NH \$8.00 ✓
10	FRT BUMPER	1	D.S \$630.00 ✓
11	FRT BUMPER SIDE RETAINER	2	LH NLS Bent \$50.00 12C ✓
12	FRT BUMPER CLIP	10	NH \$25.00 ✓
13	FRT BUMPER PROTECTOR LH	1	D.S \$55.00 ✓
14	FRT BUMPER REINFORCEMENT	1	\$275.00 ?
15	FRT BUMPER INNER SPONGE	1	To. 1 \$55.00 ✓
16	FRT BUMPER BEAM (BELOW HEADLAMP) LH	1	one \$35.00 ✓
17	FOG LAMP LH	1	320 \$105.00 ✓
18	FOG LAMP GARNISH LH	1	Yw1 \$85.00 ✓
19	FRT NOZZLE LH	1	\$105.00 ?
20	FRT NOZZLE COVER LH	1	Yw1 \$30.00 ✓
21	FRT NOZZLE MOTOR LH	1	\$80.00 ?
22	HEADLAMP LH	1	320 \$680.00 ✓
23	HEADLAMP SUPPORT PANEL	1	D.S \$500.00 ✓
24	AIRCON CONDENSER	1	\$300.00 ?
25	RADIATOR	1	\$400.00 ?
26	RADIATOR TOP HOSE	1	\$70.00 ?
27	AIR DUCT -FRONT	1	Yw1 \$25.00 ✓
28	AIR DUCT -CENTER	1	Yw1 \$20.00 ✓
29	AIR DUCT -REAR	1	\$20.00 ?
30	ENGINE TOP COVER	1	SVC \$155.00 X
31	FRT FENDER	1	N \$270.00 X
32	TOTAL:		\$5,151.00
33			
34			
35	SPECIAL NETT:		
36	FRT NUMBER PLATE		11 \$35.00 X
37	COOLANT		NH \$25.00 ✓
38	TOTAL:		\$60.00
39			
40			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____