

11/17/2017

ASS: REC BY

REF: CS/CTI/7022012/R1tb02

Special Instruction

Supervisor: Rasul

ASSIGNMENT (Office)

Muimen

From (Person): Jayn Tay

of CTI

Date/Time 17/11/17 @ 3:03pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 2350K

Insured: GBA 5001K

at Workshop m/s Prime Auto

Tel: 68610908

of 6 Benoi Place, 629927

Policy No: DMCVSN3009291700

Claim No: SNM17D06645C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time 4:01pm @ 17/11/17

Person Contacted:

Alice

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 2350K - CC3/AXA110.01798/Kpb342 - D.O.A: 13/01/2011

GBA 5001K - X

Part by Part \$3627.75

(Red: 729.25; 16%)

Surveyor: P. R. R.

REF:

62932

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 2350K

at Workshop m/s PRIME

of _____

Insured: CTI/TP

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 2350K Yr Regn: 2017 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA AXIO 1.5 CC 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 79240 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NKE1657138165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 16/11/17 D.O.I. 17/11/17

Survey held at PRIME AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1) 33/11 Typist

☒

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, \$

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.E. (\$ 3627.75)

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022012/R1tb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 5001K	Veh. Inspected	SHD 2350K
Policy No.	DMCVSN3009291700	Coverage (\$)	0.00
Claim No.	SNM17D06645C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	17/11/2017
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017		17 Nov 2017 15:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HOO SOON ENGINEERING , Co. Reg. No.: 27724100J			[Created by insurer]
Main Claimant:	PRIME CAR RENTAL & TAXI SERVICES PTE LTD , Co. Reg. No.: 199606293Z			
Vehicle Reg. No.:	SHD2350K	Date of Loss:	16/11/2017 11:00 - :59	
Claim Type:	TP / SNM17D06645C02	Policy/Cover Note No.:	DMCVSN3009291700 (Comprehensive) Coverage: 02/02/2017 - 01/02/2018	
Vehicle Reg. No. (Insured):	GBA5001K	Policy No. (Claimant):	5068045737-03	
		Excess:	\$0.00	
Repairer:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place, 629927 Pioneer - Tel: 68610908			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/11/2017]			
Adj Asg. Remarks:	1) REQUESTED FOR TWAFFIEK 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MPRI17-52037 / Prime Auto Claims Service Pte Ltd - HQ
ENTRY DATE & TIME: 15/11/2017 15:36

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/11/2017 15:36
Date Of Accident 15/11/2017 11:40
Exact Location Of Accident ANG MO KIO AVENUE 10 BLK 449 CARPARK 37
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD2350K
Insured/Policyholder
Name Of Registered Owner PRIME CAR RENTAL & TAXI SERVICES PTE LTD
Co Reg No 199605293Z
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-68982000
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA-1.5 G AXIO HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number 5068045737-03
Cover Note Number
Driver
Name of Driver LIM HONG HUAT BERNARD
NRIC No S1490117E
Date Of Birth 12/07/1961
Occupation OUTDOOR
Date Of Driving Pass 09/04/1981
Driving Experience 36 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83504916
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 125 PENDING ROAD #06-32 SINGAPORE
 Postcode 670125
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA5001K
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver KARUPPAIYAH RAUICHANDRAN
 NRIC/Passport Number 039200688
 Contact Number
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Jan 16/11/17
1430 hrs.

PR


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16.11.2017 @1140 hrs, my taxi SHD2350K was stationary along Ang Mo Kio Avenue 10 Blk 449 carpark 37. I had on my reverse light and before I reversed into carpark lot, I checked for oncoming traffic. While stationary, one lorry GBA5001K came from my right rear attempted to overtake my taxi and as a result GBA5001K left side railing hooked against my front bumper and teared outward my taxi's front bumper.

After the accident, we alighted from our vehicles to check on the damages. We took photos and exchanged particulars. I felt neck pain so I will consult doctor if my pain persisted.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/11/17
1430 hrs.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606550M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 17.11.2017

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2350K TOYOTA AXIO HYBRID (2016)

To Supply

- 1) 1pc Front bumper
- 2) 1set Front bumper clip
- 3) 1pc Front bumper lower grille
- 4) 1pc Front bumper reinforcement
- 5) 1pc Front bumper sponge
- 6) 1pc Front bumper right side retainer
- 7) 1pc Front bumper left side retainer
- 8) 1set Front bumper lower grille
- 9) 1pc Front grille
- 10) 1set Front grille clip
- 11) 1set Front grille logo
- 12) 1pc Right head lamp
- 13) 1pc Left head lamp

\$	1,370.00	M17
\$	30.00	he
\$	322.00	gld
\$	340.00	R X
\$	90.00	CRA
\$	97.00	he
\$	97.00	he X sue
\$	322.00	X su
\$	330.00	CRA
\$	30.00	he
\$	98.00	he
\$	825.00	pho
\$	825.00	CRA

Sub total Parts	\$	4,776.00	4017.00
Less: 25% discount	\$	1,194.00	-1004.25
	\$	3,582.00	3012.75

To Supply S.Nett Parts

- 1) 1pc Front No. plate

	\$	35.00	SUR ✓
Sub total S.Nett Parts	\$	35.00	✓

L/charges

1) To focus front right & left head lamp

\$ 60.00 30

2) To remove & replace front bumper, front grille, right & left head lamp.
Align & adjust front bumper & front bonnet.

\$ 400.00 300

3) To putty, respray painting front bumper. To polish

\$ 280.00 250

Sub total L/charges	\$ 740.00	560.00
Estimated Grand Total	\$ 4,357.00	3627.75

Rasul
Hp 90010068

3 days

P/P

12/11/17 @ 1750

Resury b4 paint



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Bendol Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 17.11.2017

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2350K TOYOTA AXIO HYBRID (2016)

To Supply

- 1) 1pc Front bumper
- 2) 1set Front bumper clip
- 3) 1pc Front bumper lower grille
- 4) 1pc Front bumper reinforcement
- 5) 1pc Front bumper sponge
- 6) 1pc Front bumper right side retainer
- 7) 1pc Front bumper left side retainer
- 8) 1set Front bumper lower grille
- 9) 1pc Front grille
- 10) 1set Front grille clip
- 11) 1set Front grille logo
- 12) 1pc Right head lamp
- 13) 1pc Left head lamp

\$	1,370.00	M17
\$	30.00	ne
\$	322.00	sch
\$	340.00	R
\$	90.00	CRA
\$	97.00	ne
\$	97.00	ne X mr
\$	322.00	X repeated
\$	330.00	CRA
\$	30.00	ne
\$	98.00	ne
\$	825.00	Pro
\$	825.00	CRA

Sub total Parts	\$	4,776.00
Less: 25% discount	\$	1,194.00
	\$	3,582.00

To Supply S.Nett Parts

- 1) 1pc Front No. plate

\$	35.00	scr
----	-------	-----

Sub total S.Nett Parts	\$	35.00
------------------------	----	-------

+

L/charges

- | | | |
|--|-----------|-----|
| 1) To focus front right & left head lamp | \$ 60.00 | 30 |
| 2) To remove & replace front bumper, front grille, right & left head lamp.
Align & adjust front bumper & front bonnet. | \$ 400.00 | 300 |
| 3) To putty, respray painting front bumper. To polish | \$ 280.00 | 250 |

Sub total L/charges	\$ 740.00
Estimated Grand Total	\$ 4,357.00

Rasul
Hp 900 10068

3 days

p/p

12/11/17 @ 1750

Resury b4 paint

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022012/R1TBN2

Date: 29/11/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3009291700
Claimant Vehicle No :	SHD2350K	Insured Vehicle No :	GBA5001K
Date of Loss:	16/11/2017	Nature of Claim:	TP
		Claim No:	SNM17D06645C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD2350K	Engine No:	1NZR438011
Make & Model:	TOYOTA COROLLA, 1.5 G AXIO HYBRID (A)	Chassis No:	NKE1657138165
Reg. Date:	13/01/2017 (Man. Year: 2016)	Odometer:	79240 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,617.00	3,047.75	569.25	15.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	740.00	580.00	160.00	21.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,357.00	3,627.75	729.25	16.74
+ GST 7.00/7.00% (S\$)	304.99	253.94	51.05	16.74
Nett Amount (S\$)	4,661.99	3,881.69	780.30	16.74

INSPECTION

Date of Assignment:	17/11/2017	
Date Inspected:	17/11/2017 Inspected At:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place Singapore 629927
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2017)
Parts:	143	TOYOTA COROLLA 1.5 G AXIO HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD2350K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Missing	1,370.00 FL	*1,370.00 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Scratched	322.00 FL	*322.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	340.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	90.00 FL	*90.00 FL
6	1		*FRONT BUMPER RIGHT SIDE RETAINER	Necessary	97.00 FL	*97.00 FL
7	1		*FRONT BUMPER LEFT SIDE RETAINER	Serviceable	97.00 FL	*- FL
8	1		*SET FRONT BUMPER LOWER GRILLE	Not Necessary	322.00 FL	*- FL
9	1		*FRONT GRILLE	Cracked	330.00 FL	*330.00 FL
10	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FL	*30.00 FL
11	1		*SET FRONT GRILLE LOGO	Necessary	98.00 FL	*98.00 FL
12	1		*RIGHT HEAD LAMP	Broken	825.00 FL	*825.00 FL
13	1		*LEFT HEAD LAMP	Cracked	825.00 FL	*825.00 FL
14	1		*FRONT NO PLATE	Scratched	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,811.00	4,052.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,194.00	1,004.25
Total Parts (\$\$)	3,617.00	3,047.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS FRONT RIGHT & LEFT HEAD LAMP	New	60.00	30.00
2	TO REMOVE & REPLACE FRONT BUMPER ,FRONT GRILLE ,RIGHT & LEFT HEAD LAMP,ALIGN & ADJUST FRONT BUMPER & FRONT BONNET	New	400.00	300.00
3	TO PUTTY ,RESPRAY PAINTING FRONT BUMPER .TO POLISH	New	280.00	250.00
Gross Labour Cost (S\$)			740.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >