

REF:

CC3 / AT617022040 / Arbna

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100484485-01

Claims No. 883066077054

Sum Insured:

Excess:

\$600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

130K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 Hrs

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGS3757Y

Yr Regn:

2016 / 8pt

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan.

c.c. 1395

Colour:

Grey.

A/C: Insured / Std / NI / NA

Sp. Reading

27664.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU2ZZF42HA050199.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16.

R: 205/60 R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/11/17

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16.

SGS 3757Y - CB/ENC110211154 / Rqth3

QA: 25092011

Confirm \$5216.20, 6 days
Red: 117,157.80, 77%.

RECEIVED 16 MAR 2018

Date/Time, File Pass to?

1)

Suppl

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

S - RS - SI

Photos

Others:

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

OD

Lump Sum / I.B.I: (\$ 5216.20)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17022040/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 20-11-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGS 3757Y
Policy No. 2100484485	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/11/2017	Inspection Date	17/11/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, January 06, 2018 3:34 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SGS 3757Y - OD AIG - SURVEYED 17 NOV 17
Attachments: PA11302017 - SGS 3757 Y - A4 Sedan 1.4 TFSI S-tronic - LHS Rear (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5216.20 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	5409H
Vehicle Details	
Vehicle No.	SGS3757Y
Vehicle to be Exported	No
Intended De-registration Date	20 Nov 2017
Vehicle Make	AUDI
Vehicle Model	A4 1.4 TFSI S TRONIC (NAV)
Primary Colour	Grey
Manufacturing Year	2016
Engine No.	CVN020616
Chassis No.	WAUZZZF42HA050199
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$34,777.00
Original Registration Date	29 Sep 2016
First Registration Date	29 Sep 2016
Transfer Count	0
Actual ARF Paid	\$30,688.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Sep 2026
PARF Rebate Amount	\$23,016.00
Intended COE Rebate Details	
COE Expiry Date	28 Sep 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,002.00
COE Rebate Amount	\$50,478.00
Total Rebate Amount	\$73,494.00

The information contained herein is correct as at 20 Nov 2017

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7105409H



Name
LIM SEH LENG
(LIN SHILING)

林师玲

Race

CHINESE

Date of Birth

09-02-1971

Sex

F

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7105409H

Name

LIM SEH LENG (LIN
SHILING)

Birth Date: 09 Feb 1971

Issue Date: 22 Feb 2003



2429287

NRIC No. S7105409H



Blood Group

O+

Date of issue

29-09-1994

Signature

30 SPRINGDALE AVENUE
SINGAPORE 73906

NRIC No: S7105409H

Date: 10-12-1997

No: 2466620


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

01 Mar 1995



Licence No: S7105409H

NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Seif Leng (Lin Shiling)
Period of Insurance : 29 Sep 2017 To 28 Sep 2018
Engine No. : CVN020616
Chassis No. : WAUZZZF42HA050199

Vehicle No. : SGS3757Y
Policy No. : 2100484485-01
Endorsement No. :
Issued Date : 28 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0. Own Damage - \$600. Theft - \$0. Flood Cover - \$0.

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Seif Leng (Lin Shiling) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408698 63662323.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia).

0504125211

PREMIUM LEASING - NC
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

5SP/LIC

24-HOUR AIG AUTO HOTLINE: +65 6336 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s)
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies)
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident
- Submit Writ Summons/Correspondence from third party(ies) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1130/2017/JT
Date	:	14-Nov-17

Vehicle is NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Lim She Leng
Address	:	30 Springside Avenue
		Singapore 786996
Telephone	:	HP +65 9108 6017
Type of Claim	:	Own Damage Claims
Policy No.	:	2100484485-01
Vehicle No	:	SGS 3757 Y
Model Code	:	Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year	:	Sep-16
Engine No	:	CVN 020616
Chassis No	:	WAUZZZF42HA050199
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Nov-17
Place of Accident	:	30 Springside Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 3757 Y.

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function and renew if necessary.	S/N \$ 280.00 X
2	To renew LHS 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$ 600.00 X
3	To remove and transfer LHS rear door's multi-lock system and power window devices.	S/N \$ 280.00 ✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse & relay trays, electrical and audio equipment.	S/N \$ 1,400.00 X
5	To remove and reinstall rear seat, back rest, hat trays, ABCD pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbags, etc	S/N \$ 1,400.00 X
6	To dismantle LHS rear door, rear bumper and rear lid. Cut out and weld LHS rear fender. Renew LHS rear door, align to position. Reinstall all parts removed.	\$ 5,400.00 1000/
SUB-TOTAL LABOUR CHARGES		: \$ 9,360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 3757 Y.

S/N	Nature of Jobs	Estimated Charges
7	To respray LHS rear door, LHS rear fender, LHS sill panel, LHS door entrance, LHS drain panel, LHS roof channel, and end panelling. To carry out stone chip parts removed.	\$ 4,200.00 <i>2.5 pieces. 1375/</i>
8	To renew LHS rear rim and carry out wheel alignment.	S/N \$ 280.00 <i>/</i>
9	To carry out diagnostic checks.	S/N \$ 192.00 <i>/</i>
TOTAL LABOUR CHARGES		: <u>\$ 14,032.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 3757 Y.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR DOOR - LHS <i>Dented</i>	\$ 1,745.00	✓ 1396.00
2	REAR DOOR OUTER SEAL - LHS <i>neu</i>	\$ 167.00	✓ 133.20
3	BONDING AGENT <i>Not neu</i>	\$ 42.00	X
4	REAR DOOR SEALING STRIP - LHS <i>neu</i>	\$ 14.00	X
5	REAR DOOR CATCH - LHS <i>neu</i>	\$ 102.00	X
6	REAR DOOR HANDLE COVER - LHS <i>neu</i>	\$ 21.00	+
7	REAR SECTIONAL (FENDER) PIECE - LHS <i>neu</i>	\$ 2,267.00	+
8	REAR WHEEL HOUSE LINER - LHS <i>neu</i>	\$ 208.00	+
9	REAR QUARTER GLASS - LHS	\$ 513.00	+
10	REAR WINDSCREEN	\$ 969.00	+
11	PRIMER	2 \$ 36.00	+
12	SOUND ABSORBER	\$ 213.00	+
13	ALUMINIUM RIM <i>cut</i>	\$ 465.00	— 372.00
14	REAR WINDSCREEN SEALENT <i>neu</i>	S./N \$ 200.00	+
15	1/4 QUARTER GLASS SEALENT	S./N \$ 100.00	+
16	ACRYLIC SEALER <i>neu</i>	S./N \$ 180.00	+
17	CAVITY WAX <i>neu</i>	S./N \$ 140.00	+
18	STONE CHIP <i>neu</i>	S./N \$ 180.00	✓ 180.00
19	METAL FILLER POWDER <i>neu</i>	S./N \$ 280.00	+
20	SUNDRIES <i>neu</i>	\$ 500.00	? 8.00
TOTAL SPARE PARTS		: \$ 8,342.00	
TOTAL LABOUR CHARGES		: \$ 14,032.00	
GRAND TOTAL		: <u>\$ 22,374.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 17/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : ~~For~~ Authorised Reps, OS Reps

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1130/2017/JT
Date : 14-Nov-17

Vehicle is NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 6 days to repair. - jb - 6 Dec

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim She Leng
Address : 30 Springside Avenue
Singapore 786996
Telephone : HP +65 9108 6017
Type of Claim : Own Damage Claims
Policy No. : 2100484485-01
Vehicle No : **SGS 3757 Y**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Sep-16
Engine No : CVN 020616
Chassis No : WAUZZZF42HA050199
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Nov-17
Place of Accident : 30 Springside Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 3757 Y.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall rear parking aid. Check function and renew if necessary.	S/N \$	280.00
2	To renew LHS 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$	600.00
3	To remove and transfer LHS rear door's multi-lock system and power window devices.	S/N \$	280.00 \$ 280.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse & relay trays, electrical and audio equipment.	S/N \$	1,400.00
5	To remove and reinstall rear seat, back rest, hat trays, ABCD pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbags, etc	S/N \$	1,400.00
6	To dismantle LHS rear door, rear bumper and rear lid. Cut out and weld LHS rear fender. Renew LHS rear door, align to position. Reinstall all parts removed.	\$	5,400.00 \$ 1,000.00
SUB-TOTAL LABOUR CHARGES		: \$	9,360.00 \$ 1,280.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 3757 Y.

S/N	Nature of Jobs		Estimated Charges		
		C/F		\$	1,280.00
7	To respray LHS rear door, IHS rear fender, LHS sill panel, LHS door entrance, LHS drain panel, LHS roof channel, and end panelling. To carry out stone chip parts removed.		\$ 4,200.00	\$	1,375.00
8	To renew LHS rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
9	To carry out diagnostic checks.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 14,032.00	\$	3,127.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 3757 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR - LHS	\$ 1,745.00	\$ 1,396.00
2	REAR DOOR OUTER SEAL - LHS	\$ 167.00	\$ 133.20
3	BONDING AGENT	\$ 42.00	
4	REAR DOOR SEALING STRIP - LHS	\$ 14.00	
5	REAR DOOR CATCH - LHS	\$ 102.00	
6	REAR DOOR HANDLE COVER - LHS	\$ 21.00	
7	REAR SECTIONAL (FENDER) PIECE - LHS	\$ 2,267.00	
8	REAR WHEEL HOUSE LINER - LHS	\$ 208.00	
9	REAR QUARTER GLASS - LHS	\$ 513.00	
10	REAR WINDSCREEN	\$ 969.00	
11	PRIMER	2 \$ 36.00	
12	SOUND ABSORBER	\$ 213.00	
13	ALUMINIUM RIM	\$ 465.00	\$ 372.00
14	REAR WINDSCREEN SEALENT	S./N \$ 200.00	
15	1/4 QUARTER GLASS SEALENT	S./N \$ 100.00	
16	ACRYLIC SEALER	S./N \$ 180.00	
17	CAVITY WAX	S./N \$ 140.00	
18	STONE CHIP	S./N \$ 180.00	\$ 180.00
19	METAL FILLER POWDER	S./N \$ 280.00	
20	SUNDRIES	\$ 500.00	\$ 8.00
	TOTAL SPARE PARTS	\$ 8,342.00	\$ 2,089.20
	TOTAL LABOUR CHARGES	\$ 14,032.00	\$ 3,127.00
	GRAND TOTAL	\$ 22,374.00	\$ 5,216.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGS 3757 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1130/2017/MAS

13 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGS 3757 Y, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SGS 3757 Y**, claimant, **Ms. Lim Seh Leng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012240 – S\$4,939.33
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGS 3757 Y

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	18 Nov 2017		20 Nov 2017 11:53 Edit Adj Rpt	S\$5,216.20 Edit Estimates	S\$5,216.20 View Rpt	Status Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: LIM SEH LENG, ID: S7105409H, Tel: +6591086017, Email: LSEHLENG@YAHOO.COM

Vehicle Reg. No.: SGS3757Y

Claim Type: OD / 8830660770SG

Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/11/2017]

Driver/Custodian: LIM SEH LENG (46 / Female), NRIC: S7105409H, Tel: +6591086017

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (20/11/2017): SGS3757Y / OD / 11/11/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGS3757Y (8830660770SG)
OD
Nov 11 2017 11:45PM
[LIM SEH LENG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			Use Viewer					
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print					
1	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
2	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
3	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
4	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
5	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
6	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
7	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
8	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
9	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
10	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
11	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
12	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
13	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
14	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
15	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
16	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
17	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
18	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
19	20/11/17 17:03	General View																Load JPG			<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print					
1	20/11/17 17:03	Certificate of Insurance																Load PDF					
2	20/11/17 17:03	WORKSHOP ESTIMATE																Load PDF					
3	20/11/17 17:03	Singapore Accident Statement																Load PDF					
4	20/11/17 17:03	Insured Persons NRIC & DL																Load PDF					
5	19/03/18 10:47	WORKSHOP INVOICE																Load PDF					
6	19/03/18 10:47	DISCHARGE VOUCHER																Load PDF					

Linked Accident Report Documents

			View Use Viewer		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	13/11/17 13:07	Accident Statement		Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

7	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	13/11/17 13:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/11/17 12:57	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	13/11/17 12:57	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 150px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17022040/ARB2

Date: 19/03/2018

REFERENCE

Insured/Claimant: LIM SEH LENG Policy No: 2100484485-01
Date of Loss: 11/11/2017 Nature of Claim: OD Claim No: 8830660770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS3757Y
Make & Model: AUDI A4, 1.4 T (A)
Reg. Date: 29/09/2016 (Man. Year: 2016)
Colour: Grey
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (S\$): Market Value/New Car Price
Engine No: CVN020616
Chassis No: WAUZZZF42HA050199
Odometer: 27664 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Footbrake (Serviceable): Yes
Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Tyre Size: 205/60 R16
Rear Left Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,342.00	2,089.20	6,252.80	74.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,032.00	3,127.00	10,905.00	77.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,374.00	5,216.20	17,157.80	76.69
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,774.00	4,616.20	17,157.80	78.80
+ GST 7.00/7.00% (S\$)	1,524.18	323.13	1,201.05	78.80
Nett Amount (S\$)	23,298.18	4,939.33	18,358.85	78.80

INSPECTION

Date of Assignment: 20/11/2017

Date Inspected: 17/11/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LHS	Dented	1,745.00 FS	*1,396.00 FS
2	1		*REAR DOOR OUTER SEAL-LHS	Necessary	167.00 FS	*133.20 FS
3	1		*BONDING AGENT	Not Necessary	42.00 FS	*- FS
4	1		*REAR DOOR SEALING STRIP-LHS	Not Necessary	14.00 FS	*- FS
5	1		*REAR DOOR CATCH-LHS	Not Necessary	102.00 FS	*- FS
6	1		*REAR DOOR HANDLE COVER-LHS	Not Necessary	21.00 FS	*- FS
7	1		*REAR SECTIONAL (FENDER) PIECE-LHS	Repair	2,267.00 FS	*- FS
8	1		*REAR WHEEL HOUSE LINER-LHS	Not Necessary	208.00 FS	*- FS
9	1		*REAR QUARTER GLASS-LHS	Not Necessary	513.00 FS	*- FS
10	1		*REAR WINDSCREEN	Not Necessary	969.00 FS	*- FS
11	2		*PRIMER	Not Necessary	36.00 FS	*- FS
12	1		*SOUND ABSORBER	Not Necessary	213.00 FS	*- FS
13	1		*ALUMINIUM RIM	Cut	465.00 FS	*372.00 FS
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
15	1		*1/4 QUARTER GLASS SEALANT	Not Necessary	100.00 FS	*- FS
16	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
17	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
18	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
19	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
20	1		*SUNDRIES	Necessary	500.00 FS	*8.00 FS
Total Parts (\$\$)					8,342.00	2,089.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION AND RENEW IF NECESSARY	New	280.00	-
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACITLATE FENDER RENEWAL	New	600.00	-
3	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE & RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	-
5	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAYS,ABCD PILLAR TRIMS,LUGGUAGE COMPARTMENT TRIMS,SEAT BELTS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAGS,ETC	New	1,400.00	-
6	TO DISMANTLE LHS REAR DOOR,REAR BUMPER AND REAR LID.CUT OUT AND WELD LHS REAR FENDER.RENEW LHS REAR DOOR,ALIGN TO POSITION.REINSTALL ALL PARTS REMOVED	New	5,400.00	1,000.00
7	TO RESPRAY LHS REAR DOOR,LHS REAR FENDER,LHS SILL PANEL,LHS DOOR ENTRANCE,LHS DRAIN PANEL,LHS ROOF CHANNEL,AND END PANELLING.TO CARRY OUT STONE CHIP PARTS REMOVED	New	4,200.00	1,375.00
8	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			14,032.00	3,127.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >