

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1135/2017/JT
Date : 16-Nov-17

Vehicle NOT workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chan Soo Chee
Address : 163 Jalan Kampong Chantek
Singapore 587889
Telephone : HP +65 9672 7612
Type of Claim : Own Damage Claims
Policy No. : 1700025110
Vehicle No : **SFN 163 T**
Model Code : Audi Q7 3.0 TFSI qu
Model / Year : Jul-17
Engine No : CRE 184517
Chassis No : WAUZZZ4M7HD055156
Mileage :
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Nov-17
Place of Accident : Maris Stella Kindergarden (Holland Road)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFN 163 T.

S/N	Nature of Jobs		Estimated Charges
1	To remove and transfer rear parking aid & rear lid kick sensor assy. Check function.	S/N \$	360.00 ✓
2	To remove rear fittings, dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.	\$	1,200.00 600.
3	To respray rear bumper, mid bumper and both wheel arch trims.	\$	2,100.00 1300.
4	To carry out diagnostic checks.	S/N \$	192.00 ✓
TOTAL LABOUR CHARGES		:	<u>\$ 3,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFN 163 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Byir</i>	\$ 1,027.00	<i>x</i>
2	REAR BUMPER MID BUMPER <i>3 Deland</i>	\$ 1,588.00	<i>—</i>
3	REAR BUMPER LOWER SPOILER	\$ 1,111.00	<i>—</i>
4	REAR REINFORCEMENT BEAM <i>?</i>	\$ 1,144.00	<i>?</i>
5	REAR LID SENSOR HOLDING STRIP <i>noted ?</i>	\$ 148.00	<i>?</i>
6	REAR BUMPER GUIDE- CENTRE <i>3 new</i>	\$ 115.00	<i>+</i>
7	REAR BUMPER GUIDE - LHS/RHS	\$ 102.00	<i>x.</i>
8	REAR WHEEL ARCH TRIM - LHS/RHS <i>new</i>	\$ 646.00	<i>—</i>
9	REAR BUMPER TAIL LIGHT - LHS/RHS <i>new</i>	\$ 606.00	<i>+</i>
10	REAR PARKING AID <i>new</i>	2 \$ 415.00	<i>x</i>
11	SUNDRIES <i>?</i>	\$ 300.00	<i>?</i>
TOTAL SPARE PARTS		: \$ 7,202.00	
TOTAL LABOUR CHARGES		: \$ 3,852.00	
GRAND TOTAL		: \$ 11,054.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 17/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant