

12/03/2001

ASS: REP. BY

REF: CS/AXA17022049 / T11602

Serial Instruction:

Surveyor:

menmen

Tuanhich

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

AXA

Date/Time:

20/11/17 @ 10:13am

Estimated Cost:

Bill to:

(OD)

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT6500L

Insured:

at Workshop n/s

Auto France

Tel:

8383 3190

of

305 Alexandra Road #02-01, 159942

Policy No:

P2025622

Claim No:

C0459916

Sum Insured:

Excess:

\$400.00

Make of Veh:

(Client's Record)

D.O.A.

16/11/17

(CA)

REV / REP. / REV 24 HRS

21-11-2017 @ 11:30am

owner waiting

R.O.D. Endorsement

Date/Time:

11:26am @ 20/11/17

Person Contacted:

Guo Xiang

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

SLT6500L-X

20/11

Report via menmen

7/2-


Finalized \$8,034.60. 5 days confirm (Red: 8937.80:52%)

Tanpin

AXA

From: 21-11-2017  
 Estimated Cost:  
 CD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect vehicle No: SLT 6500L  
 at: Autofrance  
 305 Alexandra Rd  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess \$900.00  
 Clients Record:  
 Make of ven: Guo Xiang  
 11:30am  
 (Policy Condition): owner waiting  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bar or Marker Value: \$120K  
 IDAO Accident Report: Consistent? Yes or No  
 G/A / PR / Seen: Consistent? Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Sum Surp: 3 Val: Yes or No  
 CA / REV / REP / 24 HRS  
 Date: Person Contacted: Vehicle IN / OUT

SLT 6500L Reg: 2017 Nov  
 Type: M/Cycle Bus / Van / Lorry / Taxi / Prime Mover  
 Truck / Trailer:  
 Make: Peugeot 308 1999  
 Colour: Blau.  
 Sc Reading: 681  
 Eng No:  
 Ch No: VF3 LRHNY W4S142327  
 Gen Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brakes: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S / Rim / STD A / Rim or  
 Tyre Size: R 225/45R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI  
 TOYO / YOKO or  
 Front: Rear:  
 R.Bal: 6 7 mm R.Bal: 7 mm  
 L.Bal: 6 2 mm L.Bal: 2 mm  
 D.O.A.: D.O.A.: 2/1/17 @ 1140.  
 Surveyed at: Autofrance  
 Des. of Damages: Frt / Rear / OS / N/S / U/O / Rooftop or  
 Frt o/s  
 The U/O / Chassis frame / Body Structure affected due to police or



Insurance received DV/Final Bill as to submit report

RECEIVED 27 DEC 2018

One Time Fee Passed:  
 [ ] Preli. Report  
 [x] Final Report  
 Day: The Fee Returned:

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Surve Fee:  
 290

Add Fee:  
 [ ] Grease: \$  
 [ ] Wash: \$  
 [ ] Test: \$  
 [ ] Other: \$

Report Return: 00  
 Lump Sum: 8034.60

290  
 290



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17022049/T1tb

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 20-11-2017



Code : AXA2

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLT 6500L
Policy No.	P2025622	Coverage (\$)	0.00
Claim No.	C0459916	Excess (\$)	400.00
Assign From	MERIMEN (YVONNE ANG)	Assign Date	20/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	16/11/2017	Inspection Date	20/11/2017
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.		

## 5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	20 Nov 2017		20 Nov 2017 10:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

<b>Insured:</b> CHEN LILY, ID: S8771397J, Tel: +6598364729		<b>[Created by insurer]</b>	
<b>Vehicle Reg. No.:</b>	SLT6500L	<b>Date of Loss:</b>	16/11/2017 16:00 - :59
<b>Claim Type:</b>	OD / C0459916	<b>Policy/Cover Note No.:</b>	P2025622 (Comprehensive)
		<b>Excess:</b>	S\$900.00
<b>Repairer:</b>	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331		
<b>Handling Insurer:</b>	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Yvonne Ang Ching Ching - 6880 4461]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 29/11/2017]</b>		
<b>Driver/Custodian:</b>	CISSY CHEN YU (33 / Female), NRIC: S8371281C, Tel: +6581827644		
<b>Adj. Asg. Remarks:</b>	basic excess \$400 + un-named driver excess \$500 <span style="float: right;">CA</span>		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## **SG AXA Insurance SM AXA SGP - Motor Survey**

---

**From:** Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>  
**Sent:** Monday, November 20, 2017 9:12 AM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Mohamed Shabir Abdul Hamid; ONG Birdie  
**Subject:** Own Damage Claim - SLT6500L  
**Attachments:** 20171116191744175\_0014.jpg; GIA - SLT6500L.PDF; estimate - slt6500l.pdf  
  
**Categories:** Shailendra

Dear officer,

Please find the attached document for your reference.

Kindly advise on the approval & excess amount.

Regards,

Wong Guo Xiang

Customer Service Advisor

AutoFrance ( PEUGEOT ) / Regent Motors (FORD)

c/o Vantage Automotive Limited

DID: 6477 7409 HP: 8383 3190

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Yvonne Ang Ching Ching

Date: 22 Nov 2017

**Preliminary Advice**

Vehicle No	: SLT6500L	Accident Date	: 16/11/2017
Make	: PEUGEOT 308	Policy No.	: P2025622
Assignment Date	: 20/11/2017	Excess	: S\$400.00
Date of Inspection	: 21/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,849.95
Revised Amount	:S\$	8,921.40
Check Items (Estimated)	:S\$	4,880.00
Total	:S\$	13,801.90
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	51,515.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,485.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : We have authorise repair, survey on 21/11/2017 @1140am.,

**Denise Tay (LKKAUTO)**

---

**From:** Wong Guo Xiang <wong.guo.xiang@sime-darby.com.sg>  
**Sent:** Saturday, 16 December, 2017 12:08 PM  
**To:** Taufikh (LKKAUTO)  
**Cc:** Mohamed Shabir Abdul Hamid; Natarajan Kavidha Rajan; SUR  
**Subject:** Finalise -SLT6500L  
**Attachments:** supp - slt6500l.pdf

Dear Taufikh,

Please find the attached finalise documents for your reference.

COR: 8034.60  
5 working days

<https://www.dropbox.com/sh/m6jy9teyr01n4vt/AAAK5pUmSxbM40K0z7hS0t9ga?dl=0>

The photos is within the dropbox link

Regards,

Wong Guo Xiang

Customer Service Advisor

**AutoFrance ( PEUGEOT ) / Regent Motors (FORD)**

**c/o Vantage Automotive Limited**

**DID: 6477 7409 HP: 8383 3190**

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Yvonne Ang Ching Ching

Date: 22 Nov 2017

## **Preliminary Advice**

Vehicle No	: SLT6500L	Accident Date	: 16/11/2017
Make	: PEUGEOT 308	Policy No.	: P2025622
Assignment Date	: 20/11/2017	Excess	: S\$400.00
Date of Inspection	: 21/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,849.95
Revised Amount	:S\$	8,921.40
Check Items (Estimated)	:S\$	4,880.00
Total	:S\$	13,801.90

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	51,515.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,485.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : We have authorise repair, survey on 21/11/2017 @1140am.,

# Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1397J

## Vehicle Details

Vehicle No.	SLT6500L
Vehicle to be Exported	No
Intended De-registration Date	22 Nov 2017
Vehicle Make	PEUGEOT
Vehicle Model	308 SW ALLURE PURETECH 1.2 A/T 2WD S/R
Primary Colour	Black
Manufacturing Year	2017
Engine No.	10XTA40699447
Chassis No.	VF3LRHNYWHS142327
Maximum Power Output	96.0 kW (128 bhp)
Open Market Value	\$22,464.00
Original Registration Date	06 Nov 2017
First Registration Date	06 Nov 2017
Transfer Count	0
Actual ARF Paid	\$13,450.00

## Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	05 Nov 2027
PARF Rebate Amount	\$10,087.00

## Intended COE Rebate Details

COE Expiry Date	05 Nov 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$41,617.00
COE Rebate Amount	\$41,428.00
<b>Total Rebate Amount</b>	<b>\$51,515.00</b>

The information contained herein is correct as at 22 Nov 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/11/2017 19:45
Date Of Accident	16/11/2017 16:05
Exact Location Of Accident	ALONG JALAN ASAS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6500L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEN LILY
NRIC No	S8771397J
Email Address	LILY9CHEN2@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98364729
Alternative Phone No	OTHERS-81827644
<b>Vehicle Particulars</b>	
Manufacturer	PEUGEOT
Model	308-1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN857349
Cover Note Number	
<b>Driver</b>	
Name of Driver	CISSY CHEN YU
NRIC No	S8371281C
Date Of Birth	11/12/1983
Occupation	INDOOR
Date Of Driving Pass	20/01/2012
Driving Experience	5 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81827644
Fax Number	
Contact Number	
Email Address	NOEMAIL

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: **WONG GUO XIANG**  
NRIC/TIN No.: **G2638773L**

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. :	BP 3443	Page No. :	1 of 2
Date Estimated :	20/11/2017		
Prepared By :	Wong Guo Xiang		

<b>- ESTIMATE REPAIR FOR -</b> Chen Lily Blk 980B Buangkok Crescent #07-77  Singapore 532980	<b>- ACCOUNT -</b> 2000 CASH - Sale service
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6500L	VF3LRHNYWHS142327	06/11/2017	308SW1.2 Allure	0

DESCRIPTION	VALUE
SUNDRIES	30- 150.00
REPLACE/REPAIR FRT BUMPER, FRT BONNET, FRT PANEL, FRT BUMPER BEAM 600	w/o support 1200 ✓ w/ support 2400 ✓ 3,000.00
RESPRAY FRT BUMPER, FRT BONNET, FRT PANEL, FRT LHS FENDER, FRT RHS FENDER 600	2400 ✓ 3,600.00
WIRING CONNECTION & CHECK (NETT)	✓ ✓ 150.00
REMOVE & REPLACE FRT PARKING SENSOR (NETT)	✓ ✓ 150.00
REMOVE & REFIX A/C CONDENSER & RADIATOR (NETT)	nn x? 600.00
TO REMOVE & REPLACE FRT HEADLIGHT SYSTEM INCLUDING REALIGN FRT HEADLIGHT BEAM LEVEL (NETT)	✓ ✓ 200.00
TO CONDUCT CAR 'O' LINER CHASSIS ALIGNMENT & MEASUREMENT (NETT)	nn x? 1,680.00
TO SUPPLY 1 UNIT FRT NUMBER PLATE (NETT)	✓ dd ✓ 70.00
TUFF KOTE @ \$60 PER PANEL	60. 240.00
SEALANT FOR FRT BONNET @ \$90 PER PANEL	✓ ✓ 90.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE (NETT)	nn x? 600.00

Total Labour 1: 10,530.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610742580	FRT BUMPER dis ✓	1	700.00	10.00	✓ 630.00
1610745580	FRT BUMPER F-LAMP MOULDING ne ✓	1	150.00	10.00	✓ 135.00
1610745680	GRILLE MOULDING x	1	100.00	10.00	nn ✓ 90.00
1610745880	RADIATOR GRILLE FRAME MDLG cra ✓	1	240.00	10.00	✓ 216.00
1610746780	FRT BUMPER ABSORBER de ✓	1	45.00	10.00	✓ 40.50
1610746880	DETECTOR SENSOR SUPPORT SET ne ✓	1	91.00	10.00	✓ 81.90
9800498680	FRT GUARD GRILLE ?	1	141.00	10.00	nn ✓ 126.90
1623159580	BRACKET SET ne ✓	1	60.00	10.00	✓ 54.00
1610745980	FRT BUMPER LWR MOULDING ?	1	168.00	10.00	nn ✓ 151.20

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road  
159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : BP 3443  
Date Estimated : 20/11/2017  
Prepared By : Wong Guo Xiang

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6500L	VF3LRHNYWHS142327	06/11/2017	308SW1.2 Allure	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610758980	FRT BUMPER C-FINISHER <i>at</i>	1	146.00	10.00	✓ 131.40
1610761380	FINISHER BUMPER <i>R</i>	1	65.00	10.00	<i>nn</i> ✓ 58.50
9805083080	FRT BUMPER PLUG <i>x</i>	1	60.00	10.00	<i>nn</i> ✓ 54.00
1610761480	SET PROXIMITY SENSOR SUPPORTS FRT <i>new</i>	1	68.00	10.00	✓ 61.20
9803184180	FRT BUMPER BRACKET RH <i>?</i>	1	48.00	10.00	<i>nn</i> ✓ 43.20
98039139XT	FRT BUMPER TOP RANGE <i>?</i>	1	45.00	10.00	<i>nn</i> ✓ 40.50
96773637XT	FRT BUMPER RANGE <i>new</i>	1	68.00	10.00	✓ 61.20
9677363980	FRT BUMPER BRACKET RH <i>?</i>	1	40.00	10.00	<i>nn</i> ✓ 36.00
1612686380	MKT LWR FRT BPR PANEL FIXINGS <i>new</i>	1	61.00	10.00	✓ 54.90
9816603980	FRT FACE TOP CROSSMEMBER <i>?</i>	1	150.00	10.00	✓ 135.00
9678525880	AIR BULKHEAD RH <i>?</i>	1	43.00	10.00	✓ 38.70
9678526080	AIR BULKHEAD <i>?</i>	1	43.00	0.00	<i>nn</i> } ✓ 43.00
1612686080	MKT FRONT MINI BUMPER FIXINGS <i>?</i>	1	132.00	10.00	✓ 118.80
9802164380	FRT FENDER LH <i>RY</i>	1	321.00	10.00	✓ 288.90
9802164280	FRT FENDER RH <i>RY</i>	1	321.00	10.00	✓ 288.90
9802163180	ENGINE BONNET - ALUM <i>bt</i>	1	750.00	10.00	✓ 675.00
98024633VD	FRT BADGE <i>new</i>	1	37.00	10.00	✓ 33.30
00006208Q3	FOG HEADLIGHT <i>?</i>	1	78.00	10.00	<i>nn</i> ✓ 70.20
1618000680	HEADLAMP ASSY LH <i>new</i>	1	1,330.00	10.00	<i>nn</i> ✓ 1,197.00
1618000780	BARE HEADLAMP RH, ADD DRIVER KIT <i>new</i>	1	1,330.00	10.00	<i>nn</i> ✓ 1,197.00

Total Parts : 6,152.20

Taujiah 97495749.  
21/11/17 @ 1140  
Ex \$900  
Approved  
5-7 days  
Resurvey before paint.  
sur@lukanto.com

### LKK Auto Consultants hence notify

#### the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Service Officer

Contact

Labour 1	:	10,530.00
Parts	:	6,152.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,167.75
Grand Total	:	17,849.95

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

19012.4

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : BP 3443

Page No. : 2 of 2

Date Estimated : 20/11/2017

Prepared By : Wong Guo Xiang

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6500L	VF3LRHNYWHS142327	06/11/2017	308SW1.2 Allure	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610758980	FRT BUMPER C-FINISHER <i>at</i>	1	146.00	10.00	131.40
1610761380	FINISHER BUMPER <i>X</i>	1	65.00	10.00	58.50
9805083080	FRT BUMPER PLUG <i>X</i>	1	60.00	10.00	54.00
1610761480	SET PROXIMITY SENSOR SUPPORTS FRT <i>new</i>	1	68.00	10.00	61.20
9803184180	FRT BUMPER BRACKET RH <i>?</i>	1	48.00	10.00	43.20
98039139XT	FRT BUMPER TOP RANGE <i>?</i>	1	45.00	10.00	40.50
96773637XT	FRT BUMPER RANGE <i>new</i>	1	68.00	10.00	61.20
9677363980	FRT BUMPER BRACKET RH <i>?</i>	1	40.00	10.00	36.00
1612686380	MKT LWR FRT BPR PANEL FIXINGS <i>new</i>	1	61.00	10.00	54.90
9816603980	FRT FACE TOP CROSSMEMBER <i>?</i>	1	150.00	10.00	135.00
9678525880	AIR BULKHEAD RH <i>?</i>	1	43.00	10.00	38.70
9678526080	AIR BULKHEAD <i>?</i>	1	43.00	0.00	43.00
1612686080	MKT FRONT MINI BUMPER FIXINGS <i>?</i>	1	132.00	10.00	118.80
9802164380	FRT FENDER LH <i>Ry</i>	1	321.00	10.00	288.90
9802164280	FRT FENDER RH <i>Ry</i>	1	321.00	10.00	288.90
9802163180	ENGINE BONNET - ALUM <i>bt</i>	1	750.00	10.00	675.00
98024633VD	FRT BADGE <i>new</i>	1	37.00	10.00	33.30
00006208Q3	FOG HEADLIGHT <i>?</i>	1	78.00	10.00	70.20
1618000680	HEADLAMP ASSY LH <i>new</i>	1	1,330.00	10.00	1,197.00
1618000780	BARE HEADLAMP RH, ADD DRIVER KIT <i>new</i>	1	1,330.00	10.00	1,197.00

Total Parts : 6,152.20

Taufik 97495749.  
2/11/17 @ 1140.

Ex \$900

Approved

5-7 days

Resumy before paint.

sur@lucanto.com

Taufik @lucanto.com

Customer Service Officer

Contact

Labour 1	:	10,530.00
Parts	:	6,152.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,167.75
Grand Total	:	17,849.95

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

**AUTOFRANCE**

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942

Service Booking: 6477 7377  
Parts: 6477 7420  
Vantage 24-Hour Asselt: 6473 8588  
Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

INVOICE NO. 114029  
DATE 11/01/2011  
CUSTOMER NAME  
ADDRESS  
CITY  
STATE  
POSTAL CODE  
PHONE NO.  
FAX NO.  
E-MAIL  
VEHICLE MAKE  
VEHICLE MODEL  
VEHICLE YEAR  
VEHICLE REG NO.  
VEHICLE CHASSIS NO.  
VEHICLE VIN NO.  
VEHICLE ENGINE NO.  
VEHICLE TRANSMISSION NO.  
VEHICLE COLOR  
VEHICLE TYPE  
VEHICLE CATEGORY  
VEHICLE SUB CATEGORY  
VEHICLE SUB CATEGORY 2  
VEHICLE SUB CATEGORY 3  
VEHICLE SUB CATEGORY 4  
VEHICLE SUB CATEGORY 5  
VEHICLE SUB CATEGORY 6  
VEHICLE SUB CATEGORY 7  
VEHICLE SUB CATEGORY 8  
VEHICLE SUB CATEGORY 9  
VEHICLE SUB CATEGORY 10  
VEHICLE SUB CATEGORY 11  
VEHICLE SUB CATEGORY 12  
VEHICLE SUB CATEGORY 13  
VEHICLE SUB CATEGORY 14  
VEHICLE SUB CATEGORY 15  
VEHICLE SUB CATEGORY 16  
VEHICLE SUB CATEGORY 17  
VEHICLE SUB CATEGORY 18  
VEHICLE SUB CATEGORY 19  
VEHICLE SUB CATEGORY 20  
VEHICLE SUB CATEGORY 21  
VEHICLE SUB CATEGORY 22  
VEHICLE SUB CATEGORY 23  
VEHICLE SUB CATEGORY 24  
VEHICLE SUB CATEGORY 25  
VEHICLE SUB CATEGORY 26  
VEHICLE SUB CATEGORY 27  
VEHICLE SUB CATEGORY 28  
VEHICLE SUB CATEGORY 29  
VEHICLE SUB CATEGORY 30  
VEHICLE SUB CATEGORY 31  
VEHICLE SUB CATEGORY 32  
VEHICLE SUB CATEGORY 33  
VEHICLE SUB CATEGORY 34  
VEHICLE SUB CATEGORY 35  
VEHICLE SUB CATEGORY 36  
VEHICLE SUB CATEGORY 37  
VEHICLE SUB CATEGORY 38  
VEHICLE SUB CATEGORY 39  
VEHICLE SUB CATEGORY 40  
VEHICLE SUB CATEGORY 41  
VEHICLE SUB CATEGORY 42  
VEHICLE SUB CATEGORY 43  
VEHICLE SUB CATEGORY 44  
VEHICLE SUB CATEGORY 45  
VEHICLE SUB CATEGORY 46  
VEHICLE SUB CATEGORY 47  
VEHICLE SUB CATEGORY 48  
VEHICLE SUB CATEGORY 49  
VEHICLE SUB CATEGORY 50  
VEHICLE SUB CATEGORY 51  
VEHICLE SUB CATEGORY 52  
VEHICLE SUB CATEGORY 53  
VEHICLE SUB CATEGORY 54  
VEHICLE SUB CATEGORY 55  
VEHICLE SUB CATEGORY 56  
VEHICLE SUB CATEGORY 57  
VEHICLE SUB CATEGORY 58  
VEHICLE SUB CATEGORY 59  
VEHICLE SUB CATEGORY 60  
VEHICLE SUB CATEGORY 61  
VEHICLE SUB CATEGORY 62  
VEHICLE SUB CATEGORY 63  
VEHICLE SUB CATEGORY 64  
VEHICLE SUB CATEGORY 65  
VEHICLE SUB CATEGORY 66  
VEHICLE SUB CATEGORY 67  
VEHICLE SUB CATEGORY 68  
VEHICLE SUB CATEGORY 69  
VEHICLE SUB CATEGORY 70  
VEHICLE SUB CATEGORY 71  
VEHICLE SUB CATEGORY 72  
VEHICLE SUB CATEGORY 73  
VEHICLE SUB CATEGORY 74  
VEHICLE SUB CATEGORY 75  
VEHICLE SUB CATEGORY 76  
VEHICLE SUB CATEGORY 77  
VEHICLE SUB CATEGORY 78  
VEHICLE SUB CATEGORY 79  
VEHICLE SUB CATEGORY 80  
VEHICLE SUB CATEGORY 81  
VEHICLE SUB CATEGORY 82  
VEHICLE SUB CATEGORY 83  
VEHICLE SUB CATEGORY 84  
VEHICLE SUB CATEGORY 85  
VEHICLE SUB CATEGORY 86  
VEHICLE SUB CATEGORY 87  
VEHICLE SUB CATEGORY 88  
VEHICLE SUB CATEGORY 89  
VEHICLE SUB CATEGORY 90  
VEHICLE SUB CATEGORY 91  
VEHICLE SUB CATEGORY 92  
VEHICLE SUB CATEGORY 93  
VEHICLE SUB CATEGORY 94  
VEHICLE SUB CATEGORY 95  
VEHICLE SUB CATEGORY 96  
VEHICLE SUB CATEGORY 97  
VEHICLE SUB CATEGORY 98  
VEHICLE SUB CATEGORY 99  
VEHICLE SUB CATEGORY 100

CODE	DESCRIPTION	UNITS	DISC %	NETT
	SUNDRIES	1	0.00	30.00
	REPLACE/REPAIR FRT BUMPER,FRT BONNET,FRT PANEL,FRT BUMPER BEAM	1	0.00	1,200.00
	RESPRAY FRT BUMPER,FRT BONNET, FRT PANEL,FRT LHS FENDER,FRT RHS FENDER	1	0.00	2,400.00
	WIRING CONNECTION & CHECK (NETT)	1	0.00	150.00
	REMOVE & REPLACE FRT PARKING SENSOR (NETT)	1	0.00	150.00
	TO REMOVE & REPLACE FRT HEADLIGHT SYSTEM INCLUDING	1	0.00	200.00
	REALIGN FRT HEADLIGHT BEAM LEVEL (NETT)	1	0.00	70.00
	TO SUPPLY 1 UNIT FRT NUMBER PLATE (NETT)	1	0.00	60.00
	TUFF KOTE @ \$60 PER PANEL	1	0.00	90.00
	SEALANT FOR FRT BONNET @ \$90 PER PANEL	1	0.00	90.00
Sub-Total :				4,350.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
98024633VD	FRT BADGE	1	10.00	33.30
1610745880	RADIATOR GRILLE FRAME MDLG	1	10.00	216.00
1610742580	FRT BUMPER	1	10.00	630.00
1610745580	FRT BUMPER F-LAMP MOULDING	1	10.00	135.00
1610746780	FRT BUMPER ABSORBER	1	10.00	40.50
1610746880	DETECTOR SENSOR SUPPORT SET	1	10.00	81.90
1610758980	FRT BUMPER C-FINISHER	1	10.00	131.40
1610761480	SET PROXIMITY SENSOR SUPPORTS FRT	1	10.00	61.20
1612686380	MKT LWR FRT BPR PANEL FIXINGS	1	10.00	54.90
1618000780	BARE HEADLAMP RH,ADD DRIVER KIT	1	10.00	1,170.00
1623159580	BRACKET SET	1	10.00	54.00
96773637XT	FRT BUMPER RANGE	1	10.00	61.20
9802163180	ENGINE BONNET - ALUM	1	10.00	675.00
1608472280	OBSTACLE DETECTION SENSOR FRT/RR	1	10.00	162.00
1608321780	OBSTACLE DETECTION SENSOR FRT/RR	2	10.00	178.20
Sub-Total :				3,684.60

Attending CSO : Wong

Should you require further explanation, please reach me at 64777409


**AUTOFRANCE**

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942Service Booking: 6477 7377  
Parts: 6477 7420  
Vantage 24-Hour Assist: 6473 8588  
Fax: 6477 7300**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT



Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	8,034.60
Labour Charges	4,350.00	Less Insurance Excess	S\$	400.00
Parts Charges	3,684.60	GST @ 7%	S\$	534.42
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	8,169.02
		Less Deposit/Voucher	S\$	0.00

Computer generated invoice. No signature is required.

Authorized Signature

S\$

11/01/2017

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

100

2000

2. 11. 1941



**Date:** . 11.12.2017

<b>Raised By Technician</b>	<b>Approved By CSA</b>	<b>Acknowledge By Parts Assistant</b>	<b>Resurvey by</b>	<b>BO Parts: Yes / No</b>  <b>ETA: _____</b>
---------------------------------	----------------------------	---	--------------------	--

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

306 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : BP 3443

Page No. : 1 of 2

Date Estimated : 20/11/2017

Prepared By : Wong Guo Xiang

- ESTIMATE REPAIR FOR -

Chen Lily

Blk 980B Buangkok Crescent

#07-77

Singapore 532980

- ACCOUNT -

2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6500L	VF3LRHNYWHS142327	06/11/2017	308SW1.2 Allure	0

### DESCRIPTION

### VALUE

SUNDRIES

30- 150.00

REPLACE/REPAIR FRT BUMPER, FRT BONNET, FRT PANEL, FRT BUMPER BEAM 600

w/o support 1200  
w support 2400

3,000.00

RESPRAY FRT BUMPER, FRT BONNET, FRT PANEL, FRT LHS FENDER, FRT RHS FENDER 600

2400 3,600.00

WIRING CONNECTION & CHECK (NETT)

✓ 150.00

REMOVE & REPLACE FRT PARKING SENSOR (NETT)

✓ 150.00

REMOVE & REFIX A/C CONDENSER & RADIATOR (NETT)

? 600.00

TO REMOVE & REPLACE FRT HEADLIGHT SYSTEM INCLUDING REALIGN FRT HEADLIGHT BEAM LEVEL (NETT)

✓ 200.00

TO CONDUCT CAR CHASSIS ALIGNMENT & MEASUREMENT (NETT)

? 1,680.00

TO SUPPLY 1 UNIT FRT NUMBER PLATE (NETT)

dd ✓ 70.00

TUFF KOTE @ \$60 PER PANEL

60. 240.00

SEALANT FOR FRT BONNET @ \$90 PER PANEL

✓ 90.00

TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE (NETT)

? 600.00

Total Labour 1: 10,530.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610742580	FRT BUMPER <i>dis</i>	1	700.00	10.00	630.00
1610745580	FRT BUMPER F-LAMP MOULDING <i>new</i>	1	150.00	10.00	135.00
1610745680	GRILLE MOULDING <i>x</i>	1	100.00	10.00	90.00
1610745880	RADIATOR GRILLE FRAME MDLG <i>cm</i>	1	240.00	10.00	213.00
1610746780	FRT BUMPER ABSORBER <i>de</i>	1	45.00	10.00	40.50
1610746880	DETECTOR SENSOR SUPPORT SET <i>new</i>	1	91.00	10.00	81.90
9800498680	FRT GUARD GRILLE <i>?</i>	1	141.00	10.00	126.90
1623159580	BRACKET SET <i>new</i>	1	60.00	10.00	54.00
1610745980	FRT BUMPER LWR MOULDING <i>?</i>	1	168.00	10.00	151.20

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2017		20 Nov 2017 10:13 <a href="#">Edit Adj Rpt</a>	<b>S\$8,034.60</b> <a href="#">Edit Estimates</a>	<b>S\$8,034.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>				<b>[Created by insurer]</b>					
Insured:	CHEN LILY, ID: S8771397], Tel: +6598364729								
Vehicle Reg. No.:	SLT6500L	Date of Loss:	16/11/2017 16:00 - :59						
Claim Type:	OD / C0459916	Policy/Cover Note No.:	P2025622 (Comprehensive)						
		Excess:	S\$400.00						
Repairer:	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Yvonne Ang Ching Ching - 6880 4461]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/11/2017]								
Driver/Custodian:	CISSY CHEN YU (33 / Female), NRIC: S8371281C, Tel: +6581827644								
Adj Asg. Remarks:	basic excess \$400 + un-named driver excess \$500								
<b>ASSOCIATED MAIL RECEIVED</b>									
<a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Claim Documents

\*SLT6500L (C0459916)  
OD  
Nov 16 2017 4:00PM  
[CHEN LILY]  
AutoFrance

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> ▼		
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/11/17 14:46	Adjuster Immediate Advice		Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
11	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
12	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
13	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
14	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
15	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
16	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
17	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
18	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
19	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
20	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
21	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
22	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
23	27/02/18 14:47	General View		Load JPG	<input checked="" type="checkbox"/>
24	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	27/02/18 14:48	Reinspection Photo		Load JPG	

					<input checked="" type="checkbox"/>
33	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	27/02/18 14:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	27/02/18 15:02	General View		Load PDF	
37	27/02/18 15:02	Reinspection Photo		Load PDF	
Documentation					<div>1 per page ▾<input checked="" type="checkbox"/></div>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/11/17 09:39	YP1703T TP GREAT EASTERN GIA_ABS		Load PDF	
2	20/11/17 09:39	SLT6500L INS GIA_ABS		Load PDF	
3	20/11/17 09:39	LICENCE_ABS		Load JPG	<input checked="" type="checkbox"/>
4	20/11/17 09:39	ESTIMATE_ABS		Load PDF	
5	20/11/17 09:39	EMAIL_ABS		Load PDF	
6	14/02/18 15:43	Workshop		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/18 17:32	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd  
8 Shenton Way #24-01, AXA Tower  
Singapore 068811

Our File No: CS/AXA17022049/T1TB2

Date: 27/02/2018

### REFERENCE

Insured/Claimant:	CHEN LILY	Policy No:	P2025622		
Date of Loss:	16/11/2017	Nature of Claim:	OD	Claim No:	C0459916

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT6500L</b>		
Make & Model:	PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)	Engine No:	10XTA40699447
Reg. Date:	06/11/2017 (Man. Year: 2017)	Chassis No:	VF3LRHNYWHS142327
Colour:	Black	Odometer:	681 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,712.40	3,784.60	2,927.80	43.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,310.00	4,250.00	6,060.00	58.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,022.40</b>	<b>8,034.60</b>	<b>8,987.80</b>	<b>52.80</b>
<b>- Excess (\$\$)</b>	<b>400.00</b>	<b>400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>16,622.40</b>	<b>7,634.60</b>	<b>8,987.80</b>	<b>54.07</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,163.57</b>	<b>534.42</b>	<b>629.15</b>	<b>54.07</b>
<b>Nett Amount (\$\$)</b>	<b>17,785.97</b>	<b>8,169.02</b>	<b>9,616.95</b>	<b>54.07</b>

### INSPECTION

Date of Assignment:	20/11/2017		
Date Inspected:	21/11/2017	Inspected At:	AutoFrance (HQ) 305 Alexandra Road, #02-01 Singapore 159942
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2018)

**Parts:** 144 PEUGEOT 308 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLT6500L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*SUNDRIES</b> (CONSISTENT)	Necessary	150.00 FS	*30.00 FS
2	1		<b>*FRT NUMBER PLATE</b> (CONSISTENT)	Dented	70.00 FS	*70.00 FS
3	1		<b>*FRT BUMPER</b> (CONSISTENT)	Distorted	630.00 F	*630.00 F
4	1		<b>*FRT BUMPER F-LAMP MOULDING</b> (CONSISTENT)	Necessary	135.00 F	*135.00 F
5	1		<b>*GRILLE MOULDING</b> (CONSISTENT)	Not Necessary	90.00 F	*- F
6	1		<b>*RADIATOR GRILLE FRAME MLDG</b> (CONSISTENT)	Cracked	216.00 F	*216.00 F
7	1		<b>*FRT BUMPER ABSORBER</b> (CONSISTENT)	Deformed	40.50 F	*40.50 F
8	1		<b>*SET DETECTOR SENSOR SUPPORT</b> (CONSISTENT)	Necessary	81.90 F	*81.90 F
9	1		<b>*FRT GUARD GRILLE</b> (CONSISTENT)	Not Necessary	126.90 F	*- F
10	1		<b>*SET BRACKET</b> (CONSISTENT)	Necessary	54.00 F	*54.00 F
11	1		<b>*FRT BUMPER LWR MOULDING</b> (CONSISTENT)	Not Necessary	151.20 F	*- F
12	1		<b>*FRT BUMPER C-FINISHER</b> (CONSISTENT)	Cut	131.40 F	*131.40 F
13	1		<b>*FINISHER BUMPER</b> (CONSISTENT)	Not Necessary	58.50 F	*- F
14	1		<b>*FRT BUMPER PLUG</b> (CONSISTENT)	Not Necessary	54.00 F	*- F
15	1		<b>*SET PROXIMITY SENSOR SUPPORTS FRT</b> (CONSISTENT)	Necessary	61.20 F	*61.20 F
16	1		<b>*FRT BUMPER BRACKET RH</b> (CONSISTENT)	Not Necessary	43.20 F	*- F
17	1		<b>*FRT BUMPER TOP RANGE</b> (CONSISTENT)	Not Necessary	40.50 F	*- F
18	1		<b>*FRT BUMPER RANGE</b> (CONSISTENT)	Cracked	61.20 F	*61.20 F
19	1		<b>*FRT BUMPER BRACKET RH</b> (CONSISTENT)	Not Necessary	36.00 F	*- F
20	1		<b>*MKT LWR FRT BPR PANEL FIXINGS</b> (CONSISTENT)	Necessary	54.90 F	*54.90 F
21	1		<b>*FRT FACE TOP CROSSMEMBER</b> (CONSISTENT)	Not Necessary	135.00 F	*- F
22	1		<b>*AIR BULKHEAD RH</b> (CONSISTENT)	Not Necessary	38.70 F	*- F
23	1		<b>*AIR BULKHEAD</b> (CONSISTENT)	Not Necessary	43.00 F	*- F
24	1		<b>*MKT FRONT MINI BUMPER FIXINGS</b> (CONSISTENT)	Not Necessary	118.80 F	*- F
25	1		<b>*FRT FENDER LH</b> (CONSISTENT)	Repair	288.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRT FENDER RH (CONSISTENT)	Repair	288.90 F	*- F
27	1		*ENGINE BONNET - ALUM (CONSISTENT)	Bent	675.00 F	*675.00 F
28	1		*FRT BADGE (CONSISTENT)	Necessary	33.30 F	*33.30 F
29	1		*FOG HEADLIGHT (CONSISTENT)	Not Necessary	70.20 F	*- F
30	1		*HEADLAMP ASSY LH (CONSISTENT)	Not Necessary	1,197.00 F	*- F
31	1		*BARE HEADLAMP RH, ADD DRIVER KIT (CONSISTENT)	Cracked	1,197.00 F	*1,170.00 F
32	1		*OBSTACLE DETECTION SENSOR FRT / RR (CONSISTENT)	Necessary	162.00 F	*162.00 F
33	2		*OBSTACLE DETECTION SENSOR FRT / RR (CONSISTENT)	Necessary	178.20 F	*178.20 F
Total Parts (\$\$)					6,712.40	3,784.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE/ REPAIR FRT BUMPER, FRT BONNET, FRT PANEL, FRT BUMPER BEAM	New	3,000.00	1,200.00
2	RESPRAY FRT BUMPER, FRT BONNET, FRT PANEL, FRT LHS FENDER, FRT RHS FENDER	New	3,600.00	2,400.00
3	WIRING CONNECTION & CHECK	New	150.00	150.00
4	REMOVE & REPLACE FRT PARKING SENSOR	New	150.00	150.00
5	REMOVE & REFIX A/C CONDENSER & RADIATOR	New	600.00	0.00
6	TO REMOVE & REPLACE FRT HEADLIGHT SYSTEM INCLUDING REALIGN FRT HEADLIGHT BEAM LEVEL	New	200.00	200.00
7	TO CONDUCT CAR O LINER CHASSIS ALIGNMENT & MEASUREMENT	New	1,680.00	0.00
8	TUFF KOTE @\$60 PER PANEL	New	240.00	60.00
9	SEALANT FOR FRT BONNET @\$90 PER PANEL	New	90.00	90.00
10	TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE	New	600.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,310.00</b>	<b>4,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >