

ASS. REC. BY: Surveyor REF: CS3/MSG17017006/R11b-1 02

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSIG Date/Time: 15-11-2017

Estimated Cost: BUD

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: S3H1400L Insured: S3G 8656K

at Workshop no/s: Trinice Tel: 6271 6422

of Blk 1001 Blk Merah Lane 3 # 01-63

Policy No: S2883302 6SMF Claim No: 528151

Sum Insured: Excess:

Make of Veh: D.O.A. 28/08/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 5/9/17 @ morning

Date/Time: 4/9/17 8:56am Person Contacted: Richard H.O.D Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	Do not Finalize
	<u>S3H1400L - NPA / INC 7016722/5 D.O.A. 28/8/2017</u>	
	<u>S3G 8656K - NPA / INC 7016722/5 D.O.A. 28/8/2017</u>	
	<u>Disassemble Part: 06092017</u>	
	<u>After repair: 07092017</u>	

031017 1148am Email to Catherine Thia thru Melimen

Lump Sum \$2,900/- (Red. 1000 : 25%)

11/1 - Typist.

[Signature]
10/1/2018

RECEIVED 1 JAN 2018.

PRG
Surinder
Indran

REF: mslh

ASSIGNMENT

From: Date: 08/09/2017
Estimated Cost:
OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
To Inspect Vehicle No: SJH 1400L
at Workshop m/s: Trinice
of: Blk 1001 Bukit Merah Lane 3
Insured: #01-63
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition) morning
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
IDAC Accident Rpt: Consistent? Yes or No
GIA / PR Seen: Consistent? Yes or No
Est. Repairs: days Res: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle. IN / OUT

Veh No: SJH 1400L Yr Regn: 2008 / Jul 28
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Mercedes Benz C 200 c.c. 1796
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 178714 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: W002040462A174121
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/40ZR18
R: -
BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 28/08/17
Rear: R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 05/09/17 @ 11.22
Survey held at: TRINICE
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE RANGE COST OF REPAIR - (3K - 4K)

RECEIVED: 15 OCT 2017

Date/Time File Pass to? ☐ : Prel. Report
1) 16.11.2017 ☐ : Final Report
Date/Time, File Return to?

Days Of Repair:
Resurvey No. of Trip:

Survey Fee:
Transportation:
S + RS: \$
Photos:
Others:

Report Format: PRG
Lump Sum / I.B.I.: (\$)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

TOTAL

180
180




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17017006/R1tb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 20-11-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJE 8656K	Veh. Inspected	SJH 1400L	
Policy No.	528833026SMF	Coverage (\$)	0.00	
Claim No.	528151	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	15/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/08/2017	Inspection Date	20/11/2017	
Survey held at	TRINICE AUTOMOBILE SERVICES BLK 1001 BUKIT MERAH LANE 3 #01-63 SINGAPORE 159724			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Lee Chee Hwee <cheehwee_lee@sg.msig-asia.com>
Sent: Wednesday, 15 November, 2017 8:43 PM
To: assignments
Cc: Catherine Thia; Monica Chung
Subject: Paper survey for SJH1400L

Dear Team,

We would like to appoint your firm to do a paper survey on the third party's vehicle.

Our Claim Ref No: 528151

Please visit Merimen to view the shared documents we've uploaded.

Kindly acknowledge upon receipt of the assignment.

Thank you.

Have A Great Week Ahead!

Dan Lee Chee Hwee
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2470 | Direct fax +65 6225 7402 | cheehwee_lee@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2017		31 Aug 2017 16:29 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div>CLAIM SUBFOLDER DETAILS [Created by insurer]</div> <div> Insured: TANG FOOK ONN, ID: S2203034E, Tel: +6596622449, Email: SALES@YUANSHENGDESIGN.COM Main Claimant: QUALITY LEASING PRIVATE LIMITED, Co. Reg. No.: 201312796G Vehicle Reg. No.: SJH1400L Date of Loss: 28/08/2017 21:00 - :59 Claim Type: TP / 528151 Policy/Cover Note No.: S28833026SMF (Comprehensive) Coverage: 12/11/2016 - 11/11/2017 Vehicle Reg. No. (Insured): SJE8656K Policy No. (Claimant): Excess: Repairer: Trinice Automobile Services (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-63, 159718 Bukit Merah - Tel: 62716422 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 01/09/2017] Driver/Custodian (Insured): TANG FOOK ONN (60 / Male), NRIC: S2203034E, Tel: +6596622449 </div> <div> View All Compose Case Mail </div>																								
ASSOCIATED MAIL RECEIVED There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								



ACRA Reg. No.
200309625D

EAST ASIA LAW CORPORATION

Advocates & Solicitors

133 New Bridge Road #10-02
Chinatown Point Singapore 059413
Tel: 65 6323 2565 Fax: 65 6323 2373
E-mail: law@ealc.com.sg
Website: www.ealc.com.sg

Kasturibai Manickam
Jocinda Wong Jia Heng

(Service of Court documents by way of fax is not accepted)

CT

Our Ref: 2017.5120.EA.MK.YA
Your Ref: SJE8656K

25-Oct-2017

WITHOUT PREJUDICE

PDX#8173
MSIG INSURANCE SINGAPORE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Department

CERTIFICATE OF POSTING
TANG FOON ONN
506 Bedok North Avenue 3
#22-323 Singapore 460506

PDX Intercompany Exchange Pte Ltd



010808249463

FROM EAST ASIA LAW CORP.
PDX Box No. 8060

Dear Sir,


CLAIMANT: QUALITY LEASING PRIVATE LIMITED
ACCIDENT INVOLVING SJH1400L & SJE8656K ON 28 AUGUST 2017 ALONG SIMS AVENUE (IN FRONT OF EUNOS MRT) AT ABOUT 2130 HOURS

QUALITY LEASING PRIVATE

We act for LIMITED, the owner of vehicle no. SJH1400L, whose vehicle was damaged as a result of the abovementioned accident by vehicle no. SJE8656K and our search reveals that you were the insurers of motor vehicle no. SJE8656K

We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1) Costs of repair	\$ 3,900.00
2) Loss of Use (PRI 2+4)	\$ 720.00
3) Survey report fee	\$ 654.00
4) LTA search fee	\$ 8.00
5) GIA search fee/report fee	\$ 29.00
6) Costs + GST	\$ 963.00
7) Incidentals + GST	\$ 53.50
Total:	\$ 6,327.50



We enclose copies of the following documents supporting our client's claim for your attention:-

- 1) GIA accident report of our client's repo SJH1400L
 - 2) LTA search for SJE8656K
 - 3) Final repair bill for SJH1400L
 - 4) Original Survey report enclosing original color copies of photographs depicting damages to vehicle no. SJH1400L
- Enclosed document may be photocopied on both sides to save paper and be environment friendly

Please note that if you are insured and you wish to claim your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days from the receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

Kasturibai Manickam
East Asia Law Corporation

Enc.

cc:

Ref: SJH1400L

Enquire Vehicle & Owner Information (Vehicle No. SJE8656K As At 28 Aug 2017 / 21:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: TRINICE-SJH1400

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S2203034E

Owner Name: TANG FOOK ONN

Registered Address Type: HDB / HUDC

Registered Block/House No.: 506

Registered Street Name: BEDOK NORTH AVENUE 3

Registered Unit No.: # 22 - 323

Registered Building Name: -

Registered Postal Code: 460506

Current Vehicle Details

Vehicle No.: SJE8656K

Make Description/Model: TOYOTA / ESTIMA 2.4X A

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
Last updated on 27 Aug 2017 at 01:09 AM

TRINICE AUTOMOBILE SERVICES

BLOCK 1001, BUKIT MERAH LANE 3 #01-63 SINGAPORE 159718

TEL: 6271 6422

Name : Quality Leasing Pte Ltd

Date : 27-Sep-17

Address : c/o Block 1001, Bukit Merah Lane 3
#01-63
Singapore 159718

Final repair bill for Mercedes Benz C180 SJH 1400 L

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 3,900.00

Dollars : Three Thousand Nine Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 20100026813

Billing Name & Address

Quality Leasing Pte Ltd
c/o Block 1001, Bukit Merah Lane 3
#01-63
Singapore 159718

Invoice No 09-17005/AY

Date 27 Sep 2017

Vehicle No : SJH 1400 L

Model : Mercedes Benz C180

Item	Descriptions	Amount S\$
1	Date of inspection : <u>5 Sep 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>94</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 654.00</u>
	SDLS : SIX HUNDRED AND FIFTY-FOUR ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Report Reference : TP / 09-17005/AY / 2017

Date of Report : 27 Sep 2017

Quality Leasing Pte Ltd
c/o Block 1001, Bukit Merah Lane 3
#01-63
Singapore 159718

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 28 Aug 2017

As per your instruction dated 5 Sep 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJH 1400 L. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJH 1400 L
Model : Mercedes Benz C180
Year / Capacity : 2008/1796
Chassis No : WDD2040462A174121
Engine No : 27195231087060
Mileage : 178714
Colour : Silver

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	225/40 R18	Michelin	6.00	mm	Sport
REAR	O/S	:	255/35 R18	Michelin	6.00	mm	Sport
FRONT	N/S	:	225/40 R18	Michelin	6.00	mm	Sport
REAR	N/S	:	255/35 R18	Michelin	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 Autotbay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Trinice Automobile Services
Block 1001, Bukit Merah Lane 3
#01-63
Singapore 159718

5. Estimated normal period of repair : 4 working days to complete.
6. Enclosed number of photograph : 94 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJH 1400 L
Report No: TP/ 09-17005/AY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Boot lid	Repair	\$ 975.00	\$
1	Boot lid logo	Necessary	\$ 28.00	\$ 28.00
1	Boot lid 'C200' emblem	Necessary	\$ 52.00	\$ 52.00
1	Boot lid 'C & C' emblem	Necessary	\$ 33.00	\$ 33.00
1	Boot lid 'AMG' emblem	Necessary	\$ 54.00	\$ 54.00
2	Rear taillamps	Damage	\$ 950.00	\$ 950.00
1	Rear end panel	Repair	\$ 670.00	\$
1	Rear end panel inner garnish	Intact	\$ 173.00	\$
1	Rear bumper	Damage	\$ 1350.00	\$ 1350.00
1	Rear bumper lower	Damage	\$ 346.00	\$ 346.00
2	Rear bumper side top brackets	Damage	\$ 84.00	\$ 84.00
1	Rear bumper reinforcement	Damage	\$ 495.00	\$ 495.00
2	Rear bumper side retainers	Necessary	\$ 110.00	\$ 110.00
			<u>\$ 5320.00</u>	<u>\$ 3502.00</u>
<u>Special Nett Items</u>				
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00
			<u>\$ 280.00</u>	<u>\$ 280.00</u>

Spare Parts Total \$ 5600.00 \$ 3782.00

Vehicle No: **SJH 1400 L**
 Report No: **TP/ 09-17005/AY / 2017**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 5600.00	\$ 3782.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 X
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 100.00	\$ 80.00 60
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 60
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 440.00 350
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 440.00 400
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	Not Required 870
Total		<u>\$ 7800.00</u>	<u>\$ 4862.00</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 3900.00

SDLS: THREE THOUSAND NINE HUNDRED ONLY


 Qualified Appraiser

2552.00
 220.00
 870.00
 3642
 209
 2913.60
 413 - 2,900
 4 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2017 15:01
Date Of Accident	28/08/2017 21:30
Exact Location Of Accident	SIMS AVE (IN FRONT OF EUNOS MRT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH1400L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	QUALITY LEASING PRIVATE LIMITED
Co Reg No	201312796G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90468708
Alternative Phone No	OFFICE-90468708

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180K
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088408070
Cover Note Number	

Driver

Name of Driver	MOHAMMED HAFEZ BIN ABD RAHMAN
NRIC No	S7307082A
Date Of Birth	24/02/1973
Occupation	OUTDOOR
Date Of Driving Pass	20/11/1996
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90468708
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	71 FLORA DRIVE #05-03
Postcode	506881
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG SIMS AVE, WHEN CAME NEAR TO EUNOS MRT THERE WAS A TRAFFIC LIGHT. THE LIGHT WAS RED AND I STOPPED WAITING FOR THE LIGHT TO TURN GREEN. SUDDENLY A VEHICLE (SJE 8656K) COLLIDED ONTO MY VEHICLE'S REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE8656K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	MOHAMMED HAFEZ BIN ABD RAHMAN
Approximate Age	
Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SJH1400L
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Accident Sketch Plan

Describe Circumstances of the Accident

Please refer to statement

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

For

Driver's Signature (if driver is not the policyholder) / Date & Time

Classified by Reporting Officer

Witnessed by Reporting Centre
Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2017		31 Aug 2017 16:29 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TANG FOOK ONN, ID: S2203034E, Tel: +6596622449, Email: SALES@YUANSHENGDESIGN.COM								
Main Claimant:	QUALITY LEASING PRIVATE LIMITED, Co. Reg. No.: 201312796G								
Vehicle Reg. No.:	SJH1400L	Date of Loss:	28/08/2017 21:00 - :59						
Claim Type:	TP / 528151	Policy/Cover Note No.:	S28833026SMF (Comprehensive) Coverage: 12/11/2016 - 11/11/2017						
Vehicle Reg. No. (Insured):	SJE8656K	Policy No. (Claimant):							
		Excess:							
Repairer:	Trinice Automobile Services (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-63, 159718 Bukit Merah - Tel: 62716422								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 01/09/2017]								
Driver/Custodian (Insured):	TANG FOOK ONN (60 / Male), NRIC: S2203034E, Tel: +6596622449								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH1400L (528151)

[SJE8656K]

TP

QUALITY LEASING PRIVATE LIMITED

Aug 28 2017 9:00PM

[TANG FOOK ONN]

Trinice Automobile Services

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	31/08/17 16:29	Accident Statement From:SC - Reg. No: SJE8656K, Claimant: TANG FOOK ONN							Load HTM		
2	31/08/17 16:29	Addendum Sheet From:SC - Reg. No: SJE8656K, Claimant: TANG FOOK ONN							Load TIF		
3	31/08/17 16:29	Accident Statement Addm. #1 From:SC - Reg. No: SJE8656K, Claimant: TANG FOOK ONN							Load HTM		
									3 per page		<input checked="" type="checkbox"/>
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/10/17 11:45	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	03/10/17 11:45	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
4	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
5	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
6	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
7	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
8	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
9	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
10	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
11	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
12	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
13	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
14	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
15	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
16	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
17	03/10/17 11:45	General View							Load JPG	<input checked="" type="checkbox"/>	
18	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
19	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
20	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
21	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
22	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
23	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
24	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
25	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
26	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
27	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
28	03/10/17 11:46	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
29	03/10/17 11:47	Photo After Spray							Load JPG		

					<input checked="" type="checkbox"/>
30	03/10/17 11:47	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
31	03/10/17 11:47	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
32	03/10/17 11:47	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
33	03/10/17 11:47	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/08/17 16:29	TP SJH1400L GIA REPORT From:SC - Reg. No: SJE8656K, Claimant: TANG FOOK ONN		Load PDF	
2	15/11/17 20:42	Acknowledgement to TP		Load PDF	
3	15/11/17 20:42	LOD		Load PDF	
4	15/11/17 20:42	TP SURVEY REPORT 1 OF 3		Load PDF	
5	15/11/17 20:42	TP SURVEY REPORT 2 OF 3		Load PDF	
6	15/11/17 20:42	TP SURVEY REPORT 3 OF 3		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/18 10:58	Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17017006/R1TBE2-1

Date: 11/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S28833026SMF

Claimant Vehicle No : SJH1400L

Insured Vehicle No : SJE8656K

Date of Loss: 28/08/2017

Nature of Claim: TP

Claim No: 528151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJH1400L

Make & Model: MERCEDES-BENZ C180K, 1.8 (A)

Engine No: 27195231087060

Reg. Date: 28/07/2008 (Man. Year: 2008)

Chassis No: WDD2040462A174121

Colour: Grey

Odometer: 178714 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,600.00	2,772.00	2,828.00	50.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	870.00	1,330.00	60.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,800.00	3,642.00	4,158.00	53.31
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	7,800.00	2,900.00	4,900.00	62.82

INSPECTION

Date of Assignment: 31/08/2017

Date Inspected: 05/09/2017 Inspected At:

Trinice Automobile Services (HQ)
BLK 1001 BUKIT MERAH LANE 3 #01-63
Singapore 159718

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2018)
Parts: 143	MERCEDES-BENZ C180K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJH1400L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	975.00 F	*- F
2	1		*BOOT LID LOGO	Necessary	28.00 F	*28.00 F
3	1		*BOOT LID C200 EMBLEM	Necessary	52.00 F	*52.00 F
4	1		*BOOT LID C & C EMBLEM	Necessary	33.00 F	*33.00 F
5	1		*BOOT LID AMG EMBLEM	Necessary	54.00 F	*54.00 F
6	2		*REAR TAILLAMPS	Serviceable	950.00 F	*- F
7	1		*REAR END PANEL	Repair	670.00 F	*- F
8	1		*REAR END PANEL INNER GARNISH	Intact	173.00 F	*- F
9	1		*REAR BUMPER	Damaged	1,350.00 F	*1,350.00 F
10	1		*REAR BUMPER LOWER	Damaged	346.00 F	*346.00 F
11	2		*REAR BUMPER SIDE TOP BRACKETS	Damaged	84.00 F	*84.00 F
12	1		*REAR BUMPER REINFORCEMENT	Damaged	495.00 F	*495.00 F
13	2		*REAR BUMPER SIDE RETAINERS	Necessary	110.00 F	*110.00 F
14	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*220.00 FS
Total Parts (S\$)					5,600.00	2,772.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	0.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	100.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	150.00	60.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	350.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	900.00	400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	100.00	0.00
Gross Labour Cost (S\$)			2,200.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >