



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR YU HANBIN BLK 430D FERNVALE LINK #16-247 SINGAPORE 794430 Contact No Mobile: 97932123	Cust No/Name /MR YU HANBIN Reg No/Reg Date SLK4964S*FS1F/ 19/01/201 Date In/Mileage / 0 Chassis No KNAHU815VG7164533 Engine No D4FDGH113349 Make/Model KIA/CARENS 1.7 A D SX SUNROOF GP8 Colour/Trim 3D BRIGHT SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	04/09/2017/ 18:53		261 / Edwin Caina	14356

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN FRT DAMAGED PORTION: RENEW FRT BUMPER & FRT BUMPER AIRDAM				550 1650.00
E PNT98000 RESPRAY FRT BUMPER , FRT BUMPER AIRDAM & OTHER AFFECTED AREAS				840 1260.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
E PNT88000 REMOVE & REFIT FRT PARKING SENSOR				80 100.00
M SUNDRY Sundries				20 30.00
P COVER-FR BUMPER	1.00	668.00	00.00	de 668.00
M CARENS BRIGHT SILVER-3D	1.00	1688.00	00.00	de 1688.00
M STRIP ASSY-FR BUMPER UPR	1.00	32.00	00.00	re 32.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	78.00	00.00	? 78.00
M RAIL ASSY-FR BUMPER	1.00	389.00	00.00	? 389.00
M EMBLEM-KIA	1.00	76.00	00.00	re 76.00

SURVEYOR NAME: Tanpin 97495749SURVEYOR SIGNATURE: [Signature]DATE: 27/12/2015REMARKS: Resurvey before paint
3 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

7% GST on	Nett 6221.00	6,221.00
		435.47
	Total Payable	6,656.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We acknowledge that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.