

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 0579/11/2017

Page : 1

Date : 17/11/2017

M/S : CHINA TAIPING INSURANCE SINGAPORE PTE LTD
3 ANSON ROAD #15-00
SPRING LEAF TOWER
SINGAPORE 079909

ACCIDENT REPAIR ON : CB 6757 P - SUNLONG
POLICY NO :
DATE OF ACCIDENT : 10/11/2017

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

- 1 FRONT RIGHT HEADLIGHT
- 2 REAR BUMPER

S\$


S\$

586.00 *an*
1,240.00 *Pr*
1,826.00

LABOUR CHARGES :

- 3 KNOCKING PUSH OUT FRONT ACCIDENT PARTS
STRIP / REFIT ABOVE ACCESSORIES
- 4 SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS

350 ✓ 300.00
-480.00
2,606.00



Couh

9507

21/11

*Not Done
HS Repair
After paint job
17/11/2017
2 w days*

Link to Consultants hence notify
the insurer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: