

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 0579/11/2017

Page : 1

Date : 17/11/2017

M/S : CHINA TAIPING INSURANCE SINGAPORE PTE LTD
3 ANSON ROAD #15-00
SPRING LEAF TOWER
SINGAPORE 079909

ACCIDENT REPAIR ON : CB 6757 P - SUNLONG
POLICY NO :
DATE OF ACCIDENT : 10/11/2017

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

- 1 FRONT RIGHT HEADLIGHT
- 2 REAR BUMPER

	S\$	S\$
1 FRONT RIGHT HEADLIGHT	586.00	
2 REAR BUMPER	1,240.00	
		1,826.00

LABOUR CHARGES :

- 3 KNOCKING PUSH OUT FRONT ACCIDENT PARTS
STRIP / REFIT ABOVE ACCESSORIES
- 4 SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS

350.00	300.00
	480.00
	<u>2,606.00</u>



Couh

\$ 950.00
21/11

*Not Done
HS Repair
After paint job
17/11/2017
2 w days*