

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLD2392S

Chassis No : JHMGK5850GX202741

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : WEE WILLIAM

Ins Policy No. : TP DIRECT SETTLEMENT

Date of Accident : 28/7/2017

Document No. : SQT17004486

Date : 1. Nov 2017

Customer No. : WZA006

Svc Advisor : JASON HENG

Engine No : L15B31021099

Date | Time : 1. Nov 2017 8:49:01 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:) OWNER: WEE WILLIAM OWNER INSURER: DIRECT ASIA INSURANCE ACC DATE: 28/7/17 SURVEYED BY: DATE: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: PA7625G						
04711-T5A-000ZZ	FACEFR.BUMPER ✓CAK	1	494.80	35	321.62	22.51	344.13
71193-T5A-000	SPACERR.FR.BUMPER ✓NEC	1	10.40	35	6.76	0.47	7.23
71198-T5A-000	SPACERL.FR.BUMPER X	1	10.40	35	6.76	0.47	7.23
91505-TM8-003	CLIPBUMPER ✓NEC	17	2.00	35	22.10	1.55	23.65
71103-T5A-N00	GARNISHR.FR.BUMPER X	1	23.20	35	15.08	1.06	16.14
71140-T5A-000	BRACKETR.HEADLIGHT ?	1	23.60	35	15.34	1.07	16.41
33100-T5A-J21	HEADLIGHT ASSY,R. ?	1	1118.60	35	727.09	50.90	777.99
Sum Item					1114.75	78.03	1,192.78
BOSUN	SUNDRIES	1	50.00 X		50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00 ?		160.00	11.20	171.20
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	2000.00 560		2000.00	140.00	2140.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1000.00 450		1000.00	70.00	1070.00
Sum Labor					3210.00	224.70	3,434.70

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 4,324.75 302.73 4,627.48

Total (Inclusive of GST) 4,627.48

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLD2392S
Chassis No : JHMGK5850GX202741
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : WEE WILLIAM
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 28/7/2017

Document No. : SQT17004486
Date : 1. Nov 2017
Customer No. : WZA006
Svc Advisor : JASON HENG
Engine No : L15B31021099
Date | Time : 1. Nov 2017 8:49:01 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
------	-------------	-----	------------	--------	--------	---------	------------------

Sathya Sai

25/6/2018

98072012

Sathya Sai@lkkawto.com

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Part by Part repair

- Question mark item photo

- Photo before paint.

Printed on 1/11/2017 8:53:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)