

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9158D -**AAD1711-185***Not Authored*
L1 Sup & Pool

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9158D - CANDY

KL1LA69RJBB058772

CHEVROLET

EPICA 2.0

14.11.2017

AXA**PART****LIST**

1	1	Front Bumper	\$	<i>N</i>	1,202.00	<i>X</i>
2	1	Front Bumper Lower Absorber	\$	<i>Sn</i>	180.00	
3	1	Front Bumper Reinforcement	\$	<i>N</i>	356.00	
4	1	Front Bumper Retainer RH	\$	<i>Sn</i>	102.00	
5	1	Front Bumper Retainer LH	\$	<i>Sn</i>	102.00	
6	1	Front Bumper Lower Grille	\$	<i>Sn</i>	78.00	
7	1	Front Bumper Lower Stiffener	\$	<i>Sn</i>	134.37	
8	1	Front Bumper Bracket LH	\$	<i>N</i>	10.00	
9	1	Front Bumper Bracket RH	\$	<i>N</i>	10.00	
10	1	Bumper Fog Lamp Cover RH	\$	<i>Sn</i>	32.40	
11	1	Bumper Fog Lamp Cover LH	\$	<i>Sn</i>	32.40	
12	1	Front Windscreen	\$	<i>Sn</i>	1,304.00	
13	1	Front Windscreen Moulding	\$	<i>Sn</i>	196.00	
14	1	Front Fender LH	\$	<i>N</i>	837.60	
15	1	Front Fender RH	\$	<i>N</i>	837.60	
16	1	Front Fender Liner RH	\$	<i>Sn</i>	47.00	
17	1	Front Fender Liner LH	\$	<i>Sn</i>	47.00	
18	1	Resonator (B/S Fender LH) AIR BOX	\$	<i>Sn</i>	134.67	
19	1	Resonator Hose	\$	<i>Sn</i>	37.00	
20	1	Bonnet	\$	<i>N</i>	1,250.00	
21	1	Bonnet hinge RH	\$	<i>N</i>	36.00	
22	1	Bonnet hinge LH	\$	<i>N</i>	36.00	
23	1	Bonnet Moulding	\$	<i>Sn</i>	161.97	
24	1	Bonnet Lock	\$	<i>N</i>	60.00	
25	1	Bonnet cable	\$	<i>Sn</i>	125.00	
26	1	Front Support Panel Assy	\$	<i>N</i>	1,222.32	
27	1	Headlamp RH	\$	<i>h3cm</i>	816.00	<i>X</i>
28	1	Headlamp LH	\$	<i>Sn</i>	816.00	
29	1	Windscreen Washer Tank - Filler Neck	\$	<i>Sn</i>	4.80	
30	1	Windscreen Washer Tank	\$	<i>Sn</i>	62.00	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-185**

NQ.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9158D -

31	1	Windscreen Washer Tank Motor	\$	51.00	}	X
32	1	Washer Tank Hose	\$	21.00		
33	1	Radiator Assembly	\$	618.00		
34	1	Radiator upper hose	\$	30.00		
35	1	Radiator lower hose	\$	120.00		
36	1	Radiator Grille (Grille A-Rad)	\$	367.00		
37	1	Radiator Grille Top Cover	\$	45.02		
38	1	Fan Blade(A/C)	\$	536.00		
39	1	Fan Blade(Radiator)	\$	634.00		
40	1	Aircon Condenser	\$	600.00		
41	1	Aircon hose - condenser to compressor	\$	450.00	}	
42	1	Aircon hose - compressor to evaporator	\$	624.00		
43	1	Aircon hose - condenser to evaporator	\$	580.00		
44	1	Air Intercooler	\$	652.00		

TOTAL	\$	15,598.15
--------------	----	------------------

10%	\$	1,559.82
------------	----	-----------------

	\$	14,038.34
--	----	------------------

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$	nn	24.00	X
2	2	Front Windscreen Sealant	\$	nn	100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	nn	100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	nn	10.00	X
5	1 Set	Front licence plate with holder	\$	pd	192.00	455n
6	1 Set	Radiator Grille clip	\$	nn	35.00	} X
7	1 Set	Front Fender Liner clip LH	\$	nn	30.00	
8	1 Set	Front Fender Liner clip RH	\$	nn	30.00	
9	1 Set	Louver Cowl Top clip	\$	nn	30.00	
10	2	Bonnet stopper	\$	sl	15.00	
11	1	Door Sticker "Trans-cab"RH	\$	nn	80.00	}
12	1	Front Tyre RH	\$	sl	180.00	
13	1	Front Tyre Rim RH	\$	sl	126.00	
14	1	Front Tyre LH	\$	sl	180.00	
15	1	Front Tyre Rim LH	\$	sl	126.00	}

TOTAL	\$	1,258.00
--------------	----	-----------------

TOTAL PARTS	\$	15,296.34
--------------------	----	------------------

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-185**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9158D -

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	1001
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00	~ X
Putty and spray painting of the affected portion.	\$	5,350.00	2001
Towing Fees.	\$	120.00	~ X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	~ X
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To replace, refix and top up coolant for radiator	\$	170.00	~ X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	~ X
To rust-proofing of the affected areas.	\$	170.00	~ X

TOTAL	\$	12,970.00
Over All Total	\$	28,266.34

Repair Days~~15 Days~~
1 day